# Heritage at Risk



# Contents

The Register	IV	Hastings	132
Criteria	IV	Lewes	135
		Rother	135
Key statistics	VII	South Downs (NP) Wealden	136 138
Key to the Entries	VIII	Hampshire	130
Entries on the Register by local planning	X	Basingstoke and Deane	139
authority		East Hampshire	139
Greater London	I	Eastleigh	140
Barking and Dagenham	ı	Fareham	140
Barnet	2	Gosport	140
Bexley	4	Hart	142
Brent	4	Havant	143
Bromley	6	New Forest	143
Camden	11	New Forest (NP)	144
City of London	17	Rushmoor	145
Croydon	18	Test Valley	148
Ealing	20	Winchester	149
Enfield	23	Isle of Wight (UA)	152
Greenwich	27	<b>G</b> ( )	157
Hackney	29	Kent	
Hammersmith and Fulham	36	Ashford	157
Haringey	38	Canterbury	158
Harrow	42	Dartford	160
Havering	46	Dover	160
Hillingdon	48	Folkestone and Hythe	163
Hounslow	56	Maidstone Sevenoaks	165 167
Islington	61	Swale	167
Kensington and Chelsea	66 74	Thanet	171
Kingston upon Thames	74	Tonbridge and Malling	171
Lambeth Lewisham	76 83	Tunbridge Wells	172
London Legacy (MDC)	87	Kent (off)	173
Merton	88		
Newham	92	Medway (UA)	175
Redbridge	94	Milton Keynes (UA)	177
Richmond upon Thames	96	Oxfordshire	178
Southwark	99	Cherwell	178
Sutton	106	Oxford	170
Tower Hamlets	107	South Oxfordshire	180
Waltham Forest	114	Vale of White Horse	183
Wandsworth	117	West Oxfordshire	184
Westminster, City of	119	Portsmouth, City of (UA)	185
Bracknell Forest (UA)	123	, , ,	
Brighton and Hove, City of (UA)	123	Reading (UA)	188
South Downs (NP)	126	Southampton, City of (UA)	189
Buckinghamshire (UA)	127	Surrey	190
East Sussex	131	Elmbridge	190
Eastbourne	131	Epsom and Ewell Guildford	190 191

II

Mole Valley	191
Reigate and Banstead	193
Runnymede	193
Spelthorne	193
Tandridge	193
Waverley	194
Woking	194
West Berkshire (UA)	195
West Sussex	197
Adur	197
Arun	197
Chichester	198
Horsham	199
Mid Sussex	200
South Downs (NP)	201
Worthing	204
Windsor and Maidenhead (UA)	205
Wokingham (UA)	205

## THE REGISTER

The Heritage at Risk Register includes historic buildings and sites that are at risk of loss through neglect, decay or development, or are vulnerable to becoming so. It includes all types of designated heritage assets, including Conservation Areas, which are designated and assessed by Local Planning Authorities.

The aim of the Register is to focus attention on those places in greatest need. Historic England, in partnership with others, is able to help tackle heritage at risk. We work with owners, friends groups, developers and other stakeholders to find imaginative solutions for historic places and sites at risk across England.

More information about our role, the advice and funding available, and useful <u>publications</u> and <u>guidance</u> is available on our <u>website</u>.

# Criteria for inclusion on the Register

#### **RISK ASSESSMENTS**

Heritage assets included on the Register are assessed according to the nature of the site. The risk assessment methodologies outlined below are based on factors which can threaten the different types of heritage assets and lead to them becoming at risk.

#### **BUILDINGS AND STRUCTURES**

To be considered for inclusion on the Register, buildings or structures must be listed on the National Heritage List for England; and in secular (non-worship) use. And either:

- a grade I or II\* listed building, or
- a grade II listed building in London, or
- a structural scheduled monument with upstanding remains.

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'part-occupied', 'occupied', 'not applicable', or occasionally, 'unknown'.

Many structures fall into the 'not applicable' category, for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. A few buildings remain on the Register in good condition whilst solutions are being implemented as a reminder of the need for monitoring, and to ensure that repair and re-use are seen through to completion.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

### PLACES OF WORSHIP

To be considered for inclusion on the Register, places of worship must be listed grade I, grade II\* or grade II on the National Heritage List for England and be used as a public place of worship at least six times a year.

The method used to assess whether a place of worship is at risk is essentially the same as that used to assess other historic buildings or structures (as outlined above), with one important difference: the criterion as to whether a building is occupied is not used as by their nature, places of worship are in use. Places of worship will be assessed as at risk and added to the Register if their condition is assessed to be very bad or poor.

It is often the case that only part of a church building, e.g. the tower or one of the aisles, is in very bad or poor condition, and it then becomes a matter of professional judgement whether this puts the whole building at risk. Usually if a major or a very significant element of a church is considered to be at risk then the judgement is made that the whole building is at risk and it is included in the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even to good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

#### **ARCHAEOLOGY**

To be considered for inclusion on the Register, archaeological sites must be designated as scheduled monuments on the National Heritage List for England.

Archaeology assessments cover scheduled earthworks and buried archaeology.

The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from 'extensive significant problems' to 'minor localised problems'. The trend will also be recorded as 'improving', 'stable', 'declining' or 'unknown'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

#### PARKS AND GARDENS

To be considered for inclusion on the Register, parks and gardens must be designated as grade I, grade II\* or grade II on the National Heritage List for England. Parks and gardens are assessed in terms of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

#### **BATTLEFIELDS**

To be considered for inclusion on the Register, battlefields must be included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

Each battlefield is assessed against four key criteria:

• Landscape readability – is it possible to understand the context of the battle?

- Landscape features are hedgerows, walls and trees which had a significant impact on the battle still in place?
- Archaeological integrity is the archaeology of the battle being disturbed?
- Ambiance are activities such as development having a negative impact on the setting of the site?

Current condition, future vulnerability and trend are all taken into account.

Battlefields are removed from the Register either when damaging activities cease/are managed, or when threats recede due to effective planning.

#### WRECK SITES

To be considered for inclusion on the Register, wrecks must be designated as protected wreck sites on the National Heritage List for England.

Wreck sites are assessed based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability.

Wrecks are considered to be at risk if there is a significant likelihood of loss or further loss of historical, archaeological or artistic significance from it within the foreseeable future.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage. The monitoring process ensures that the significance of the site is identified and maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

#### CONSERVATION AREAS

Once a year Historic England asks every local authority in England to consider the state of its conservation areas and fill in (and update as appropriate) risk assessment questionnaires for those that cause concern or are believed to no longer be at risk.

Conservation areas that are deteriorating or are in very bad or poor condition and not expected to change significantly in the next three years are defined as being at risk.

Categories for condition, vulnerability and trend are included for each conservation area on the Heritage at Risk Register.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. Conservation areas identified as at risk in 2009 but not reassessed since using the revised methodology are included on the Register but with limited information.

Conservation area entries are removed from the Register once issues have been identified, plans put in place to address them, and positive progress is being made.

# THE EFFECT OF COVID-19 ON THE COLLECTION AND COLLATION OF THE STATISTICS USED FOR THE 2022 REGISTERS

Since early 2020, the Covid-19 pandemic has impacted on data collection and collation for both our staff and our local authority colleagues. As there was less disruption during the 2022 reporting year, we have been able to carry out more on-site checks of entries on, additions to and removals from the Register. Where this hasn't been possible desk-based assessments and updates have been carried out.

## Key Heritage at Risk Statistics for London & South East 2022

#### **BUILDINGS AND STRUCTURES**

- Of the 22,516 grade I and II\* listed buildings (excluding places of worship) in England, 756 (3.4%) are on the Register. Of the 5,925 listed secular buildings (of grade I and II\*) in London & South East 135 (2.3%) are on the Register.
- Of the 16,770 grade II secular buildings in London 367 (2.2%) are on the Register.
- In addition to this, of the 2,848 scheduled monuments in London & South East, 73 (2.6%) are on the Register assessed as structural scheduled monuments (i.e. using the buildings or structures methodology).
- 18 building or structure entries (of all grades and including structural scheduled monuments) have been removed from the previous London & South East Register (2021) for positive reasons and 14 have been added.

#### **PLACES OF WORSHIP**

- Of the 14,792 listed places of worship in England, 919 (6.2%) are on the Register. Of the 3,086 listed places of worship in London & South East 179 (5.8%) are on the Register.
- 4 places of worship entries have been removed from the previous London & South East Register (2021) for positive reasons and 9 have been added.

#### **ARCHAEOLOGY**

- Of the 19,933 scheduled monuments in England, 1,961 (9.8%) are on the Register assessed as archaeology. Of the 2,848 scheduled monuments in London & South East, 164 (5.8%) are on the Register assessed as archaeology.
- 5 archaeology entries have been removed from the previous London & South East Register (2021) for positive reasons, and 6 have been added.

#### **PARKS AND GARDENS**

• Of the 1,699 registered parks and gardens in England 104 (6.1%) are on the Register. Of the

- 547 registered parks and gardens in London & South East, 37 (6.8%) are on the Register.
- No park and garden entries have been removed for positive reasons and one has been added to the previous London & South East Register (2021).

#### **BATTLEFIELDS**

Of the 47 registered battlefields in England, 3
 (6.4%) are on the Register. None of the seven
 registered battlefields in London & South East are
 on the Register.

#### **WRECK SITES**

• Of the 54 protected wreck sites around England's coast, 4 (7.4%) are on the Register. Of the 4 on the Register, 3 are off the coast of Kent in the London & South East region and the other is in the in the Thames Estuary East of England region.

#### **CONSERVATION AREAS**

- There are 490 conservation areas on the Register across England. Of these, 137 are in London & South East.
- 2 conservation areas have been removed from the previous London & South East Register (2021) for positive reasons and none have been added.

#### HISTORIC ENGLAND FUNDING

- £2.41 million in grant was spent on 39 entries on the London & South East Register during 2021/22.
- In addition, £0.83 million of Covid-19 pandemic recovery funding was spent on 3 entries.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include structural scheduled monuments and listed buildings (excluding listed places of worship); archaeology assessments include earthworks and buried archaeology. Please note that some sites may have more than one entry under different risk assessment methodologies, for example if a site has more than one listing for its different elements or if it consists of both buried and structural remains.

2022 HAR data as at 11am 11 July 2022 2021 HAR data as at 12am 19 July 2021

## Key to the entries

The Register includes the following risk assessment types:

- Building or structure (for grade I and II\* listed Buildings, grade II listed buildings in London and structural scheduled monuments)
- Place of worship (for grade I, II\* and II listed buildings)
- Archaeology (for scheduled monuments earthworks and buried archaeology)
- Park and garden (for Registered parks and gardens)
- Battlefield (for Registered battlefields)
- Wreck site (for Protected wreck sites)
- Conservation area (for conservation areas)

(Please note not all assessment types appear in each of the regional registers.)

#### ORDER OF ENTRIES

Please refer to the 'Contents' page to see the order that the Planning Authorities are presented in.

Please note that Unitary Authorities are ordered under their own names and may not appear in the same section as the other planning authorities in their ceremonial (or former) county.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

### **DESIGNATION/LISTING**

The principal designation/listing type is noted for each entry:

- Listed Building (LB) grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\* or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CA)

Any other listing types that also apply to the site are also noted (e.g. location within a World Heritage Site (WHS); where a LB or SM is sited within a CA or RPG; or where a CA contains many LBs or SMs).

If an entry is dual designated on the National Heritage List for England (i.e. it is both a listed building and a scheduled monument) the two designations will be joined with an 'and' (e.g. 'Scheduled Monument and Listed Building grade I').

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site has dual list entries, all relevant List Entry Numbers are noted.

#### CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments – archaeology assessments, parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established)

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

#### OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use.

Occupancy (or use) is noted as follows:

- vacant (or not in use)
- part occupied (part in use)
- occupied (in use)
- unknown
- not applicable (for structural scheduled monuments)

#### **VULNERABILITY**

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as 'high', 'medium' or 'low'.

#### PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

The priority category for the previous year for the entry is given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

#### TREND

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

#### **OWNERSHIP**

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

#### CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

#### **ABBREVIATIONS**

CA Conservation Area
HE Historic England

NLHF National Lottery Heritage Fund

LB Listed Building

LPA Local Planning Authority

NP National Park

PWS Protected Wreck Site RB Registered Battlefield

RPG Registered Park and Garden SM Scheduled Monument

UA Unitary Authority

WHS World Heritage Site

# Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
GREATER LONDON							
Barking and Dagenham	4	l I	1	0	0	0	1
Barnet	4	4	1	0	0	0	1
Bexley	3	0	0	0	0	0	0
Brent	7	3	0	0	0	0	0
Bromley	19	I	3	I	0	0	I
Camden	17	14	0	0	0	0	0
City of London	0	2	0	0	0	0	0
Croydon	6	5	2	0	0	0	I
Ealing	7	I	2	0	0	0	5
Enfield	- 11	2	I	4	0	0	2
Greenwich	8	2	0		0	0	3
Hackney	20	11	0		0	0	2
Hammersmith and Fulham	12	ı	0		0	0	I
Haringey	11	5	0		0	0	5
Harrow	12	I	5		0	0	0
Havering	9	0	ı	0	0	0	I
Hillingdon	29	2	3		0	0	9
Hounslow	20	I	2		0	0	2
Islington	12	9	0	1	0	0	10
Kensington and Chelsea	31	4	0		0	0	10
Kingston upon Thames	5	1	0		0	0	3
Lambeth	26	<u> </u>				0	
		1	0		0	0	3
Lewisham	16	2	0		0		1
London Legacy (MDC)	4	0	0	0	0	0	2
Merton	14	0	1	1	0	0	6
Newham	13	0	0		0	0	0
Redbridge	3	2	0		0	0	3
Richmond upon Thames	15	0	0		0	0	l
Southwark	25	4	2		0	0	2
Sutton	5	I	0		0	0	I
Tower Hamlets	22	8		0	0	0	5
Waltham Forest	12	4	0		0	0	0
Wandsworth	7	0	0	1	0	0	0
Westminster, City of	12	9	0	0	0	0	0
BRACKNELL FOREST (UA)	1	I		1		I	1
Bracknell Forest (UA)	0	0	0	2	0	0	0
BRIGHTON AND HOVE, CI	TY OF (UA)	I	l	I	I	I	
Brighton and Hove, City of (UA)	6	5	0	1	0	0	5
SOUTH DOWNS (NP)							
South Downs (NP)	0	0	1	0	0	0	
BUCKINGHAMSHIRE (UA)	0	0	<u> </u>	0	0	0	<u> </u>
	8	5	8	2	0	0	0
Buckinghamshire (UA)	8	5	8	Z	0	0	0
EAST SUSSEX							
Eastbourne	5	0	1	0	0	0	0
Hastings	5	6	0		0		
Lewes		0	0		0		0
Rother	4	I		0	0		0
South Downs (NP)	2	0	5	0	0	0	0
South Downs (NP) / Brighton and Hove, City of (UA) / Lewes <sup>†</sup>	0	0	0	ı	0	0	0
Wealden	2	2	0	I	0	0	0
Wealden / Tunbridge Wells <sup>†</sup>	0		1	0	0	0	0

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
HAMPSHIRE							
West Berkshire (UA) / Basingstoke and Deane <sup>†</sup>	0	0	0	ı	0	0	0
Basingstoke and Deane	I	0	I	0	0	0	0
East Hampshire	0	0	I	0	0	0	0
Eastleigh	0	0	1	0	0	0	0
Fareham	2	0	0	0	0	0	0
Gosport	6	0	3	0	0	0	3
Hart	1	0	0	2	0	0	0
Havant	0	I	0	0	0	0	1
New Forest	0	1	5	0	0	0	0
New Forest (NP)	0	I	3	0	0	0	0
Rushmoor	2	I	0	0	0	0	0
South Downs (NP)	2	0	10	0	0	0	5
Test Valley	0	0	9	I	0	0	0
Winchester	1	I	4	0	0	0	8
Portsmouth, City of (UA) / Winchester <sup>†</sup>	1	0	0	0	0	0	0
ISLE OF WIGHT (UA)		1					
Isle of Wight (UA)	8	10	2	2	0	0	7
KENT							
Ashford	4	0	1	0	0	0	0
Canterbury	5	3	2	0	0	0	0
Dartford	0	0	3	0	0	0	0
Dover	5	3	2	0	0	0	3
Folkestone and Hythe	7	2	4	0	0	0	0
Maidstone	6	3	2	0	0	0	2
Sevenoaks	1	0	1	I	0	0	0
Sevenoaks / Tunbridge Wells <sup>†</sup>	0	0	0	I	0	0	0
Swale	5	4	0	0	0	0	8
Thanet	3	2	4	0	0	0	- 1
Tonbridge and Malling	0	I	3	0	0	0	0
Tunbridge Wells	1	0	0	0	0	0	1
Tunbridge Wells / Wealden <sup>†</sup>	0	0	I	I	0	0	0
KENT (OFF)							
Kent (off)	0	0	0	0	0	3	0
MEDWAY (UA)							
Medway (UA)	- 11	0	0	0	0	0	4
MILTON KEYNES (UA)	I	1		T.	l .		
Milton Keynes (UA)	0	I	4	0	0	0	1
OXFORDSHIRE		1		T			
Cherwell	2	2	2		0	0	2
Oxford	0	2	0		0	0	0
South Oxfordshire	4	1	9	0	0	0	0
South Oxfordshire / Wokingham (UA) <sup>†</sup>	0	0	0		0	0	0
Vale of White Horse	1	I	4	0	0	0	0
West Berkshire (UA) / Vale of White Horse <sup>†</sup>	0	0	I	0	0	0	0
West Oxfordshire	0	I	7	0	0	0	0
PORTSMOUTH, CITY OF (U				1			
Portsmouth, City of (UA)	12	3	0	0	0	0	0
READING (UA)							
Reading (UA)	2	0	0	0	0	0	1

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
SOUTHAMPTON, CITY OF	(UA)						
Southampton, City of (UA)	2	I	0	0	0	0	1
SURREY							
Elmbridge	3	0	0	0	0	0	1
Epsom and Ewell	0	0	0	0	0	0	2
Guildford	1	I	0	1	0	0	0
Mole Valley	3	I	2	1	0	0	0
Reigate and Banstead	1	0	0	0	0	0	0
Runnymede	0	0	0	1	0	0	0
Spelthorne	0	I	0	0	0	0	0
Tandridge	1	I	0	0	0	0	0
Waverley	0	I	1	0	0	0	0
Woking	0	0	0	1	0	0	1
WEST BERKSHIRE (UA)							
West Berkshire (UA)	4	2	4	2	0	0	0
WEST SUSSEX							
Adur	0	I	0	0	0	0	1
Arun	2	I	0	0	0	0	0
Chichester	2	0	3	I	0	0	I
Horsham	1	2	2	0	0	0	1
Mid Sussex	0	I	I	0	0	0	1
South Downs (NP)	3	I	17	0	0	0	I
Worthing	0	I	0	0	0	0	0
WINDSOR AND MAIDENHI	EAD (UA)						
Windsor and Maidenhead (UA)	3	0	0	0	0	0	1
WOKINGHAM (UA)							
Wokingham (UA)	2	0	3	I	0	0	0
TOTAL	575	179	164	37	0	3	137

 $<sup>^{\</sup>dagger}$  Sites that cross local planning authority boundaries

#### **GREATER LONDON**

#### **BARKING AND DAGENHAM**



© Historic England

SITE NAME: The Old Vicarage, Crown Street, Dagenham DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: Part occupied/part in use

D (D)

Commercial company LIST ENTRY NUMBER: 1064411

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

House, dated 1665, and remodelled in the C19. The building is currently partly occupied and has been at risk of vandalism. Planning Permission has been granted for residential conversion into flats. The Local Authority is awaiting the submission of conditions relating to the consented scheme.

Contact: Alex Philpott (LPA) 07925 357065



© Historic England

SITE NAME:	The Marks Stones, Whalebone Lane North, Chadwell Heath
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Crown
LIST ENTRY NUMBER:	1079887

Boundary marker of the Liberty of Havering-atte-Bower, set up in 1642. There are two stones; one inscribed 'Marks Stone' and one inscribed 'Marks Stone Sept 1642'. One stone is broken and in safekeeping, the other remains in its original position. The stones are to be repaired by the quarry operators once restoration of the area is complete. A feasibility report, with funding from the National Lottery Heritage Fund in 2015, explored the potential of the site. The site's use and maintenance are being discussed with the Local Authority, the Crown Estate and Historic England.

Contact: Alex Philpott (LPA) 07925 357065



© Historic England Archive

SITE NAME:	The Warren Stone, Whalebone Lane North, Chadwell Heath
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Crown

1184884

Boundary stone erected in 1642. The stone marked the boundary of Hainault Forest, along with the Marks Stones and the Forest Bounds Stone. The stone is in storage at Warren Farm during ongoing quarrying operations. The stone will be reinstated in its original position once quarrying is finished and land levels have been restored. A feasibility report, with funding from the National Lottery Heritage Fund in 2015, explored the potential of the site. The site's use and maintenance are being discussed with the Local Authority, the Crown Estate and Historic England.

Contact: Alex Philpott (LPA) 07925 357065



© Historic England

SITE NAME:	Chadwell Heath anti-aircraft gun site, Whalebone Lane North (off), Chadwell Heath
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Crown
LIST ENTRY NUMBER:	1079855

The remains of a World War II anti-aircraft battery, with pits for eight guns in two groups of four, and associated structures. The buildings are in an isolated spot and have been subject to vandalism. The former quarry is being restored, including the land levels around the gun site, and when complete there will be a five-year aftercare plan. A feasibility report, with funding from the National Lottery Heritage Fund in 2015, explored the potential of the site. Discussions are ongoing between the Local Authority, the Crown Estate and Historic England regarding its future use and management.

Contact: Alex Philpott (LPA) 07925 357065



© Historic England

SITE NAME:	Church of St Peter and St Paul, Crown Street, Dagenham
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1359302

Most of the church was rebuilt in 1800 in the Strawberry Hill Gothic style, using red brick quoins and dressings to frame ashlar and ragstone panels. A fine open-truss roof spans the nave. The chancel and north chapel are medieval, rendered over ragstone; the interior has been re-ordered. Repairs to the tower roof and lantern, held up by the Covid 19 pandemic, were funded by the National Lottery Heritage Fund and are now complete. Drainage to the north side of the church is being investigated.

Contact: lan Harper 020 7973 3786

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

SITE NAME:	Barking Abbey		
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1003581
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Chadwell Heath Anti-Aircraft Gun Site, Marks Ga	te	
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Alex Philpott (LPA) 07925 357065

#### **BARNET**



SITE NAME: College Farm - main building, Fitzalan Road N3

DESIGNATION: Listed Building grade II, CA

CONDITION:

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: C(C)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1359127 Stables, teashop and dairy, built in 1883 to the design of Frederick Chancellor in a picturesque style. Model dairy farm of the Express Dairy Company. The site is owned by the College Farm Trust. The building is in a deteriorating condition and discussions are ongoing regarding the future use of the site and necessary repairs.

Contact: Jonathan Hardy (LPA) 020 8359 4655



SITE NAME: College Farm Dairy, Fitzalan Road N3

DESIGNATION: Listed Building grade II, CA CONDITION:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1064789

Dairy built in 1883 to the design of Frederick Chancellor, with an ornate timber lantern roof and decorative tilework to the interior. The site is owned by the College Farm Trust. The building is in a deteriorating condition and discussions are ongoing regarding the future use of the site and necessary repairs.

Contact: Jonathan Hardy (LPA) 020 8359 4655



SITE NAME: Silo, Fitzalan Road, College Farm N3 DESIGNATION: Listed Building grade II, CA CONDITION: OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Charity (heritage)

Silo built in 1883 to the design of Frederick Chancellor as part of the Express Dairy Company's pioneering model farm. The site is owned by the College Farm Trust. The building is in a deteriorating condition and discussions are ongoing regarding the future use of the site and necessary

© Historic England

© Historic England

LIST ENTRY NUMBER: 1359128

Contact: Jonathan Hardy (LPA) 020 8359 4655



© Historic England

SITE NAME: Railway Hotel including sign in front and former off-sales building to west, Station Road, Edgware DESIGNATION: Listed Building grade II CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C(C)OWNER TYPE: Private

1096066

The Railway Hotel dates from 1931 and was designed by AE Sewell for the brewers, Truman Hanbury Buxton. It is a large three-storey half-timbered roadhouse, no longer in use as a public house and damaged by a fire in 2016. The listing includes the former off-sales building and the gibbet sign on the frontage. An approved scheme for hotel use has not been implemented. The Local Authority has taken enforcement action relating to the building's condition and use of the surrounding site.

Contact: Jonathan Hardy (LPA) 020 8359 4655

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**



© Historic England

SITE NAME:	Church of St Jude, Central Square, Hampstead Garden Suburb NW11
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1294714

Designed by Sir Edwin Lutyens, St Jude's was consecrated in 1911 with the west end completed in 1935. There are frescoes throughout by Walter Starmer, dating from 1919-30. The church has damp issues; there is cracking evident internally and some areas of the frescoes are suffering from salt damage. The heating system requires overhauling. The weathervane was reinstated in 2021 and the lead spire repaired, damaged when the weathervane fell. A Historic England Heritage at Risk grant was awarded for emergency repointing of open joints in the brick tower at the same

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Parish Church of St Mary, Church End, Hendon NW4
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1359029

St Mary's dates to the mid C13, with a C15 north aisle, C16 north chapel and nave, and south aisle added alongside existing by Temple Moore in 1915. The font is C12. North chapel glass by Kempe, altar screen by Bodley, and altar hangings by Comper. There are various defects in the roofs and gutters; structural movement particularly to the south and west; hard renders on the external walls; and issues with drainage at and below ground level. These issues are having a detrimental effect on the fabric, particularly evident on plasterwork internally, and where water is damaging wall paintings.


Contact: Tracey Craig 020 7973 3756



SITE NAME:	All Saints Church, Durham Road, East Finchley N2
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1396401

This is a prominent suburban church of high quality designed by JEK and JP Cutts and built in 1892. The chancel with transepts was built in 1911, with parish room on north side. There is a fine hammer-beam roof over the nave. As part of a re-ordering by Bruno Hooker in the late 1980s the rood screen was moved to the west end and the adjacent hall (c1935) demolished. The plain tiled roofs were repaired in 2019, funded by the National Lottery Heritage Fund. The cracking in brick masonry at the east end is still under investigation.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Church of All Saints, Oakleigh Road, Friern Barnet N20
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1064881

Built in 1883, designed by Joseph Clark in Early English style, with tiled pitched roofs and flint faced walling with ashlar dressings. It has a tall tower and stone spire. The structure has suffered from general erosion of stonework and has extensive cementitious repairs, which are failing. There are areas of bulging and missing flints. Repairs to the spire and tower grant-aided by the National Lottery Heritage Fund were completed in 2019. Further repairs to roofs and masonry are required, particularly to the west end, the east end vestry and to the south porch.

Contact: Tracey Craig 020 7973 3756

SITE NAME:	Brockley Hill Romano-British pottery and settlement		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018006
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	College Farm, Finchley N3		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jonathan Hardy (LPA) 020 8359 4655

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

#### **BEXLEY**



© London Borough of Bexley

SITE NAME: Section of garden wall to the north of Hall Place, Bourne Road, Bexley, DA5 Listed Building grade I, part in DESIGNATION: RPG grade II CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A (A)

1064250

repair. There is also severe erosion of brickwork and mortar pointing parallel with the A223 Bourne Road. A potential solution with Listed Building Consent is being discussed by the Local Authority and Historic England. Local authority

Contact: Elizabeth Whitbourn 07889 808145

-			
4	- Andrews	1	
m	PY-YA	W.	3
144		Mile	

© Historic England

SITE NAME:	Crossness Pumping Station, Belvedere Road SE28
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Good
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1064241

1064241

Opened 1865; the engineer was Joseph Bazalgette. The building retains important cast iron interior fittings and four colossal beam engines by James Watt and Co. Opened to the public in 2016 as a heritage attraction following major restoration funded by the National Lottery Heritage Fund, Historic England and others. Run by the Crossness Engines Trust, who have restored one of the engines to working order. Concerns about structural safety have, however, limited public access and further major stabilisation and repair works are needed. Discussions about funding the repairs are continuing.

 $C16\ red\ brick\ garden\ wall\ which\ was\ part\ rebuilt\ in\ C18,$  enclosing Hall Place and its formal gardens. A section of the

wall between the gatehouse and a brick pier has a severe

lean and in places has collapsed and requires structural

Contact: Elizabeth Whitbourn 07889 808145



© Historic England

SITE NAME:	Chapel House, 497, Blackfen Road, Sidcup
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1064248

An eye-catcher built as part of the layout of Danson Park circa 1761 and attributed to Lancelot 'Capability' Brown. The Chapel House is now separated from the park by the A2 trunk road and modern houses. The owner continues to maintain the building, carried out vegetation clearance in 2017 and has discussed render repairs with the Local Authority. A previously consented scheme was not implemented and there are no immediate plans to bring the building back into use.

Contact: Helen Broughton (LPA) 0203 0453 334

#### **BRENT**



© London Borough of Brent

Former Savoy Cinema, Burnt Oak Broadway, Edgware
Listed Building grade II
Poor
Vacant/not in use
D (D)
Commercial company

LIST ENTRY NUMBER: 1384932

The Savoy Cinema was built for the independent circuit Goide & Glassman and was designed by cinema architect George Coles. It opened on 29th June 1936 with Bobby Breen in "Rainbow on the River". It is an impressive cinema with all of its internal Moderne fittings intact. It operated as a bingo hall from the 1960s but closed in 2014. The building remains empty and in a declining state with crumbling plasterwork. Applications for Planning Permission and Listed Building Consent to re-purpose and restore the building were approved in March 2021.

Contact: Mark Price (LPA) 0208 937 5236



© Historic England

SITE NAME: Goetze Grave, Paddington Cemetery, Willesden Lane NW6 NW6 Listed Building grade II, RPG DESIGNATION: grade II, CA CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown

1389534

Pink granite Celtic cross on a two-stage base set within a kerb of granite surrounded by railings. Circa 1911, by Kelly, monumental masons, incorporating figural elements ascribed to Sir Alfred Gilbert. Commemorates James Goetze and his wife Rosina and is the only listed memorial in the cemetery. It is vulnerable to heritage crime and one of the allegorical cowled figures is missing. Discussions are underway regarding the necessary repair works.

Contact: Mark Price (LPA) 020 8937 5236

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

ADDREVIA HONS		
CA LB LPA NP RPG SM UA	Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garde Scheduled Monument Unitary Authority World Heritage Site	
	O O	

A DDDE\/IATIONIC



© Historic England

© Historic England

SITE NAME:	Cambridge Hall, Cambridge Avenue, Kilburn NW6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Other not for profit group

appraisal, funded by Historic England, are ongoing, prior to seeking funding for full repair.

Contact: Mark Price (LPA) 0208 937 5236

Built in 1863 as St James's Episcopal Chapel. It is a prefabricated structure of corrugated iron with boarded roof covered in corrugated asbestos. Since 1920 it has been the home of the Willesden & St Marylebone Cadet Corps, which converted the interior to resemble a boat, in itself of historic interest. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for high priority repairs. Discussions and an options

ends to the ground floor due to damp penetration. A

condition assessment was produced in 2016, with funding from Historic England, and priority works identified in that

survey to safeguard the building were completed in 2017.

through a Section 106 agreement but this has not yet been

Funding for repair of the front façade has been secured

implemented. The building has recently been sold and discussions are underway with the new owner.

Summerhouse, circa 1899, by William West Neve, who

Old Oxgate Farm, Coles Green	C16 and C17 timber-framed building suffering from
Road, Cricklewood NW2	subsidence to the brick plinth and structural failure of beam

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

1271962

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: A (A)

OWNER TYPE: Private

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

SITE NAME:

LIST ENTRY NUMBER: 1078875 Contact: Elizabeth Whitbourn 07889 808145



© London Borough of Brent

SITE NAME:	Summerhouse, Kingsbury Manor, 288, Kingsbury Road
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1322049

designed the adjoining Kingsbury Manor for Mary Blair, Duchess of Sutherland. Built in the Arts and Crafts style, timber-framed with patterned brick nogging on a brick plinth edged with stone, and a hipped thatched roof. The thatched roof is deteriorating and the building is in need of repair. The Local Authority and the leaseholder have begun discussions to develop a strategy for the summerhouse's repair and re-use.

Contact: Mark Price (LPA) 020 8937 5236



© Historic England

SITE NAME:	Wembley Hill Lodge, 114, Wembley Hill Road, Brent HA9
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Private

1359001

Wembley Park. Single storey and attic with gable to the front. Featuring twin chimneys and thatched catslide roof. The detached property was severely damaged by a fire in 2013. A new owner secured Planning and Listed Building Consent in 2021, which includes reinstatement of the lodge.

Early C19 orné style cottage which was formerly a lodge to

Contact: Mark Price (LPA) 0208 937 5236



© Historic England

SITE NAME:	The Chapels at Paddington Cemetery, Willesden Lane
DESIGNATION:	Listed Building grade II, RPG grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Local authority

1359002

Mid-C19 twin Anglican and Nonconformist chapels connected by a pair of carriage-porches and a central bell tower. Designed by Thomas Little in 1855 as part of a new cemetery. The vacant buildings are isolated within the cemetery and too dangerous to use. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for holding repairs to the walls, roof and rainwater goods, with the purpose of allowing the Heras fencing surrounding the building to be removed. Additional work to finalise this, funded by the Council, is due to start late 2022.

Contact: Mark Price (LPA) 0208 937 5236

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© John Scott

SITE NAME:	New Parish Church of St Andrew, Church Lane, Kingsbury NW9
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)

OWNER TYPE: Religious organisation LIST ENTRY NUMBER:

1078874

Built 1847 in Wells Street in London's West End, designed by Guy Daukes. It fell into disuse and in 1933 was dismantled and rebuilt in Kingsbury. The interior was reconstructed in its entirety apart from the north and south galleries and has works commissioned from many leading C19 architects and artists. Holding works have been carried out to the spire, which has suffered from rust jacking. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for project development for the roof and spire and holding repairs to gutters to prevent the ingress of water.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Church of St Andrew, High Road, Willesden Green NW10
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1078881

Designed by James Brooks and built in 1885. Brooks also designed the adjacent grade II vicarage. The church suffers from cracking, some severe, mainly at the eastern end. Potentially loose stones internally have been pinned to secure them and the church is undergoing monitoring and various investigations in order to ascertain the cause of the movement which is resulting in the cracking. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant to address a number of maintenance issues to the church fabric. Still to address is movement at the east end.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	St Michael's Church, St Michael's Road, Cricklewood NW2
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1262125

Designed by John Samuel Alder and built in 1910 in stone with tiled pitched roofs and flat roofs to the aisles, which are felted. In the northwest corner is the base of a tower which was never built. The church generally is in poor condition with movement resulting in cracking, and faulty rainwater goods allowing water ingress with much staining internally. The west end window is supported by a framework of scaffolding poles.

Contact: Tracey Craig 020 7973 3756

#### **BROMLEY**



© Historic England

SITE NAME:	Base of the Southern Crystal Palace Water Tower, SE 19
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1469984

Base, trenches and pipework of the southern Crystal Palace water tower. Built for the Crystal Palace Company by Fox, Henderson and Company to designs by Isambard Kingdom Brunel between 1854 and 1856. The tower itself was demolished in 1940-1941. The structure comprises a thick, tapering, ring of brickwork, beneath which is a subterranean area enclosed within the circular mass concrete foundation. The brickwork has a coating of cement render which has fallen off in places so that it is now vulnerable to further weather and vegetative damage.

Contact: Simon Went (LPA) 020 8464 3115



© Historic England

SITE NAME:	The Ice House and Ha-Ha Wall at Bromley Palace Park, Kentish Way
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1393912

Ice house and ha-ha wall to Bromley Old Palace. Ice house probably dating from the late C18 and remodelled in the early C19 as a garden shelter. Despite previous repairs, and a fence constructed to protect the rear chamber, further substantial works are required, and it has been subject to extensive vandalism. The ha-ha has been cleared of vegetation, but also requires repair. The Local Authority is commissioning surveys with a view to identifying suitable approaches to repair.

Contact: Simon Went (LPA) 020 8464 3115

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

ABBREVIATIONS		
CA LB	Conservation Area Listed Building	
LPA	Local Planning Authority	
NP	National Park	
RPG	Registered Park and Garde	
SM	Scheduled Monument	
UA	Unitary Authority	
WHS	World Heritage Site	

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Victorian Folly of 'Medieval Ruins' in Bromley Palace Park, Rafford Way
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Private

1186785

Folly with Norman-style detailing, probably of mid-1860s and by the important firm of garden contractors, Pulham. The structure had been cleared of ivy and other woody vegetation, which was seriously damaging the stonework and lime render, but this has now regrown and is causing further damage. Recently sold as part of a development site, Historic England and the Local Authority have made contact with the new owners and it is expected that appropriate conservation works will be undertaken.

Contact: Simon Went (LPA) 020 8464 3115



© Historic England

SITE NAME:	Wickham Court, Layhams Road
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	F(A)
OWNER TYPE:	Private

1055809

A large C15 semi-fortified manor house built by Sir Henry Heydon. The square plan has castellated octagonal turrets located at each corner. The once-open courtyard has been roofed in and contains a central stair. The house is leased and occupied by a private school. The building suffered from storm damage and a lack of maintenance, but a collapsed tower has now been rebuilt and repairs are in progress to address the effects of a lack of regular maintenance.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	Pedestrian subway under Crystal Palace Parade, Crystal Palace SE19
DESIGNATION:	Listed Building grade II*, part in RPG grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F(E)
OWNER TYPE:	Local authority

1385457

The Subway was designed by Charles Barry Junior and opened in 1865. It provided a direct link from his High-Level Station (demolished 1961) into the Crystal Palace via a ticketing hall, currently roofless, and the spectacular diaper brickwork of the subway vaulting. Historic England is providing grant aid for an extensive repair project, funded primarily by the Greater London Authority's Strategic Investment Pot, with support from the Friends of Crystal Palace Subway. Repairs commenced in spring 2022 and are due to complete in March 2023.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Prehistoric animal sculptures, geological formations and lead mine on islands in lake, Crystal Palace Park SE19
DESIGNATION:	Listed Building grade I, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1067798

Sculptures of dinosaurs and other prehistoric animals, with associated geological strata, constructed between 1852 and 1855 for The Crystal Palace Company. They form a unique display of prehistoric life as then understood, but are now deteriorating significantly, likely owing to ground movement, vegetation, and water ingress. Historic England is leading a project drawing on specialisms across the organisation to record and investigate underlying issues, working with key stakeholders including the Local Authority and Friends of Crystal Palace Dinosaurs, to develop conservation recommendations.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	Upper and Lower Terraces, Crystal Palace Park SE19
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1064352

Terraces designed by Sir Joseph Paxton and situated to the east of the site of the Crystal Palace (re-erected here in 1852-4 and burnt down in 1936), at the top of Crystal Palace Park. The terraces are in a very poor condition and suffering from erosion, with fenced-off balustrading. Repair and conservation works were undertaken on the six sphinxes which adorn them, funded by the Local Authority, the Mayor of London, and Historic England. Discussions are ongoing to determine an approach to further conservation works as part of the wider strategic regeneration plan for the park.

Contact: Simon Went (LPA) 020 8464 3115

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise,

I PA ΝP New Entry is noted). RPG



© Historic England

SITE NAME: Building 10 (Junior Ranks Mess, former Airmen's Institute) West Camp, Main Road, Á233 (east side), Biggin Hill DESIGNATION: Listed Building grade II, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C(C)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1416723

Former Airmen's Institute and recreation centre of c1926 design and built in 1930. It was one of the principal barracks buildings at Biggin Hill, the internationally renowned historic fighter base. The building has been vacant since the RAF withdrew from Biggin Hill in 1993. Repairs have been undertaken to the roof. Having met with the owner, the Local Authority and Historic England are discussing ways in which they can assist in identifying new uses for the building.

Contact: Simon Went (LPA) 020 8464 3115



© Historic England

SITE NAME: North and south railings, Crystal Palace Parade, Crystal Palace Park SE19 Listed Building grade II, RPG DESIGNATION: grade II\* CONDITION: Poor OCCUPANCY: N/A

C(C)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1393659

PRIORITY CATEGORY:

Decorative cast iron railings on gault brick plinths with stone copings, which formed the main pedestrian entrance to the Crystal Palace (demolished following a major fire in 1936) from Crystal Palace Parade. There is damage to some cast iron panels and the dwarf wall, and a long section of curved railing is missing from the north section. A condition survey of the railings was completed in 2015, with funding from Historic England. Discussions are ongoing to secure their full repair as part of the park's wider regeneration plan.

Contact: Simon Went (LPA) 020 8464 3115



© Historic England

91, High Street, St Mary Cray SITE NAME: DESIGNATION: Listed Building grade II, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B) OWNER TYPE: Private

1298993

poor condition and a flank wall is at risk of collapse. Listed Building Consent has been granted for repairs to the structure, and applications for Planning Permission and Listed Building Consent have been approved for works in connection with development for residential use. However, no works have yet been carried out. The Local Authority is considering enforcement action.

C16 dwelling with crown post roof. The building is in a very

Contact: Simon Went (LPA) 020 8464 3115



© Historic England

SITE NAME: The Royal Bell Hotel, 173-177, High Street, Bromley DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Commercial company

1054095

The Royal Bell Hotel is part of a range of buildings rebuilt in 1898 on the site of an earlier hostelry of 1666. It has been vacant for some years and is in need of repair to halt its decline. Following a change of owner, Planning Permission and Listed Building Consent have been granted to bring the hotel back into use, with enabling development on the stable yard. Works are progressing on site.

Contact: Simon Went (LPA) 020 8464 3115



© London Borough of Bromley

SITE NAME: Building 12 (Candidates' Club, Former Sergeants' Mess), West Camp, Main Road, A233 (east side), Biggin Hill DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C(C)OWNER TYPE: Commercial company

1391606

Sergeants' mess, dating from 1932, built by the Air Ministry's Directorate of Works and Buildings. The building has been vacant since the RAF withdrew from Biggin Hill, the internationally renowned historic fighter base, in 1993. The Local Authority is considering action to secure works. Having met with the owner, the Local Authority and Historic England are discussing ways in which they can assist in identifying new uses for the building.

Contact: Simon Went (LPA) 020 8464 3115

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise.

#### I PA ΝP New Entry is noted). RPG

#### **ABBREVIATIONS**



© Historic England

SITE NAME:	Building 15, Hawkinge Block, West Camp, Main Road, A23 (east side), Biggin Hill
DESIGNATION:	Listed Building grade IL CA

CONDITION:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C(C)OWNER TYPE:

LIST ENTRY NUMBER: 1391604

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Barrack block dated 1934, built by the Air Ministry's Directorate of Works and Buildings. The building has been vacant since the RAF withdrew from Biggin Hill, the internationally renowned historic fighter base, in 1993. The Local Authority is considering action to secure works. Having met with the owner, the Local Authority and Historic England are discussing ways in which they can assist in identifying new uses for the building.

Contact: Simon Went (LPA) 020 8464 3115



© London Borough of Bromley

SITE NAME:	Building 33 (Station HQ), West Camp, Main Road, A233 (east side), Biggin Hill
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1391587

Commercial company

Office block dated 1931, formerly the station headquarters building. The building has been vacant since the RAF withdrew from Biggin Hill, the internationally renowned historic fighter base, in 1993. The Local Authority is considering action to secure works. Having met with the owner, the Local Authority and Historic England are discussing ways in which they can assist in identifying new uses for the building.

Contact: Simon Went (LPA) 020 8464 3115



© Historic England

SITE NAME:	Buildings I-5 (Airmen's barrack blocks), West Camp, Main Road, A233 (east side), Biggin Hill
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1391589

Group of five airmen's barracks blocks, dating from 1930. The buildings have been vacant since the RAF withdrew from Biggin Hill, the internationally renowned historic fighter base, in 1993. Roof repairs have been carried out to one block but urgent repairs are required to the roofs and rainwater goods of the remaining blocks. The Local Authority is considering action to secure these works. Having met with the owner, the Local Authority and Historic England are discussing ways in which they can assist in identifying new uses for the buildings.

Contact: Simon Went (LPA) 020 8464 3115



© Historic England

SITE NAME:	Ice house to Sundridge Park, Plaistow Lane, Bromley
designation:	Listed Building grade II, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)

Ice house circa 1800, in the south west corner of a late C18 landscape park designed by Humphry Repton, now a golf course. The ice house has previously been subject to vandalism despite strenuous efforts by the owners to prevent access. A local archaeological group has identified its exact location but access to reassess its condition is difficult. No further progress has been made.

Pulhamite rockwork garden feature constructed circa 1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The fernery is at the northern end of the ornamental lake and is in need of repair. The Local Authority is commissioning surveys with a view to

OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1254001

Contact: Simon Went (LPA) 020 8464 3115



© Historic England

SITE NAME:	Pulhamite fernery, Stockwell Close, Bromley Palace Park
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1392584

Contact: Simon Went (LPA) 020 8464 3115

identifying suitable approaches to repair.

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**



© Historic England

SITE NAME:	Pulhamite waterfall, Stockwell Close, Bromley Palace Park
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

Pulhamite rockwork garden feature constructed circa 1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The waterfall is at the southern end, adjacent to an ice house, probably of late C18, and is in need of repair. Vegetation clearance takes place periodically, but structural works are needed. The Local Authority is commissioning surveys with a view to identifying suitable approaches to repair.

Contact: Simon Went (LPA) 020 8464 3115

Former Town Hall building built in 1906 and used as premises for Bromley College until 2006/07. Consents have been granted for conversion of the building for office, hotel and leisure uses. Works are at an advanced stage.



LIST ENTRY NUMBER:

SITE NAME:	Old Town Hall, Tweedy Road, Bromley
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority

1299012

Contact: Simon Went (LPA) 020 8464 3115



© Historic England

© Historic England

SITE NAME:	Church of St John the Evangelist, High Street, Penge SE20
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1186832

The church was designed by John Nash and Edwin Nash of Bermondsey in the Early English style and completed in 1849. It is built of ragstone with Bath stone dressings, including the spire. The church suffers from water ingress at roof and lower levels, and dampness at lower levels. High level repairs were completed in 2013 at the east end, grant-aided by Historic England and the National Lottery Heritage Fund. Further repairs are required to the west end but await the outcome of discussions between Historic England and the church regarding a development scheme.

Contact: lan Harper 020 7973 3786

SITE NAME:	Iron Age settlement and Roman villa at Warbank,	Keston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002024
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Scadbury Manor moated site and fishponds		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1409786
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Romano-British masonry building and Saxon cemer	tery, Fordcroft, Or	pington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001973
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

CITE NIAME.



© Historic England Archive

SITE NAME:	Crystal Palace Park SE19	
DESIGNATION:	Registered Park and Garden grade II*, 11 LBs, part in CA	
CONDITION:	Generally satisfactory but with significant localised problems	
VULNERABILITY:	Medium	
TREND:	Stable	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1000373	

Mid-C19 pleasure grounds designed by Sir Joseph Paxton as a setting for the Crystal Palace, burnt down in 1936. The park is in variable condition with related listed structures also at risk. The Local Authority has approved a regeneration plan for the park to realise much of the vision of the 2010 masterplan and is securing the agreements for its implementation alongside a new sustainable governance and management model. The Local Authority, Historic England and key stakeholders are focusing on a project to conserve the Lower Lake, prehistoric animal sculptures and geological illustrations.

Contact: Christopher Laine 020 7973 3473

SITE NAME:	Biggin Hill RAF		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Simon Went (LPA) 020 8464 3115

#### **CAMDEN**



© Historic England

SITE NAME:	39, Tottenham Street WIT WI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1379039

Late C18 terraced house with a later shop, of four storeys with a basement and constructed of darkened stock brick with upper parts refaced. The property was used for a community purpose on the ground floor with flats above but has been vacant for several years. Following roof leaks temporary remedial works have taken place to keep the building watertight and structurally safe. In 2018 permission was granted for the change of the ground floor unit to a commercial unit with separate flats above; however this scheme has not been implemented.

Contact: Alan Wito (LPA) 020 7974 6392



© London Borough of Camden

SITE NAME:	Station, Rosslyn Hill NW3 NW3
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1130397

Former Hampstood Police

Former police station and courthouse including stable and harness room, railings and lamps. Built in 1913 by J Dixon Butler, surveyor to the Metropolitan Police. The building has been empty since 2013 and is now secure after illegal entry in 2014 and 2020. Applications for a proposed new use as a school were refused by the Local Authority in 2019 and were dismissed at appeal in 2020. In 2021 the building was sold and in 2022 applications were submitted to the local authority for the conversion of the stables to residential.

C18 red brick graveyard wall with stone copings to the piers. The burial ground was closed in 1854 and reopened as public gardens in the late C19. The wall is lined with gravestones formerly located within the burial ground. Some sections of wall have been repaired but there are structural problems on this southern section. Discussions

Contact: Jane Wylie (LPA) 0207 974 8737



© Historic England

SITE NAME:	Wall to the south of St George's Gardens, Handel Street, WCI WCI
DESIGNATION:	Listed Building grade II, part in RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners

1378729

are underway with the owners of the wall regarding the necessary repairs.

Contact: Jane Wylie (LPA) 0207 974 8737

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park

NP National Park
RPG Registered Park and Garden
SCHEDURG Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Cattle trough to south east of the Roundhouse, Chalk Farm Road NW I
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1258104

Late C19 granite cattle trough. Placed by the Metropolitan Cattle Trough and Drinking Fountain Association in memory of the Christian Socialist Charles Kingsley. Some repairs have been carried out but investigation into the stability of the trough on the plinth is required. It is vulnerable given its location adjacent to the bus lane and bus stop.

Contact: Jane Wylie (LPA) 0207 974 8737



© Historic England

SITE NAME:	Drinking fountain set in wall next to the Roundhouse, Chalk Farm Road NWI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER	1258105

Late C19 Gothic style drinking fountain presented by the Metropolitan Cattle Trough and Drinking Fountain Association. Cleaning has been carried out, but the drinking fountain remains prone to littering and damage. Options for repair are being explored with partner organisations.

Contact: Jane Wylie (LPA) 0207 974 8737



© Historic England

SITE NAME:	Former Strand Union Workhouse (Middlesex Hospital Annex), 44, Cleveland Street WI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Health authority

1242917

Former Strand Union Workhouse, dating from 1778, with an austere symmetrical brick building facing Cleveland Street behind later high brick walls. Vacated by University College London Hospital and in temporary occupation by live-in guardians and site staff in the adjoining unlisted buildings. The buildings are weathertight and secure. Applications for refurbishment and alterations to provide residential accommodation and mixed-use development to the rear of the listed building have been approved. Works have started on site and are progressing.

Contact: Jane Wylie (LPA) 0207 974 8737



© Historic England

SITE NAME:	26, Denmark Street WC2
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1271982

Early C18 terraced house; windows altered in C20. The windows, parapets and gutters are in poor condition. Listed Building Consent and Planning Permission have been granted as part of a wider scheme which includes residential use on the upper floors and repairs to the roof and front parapet. Repair works are continuing on site with the front façade being refurbished and tied back into the building.

Contact: Alan Wito (LPA) 020 7974 6392



© London Borough of Camden

SITE NAME:	3, Endsleigh Street
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Good
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	E (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1078298

One in a terrace of four houses, dating from circa 1825, built by Thomas Cubitt and constructed from multicoloured stock brick. It comprises four storeys and a basement with a round-arched doorway and first floor casements with continuous cast iron balconies. Planning Permission and Listed Building Consent were granted in 2018 to convert the ground floor to a gallery and the works have been completed. Whilst the building is occupied and in good condition there are a number of outstanding matters which are currently (May 2022) being dealt with.

Contact: Catherine Bond (LPA) 020 7974 2669

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	The Elms (formerly Elm Lodge) Fitzroy Park N6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F(D)

1078355

Commercial company

dealt with.

Contact: Catherine Bond (LPA) 020 7974 2669

Detached house built between 1838 and 1840 to the design of George Basevi. A listed building enforcement notice was served in 2012 following unauthorised works during refurbishment. The building is wind and watertight. Planning Permission and Listed Building Consent have been granted to rectify these unauthorised works and some work has been completed. There are a number of outstanding matters which are currently (May 2022) being



SITE NAME:	43, Fitzroy Street
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1322184

One of a terrace of four houses, dating from the late C18, constructed from darkened multi-coloured stock brick with some stucco dressings. It comprises four storeys and a basement. The property is partially occupied and in a deteriorating condition. The Local Authority has contacted the owner to discuss the building's condition.

Contact: Jane Wylie (LPA) 0207 974 8737



© Historic England

© Historic England

SITE NAME:	34 and 39, Great James Street
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company, multiple owners

1113203

Two in a terrace of 14 houses, dating from 1720-24, all of four storeys with basements and constructed from brown brick. Both properties are currently empty. Listed Building Consent and Planning Permission were granted in 2018 for refurbishment and a rear extension at 39, and in 2019 for 34 Great James Street. Works have started at 34 Great James Street.



© Historic England

ITE NAME:	Four sculptures surrounding pond in Italianate Garden, Witanhurst, Highgate West Hill N6
DESIGNATION:	Listed Building grade II, CA

CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

Private

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE:

LIST ENTRY NUMBER:

1379028

Four carved figures, circa 1913, probably part of Harold Peto's design for Sir Arthur Crosfield's garden. The original sculptures are missing from the completed scheme.

Contact: Elizabeth Whitbourn 07889 808145



© Historic England

SITE NAME:	Drinking fountain on north west corner, Lincoln's Inn Fields
DESIGNATION:	Listed Building grade II, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1379337

Stone gabled drinking fountain with a semi-circular basin on a half pedestal. Erected in 1861, restored circa 1992, and inscribed "The Fear of the Lord is a Fountain of Life". An early public drinking fountain erected at the time when the St Giles's parish wells were polluted and when Lincoln's Inn Fields was being restored and renovated. The fountain is not functioning and has a plaque missing. The Local Authority replaced the rear maintenance panel in 2019 and is working towards a repair scheme.

Contact: Alan Wito (LPA) 020 7974 6392

Contact: Jane Wylie (LPA) 0207 974 8737

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© London Borough of Camden

SITE NAME:	Heath House, North End Way NW3
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1113183

Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof. An internal inspection in December 2021 showed it to be secure, wind and watertight.

Contact: Elizabeth Whitbourn 07889 808145



© Historic England

SITE NAME:	Section of boundary wall to St Stephen's Church, Rosslyn Hill NW3
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (non-heritage)

1130395

LIST ENTRY NUMBER:

Brick and stone boundary wall along Hampstead Green, dating from 1869. Repairs are complete to the wall and piers by the entrances, but other areas on Rosslyn Hill and fronting Hampstead Green need repairs to the stone copings and repointing. The Local Authority has approved an application for further remedial works to part of the wall.

Contact: Jane Wylie (LPA) 0207 974 8737



© Historic England Archive

SITE NAME:	St Stephen's Church, Rosslyn Hill NW3
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1130394

Former church, built 1869-71 to the design of SS Teulon, in an early French Gothic style. The London Diocesan Fund has leased the church to St Stephen's Restoration and Preservation Trust for use by Hampstead Hill School and as a community lifelong learning centre. Repair works to the south slope of the nave roof, grant-aided by Historic England, were completed in March 2016. Further repairs are needed to the other roofs and the tower.

Contact: Ian Harper 020 7973 3786



SITE NAME:	Toll Gate House, Spaniards Road, Highgate NW3
DESIGNATION:	Listed Building grade II, part in CA
CONDITION:	Good
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1378793

Late C18 toll house, marking the spot where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. A bollard was erected in late 2008 to provide protection from traffic. Roof and guttering repair works have been undertaken and the property is regularly inspected. It is now in good condition; but remains unoccupied.

Contact: Alan Wito (LPA) 020 7974 6392



© Historic England

SITE NAME:	St George's Cathedral (formerly Christ Church), Albany Street, Camden NWI
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1378620

Former parish church. Antiochian Orthodox Cathedral since 1989. Designed by Sir James Pennethorne, built in 1837 in neo-Grecian style to serve Nash's development east of Regents Park, with later alterations. The Roman cement mouldings and past repairs in cementitious mortar are failing in places. Cracking is evident, particularly on the principal street elevations. The tower, spire and main cornice have been netted for safety. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for a condition survey of the spire to inform a future package of repairs.

Contact: Tracey Craig 020 7973 3756

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise,

I PA ΝP New Entry is noted). RPG

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Church of St Michael, Camden Road, Camden NWI
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1244156

The nave and aisles were built in 1881, designed by GF Bodley and T Garner; the chancel was added in 1894 and the vestries in 1908. The church has undergone structural and stonework repair, re-roofing and drainage works. New electrical and lighting installations were completed in 2016. grant-aided by the National Lottery Heritage Fund. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk grant which, with additional fundraising, saw the repair of the nave painted ceiling where water damage had resulted in flaking paint. Interior fabric and heating remain in need of attention.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Church of the Holy Trinity with St Barnabas, Clarence Way, Kentish Town NWI
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1356761

Built in 1849-50 in a C14 Gothic style to the design of Thomas H Wyatt and David Brandon. The building was bomb damaged during World War II. The tower roof was re-covered and the roofs re-slated with a grant from the National Lottery Heritage Fund and Historic England. The church was awarded a subsequent grant from the National Lottery Heritage Fund for repairs to the tower stonework and this was completed in summer 2015. The western end of the south aisle has suffered from structural movement and in part there is shoring in place externally and scaffolding internally.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Church of the Holy Cross, Cromer Street, Camden Town WCI
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1067375

Church in the Early English style built in 1885 by Joseph Peacock, with internal features by Charles Nicholson circa 1913. Built of yellow stock brick under clay tiled roofs; stone dressings inside and out with red brick banding inside. An unusual two-storey narthex houses the organ gallery. There is settlement of the foundations at the northeast corner causing structural cracking to the vestry and adjacent walls of the church. Other repairs are needed to the east end roofing, north side guttering and brickwork. The congregation and Diocese are actively exploring possible sources of funding.

Contact: Ian Harper 020 7973 3786



© Historic England

511210112	Dartmouth Park Road, Hampstead NW5
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

LIST ENTRY NUMBER:

1067389

Church of St Mary Brookfield

The church was built in the late C19 by W Butterfield with the chancel added by WC Street in 1881. Construction is of stock brick with red brick bands, diaper work and stone dressings under a slated roof. The church has a fine interior. There is severe spalling to brickwork internally to chancel walls and weathering of stone dressings at high level externally, caused by previous failure of parapet gutters and rainwater goods at the east end. The parish is preparing a project to carry out the necessary repairs and is investigating sources of funding.

Contact: lan Harper 020 7973 3786



© Historic England

SITE NAME:	Church of St Mary the Virgin, Eversholt Street, Somers Town NW1
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1342049

1342049

Built in 1824-7, designed by H and HW Inwood in Gothic style with the apse added in 1888 by Ewan Christian, who also removed the side galleries. The church has slate pitched roofs and brick walling with stone dressings. There is a central tower at the west end. Inspection by roped access and a drone has shown that the roofs are in poor condition along with the gutters, flashings and rainwater goods. Water staining is evident internally, along with dampness at low level. Areas of the stone window surrounds are decayed and there are some failing past cementitious repairs.

Contact: Tracey Craig 020 7973 3756

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© Historic England Archive

SITE NAME: Christ Apostolic Church (formerly Church of St John), Highgate Road, Kentish Town NW5

DESIGNATION: Listed Place of Worship grade II

CONDITION: Very bad

PRIORITY CATEGORY: A (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | 379013

Church built on the site of the Kentish Town Chapel of 1783 by James Wyatt, of which the nave walls and apse remain. The rest was rebuilt in 1843-45 by JH Hakewill. High level repairs to the west end, grant-aided by the National Lottery Heritage Fund and Historic England, were completed in 2011. The Diocese commissioned a full dilapidations report in 2020 and is in discussion with the church. Some stained-glass windows have been sent to a studio for repair. The church is seeking funding for this and other necessary internal and external repairs.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:

St Andrew's Cathedral (former Church of St Barnabas), Kentish Town Road, Hampstead NWI

DESIGNATION:

Listed Place of Worship grade II,

CONDITION: Poor
PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | 137924|

This church was constructed in the style of a three-aisled basilica (without a dome) by Ewan Christian in 1884-85. It has been in use by the Greek Orthodox Church since 1957 and became St Andrew's Cathedral in 1970. All internal walls and ceilings have been decorated in the traditional Byzantine style, and large areas have been repainted where damaged by dampness. Externally the tabled guttering to the aisles and apse needs renewal.

Contact: Ian Harper 020 7973 3786



© Historic England

Church of St Mary Magdalene,
Munster Square, Camden Town
NW I

DESIGNATION: Listed Place of Worship grade
II\*, CA

CONDITION: Poor

PRIORITY CATEGORY: A (A)

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | | | | 3 | 57

The church, designed by RC Carpenter and completed in 1852, was described in the Ecclesiologist as the 'most artistically correct new church in London'. Even so, it was altered in 1866-67, and in 1883-84 the north aisle and crypt were added. Built of ragstone with Welsh slate roofs on Baltic fir collar-braced trusses. The interior is richly decorated with marbles and frescoes. The condition of the frescoes is poor as a result of damp caused by leaks in the roof and defective rainwater goods. Externally there is localised decay to the stonework.

Contact: lan Harper 020 7973 3786



© Historic England

SITE NAME:	St Pancras Old Church, Pancras Road, Camden NWI
DESIGNATION:	Listed Place of Worship grade II*, RPG grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (B)
OWNER TYPE:	Religious organisation

Religious organisation

Church dating from the C13 and enlarged in the mid C19 by AD Gough and RL Roumieu, retaining C13 and C15 fabric and wall memorials. Restored by AW Blomfield in the late C19 and by Erith and Terry in 1980. The church has cracks externally and internally along with blown plaster. A deep and narrow C19 gully around the building was modified in 2015 along with new drainage, with a grant from the National Lottery Heritage Fund. Emergency repairs to the most unstable areas were completed in March 2021, grant aided with a Historic England Heritage at Risk repair grant.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Church of St Mary, Priory Road, Camden NW6
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1139083

Designed by Frederick and Horace Francis in 1856 with the spire added in 1872. The church is built of Kentish ragstone with Bath stone dressings and slate roofs. Stonework repairs to the north and south transept gables and east end of the nave were carried out in 2008, grant-aided by Historic England. Repairs to the west elevation of the nave and north aisle are also complete, jointly funded by the National Lottery Heritage Fund and Historic England. Further repairs are required to the tower and spire stonework.

Contact: Tracey Craig 020 7973 3756

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### CA C egory is LB L erwise, LPA L NP N RPG R SM S

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Church of St George the Martyr, Queen Square, Holborn WCI
DESIGNATION:	Listed Place of Worship grade II*, CA

CONDITION: Poor

PRIORITY CATEGORY: C (C)

LIST ENTRY NUMBER:

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1245485

Built 1706 by Arthur Tooley with major re-modelling 1869 by SS Teulon who altered the exterior, added a chancel, and removed most of the galleries. The roof is in poor condition and this, along with defects in the rainwater goods, may have contributed to falls of plaster which necessitated the church to close. Emergency stabilisation works were carried out in 2019 which permitted worship in the church again. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant to undertake a condition survey of the ceiling and prepare a schedule of work.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME: Church of St Pancras, Upper Woburn Place, Camden NWI Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: C(C)OWNER TYPE: Religious organisation

1379062

restored in 1953. The earliest Greek Revival church in London. The west end has an Ionic portico to a vestibule with tower above. The north and south facades each have a tribune with a portico supported by four caryatids with a sarcophagus behind. Repairs to the west portico roof and surrounding stone parapets were completed in early 2016, with funding from the National Lottery Heritage Fund. The condition of the tower, front portico and caryatids has been investigated and all are in need of repair.

Designed by H and HW Inwood, built in 1822 and

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Church of St Martin, Vicars Road, Gospel Oak, Camden NW5
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1379098

Designed by Edward Buckton Lamb and built 1864-6. The choir vestry added in 1928 is now subdivided for wider community use. Repairs to the tower stonework and restoration of the pinnacles were completed in 2014, grant-aided by the National Lottery Heritage Fund. The church has a history of subsidence and has been underpinned in part but there is cracking to the choir vestry and more recently in the southeast corner. The west end window to the choir vestry was repaired in 2020. The church is undergoing continual structural monitoring.

Contact: Tracey Craig 020 7973 3756

### CITY OF LONDON



© Historic England

511 E 1 <b>4</b> 11 IE.	King William Street, City of London EC3
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

LIST ENTRY NUMBER:

1064620

Church of St Mary Woolnoth

This square-plan church was built between 1716 and 1727 by Nicholas Hawksmoor on a tight site between Lombard Street and King William Street. In 1875-6 William Butterfield raised the chancel floor and removed the galleries, setting the carved fronts against the walls. The church is dominated by a baroque tower: this has settlement cracks which are currently being monitored. Elsewhere asphalt roofing needs to be repaired. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for investigations and a costed dilapidations report to inform a repairs programme.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Church of St Margaret, Lothbury, City of London EC2
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1064634

Designed by Sir Christopher Wren, the church was built between 1686 and 1695. The form is a simple rectangle orientated north-south with a vestry to the east and a tower to the west. The south elevation is faced in Portland stone; the others are rendered brick with stone quoins. Internal fittings are contemporary. The spire was fully repaired in 2018-2019 with a grant from the National Lottery Heritage Fund. However, further settlement of the nave floor is causing concern and is being monitored, along with the tower which leans towards the street.

Contact: Ian Harper 020 7973 3786

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **CROYDON**



© London Borough of Croydon

SITE NAME:	Kennedy's, 18a, High Street, South Norwood SE25
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1392596

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Built in 1926 for Kennedy, a chain of South London butchers, now closed. It is hoped the ground floor shop can be brought back into use. Applications for residential use of the upper floors were consented in 2015 and 2016, and works to implement these have now commenced. The Local Authority's enforcement team has a live case regarding unauthorised works to the building's front elevation.

Contact: Robert Buckley (LPA) 020 8726 6000

Public house circa 1900 in Arts and Crafts style. The ground floor of the building has been vacant for many years and its condition is deteriorating, particularly the interiors. The upper floors have now been converted to flats. In 2017 and 2019 repairs were carried out, including to the front parapet wall, and rubbish was cleared from the front of the building. Discussions with the Local Authority on the future use of the building have taken place but no progress



© London Borough of Croydon

SITE NAME:	Leslie Arms public house, 62, Lower Addiscombe Road, Addiscombe
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)

Commercial company

Contact: Robert Buckley (LPA) 020 8726 6000

has been made.



© Historic England

SITE NAME:	Segas offices, 32, Park Lane, Croydon
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (E)
OWNER TYPE:	Commercial company

1262041

1272418

Gas company showroom and office, built 1939-41 in Moderne style. The building is in need of maintenance and is vacant. Approved soft strip works and temporary use of the ground floor as a marketing suite are being implemented, and discussions are ongoing regarding the long-term use of the building as part of the wider Queen's Square development (St George's Walk). The Mid Croydon Masterplan and Opportunity Area Planning Framework emphasise the need for a new use to be found for the building.

Contact: Robert Buckley (LPA) 020 8726 6000



© London Borough of Croydon

SITE NAME:	Former lodge to Croydon Airport Terminal, Purley Way, Croydon
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Commercial company

1079299

Single storey lodge to Airport House, built circa 1928. In spring 2019 works were completed on repairs to the roof, walls and interior to ensure it is secure and watertight. The building is vacant and discussions are ongoing between the owner and the Local Authority, with advice from Historic England, regarding the building's use and a second phase of work to include further internal works and repair of the Crittal windows.

Contact: Robert Buckley (LPA) 020 8726 6000

Pumping station, built in four phases from 1851. The



© Historic England

SITE NAME:	Surrey Street Pumping Station, Surrey Street, Croydon
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1079248

building is secure and watertight; but remains vacant. Located within the Old Town Masterplan area, its future use has been identified as key to the regeneration of Croydon's Old Town. Discussions with the Local Authority are ongoing regarding the future use and repair of the pumping station and regeneration of the surrounding area.

Contact: Robert Buckley (LPA) 020 8726 6000

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

LIST ENTRY NUMBER:




© Historic England

SITE NAME:	2, Woodside Green, South Norwood SE25
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1079280

Early C18 timber-framed house with brick gable ends and catslide roof to the rear. The building is unoccupied and in poor condition following fire damage in 1991. Planning Permission and Listed Building Consent for residential use were granted in 2015. The Local Authority and Historic England are continuing to advise on the condition of the building and repair works. The chimneys have been rebuilt, wall timbers repaired, and the roof is in the process of being reinstated to make the building wind and weathertight.

Contact: Robert Buckley (LPA) 020 8726 6000



© Historic England

© Historic England

SITE NAME:	Church of St Mark, Albert Road, South Norwood SE25
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1323688

Designed by GH Lewis of Linden and Lewis, the nave was built in 1852 and the rest completed by 1890. The church has slate pitched roofs and Kentish ragstone walling. Stonework repairs were completed in 2013, grant-aided by Historic England and the National Lottery Heritage Fund. The chancel and south slopes of the nave and aisle were re-roofed in 2016 with funding secured from the Listed Places of Worship Roof Repair Fund. The north slopes of the nave and aisle roofs remain in need of repair.

Contact: Tracey Craig 020 7973 3756



SITE NAME: Old Tithe Barn, Purley Way, Waddon DESIGNATION: Listed Place of Worship grade II CONDITION: Fair PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1079247

C18 former barn, now in use as a place of worship. The barn is an unusual structure of two parallel ranges with an M-shaped roof. The timber frame is clad in light brickwork with steeply pitched tiled roofs and wooden louvres at the end of each range. Some repairs have been undertaken to make the building watertight, however further work is required to the roof and to clear the rainwater goods.

Contact: Tracey Craig 020 7973 3756



SITE NAME:	Church of St Andrew, Southbridge Road, Croydon
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1079305

Church dating from 1857 by Benjamin Ferrey, with aisles added in 1879; chancel rebuilt and Lady Chapel added in 1891, designed by HB Walton. The church has been reordered internally. The unusual bellcote feature has been dismantled due to its poor structural condition and needs to be reinstated. Works are also required to the roofs, rainwater goods, stonework and windows.

Contact: Tracey Craig 020 7973 3756

© Historic England



© Historic England

SITE NAME:	Church of St Augustine, St Augustine's Avenue, South Croydon
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1079301

Designed by John Oldrid Scott and built in 1884. Reordered in 1989 to provide hall accommodation. The church has clay tiled roofs, with flint walling. Roof repairs to the south transept and south chapel, along with associated overhauling of rainwater goods and stone and flint repairs, were completed in 2015 grant-aided jointly by the National Lottery Heritage Fund and Historic England. Further repairs are needed to the north aisle roof, rainwater goods and tower stonework.

Contact: Tracey Craig 020 7973 3756

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

## I PA ΝP RPG

**ABBREVIATIONS** 



© Historic England

SITE NAME:	Church of St John, Sylvan Road Upper Norwood SE19
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1079275 Built in 1882, designed by John Loughborough Pearson. The church is located on a hill of shrinkable clay and has been subject to ongoing differential movement for many years which has resulted in substantial cracking, mainly to the south side of the building. Underpinning, stitching of the most severe cracks and securing the brick and stone vaulting in the south aisle was completed in 2017, grantaided by the National Lottery Heritage Fund. Funding through Grants for Programmes of Major Works enabled the structural repair of the inner south aisle east window.

Contact: Tracey Craig 020 7973 3756

SITE NAME:	Three of four World War II fighter pens at the former airfield of RAF Kenley		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1021242
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808   45
SITE NAME:	Surrey Iron Railway embankment, approximately 130m south west of Lion Green Road, Coulsdon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021441
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	South Norwood, South Norwood, Croydon SE25		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Robert Buckley (LPA) 020 8726 6000

#### **EALING**



© Historic England

SITE NAME:	Walled garden at Twyford Abbey, Twyford Abbey Road NW10 NW10
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use

PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1189519 C18 walled garden north of Twyford Abbey. Red brick wall approximately 12 foot high enclosing a large area, once a kitchen garden. An important feature of the Twyford Abbey group. There are some structural problems, particularly on the eastern side and with the lintels over the garden entrances, and some urgent stabilisation works have been carried out. Planning Permission and Listed Building Consent were granted in 2017 for an educational use for the Abbey and the site, however it is currently (May 2022) being marketed.

Contact: Planning Officer (LPA) 020 8825 5000



© Historic England

SITE NAME:	Stable Block at Brent Lodge Park, Church Road, Hanwell W7
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Good
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Local authority

1079410

Late C19 two-storey building, built of yellow stock brick. Urgent works to the slate hipped roof and underpinning were undertaken to control water ingress and stabilise the building. A new application for reuse of the building was approved in 2019 and applications to clear the conditions attached to this were submitted in early 2020 and are under consideration.

Contact: Planning Officer (LPA) 020 8825 5000

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

LIST ENTRY NUMBER:



© London Borough of Ealing

SITE NAME:	Hanwell Community Centre, Cuckoo Avenue, Hanwell W7
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Good
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1358760

Administration block of the former London District Schools, 1856. The Local Authority carried out major repairs in 2010 and the building is now in good condition. Management of the building has reverted to the Local Authority. Planning Permission and Listed Building Consent have been granted for conversion to a learning and development centre with a new café, dance studio and community facilities. A long-term business plan has been formulated to support the new school which has taken over one of the wings.

Contact: Planning Officer (LPA) 020 8825 5000



© Historic England

1079330

Built 1801-3 by Sir John Soane for the auctioneer and estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the present owner. Works are ongoing to restore the house and a new school complex has been built in the grounds.

Contact: Planning Officer (LPA) 020 8825 5000



© Historic England

SITE NAME:	Two chapels at South Ealing Cemetery, South Ealing Road W5
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1380227

The two chapels are linked by a porte cochère with clock and belfry above, designed by Charles Jones and built in 1861. The buildings have fallen into disrepair and are too dangerous to use. An options appraisal and condition survey of the building, funded by the National Lottery Heritage Fund, was completed in 2020. Historic England are currently (May 2022) grant aiding proposals for urgent repairs and enabling works that would see the building safe and secure, and able to accommodate a meanwhile use. Discussions about the full repair and long-term use of the building are ongoing.

Contact: Planning Officer (LPA) 020 8825 5000



© Historic England

SITE NAME:	Twyford Abbey, Twyford Abbey Road NW10 NW10
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1079383

Gothic country house built 1807-9 by William Atkinson; brick and cement fronted with a crenelated parapet, last used as a nursing home. In 2017 some urgent stabilisation works were carried out to the roof and floors, however more work is needed to get the building wind and weathertight. Planning Permission and Listed Building Consent were granted in 2017 for an educational use for the Abbey and the site, however it is currently (May 2022) being marketed.

Contact: Planning Officer (LPA) 020 8825 5000



© Historic England Archive

SITE NAME:	St Bernard's Hospital, Uxbridge Road, Southall
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Health authority
LIST ENTRY NUMBER:	1079364

Former mental asylum of 1829 by William Alderson; extended in 1854-57. Part of the original complex has been restored for continuing healthcare use. Applications for the conversion of the listed wards to private residential use were approved in 2013 and the site is now partially refurbished. The chapel, ballroom and remaining wards are still vacant but work on these is now in progress.

Contact: Planning Officer (LPA) 020 8825 5000

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME:	Christ the Saviour Church, New Broadway, Ealing W5
DESIGNATION:	Listed Place of Worship grade

CONDITION: Poor PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1079392

C12 in origin, largely rebuilt in C15 and clad in brick in 1772. Restored in 1855 and 1871 by Ewan Christian and in 1889 by W Gilbert Scott. The church was awarded a grant from the National Lottery Heritage Fund for repair works to the tower; these works were completed in early 2016. The nave and aisle roofs are in need of re-covering.
Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant in 2020 to carry out a condition survey of high-level roofs and gutters along with some permanent and holding repairs to slates, gutters and rainwater goods.

Contact: Tracey Craig 020 7973 3756

SITE NAME:	Hanwell flight of locks and brick boundary wall of S	St Bernard's Hospit	al
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001963
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Moated site at Down Barns Farm		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005552
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Acton Town Centre, Acton W3		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000
SITE NAME:	Cuckoo Estate, Hanwell W7		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000
SITE NAME:	Ealing Town Centre, Ealing W5		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000
SITE NAME:	Haven Green, Ealing W5		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000
SITE NAME:	Norwood Green, Southall		
DESIGNATION:	Conservation Area, 7 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

#### **ENFIELD**



© Historic England

Holly Hill Farmhouse, The SITE NAME: Ridgeway DESIGNATION: Listed Building grade II CONDITION: Very bad

1188655

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A(A)

LIST ENTRY NUMBER:

OWNER TYPE: Local authority Mid C19 villa of London stock brick, formerly a farmhouse, with later additions and outbuildings to the rear. The house has been vacant for many years and has suffered from the effects of water ingress, blocked rainwater goods, vegetative growth, broken windows and rotten joinery The building is now secured, and Historic England and the Local Authority have identified urgent works needed to arrest further decline whilst a decision is made on the future use of the building.

Contact: Christine White (LPA) 020 8379 3852



© London Borough of Enfield

SITE NAME:	North Lodge, Whitewebbs Road
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1079477

an attic, with a steep-pitched roof of fishscale tiles with barge-boarded gable ends. The building has been empty and neglected for many years and part of the building has now been subject to unauthorised demolition works. The Local Authority has undertaken extensive works to secure and protect the building under enforcement regulations. Steps are now being taken to ensure appropriate consents are obtained, and full repair of the building secured.

Small Victorian Gothic stuccoed cottage of one storey and

Contact: Christine White (LPA) 020 8379 3852



© Historic England

SITE NAME:	Southgate House, High Street N14
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (A)
OWNER TYPE:	Local authority

1079541

Late C18 house with early C19 extension in similar style, with an elliptical entrance hall. Formerly used as a college, it is now vacant whilst a new use is secured. Water ingress, now halted, has led to outbreaks of dry rot, and vegetation growth has hampered ventilation and drainage to the building. The building was sold in 2020. The Local Authority and Historic England are working with the new owner to bring forward a suitable proposal to secure its future. Some works have been carried out but further works are needed to stabilise the building.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	Broomfield House, Broomfield Park, Broomfield Lane N13
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

1078934

C16 house with late C18 additions, situated in a public park. The building is severely fire damaged, although significant parts of the interior are in safe storage. Additional scaffolding works were carried out in 2016 funded by Historic England and the Local Authority. Following extensive discussions and commissioned reports, further work is being carried out to help inform a decision on the future of the building.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	Stable block in Broomfield Park, Broomfield Lane N13
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

1188544

Early C18 stable block to Broomfield House. The building is vacant. Internal propping works have been undertaken to stabilise the floors, and further works carried out following subsequent fire and water damage. Following extensive discussions and commissioned reports, further work is being carried out to help inform a decision on the future of the building.

Contact: Verena McCaig 020 7973 3718

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise.

## ΝP New Entry is noted).

## **ABBREVIATIONS**



© Historic England

SITE NAME:	Nonconformist Chapel, Lavender Hill Cemetery, Cedar Road
DESIGNATION:	Listed Building grade II

Listed Building grade II

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C(C)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1079458

CITE NIAME.

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

1870-1 Gothic Revival cemetery chapel. The chapel is in poor condition and in need of an appropriate use. Repairs are required to arrest deterioration of damaged stonework and a decision is needed on the future of the building.

Contact: Christine White (LPA) 020 8379 3852



© Historic England

SITE INAME:	Charity School, Church Street Edmonton N9
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1079547

Former Edmonton Girls'

Single-storey building, with a central arched doorway to the street and sash windows to either side. Above the doorway is a statuette of a female pupil. Historic England and the Local Authority are working with the current owners and London Historic Buildings Trust to secure a repair project. Potential new users have been identified and discussions are ongoing to identify funding sources. In the meantime, live-in guardians continue to safeguard the property.

Contact: Christine White (LPA) 020 8379 3852



© Historic England

SITE NAME:	24, Church Street, Edmonton N9
DESIGNATION:	Listed Building grade II, 2 CAs
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1079546

Former teacher's accommodation to the adjoining Charity School. C18 cottage of red brick with renewed pantile roof. Historic England and the Local Authority are working with the current owners and London Historic Buildings Trust to secure a repair project. Potential new users have been identified and discussions are ongoing to identify funding sources. In the meantime, live-in guardians continue to safeguard the property.

Contact: Christine White (LPA) 020 8379 3852



© Historic England

SITE NAME:	Trent Park House terrace, Cockfosters Road, Trent Park
DESIGNATION:	Listed Building grade II, RPG grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

Brick and stone terrace reconstructed in the 1920s. The terrace is in very poor condition, with temporary propping in place. Vegetation clearance and further propping works were undertaken after additional surveys were carried out in 2015. Full repair and conservation are expected to take place as part of the planned redevelopment of the wider site, which is in progress.

LIST ENTRY NUMBER: 1078931

Contact: Christine White (LPA) 020 8379 3852



© Historic England

SITE NAME:	Enfield Electricity Works, 20, Ladysmith Road, Enfield
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Utility
LIST ENTRY NUMBER:	1389537

Former Enfield Electricity Works dating from 1906, architect unknown. The building is partially occupied. Extensive works have been undertaken to stabilise the building and make it watertight. However, further works are required to the exterior tile-work and masonry to prevent water ingress and further damage. Future operational options are under consideration for the site which will inform its future repair and re-use.

Contact: Christine White (LPA) 020 8379 3852

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

LIST ENTRY NUMBER:



© London Borough of Enfield

SITE NAME:	Barn at Whitewebbs Farm, Whitewebbs Road
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1079480

Simple, timber-framed barn probably dating from the late C17. Works have been undertaken to prop the building to secure the structure. Planning Permission and Listed Building Consent have been granted for residential conversion. Planning conditions have yet to be discharged and works have yet to commence on site.

Contact: Christine White (LPA) 020 8379 3852



© Colin Kerr (Architect)

SITE NAME:	All Saints Church, Church Street, Edmonton N9
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1079548

C12 in origin, largely rebuilt in the C15 and clad in brick in 1772. Restored in 1855 and 1871 by Ewan Christian and in 1889 by William Gillbee Scott. The church has a Kentish ragstone medieval tower, 1772 brick-faced east and north sides, and stone south and west sides. The church was awarded a grant from the National Lottery Heritage Fund for repair works to the tower which were completed in early 2016. The nave and aisle roofs are in need of recovering. A fall of stone internally necessitated general investigations and temporary holding repairs until a scheme of work can be prepared.

Contact: Tracey Craig 020 7973 3756



SITE NAME:	Church of St Andrew, Church Walk, Enfield
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1079549

The church and tower have C12 origins, were extended in C15 and C16 (Sir Thomas Lovell), repaired in C18, and restored in C19 (including all new roofs) by variously Lochner, St Anbyn and Scott. It is built of rubble masonry including brick and flint with stone quoins and window dressings. There are fine C15 and C16 monuments but these are deteriorating due to dampness caused by poor drainage. The leaking tower roof has caused a structural failure in the belfry. Holding repairs are in place and the Parish is seeking funding for a comprehensive development and repair project.

Contact: Ian Harper 020 7973 3786

© Historic England

SITE NAME:	Site of Elsynge Hall, Forty Hall		
DESIGNATION:	Scheduled Monument, part in RPG grade II, CA	LIST ENTRY NUMBER:	1002040
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145



© Historic England Archive

SITE NAME:	Broomfield Park N13
DESIGNATION:	Registered Park and Garden grade II, 4 LBs, part in CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1000517

Early C18 formal gardens associated with Broomfield House, comprising a walled enclosure focussed on a series of formal lakes, and set within a landscape park. Converted for use as a public park in the early C20, with input from Thomas Mawson. The lakes are in poor condition and the historic parkland has suffered losses to development. The house and stable block are in very bad condition and further work is being carried out to help inform a decision on the future of the buildings. A Conservation Management Plan exists for the landscape and discussions are needed to secure its implementation.

Contact: Christopher Laine 020 7973 3473

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© Historic England Archive

SITE NAME:	Grovelands Park N14
DESIGNATION:	Registered Park and Garden grade II*, 5 LBs, part in CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000395

Late C18 landscape park and lake by Humphry Repton, extended in the mid-C19 and laid out as a public park in the early C20 by Thomas Mawson. The mansion and immediate grounds are now a private hospital. The divided ownership of the park between the Local Authority, Thames Water and the hospital has led to differential management regimes. The sports area is in very bad condition with intrusive fencing and redundant structures. A Conservation Management Plan requires completion and discussions are needed in order to then secure its implementation.

Contact: Christopher Laine 020 7973 3473



© Historic England Archive

SITE NAME:	Trent Park
DESIGNATION:	Registered Park and Garden grade II, 19 LBs, SM, part in CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000484

Late C18 landscape park further developed in the early C20 by Sir Philip Sassoon. Developers are implementing their approved scheme for improvements to the core of the historic landscape around the mansion house. There remain significant issues in the surrounding parkland, owned and managed by the Local Authority as a country park. Discussions continue towards improving the interrelationship between the wider park and the historic core, and improvements are sought to the management of the parkland and water bodies more generally.

Contact: Christopher Laine 020 7973 3473



© Historic England Archive

SITE NAME:	Forty Hall
DESIGNATION:	Registered Park and Garden grade II, 5 LBs, part in SM, CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	Yes
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1001357

Mid-to-late C18 pleasure grounds overlying C17 formal gardens focussed on Forty Hall, built 1629-36 for Sir Nicholas Rainton, and set within a C18 landscape park developed over a C16 royal palace and associated water gardens. Owned and managed by the Local Authority as a country park, with the Home Farm and ferme ornée to the west (outside of the registered area) leased to a horticultural college. Numerous issues affect the site, particularly lapsed woodland and grassland management which threatens the character and legibility of the designed landscape and the condition of individual features.

Contact: Christopher Laine 020 7973 3473

SITE NAME:	Church Street, Edmonton N9		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Christine White (LPA) 020 8379 3852
SITE NAME:	Fore Street, Edmonton N18		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Christine White (LPA) 020 8379 3852

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# **ABBREVIATIONS**

#### **GREENWICH**



© Historic England

SITE NAME: Garden House to south east of Rush Grove House, Rush Grove Street SE18

DESIGNATION: Listed Building grade II, CA

CONDITION: Very bad OCCUPANCY: N/A

PRIORITY CATEGORY: A(A)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1289930 Late C18 or early C19 octagonal building with pointed slate roof of moderate pitch. The walls are set back to provide an open loggia with round wooden arches set in trellis. Extensive loss of tiles from the roof has led to considerable water ingress. The building is suffering from a prolonged lack of maintenance and is deteriorating rapidly. Efforts to contact the owners have not yet been successful and the Local Authority is considering taking enforcement action.

Contact: Conservation Team (LPA) 020 8921 5355



© Royal Borough of Greenwich

SITE NAME: Gazebo in the grounds of Shrewsbury House, Bushmoor Crescent SE18

DESIGNATION: Listed Building grade II, CA

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (A)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1409363

Brick gazebo with a hipped tile roof, and round-headed multi-pane windows and entrance, one of several subsidiary features in the grounds of the grade II listed early C20 country house, Shrewsbury House. Whilst joinery and brickwork appear to be largely intact, the significant and continuing loss of tiles from the roof and inadequate or missing rainwater goods are contributing to its serious decline. A temporary roof has been erected to prevent water ingress. A condition survey is being undertaken to inform a programme of roof and joinery repairs.

Contact: Conservation Team (LPA) 020 8921 5355



© Historic England

SITE NAME-Winter Garden of former Avery Hill Training College, Bexley Road, Eltham SE9 DESIGNATION: Listed Building grade II CONDITION: Poor OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: C (C) OWNER TYPE: Educational (state sector)

LIST ENTRY NUMBER: 1079082

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Large conservatory built in 1889 in a classical style, with domed glass roofs and surmounted by a figure of Mercury. The wider site has been sold for new educational use. The building was deteriorating due to blocked rainwater goods and lack of maintenance, especially to joinery at roof level. The Local Authority is ensuring that urgent works are being carried out to improve the building's condition and make it watertight. Joinery repairs to the east and west roof lanterns are now complete. Discussions are continuing to secure the future management and use of the building.

Contact: Conservation Team (LPA) 020 8921 5355



© Historic England

SITE NAME: Garden House to north west of Charlton House, Charlton Road, Charlton SE7 DESIGNATION: Listed Building grade I, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE:

1291892

Charity (heritage)

Small red brick garden house with undercroft and high pyramidal swept roof, dating from the mid to late CI7 and attributed to Inigo Jones. It was previously used as a public lavatory but is now vacant. A condition survey and heritage assessment commissioned by the Royal Greenwich Heritage Trust is informing a programme of works to restore and re-use the building. Further enabling and investigative works have been carried out, funded by Historic England.

C17 or earlier stable building with three diagonal chimney

shafts. Although the building has been made weathertight, it is showing signs of a lack of maintenance. It is currently in

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME: 95A, Eltham High Street, Eltham DESIGNATION: Listed Building grade II CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1219821

Contact: Conservation Team (LPA) 020 8921 5355

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

residential use.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

OWNER TYPE:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Forecourt railings and gates to Red Barracks, and Gate Lodge, Frances Street, Woolwich SE18
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (A)

Local authority

1358950

Railings, entrance gateway and lodge to the former Red Barracks (1858-60 but now demolished). Structural repairs and repointing to the small watch tower to the north were completed in 2013. The railings, piers, and gate piers are generally in good condition. The gate lodge is in very poor condition, although the Local Authority has removed debris and most of the vegetation threatening the building. However, the main structure is derelict and continues to deteriorate. The Local Authority and Historic England are in discussion regarding potential approaches to secure its repair and new use.

Contact: Conservation Team (LPA) 020 8921 5355



© Historic England

The Rotunda, Green Hill, Woolwich Common SE18
Listed Building grade II*, CA
Very bad
Vacant/not in use
A (A)
Government or agency

1078987

24-sided polygon, single-storey building designed by John Nash. Concave conoid roof. First erected in the grounds of Carlton House in 1814 for (premature) celebration of Allied victory in the Napoleonic Wars. The Rotunda housed the reserve collection of the 'Firepower' museum but is now vacant. The roof covering is leaking and there is considerable concern about the condition of structural roof timbers. Propping works are urgently needed and investigations into the roof are outstanding. Efforts are being made by the Local Authority and Historic England to secure these urgent repairs.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	24, Royal Hill, Greenwich SEI0
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENITRY NILIMBER:	1391249

Early C18 small urban house of central chimneystack plan, the smallest known example of the 1703 Moxon Plan. The building has been vacant for some years and is in poor condition. A scheme for restoration and conversion was agreed in 2011-2012 but, although works were started, they were halted for some years. Following discussions with the Local Authority and Historic England, the owner re-commenced internal works but this has been sporadic.

Contact: Conservation Team (LPA) 020 8921 5355



© Photo © Stephen Craven (cc-bysa/2.0)

SITE NAME:	Church of St Saviours, Middle Park Avenue, Eltham SE9
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1212904

This vast church of purple brick and shallow concrete roofs was built in 1932 to the designs of Cachemaille-Day and is largely unaltered since then. The RIBA gold medal was awarded for the design in 1933. The vicarage was built in 1960. The church has always suffered from having internal rainwater pipes and from poor access for high-level maintenance. Roof coverings were repaired in late C20 but are now in need of renewal. Windows to the Lady Chapel are decayed and high-level plasterwork partially removed. The church is seeking funding for emergency repairs and health and safety works.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Roman Catholic Church of St Peter, Woolwich New Road, Woolwich SE18
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1212426

This church in the Gothic style was completed by AW Pugin in 1843. It is listed together with detached school buildings on the south side, completed a decade later by EW Pugin. The external masonry and roofing of the church, along with internal plastered ceilings, were repaired in 2017 with a grant from the National Lottery Heritage Fund. The condition of the adjacent two-storey school buildings is poor; the upper hall is closed due to structural problems and roof leaks. The congregation is now seeking funding to repair the school buildings to bring them back into use.

Contact: Ian Harper 020 7973 3786

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise,

I PA ΝP New Entry is noted). RPG

SITE NAME:	Charlton Village SE7		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Conservation Team (LPA) 020 892 I 5355
SITE NAME:	Thames Barrier and Bowater Road		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Rebecca Duncan (LPA) 0208 9215355
SITE NAME:	Woolwich Town Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Unknown
VULNERABILITY:	High	CONTACT:	Rebecca Duncan (LPA) 0208 9215355

#### **HACKNEY**



© Historic England

SITE NAME:	25 and 27, Hackney Grove E8 E8
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Government or agency

1226756

LIST ENTRY NUMBER:

Early C19 pair of three-storey townhouses. They have been vacant since about 2016. Although Planning Permission and Listed Building Consent were granted in 2017 for works in connection with conversion for use as a school, the scheme has not been implemented and the buildings have fallen into disrepair. The building was illegally occupied, causing damage to historic fabric. A lack of maintenance has caused the roof and rainwater goods to fail and water is now penetrating the building. The Local Authority is in discussion with the owners to secure urgent repairs.

Contact: Tim Walder (LPA) 020 8356 4813



© Historic England

SITE NAME:	98 and 98a, Clapton Common (also known as I-4 Belz Terrace) E5
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1226457

Regency stucco-fronted villa of 1825 with central portico entrance and pairs of curved bay windows, facing onto the nearby common. It was used as a home for destitute children in C19 and converted into flats in 1928, becoming a school in about 1985. There are longstanding unlawful works and the building suffered a fire in 2017. Planning Permission and Listed Building Consent were granted for repairs and extensions as a school in 2018, and works have commenced. However, the building is still deteriorating, and the Local Authority has since taken enforcement action.

Contact: Tim Walder (LPA) 020 8356 4813



© London Borough of Hackney

175, Stoke Newington Church Street N16
Listed Building grade II, CA
Poor
Vacant/not in use
D (D)
Private
1235427

Mid C18 two-storey building of brown brick with red brick dressings, cornice band and parapet, and sash windows, with mid-late C19 projecting ground floor shop. The roof is leaking and there are structural issues in evidence, although the building is propped in places. The building is generally in a very poor condition and there are areas of dry rot. Planning Permission and Listed Building Consent were granted in January 2020 for a scheme to repair the building and bring it back into use as a shop and office, with modest extensions to the roof and rear. However, this has not been implemented.

Contact: Tim Walder (LPA) 020 8356 4813

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	179, Stoke Newington Church Street N16
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private

1235521

The western half of a mid C18 house, converted to shops in C19. The building, including an unusual C19 extension to the rear side, was in use as a Chinese restaurant at ground floor level with staff accommodation above. Planning Permission was granted for conversion and extension to the rear to form a shop and flats in 2018, but the scheme has yet to be implemented. There are both structural and asbestos issues. The building has been vacant for several years and is in poor condition.

Contact: Tim Walder (LPA) 020 8356 4813



© Historic England

SITE NAME:	Forecourt Wall, Gates and Railings to Church of the Good Shepherd, Rookwood Road N16
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

Late C19 wall and railings with decorated square piers topped with obelisk finials associated with the church. The wall is suffering from structural movement possibly caused by neighbouring trees. There is also evidence of inappropriate previous repairs.

Contact: Tim Walder (LPA) 020 8356 4813



© London Borough of Hackney

SITE NAME:	Cleeve Workshops, Calvert Avenue E2
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1264906

1235330

Row of workshops built 1895-8 to the design of Reginald Minton Taylor of London County Council as part of the Boundary Estate. All the workshops are in use and some repair and security works have taken place. Listed Building Consent was previously granted in 2019 for their refurbishment, and partially implemented. The Local Authority has taken enforcement action against multiple incidences of unlawful works. Planning Permission and Listed Building Consent applications for a revised repair and refurbishment scheme are under consideration.

Contact: Tim Walder (LPA) 020 8356 4813



© London Borough of Hackney

SITE NAME:	7, Clapton Square E5
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1226411

Early C19 terraced house. Listed Building Consent was granted for the restoration and conversion of the building to accommodate three flats. However, the building suffered from inappropriate and unauthorised works and the Local Authority took enforcement action. The property was sold in autumn 2019 and the new owner has submitted applications for Planning Permission and Listed Building Consent to rectify the unauthorised works, and these are now being considered.

Contact: Tim Walder (LPA) 020 8356 4813



© Historic England

SITE NAME:	Forecourt wall and railings, 25, Hackney Grove E8
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Government or agency
LICT ENITDY NILIMBED.	1375703

Early C18 brick wall with square pier at end and contemporary wrought iron railings with spearhead standards and urn finials. The building to which they relate is vacant and not being maintained. Repairs are required.

LIST ENTRY NUMBER: 1265682 Contact: Tim Walder (LPA) 020 8356 4813

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England Archive

SITE NAME:	Sisters' House and School to S Columba's Church, Kingsland Road NI
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad

A (New entry)

OCCUPANCY: Part occupied/part in use

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1265691

PRIORITY CATEGORY:

CITE NIANE

LIST ENTRY NUMBER:

Anglican school and house for nuns built in 1898 to the design of James Brooks. This completed the collegiate assemblage of his church and vicarage (both separately on the Heritage at Risk register) completed in 1869. Leased to a Christian group. Full condition surveys have been carried out funded by Covid19 Emergency Heritage at Risk Response Fund grants and the Diocese of London. Urgent repairs are required to the roofs, brickwork and railings. Discussions are on-going regarding future appropriate uses and sources of funding.

Contact: lan Harper 020 7973 3786



© Historic England Archive

SITE NAME:	St Columba's Vicarage and link to church, Kingsland Road E2
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1265658

Gothic Revival vicarage built 1873-4 to the design of James Brooks. The vicarage forms part of a larger group of listed buildings by the same architect, including the church and Sisters' House. A condition survey in 2018 and more recent drone and drainage surveys funded by Covid 19 Heritage at Risk emergency grants and the Diocese of London have highlighted the seriousness of the condition. Discussions have taken place regarding a programme of roof and other high-level repairs, which led to the submission of an application for Listed Building Consent in early 2020. Funding is being sought.

Contact: Ian Harper 020 7973 3786



© London Borough of Hackney

SITE NAME:	592, Kingsland Road E8
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1226776

C18 terraced house with a shop on the ground floor and vacant upper floors. Listed Building Consent was granted in 2008 and again in 2018 for rebuilding the upper parts of the north and east wall following structural problems. These works were completed in March 2020. However, the roof is still in poor condition with signs of water ingress and unlawful sub-divisions throughout the property, and the Local Authority is considering enforcement action.

Contact: Tim Walder (LPA) 020 8356 4813



© London Borough of Hackney

SITE NAME:	Orphan Asylum, Linscott Road E5
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority

1265630

Daue: -- +- fauurau I au dau

The remaining part of the London Orphan Asylum, circa 1823 by WS Inman. The rest of the building was demolished in 1975 and the portico was derelict until 2003. It now consists of an entrance portico with colonnades. Behind the entrance is a computer centre by Brady Mallalieu from 2005 on the site of the former chapel. The building was associated with the nearby Clapton Girls Academy until 2017. Planning Permission and Listed Building Consent were granted in 2021 for a scheme to extend and convert the building into a medical surgery, but the scheme has not yet been implemented.

Contact: Tim Walder (LPA) 020 8356 4813



© Historic England Archive

SITE NAME:	New Lansdowne Club, 195, Mare Street E8
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (E)
OWNER TYPE:	Commercial company

1265590

Substantial detached house, dating from 1699. Planning Permission and Listed Building Consent were granted in 2018, subject to a Section 106 agreement, to convert the house to offices, with enabling residential development to the rear. These works are now nearing completion. All enforcement issues are resolved.

Contact: Verena McCaig 020 7973 3718

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## I PA ΝP



© London Borough of Hackney

SITE NAME:	Hackney Borough Disinfecting Station, Millfields Road E5
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1253493

Disinfecting station built in 1900 by Gordon and Gunton for Hackney Borough Council. The building is in very poor condition following years of water ingress. A number of surveys and reports have been undertaken in order to better understand the building's significance and condition. Asbestos and stored items have been cleared. Emergency repairs and mothballing works have largely been completed, including propping to unstable areas. The Local Authority is in discussions with internal and external stakeholders regarding its restoration and to identify and secure a new use.

Contact: Tim Walder (LPA) 020 8356 4813



© London Borough of Hackney

SITE NAME:	Air Raid Precaution Centre, Rossendale Street (east side) E5
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1235876

Air raid shelter built in 1938. The building has previously suffered from flooding. Planning Permission and Listed Building Consent were granted in 2004 for the retention of the air raid shelter as a museum and the construction of flats above. These works are largely complete and the flats occupied. However, the ownership of the Air Raid Precaution Centre is uncertain, and the space is currently used for storage.

Contact: Tim Walder (LPA) 020 8356 4813



© Historic England Archive

SITE NAME:	Walls and gates to Bishopsgate Goods Station, Shoreditch High Street EI
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Utility

Late C19 walls to the demolished goods station. The gates were repaired some years ago and are now in situ beneath the hoarding. The repair of the listed wall forms part of a large redevelopment proposal for the entire Bishopsgate Goodsyard site, which was approved by the Mayor of London in 2020. Works have yet to commence on site.

Contact: Tim Walder (LPA) 020 8356 4813



© London Borough of Hackney

SITE NAME:	187, Shoreditch High Street EI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1235320

1235316

LIST ENTRY NUMBER:

Early C18 terraced house with an altered facade. The roof, front elevation and windows have been restored and the building is now weathertight. A new shopfront has also been fitted. The future use of the building forms part of a wider development scheme currently being implemented.

A rare and complete example of a temporary iron mission church built in 1858. The building is now clad in corrugated asbestos sheeting. The building is in use occasionally as a church. The property is currently advertised for sale.

Contact: Tim Walder (LPA) 020 8356 4813



© Historic England

SITE NAME:	Shrubland Road Evangelical Church, Shrubland Road E8
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1245303

Contact: Tim Walder (LPA) 020 8356 4813

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**



© Historic England

SITE NAME:	Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16
DESIGNATION:	Listed Building grade II, RPG grade II, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use

Part occupied/part in use

1265023

PRIORITY CATEGORY: F (F)

LIST ENTRY NUMBER:

OWNER TYPE: Local authority

Contact: Tim Walder (LPA) 020 8356 4813

events. Works are on-going on site.



© Historic England

SITE NAME:	Haggerston Baths, Whiston Road E2
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority

LIST ENTRY NUMBER: 1235838

Public baths and swimming pool, dating from 1904. The building is vacant and in a state of disrepair. Following a competitive bidding process and public consultation, the Local Authority selected a developer in 2017 to repair the building and bring it back into use. Planning Permission and Listed Building Consent have been granted for a scheme involving restoration and re-purposing as community space, workshops, café, gym and other uses, with demolition of part of the building and erection of a new six-storey office building. Works have yet to commence.

Gothic Revival cemetery chapel, dating from 1839. The chapel is situated in the centre of the early C19 cemetery. A first phase of repairs to the roof, spire and high-level stonework was completed in 2017, with funding from Hackney Council and Historic England. The Local Authority has been awarded significant funding from the National Lottery Heritage Fund for a project to improve the cemetery landscape. This includes a second phase of repairs to the chapel including underpinning and new

windows, enabling it to be used for community uses and

Contact: Tim Walder (LPA) 020 8356 4813



© Historic England

SITE NAME:	Church of St Andrew, Bethune Road, Stoke Newington N16
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1264896

The church was built in 1883-4 by Sir Arthur Blomfield in the Early English style, using Kentish ragstone with Bath stone dressings. Although plain externally, the interior is richly decorated. Two phases of repairs are complete, funded by the National Lottery Heritage Fund. The nave and aisle roofs are repaired and also external masonry and windows to clerestory and west wall. A third and final phase of roofing repair is required to the transepts and chancel roofs and related masonry.

Contact: lan Harper 020 7973 3786



SITE NAME:	Church of St Chad, Dunloe Street, Hackney E2
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1265793

© Historic England

compl poor s church contra The vi were i brickw above	h by Victorian Gothicist architect James Brooks, eted in 1869 to provide for rapidly expanding but suburbs. The adjacent vicarage dates from 1874. The is high and lofty, with plain detailing in red brick and sting with Bath stone dressings under slated roofs. carage, transept roofs and north nave brickwork repaired in the late C20. More repairs are needed to vork and rainwater goods, and the timber bellcote the crossing is in urgent need of assessment and . The church is actively seeking funding.

Contact: Ian Harper 020 7973 3786



© Historic England

SHE NAME:	(formerly St Columba), Kingsland Road, Hackney E2
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1226862

Christ Apostolis Church

The parish church was built in the Gothic Revival style in 1868-9 by James Brooks and the mortuary chapel was added in 1904-5 by E Geldart. It forms an enclosed courtyard with the vicarage and Sisters' House, listed separately. Construction is in red brick with Bath stone dressings. A drone survey has confirmed serious decay in the high-level lantern above the central tower and the rainwater goods; a drainage survey was funded in 2020 by a Covid-19 Emergency Heritage at Risk Response Fund grant. The Diocese and the congregation are discussing future management of the church and the site.

Contact: Ian Harper 020 7973 3786

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

CITE NIAME

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

## I PA ΝP RPG



© Historic England

SITE NAME:	Church of St Thomas, Old Hill Street, Clapton Common N16
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1265859

Only the crypt (c1777), the tower and belfry (1827) survived World War II bomb damage in December 1940. The church was re-opened in October 1958 to designs by NF Cachemaille-Day; he incorporated the apse from William Burges's remodelling in 1873 and the 1921 World War I memorial. The asphalt finish of the reinforced concrete roof slab has been much repaired over previous decades, raising concerns about the structural integrity of the roof. The congregation is seeking funding for a repair project and has commissioned a development appraisal.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Church of St John the Baptist, Pitfield Street, Hackney N I
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1235285

St John the Baptist, a Commissioners' church funded under the 1818 Act, was completed in 1826 by Francis Edwards, a pupil of Sir John Soane. Built of stock bricks contained within limestone dressings under a slated roof, the spacious interior has galleries on three sides and a fine early C20 painted ceiling by J A Reeve. The tower and galleried cupola at the west end have structural problems due to the rusting of embedded cramps. These are causing jacking in the masonry above roof level, which needs to be addressed.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Church of the Ark of the Covenant, Rookwood Road, Stoke Newington N16
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1235310

The church, located at the north end of Clapton Common in Hackney, was designed by Joseph Morris and Sons for the Agapemonite Church and finished in 1895. Carvings on the west tower were by A G Walker, and the window glass was designed by Walter Crane. The building passed to the Catholic Church 1956 -2007, and then to the Georgians. External elevations are in squared rubble ragstone; at some time hard cement pointing has led to stone decay. The plain clay roof tiles are slipping off and have caused plaster falls in the nave.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Church of St Barnabas, Shacklewell Row, Hackney E8
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1265135

St Barnabas was built as a Mission church between 1910 and 1911 by Professor Sir Charles Reilly. Constructed in mass brickwork it was roofed in concrete vaults on steel reinforcement, finished in asphalt and set behind parapets. The roof was repaired with an RGPOW grant in 2014 but the design of the rainwater disposal system cannot discharge storm water sufficiently and the condition is poor again, with leaking parapet gutters causing damage to the structure. Uncontrolled tree growth along boundaries is also damaging the church.

Contact: Ian Harper 020 7973 3786



© Historic England Archive

TE IVALLE.	Shoreditch High Street, Shoreditch El
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
RIORITY CATEGORY:	A (C)
OWNER TYPE:	Religious organisation

1235382

Church of St Leonard

Built 1740 to the design of George Dance the Elder. Constructed in brick with a Portland stone facade and dressings, and slate roofs. The roofs to the north and south aisles and the flat roofs either side of the tower have been repaired with funding from the National Lottery Heritage Fund and Historic England. The nave roof was re-slated in 2017 with funding from the Listed Places of Worship Roof Repair Fund. Repairs were completed in 2019 to the tower, pediment, columns and portico roofs, and temporary repairs were made to the spire, grant-aided by the National Lottery Heritage Fund.

Contact: Tracey Craig 020 7973 3756

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

SITE NAME

LIST ENTRY NUMBER:

D

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:



© Historic England

Old Church of St Mary, Stoke Newington Church Street, Stoke Newington N16
DESIGNATION: Listed Place of Worship grade II*, CA
condition: Poor
PRIORITY CATEGORY: A (A)
OWNER TYPE: Religious organisation

1235419

The old parish church of St Mary dates from 1563. It was restored in 1827-29 by Charles Barry who added the clerestory, the spire and the outer north aisle, subsequently lost in WWII. The exposed soft brick of the north wall is weathering badly. In 2017 the south aisle roof was repaired with a grant from the Listed Places of Worship Roof Repair Fund. Further work is needed to deal with dampness and investigate and monitor worsening structural movement of the ceiling. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for repairs to the tower windows.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Church of St Michael and All Angels N16
DESIGNATION:	Listed Place of Worship grade II CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1476310

The Church of St Michael and All Angels was designed by JEK Cutts and completed in 1884. It was listed at grade II on 15 December 2021. Although typical of his many robust Gothic Revival church designs, this one employed cast concrete to imitate stone for all the window and other dressings, including the tracery of the East window. The church has suffered structural movement in the past and the chancel arch and west porch were underpinned in 1994 and 1997 respectively. Of major concern is the instability of the west wall, and this will need careful monitoring and assessment.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Church of St Matthias, Wordsworth Road, Stoke Newington N16
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1265031

The church was completed in 1851 to an innovative design by William Butterfield in free Gothic style. Stock brick with Bath stone dressings. Repairs to the nave roof and rainwater goods were completed in May 2015 with funding from the National Lottery Heritage Fund and Historic England. Another phase of work is required to the aisle roofs, as well as the roof, belfry louvers and masonry of the tower. The church is seeking funding for project development and repair.

Contact: Ian Harper 020 7973 3786



© Historic England Archive

SITE NAME:	Abney Park Cemetery N16
DESIGNATION:	Registered Park and Garden grade II, 18 LBs, part in CA
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1000789

Laid out as an arboretum cemetery in 1840 from the gardens of two C17 houses, Abney Park is one of London's most important Nonconformist cemeteries. Features of the historic designed landscape survive but are in poor condition and, in places, illegible. A Development Board is using a Conservation Management Plan to guide future management and maintenance, and volunteers continue to carry out improvements. A major restoration project developed by the Local Authority and partners, with grant funding from the National Lottery Heritage Fund and the National Lottery Community Fund, is now underway.

Contact: Christopher Laine 020 7973 3473

SITE NAME:	Mare Street, Hackney Central E8		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Matt Payne 020 8356 8106
SITE NAME:	Sun Street, City of London EC2		
SITE NAME:  DESIGNATION:	Sun Street, City of London EC2 Conservation Area, LB grade II	NEW ENTRY?:	No
	·	NEW ENTRY?: TREND:	No Unknown
DESIGNATION:	Conservation Area, LB grade II		

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Full ladar repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

OWNER TYPE:

#### HAMMERSMITH AND FULHAM



© Historic England

SITE NAME:	Draped woman sculpture, North Verbena Gardens W6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Local authority

LIST ENTRY NUMBER: 1431422 Cast concrete sculpture, circa 1959 by Karel Vogel, situated in an open space off the Great West Road. It was an early commission of the London County Council's Patronage of the Arts scheme, unusually commissioned to provide visual amenity in compensation for a major road scheme. The cast concrete is cracking, damaged by rusting structural iron elements, and past repairs are both unsightly and failing. A condition survey has been carried out, funded by local amenity groups. Local Authority funding is in place to undertake further investigations prior to planning for full repair.

Contact: Adam O'Neill (LPA) 020 8753 3318



© Historic England

SITE NAME:	Number 2 Gasholder, Former Fulham Gas Works, Imperial Road SW6
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1261959

LIST ENTRY NUMBER:

Gasholder dating from 1830, and considered to be the oldest surviving gasholder in the world. It consists of a single lift wrought iron holder, with cast iron guide standards in tripod form and wrought iron framework. The Gas Works site has been decommissioned. Outline Planning Permission for redevelopment has been obtained, with a Š106 Agreement to secure protective and investigatory works. Preliminary works are underway, and the results will help inform the future restoration and repurposing of the gasholder on site in consultation with the developer, Local Authority and Historic England.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	Reception House, Hammersmith Cemetery, Margravine Road W6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (A)
OWNER TYPE:	Local authority

1436663

circa 1869, probably by George Saunders, built to provide temporary resting places for bodies prior to burial. The rainwater goods are inadequate and failing, leading to deterioration of stone dressings, brickwork and mortars. The Friends of Margravine Cemetery funded a costed condition survey. The Local Authority has commissioned consultants to oversee repair and conservation works, and is working with the Friends of Margravine Cemetery and Historic England to identify appropriate funding sources.

Single-storey octagonal brick building with a slate roof,

Contact: Adam O'Neill (LPA) 020 8753 3318



© I	London	Borough	ot	Hamme	rsmith	and
Ful	ham					

SITE NAME:	Refreshment Room, Ravenscourt Park W6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1358588

Former stable block of C18 Ravenscourt Park House, partially demolished and converted into a refreshment room late C19. Recently used as a park tea room, it has been vacant since the end of 2019. The roof is failing, exacerbated by heritage crime and subsequent water ingress, and needs replacing, along with rainwater goods. One floor is inaccessible owing to previous layout interventions. The Local Authority is exploring options to secure full repair and long-term viable use of the building. Consents have been granted and external refurbishment is underway, funded by the Local Authority.

Contact: Adam O'Neill (LPA) 020 8753 3318



© Historic England

SITE NAME:	Tomb of Abraham Smith, Hammersmith Cemetery, Margravine Road W6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1072616

White marble monument with a tall, enriched cross surmounting a rubble-carved base circa 1923, by CJ Jordan & Son, Acton, dedicated to a gold prospector. A carved vignette on the cross depicts a gold prospector in a shelter. The surface of the marble is suffering considerable decay and soiling, leading to a loss of detail, and the monument is also leaning significantly. A full condition survey has been undertaken to inform future repair works and advice sought from a structural engineer. The Local Authority, Historic England and Friends of Margravine Cemetery are exploring funding options.

Contact: Adam O'Neill (LPA) 020 8753 3318

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS		
CA LB	Conservation Area Listed Building	
LPA	Local Planning Authority	
NP	National Park	
RPG	Registered Park and Garde	
SM	Scheduled Monument	
UA	Unitary Authority	
WHS	World Heritage Site	

OWNER TYPE:

LIST ENTRY NUMBER:



© London Borough of Hammersmith and Fulham

SITE NAME:	Harwath Mausoleum, St Thomas Of Canterbury Churchyard SW6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

1463196

Neoclassical stone mausoleum dating from 1918 with elaborate exterior and intact interior fittings. It was designed by Arthur Henry Durand FRIBA, architect and interior designer who assisted in the design of the Eiffel Tower and interiors of RMS Titanic and RMS Olympic. It was built by Simon Harwath, a Slovenian immigrant who became a West End hotelier, for his wife Mathilde who helped manage their businesses. The decorative ceiling and plaques are damaged, likely from water ingress through the roof. Further investigation is required to determine an appropriate conservation approach.

Contact: Adam O'Neill (LPA) 020 8753 3318



© London Borough of Hammersmith and

SITE NAME:	Circular garden building, boundary wall and railings, formerly to St Paul's School, Hammersmith Road
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (A)

Local authority 1079820

Circular red brick building and boundary wall, with railings and terracotta finials to brick piers, all formerly part of St Paul's School, 1881-85 by Alfred Waterhouse, now part of St Paul's Open Space. The building is disused and subject to vandalism, with missing roof tiles and damp. The Local Authority commissioned a condition survey for the building and will be seeking consents for its repair and future re-use for garden storage. Conservation repairs to the adjacent wall following damage from a car collision are complete. Repairs to the railings are being investigated.

Contact: Adam O'Neill (LPA) 020 8753 3318



© Historic England

SITE NAME:	public house, 20 Macbeth Street, Hammersmith W6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Good
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1392791

Public house in neo-Georgian style dating from 1936. Built for Truman's as part of a housing estate. The building is an unusual survival with two exceptionally intact 1930s bar interiors. The public house business closed in 2012. The ground floor is used for occasional filming and the upper floors are occupied and in residential use. Original external signage and some internal ironmongery in the bar areas have been removed.

Contact: Adam O'Neill (LPA) 020 8753 3318



© Historic England

SITE NAME:	Tomb of Frederick Harold Young, Hammersmith Cemetery, Margravine Road W6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1072617

Mausoleum dating from 1884. The parapet to the west elevation is missing and there is some broken and missing glass. There are structural defects to the floor. The Local Authority has commissioned a structural report and architectural consultants to prepare a fully detailed schedule of repairs and conservation works, with funding from Historic England. The Local Authority is also working with the Friends of Margravine Cemetery and Historic England to identify appropriate funding sources to enable full repair and conservation works to be carried out.

Table tomb over a brick and stone plinth dating from the end of the C18. There is evidence of severe mechanical damage and erosion as well as rusting of the remaining railings. Invasive vegetation and dumped rubbish continue to be a problem. A suitable proposal is awaited from the church to secure the repair of the monument and improve

Contact: Adam O'Neill (LPA) 020 8753 3318



© Historic England

SITE NAME:	Tomb of Samuel Jones, Queen Caroline Street, St Paul's Churchyard W6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1246022

Contact: Adam O'Neill (LPA) 020 8753 3318

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

its setting.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

OWNER TYPE:

OWNER TYPE:

Medium

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME: Ashlar Court, Former Royal Masonic Hospital Nurses Home, Ravenscourt Gardens DESIGNATION: Listed Building grade II, CA CONDITION: Good OCCUPANCY: Occupied/in use PRIORITY CATEGORY: F (F)

Commercial company

Commercial company

Nurses' home, 1938, by Burnet, Tait and Lorne. Works for conversion to residential use have been completed and the building is now occupied. Outstanding conditions attached to the Listed Building Consent, including the display of artefacts, are yet to be discharged.

Contact: Adam O'Neill (LPA) 020 8753 3318

Hospital, 1933, by Thomas Tait, funded by the

Freemasons. The building has been vacant since the closure of the NHS facility in 2006. Walls within the landscaped garden were demolished in anticipation of implementation of an approved scheme but works then stalled. The building is currently mothballed whilst a suitable scheme for



© Historic England

SITE NAME:	Former Royal Masonic Hospital, Ravenscourt Park, Hammersmith W6
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)

1192740

1269052

Contact: Verena McCaig 020 7973 3718

its repair and re-use is awaited.



SITE NAME:	Church of St John, North End Road, Walham Green SW6
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1079751

Church built in 1827, designed by George Ledwell Taylor. Stonework repairs to the tower and re-roofing of the aisles were completed in 2016, grant-aided by Historic England and the National Lottery Heritage Fund. The nave and chancel were re-roofed in 2017 with funding from the Listed Places of Worship Roof Repair Fund. The church interior and electrics remain in poor condition and a new drainage system is required. Work is anticipated to commence summer 2022 on a first phase replacing and upgrading of all the hoppers, overflows and downpipes serving the nave and aisle roofs.

3 3756

CONTACT:

© Historic England		Contact: Trac	ey Craig 020 7973
SITE NAME:	St Mary's, Kensal Green NW10		
DESIGNATION:	Conservation Area, 10 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving

### **HARINGEY**

VULNERABILITY:



© London Borough of Haringey

SITE NAME:	37, North Road, Highgate N6 N6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Unknown
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENITRY NILIMBER:	1180311

Early C19 house of two storeys and basement, part of two pairs linked by recessed porches. The building is built of red brick, with cement detailing including pilaster strips, entablature and cornice. The condition of the property is deteriorating. The Local Authority is considering options to secure the full repair of the building.

Adam O'Neill (LPA) 020 8753 3318

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**



© Historic England

SITE NAME:	Alexandra Palace, Alexandra Palace Way, Wood Green N10 N10
DESIGNATION:	Listed Building grade II, part in RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Charity (heritage)

1268256

Entertainment complex including exhibition halls and theatre, built 1868-75. From 1935 part of Alexandra Palace was leased to the BBC. Repairs to the loggia on the south terrace (western end) and south-east roofs were completed in 2013. Repairs to the eastern part of the building, including the theatre, were completed in 2018, as part of a National Lottery Heritage Fund project. However, large parts of the building remain in a derelict condition with the north-east office building, where Historic England has funded project development work, of particular concern and this is under discussion.

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497



© Historic England

SITE NAME:	Hornsey Town Hall, Broadway N8 N8
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1263688

Built in 1935 to the design of RH Uren. Modelled on Dudock's seminal town hall at Hilversum and an important influence on subsequent British town hall design. The building was in a poor condition, particularly the Assembly Hall to the rear. The Local Authority has transferred ownership to Far East Consortium International Ltd. This includes an agreement to guarantee continued public access to, and use of, parts of the building. The town hall will also accommodate a hotel, with new residential development to the rear. Work has started on site.

Contact: Elizabeth Whitbourn 07889 808145



© London Borough of Haringey

SITE NAME:	Former public toilets, Bruce Grove, Tottenham NI7 NI7
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1259316

Public toilet circa 1920, with fine external ironwork. The building is currently empty. The Local Authority commissioned a structural survey in 2018 and has secured funding for repair and renovation of the building. The ironwork has been restored and works are progressing on site, relevant demolitions have occurred, cleaning and repair trials have been agreed. Discharge of planning conditions in respect of the approved Planning and Listed Building Consent applications are reaching their conclusion prior to completing work to refurbish the toilets as a community arts café.

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497



© London Borough of Haringey

SITE NAME:	7, Bruce Grove, Tottenham N17 N17
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1188605

One of a pair of early C19 houses. The building is vacant and has suffered substantial internal collapse. A scheme of refurbishment and conversion to flats was approved. A proposal to amend the approved scheme in order to optimise the configuration of the second and top floors is under discussion. The building was sold to a new owner in 2020. The Council took enforcement action in 2021 to obtain access and carry out a condition survey and are in discussion with the owner regarding the next steps.

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497



© London Borough of Haringey

SITE NAME:	West wall, Bruce Castle Park, Church Lane, Tottenham N17 N17
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1294666

C17 red brick boundary wall to Bruce Castle Park. In urgent need of essential repairs as the brickwork is deteriorating. An initial programme of repairs has been undertaken, but further works are needed.

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## I PA ΝP RPG



© Historic England

SITE NAME:	662, High Road, Tottenham N17 N17
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use

PRIORITY CATEGORY: F (F) OWNER TYPE: Commercial company

1358832 LIST ENTRY NUMBER:

Early C18 building of three storeys, in stock brick with stone coped parapet, lower than the neighbouring properties with which it has group value. The building was badly fire damaged during the 2011 riots. The upper floors and roof of the building have been renovated and repaired. Listed Building Consent was granted in 2019 for renovations to the ground floor of the building with restoration of the shop frontage, and works are due to start on site.

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

Fine house built circa 1715 as part of a symmetrical pair. Planning Permission and Listed Building Consent have been granted for the refurbishment and re-use of the building as part of Tottenham Hotspur Football Club's wider redevelopment proposals. Work has not yet started.



© London Borough of Haringey

SITE NAME:	810, High Road, Tottenham N17 N17
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1358835

Contact: Elizabeth Whitbourn 07889 808145



© London Borough of Haringey

SITE NAME:	Retaining wall along Highgate Hill (The Bank), Highgate Hill, Highgate N6 N6
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1079237

Early C19 retaining wall along Highgate Hill between the street pavement and higher paved walk. Some repairs were carried out in 2010/11. Temporary measures were implemented in January 2018 to safeguard the wall and the Local Authority is undertaking investigations to identify an appropriate permanent solution.

© London Borough of Haringey

SITE NAME:	South boundary wall to Bruce Castle Park, Lordship Lane, Tottenham N17 N17
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1079218

Red brick wall of probable early C17 date in Flemish bond, with tall sloped coping and plinth. The wall is ramped gently up at intervals towards the west. It is now seriously deteriorating with open decayed pointing, loose and unstable brickwork, previous re-pointing damage, and extensive ivy/creeper and frost damage. A programme of urgent repairs has been undertaken, but further repairs are required.

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497



© London Borough of Haringey

SITE NAME:	Porters and Walters Almshouses, St Leonard's Almshouses, Nightingale Road, Wood Green N22 N22
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1079222

Four two-storey almshouses, circa 1904, which form a group with a commemorative stone and front railings. The buildings have suffered from a lack of proper maintenance over a number of years and there was a partial collapse of the boundary wall in 2018. Listed Building Consent has been granted for partial demolition and rebuilding, and work is in progress.

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME:	Church of St Augustine, Archway Road, Hornsey N6
DESIGNATION:	Listed Place of Worship grade II CA
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation

1358860

The Art Workers Guild background of the three architects involved in this late C19 church is very apparent. JF Sedding started the work, was succeeded by his pupil Henry Wilson (west nave and Lady Chapel) and Harold Gibbons, who in 1916 completed the Arts and Crafts facade with its Calvary. The London stock brickwork is dressed in Bath stone and red brick under a plain tiled roof. Internal fittings are of a high quality. The tower roof was repaired in 2017 and the Calvary Statuary in 2018, with grants from the National Lottery Heritage Fund. There remain repairs needed to roofs and gutters.

Contact: Ian Harper 020 7973 3786



© Donald Insall Associates

SITE NAME:	Former Gaumont Palace cinema, Broadway, Wood Green N22	
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (New entry)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1263635	

1263635

The former Gaumont Cinema was built in 1934, designed by architects William Edward Trent and Ernest F Tulley. It is constructed with a steel frame clad in brick. The entrance façade combines artificial stone with brick and is in the Moderne style, as are the decorations and fittings internally. In 2018 a piece of the high-level cornice fell to the ground. Access scaffolding was erected for inspection and emergency repairs. In 2020 it was discovered that the steels supporting the high-level upper and lower cornices were extensively corroded. A repair solution is now being sought.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Parish Church of All Hallows, Church Lane, Tottenham N17
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1188633

This medieval church incorporates a C14 tower with C18 battlements. The north aisle was rebuilt in 1855. The chancel, east end extensions and raised clerestories were by William Butterfield in 1875-7. In 2017 the roofs and valley gutters were repaired with a grant from the Listed Places of Worship Roof Repair Fund. Much C14 and C15 architectural fabric survives internally but is suffering from dampness and requires repair. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for repairs to the vestry roof. The felted tower roof is ponding and a big risk.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE INAPIE:	Craven Park Road, Tottenham N15
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1079264

Church of St Parthalamour

Arts and Crafts parish church designed by WD Caroe, completed in 1904. Plain tiled roofs and mass soft red-brick walls contain a finely carpentered roof and original interior furnishings including some by Gibbons from St Bartholomew by the Bank. Vicarage on north side of the church also by Caroe. The roof batten fixings to the boards are failing in some areas, especially to chancel and Lady Chapel roofs, causing the battens and tiles to creep down the roof with resultant leakage. This condition needs to be addressed urgently in order to prevent roof decay.

The former Tottenham Palace Theatre was built in 1908 by Wylson Long as a variety theatre. The building is now in use for worship. It is suffering from water ingress, which is causing significant damage to both the structure and interior plaster work. Some repairs were carried out to the front roofs in 2015, but considerable further work is required. Discussions between the Local Authority and the congregation are ongoing to secure necessary urgent

Contact: Ian Harper 020 7973 3786



© Historic England

ITE NAME:	The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Policious organisation

Contact: Ian Harper 020 7973 3786

works.

DESIGNATION:	Listed Place of Worship grade II. CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1249660

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Bruce Grove N17		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	Clyde Circus N15		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	Hornsey Water Works and Filter Beds, Hornsey	N8	
DESIGNATION:	Conservation Area, 2 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	North Tottenham High Road N17		
DESIGNATION:	Conservation Area, 30 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	Scotland Green N17		
	Consequetion Anna ALDa	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 4 LBs		110
DESIGNATION:  CONDITION:	Very bad	TREND:	No significant change

#### **HARROW**



0	Historic	Fngland	

SITE NAME:	Former Wealdstone Police Station, High Street HA3
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1245418

Former police station with magistrates' court, later part library and then entirely a police station. Built in 1908-9 by J Dixon Butler in Free Tudor style. The building has been empty since 2015 and was illegally occupied in 2016. Applications were refused in 2016 and 2017 for extensions and new buildings, and an appeal was dismissed in 2018. Planning Permission and Listed Building Consent was approved in 2020 for a mixed-use scheme for the building with offices, café and 6 flats. Work is now complete (May 2022) but the building is not yet occupied.

SITE NAME: Former White Hart Hotel, High Street, Edgware HA8

© Historic England

DESIGNATION: Listed Building grade II CONDITION: OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1079726

C17 three-storey stuccoed building with a hipped tile roof and wooden eaves cornice. It is no longer in use as a public house or as a restaurant but is closed and out of use. The upper floors are in a poor condition after unauthorised works and there are holes in the walls and ceilings. A new leaseholder took over in 2020. More extensive unauthorised works were carried out in parts of the building during Covid-19 Lockdown. The Local Planning Authority halted these and is carrying out enforcement

Contact: Lucy Haile (LPA) 020 8736 6101

Contact: Lucy Haile (LPA) 020 8736 6101

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**



© Historic England

SITE NAME:	Kenton Lane Farmhouse, Kenton Lane HA3
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (D)
OWNER TYPE:	Commercial company

1253950

Two-storey former farmhouse built circa 1808, to the designs of William Loudon and Robert Abraham in Flemish bond red brick with a hipped slate roof. Listed Building Consent and Planning Permission were approved in 2013 for repairs and conversion to residential, linked to an adjacent housing scheme. Whilst the new homes have been built, works to the listed buildings have not been carried out. The house and farm buildings were damaged by illegal entry in early 2019. The site is now secure and the Local Planning Authority is carrying out enforcement

Contact: Lucy Haile (LPA) 020 8736 6101



Historic England

SITE NAME:	Kenton Lane former farm buildings, Kenton Lane HA3
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (D)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1253952

Former farm buildings built circa 1808, to designs of William Loudon and Robert Abraham in colour washed Flemish bond brick. The vacant buildings surround three sides of a designed courtyard. Listed Building Consent and Planning Permission were approved in 2013 for conversion to residential, linked to an adjacent housing scheme. Whilst the new homes have been built, works to the listed buildings have not been carried out. The buildings were damaged by illegal entry in 2019 but the site is now secure and discussions are ongoing between the Local Authority and the owner regarding the scheme.

Contact: Lucy Haile (LPA) 020 8736 6101



© Historic England

SITE NAME:	Old Pye House, West Street, HAI 3EL
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1358651

The CI5 two-storey building was part of a larger hall building. It has a slate roof, timber-framed walls and gable ends with a central tie beam, and a plain kingpost. The south front is C18 or early C19 red brick. Unoccupied and in poor condition, the original first floor was removed when it was used as a plastics factory. Internal scaffolding has now been installed, a modern extension and yew tree have been removed, and the ground level lowered inside the building. Discussions about proposals, including external scaffolding, are taking place between the owner and the Local Authority.

C19 wall, 11 foot high, with stone copings, recessed in the centre to pass through the porte-cochère. The wall forms a curved forecourt and screening to Springbok House, now the Hussaini Shia Islamic Centre. A leaning section of the wall was deemed a dangerous structure by the Local Authority and was taken down in 2018 for safety reasons. The wall has temporary protective hoarding and scaffolding in place whilst discussions continue with the owner on its

Contact: Lucy Haile (LPA) 020 8736 6101



© London Borough of Harrow

SITE NAME:	Wall to west and north of Springbok House, Wood Lane
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (non-heritage)
LIST ENTRY NUMBER:	1358673

Contact: Lucy Haile (LPA) 020 8736 6101

reinstatement and funding of the work.



© London Borough of Harrow

SITE NAME:	Gate pier at entrance to Canons Drive, Edgware HA8
DESIGNATION:	Listed Building grade II, RPG grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Commercial company

1079736

repair and reinstatement.

One of the two decorated early C18 gate piers, belonging to and contemporary with Canons (now demolished), collapsed in a storm in early 2022 due to a tree fall. The Local Authority is in discussion with the owner regarding

Contact: Lucy Haile (LPA) 020 8736 6101

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

I PA ΝP RPG



© London Borough of Harrow

SITE NAME:	Brick Kiln to south east of the Kiln, Common Road, Stanmore
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1079710

Lower part of a C18 brick kiln conical chimney, of which the upper part no longer exists. In urgent need of structural stabilisation and repair.

Contact: Lucy Haile (LPA) 020 8736 6101



© London Borough of Harrow

SITE NAME:	Pinner Park Farmhouse, George V Avenue, Pinner
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1079715

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

The building dates from circa 1750. It is two storeys with three bays plus hipped wing. The windows to the main house are altered. The building appears in good condition externally but the interior requires attention. There has been some damage from water penetration and the building is partly vacant. Listed Building Consent was approved in 2018 to replace an existing steel beam and repair the central valley gutter, and in 2019 this work was completed.

Contact: Lucy Haile (LPA) 020 8736 6101



© London Borough of Harrow

SITE NAME:	Garden wall to Bernays Gardens, Old Church Lane, Stanmore
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Local authority

1079749

C19 wall with buttresses. Many of the bricks were significantly decayed and the wall was in need of repointing. The Local Authority obtained Listed Building Consent for works to repair the wall and Historic England are currently grant aiding a programme of repairs which is nearing completion (May 2022).

Contact: Lucy Haile (LPA) 020 8736 6101

Contact: Lucy Haile (LPA) 020 8736 6101



© London Borough of Harrow

SITE NAME:	Boundary wall fronting road from Nos 118-128, Stanmore Hill (east side), Stanmore
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private
PRIORITY CATEGORY:	D (C)

C18 brick wall with buttresses with chamfered bases. Many bricks at the base have weathered away and parts require repointing. Listed Building Consent was approved in 2021 for repairs to the wall.



© London Borough of Harrow

SITE NAME:	The Rayners public house, 23, Village Way East
DESIGNATION:	Listed Building grade II
CONDITION:	Good
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1194205

A virtually unaltered 1930s public house retaining its internal plan form and original fittings. Listed Building Consent was granted for the repair, renovation and re-use of the building. These works have largely been implemented and the building is now in educational use. However, unauthorised signage and some alterations to the interior still need addressing.

1392310 Contact: Lucy Haile (LPA) 020 8736 6101

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME:	Old Stanmore Church, Church Road, Stanmore
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION	Poor

Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

1079747

The now roofless ruined church of St John the Evangelist was built in 1632, attributed to Nicholas Stone. The wall heads have exposed brickwork allowing rainwater ingress. This is resulting in the erosion of mortar and bricks and in supporting deleterious plant growth. There is decayed mortar, brick, stone and timber elsewhere around the building along with some vertical cracking in the walling. The church is occasionally used for worship.

Contact: Tracey Craig 020 7973 3756

SITE NAME:	Grim's Ditch: section extending 1500yds (1370m) north east from Oxhey Lane		
DESIGNATION:	Scheduled Monument, part in RPG grade II, part in CA	LIST ENTRY NUMBER:	1002044
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Grim's Ditch: section north of Blythwood House		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002007
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Linear earthworks in Pear Wood, west of Watling	Street	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001996
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Pinner deer park, Pinner Park Farm		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1019135
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Grim's Ditch: four linear sections between Uxbridge Road and Oxhey Lane		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003530
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**



© Historic England

SITE NAME:	Bentley Priory
DESIGNATION:	Registered Park and Garden grade II, LB grade II*
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001440

A C16 estate enlarged and improved in the late C18. Sir Uvedale Price and William Gilpin influenced the design in the early C19. Royal Air Force Fighter Command occupied the mansion from 1936, which played a central role in World War II, now converted to a museum with residential units, and new housing in the grounds. The Italian gardens and pleasure grounds around of the mansion have been restored, but boundary treatment, views and the character of the lake in land owned and managed by the Local Authority, much of it a Site of Special Scientific Interest, remain issues to be resolved.

Contact: Christopher Laine 020 7973 3473

#### **HAVERING**

© Historic England



SITE NAME: The Rom Skatepark DESIGNATION: Listed Building grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1419328

LIST ENTRY NUMBER:

Built in 1978, The Rom Skatepark was designed by Adrian Rolt of G-Force and in 2014 became the first skatepark in England to receive national listed status. Following a fire in 2018 the park lost its (unlisted) indoor facilities which ultimately led to its closure in September 2019. The park has re-opened but requires concrete and drainage repairs. Historic England has provided advice to owners on surveys required to identify appropriate approaches to repair.

Contact: Azizul Karim (LPA) 01708 433 100

© London Borough of Havering

SITE NAME:	Garden walls to former North Ockendon Hall, Church Lane, North Ockendon
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1300500

C16 and later garden walls to Ockendon Hall (now demolished). These extensive walls are slowly deteriorating although the owners are making efforts to prevent further damage from vegetation.

Contact: Azizul Karim (LPA) 01708 433 100



© Historic England

SITE NAME:	Outbuilding to the rear of The Old Anchor, Harwood Hall Lane
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1079891

C19 timber-framed outbuildings which continue the line of the rear wing of The Old Anchor, a C18 timber-framed house. The building is currently used as a workshop. It is in need of roof and brickwork repairs, new rainwater goods, and renewal of the timber lintels. The Local Authority and Historic England are monitoring the condition of the building and have discussed essential repairs with the owner.

Contact: Azizul Karim (LPA) 01708 433 100



© Historic E	ngland
--------------	--------

SITE NAME:	High House Farmhouse, Ockendon Road
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1079867

Three-storey house of brick and timber frame circa 1700 with an older timber-framed wing. The timber frame to the three-storey section is under stress, the porch is propped by scaffold and there is significant water damage from the roof. A number of the rooms are uninhabitable. Much of the extensive vegetation growth on the exterior of the building has been removed and some surveys have been carried out but the building requires urgent repairs to prevent further decay and possible localised collapse. The Local Authority and Historic England are continuing discussions with the owners.

Contact: Verena McCaig 020 7973 3718

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority categor shown in brackets (otherw New Entry is noted).

ry is vise,	CA LB LPA NP RPG SM UA WHS	Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site
----------------	---	---

**ABBREVIATIONS** 



© London Borough of Havering

51171115 500 111 E 151 7 11/1 E 1111 1G		
	SITE NAME:	Two brick barns and garden walls to south of Bretons House, Rainham Road, Hornchurch
	DESIGNATION:	Listed Building grade II
	CONDITION:	Very bad
	OCCUPANCY:	Part occupied/part in use
	PRIORITY CATEGORY:	A (A)
	OWNER TYPE:	Local authority

1300053

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Two Tudor barns set around a cobbled courtyard close to the C16 garden walls, all associated with Bretons House. One barn is watertight and in partial use although deteriorating, with some earlier unsympathetic alterations and additions. The other barn is in need of extensive repair, particularly to the roof and walls, and suffers from vandalism. The garden walls are also in need of extensive repair and protection, with areas of collapse. A Conservation Statement has been prepared for these assets and plans for the wider site are being developed. However, immediate repairs are required.

Contact: Azizul Karim (LPA) 01708 433 100



© Historic England

SITE NAME:	Upminster Windmill, St Mary's Lane, Upminster
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1079878

Smock mill 1803, retaining original machinery. The Friends of Upminster Windmill, in conjunction with the Local Authority, have been awarded a grant from the National Lottery Heritage Fund. The project includes the full restoration of the mill, and the provision of a workshop and visitors' centre on the site. Restoration works are near completion on the windmill and the sails are operational. It is due to open to the public in 2023.

Contact: Verena McCaig 020 7973 3718



© London Borough of Havering

SITE NAME:	Garden walls at Cranham Hall, The Chase, Cranham
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1183600

C16 walls to an earlier house on the site of Cranham Hall. The wall is in need of extensive repairs. Previous localised repairs are inappropriate and uncontrolled tree and other plant growth is causing further damage and deterioration.



© Historic England

SITE NAME:	Mill Cottage, The Dell, High Street, Hornchurch
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1079898

and continuing to deteriorate. The roof has undergone extensive temporary repair but continues to present major maintenance problems.

Single-storey timber-framed range, now one dwelling, dating from the C17. The building is in very bad condition

Contact: Azizul Karim (LPA) 01708 433 100

Contact: Azizul Karim (LPA) 01708 433 100



© Historic England

SITE NAME:	Footbridge to rear of Nos. 52 and 54, The Grove, Upminster
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1323729

Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s for Sir James Esdaile, Lord Mayor of London 1777-78. Erection of fencing on the bridge has seriously damaged the structure. Extensive vegetation growth is further threatening its stability. Some structural repairs have been carried out in the past but further works are urgently required.

Contact: Azizul Karim (LPA) 01708 433 100

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Dagnam Park Farm moated site, Noak Hill, Romford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001988
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Romford		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Planning Service (LPA) 01708 433100

#### HILLINGDON



SITE NAME: Granaries at Knightscote Farm, Harefield UB9 DESIGNATION: Listed Building grade II CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Local authority

A pair of early to mid C19 weatherboarded granaries, each with timber frames, standing on staddle stones, with tiled roofs. These are examples of a once-common agricultural building type in Middlesex, but now rare. The northern granary re-uses a C18 six-panel door and has a queen strut roof with clasped purlins. The southern granary has now collapsed.

© Historic England

LIST ENTRY NUMBER: 1376634

Contact: Mark Butler (LPA) 020 7361 2465



SITE NAME: Wall and gate piers at St Martin's churchyard entrance, Church Road, Hillingdon UB7 DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Religious organisation

Restored C16 red brick churchyard entrance wall and gate piers, with wrought iron gates, at St Martin's Church. Lower parts of C16 red brick, with the upper part rebuilt probably in the CI9. A survey of the churchyard walls has been carried out, with funding from Historic England, and funding will be sought to enable the necessary repair works to be carried out.

© MRDA

LIST ENTRY NUMBER: 1080275

Contact: Mark Butler (LPA) 01895 558196



© Historic England

SITE NAME: Wall running south from the Old Gatehouse west along Church Road, Hillingdon DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1358326

C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition. A condition assessment has been prepared, with funding from Historic England, and discussions are underway with the owners of the wall regarding the necessary repairs.

Contact: Elizabeth Whitbourn 07889 808145

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**



© Historic England

SITE NAME: Walls around St Martin's churchyard, north side, Church Road, Hillingdon UB7 DESIGNATION: Listed Building grade II\*, CA CONDITION:

Very bad OCCUPANCY: N/A

PRIORITY CATEGORY: A(A)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1286366

Red brick boundary and retaining wall for St Martin's churchyard. C16 red brick walls, with tall sloped coping, along the east and north sides of the churchyard and the northern part of the west side. At the south end of the east side there is a square pier with stone cornice and ball finials. A survey of the churchyard walls has been carried out, with funding from Historic England, and funding will be sought to enable the necessary repair works to be carried out.

Contact: Elizabeth Whitbourn 07889 808145



© Historic England

© Historic England

SITE NAME: Walls around St Martin's churchyard, south side, Church Road, Hillingdon UB7 DESIGNATION: Listed Building grade II, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Religious organisation

Red brick boundary and retaining wall along the south part of the west side and the south side of St Martin's churchyard. Lower parts of C16 red brick, with the upper part rebuilt probably in the C19. A survey of the churchyard walls has been carried out, with funding from Historic England, and funding will be sought to enable the necessary repair works to be carried out.

Contact: Mark Butler (LPA) 01895 558196



SITE NAME: Lych gate to south of Church of St Mary, Church Walk, Hayes DESIGNATION: Listed Building grade II, CA CONDITION: Poor

1080276

OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1080234

LIST ENTRY NUMBER:

Circa C16 timber lych gate with tiled roof. The timber supports and base are in a very poor state of repair and tiles are slipping from the roof. No repairs are planned.



© London Borough of Hillingdon

SITE NAME: Barn to the west of Weekly House, Bath Road, Harmondsworth

DESIGNATION: Listed Building grade II, CA

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A(A)OWNER TYPE: Private

LIST ENTRY NUMBER: 1286544

Late C17 or early C18 weatherboarded barn with tiled roof and Queen post truss at the west end. Weekly House, the boundary wall and the barn form a group. The barn is in a dilapidated state.

Contact: Mark Butler (LPA) 01895 558196

Contact: Mark Butler (LPA) 01895 558196



© London Borough of Hillingdon

SITE NAME: Former King Henry public house and stables, 456, Bath Road, Longford DESIGNATION: Listed Building grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

Private

1080296

Converted to a house, the rear of the building is the former King Henry public house. The front part of the property has been rebuilt, using old material, after a fire. All the walls have exposed timber framing with brick filling and tiled roofs. The adjacent stables are also of interest with an early diamond mullioned window. The buildings are in poor condition; but have been secured by the owner. They have been included in larger development proposals.

Contact: Mark Butler (LPA) 01895 558196

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

OWNER TYPE:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**



© London Borough of Hillingdon

SITE NAME:	Enterprise House, Blyth Road, Hayes
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1244861

1912 factory building by the Trussed Concrete Steel Company for HMV. It has an unusual design with a highlevel water tank and is an important local landmark. The building is partially occupied but in a deteriorating condition. Proposals for conversion to residential use have now been agreed and works have started on the consented scheme.

Contact: Mark Butler (LPA) 01895 558196

A			
=			
	1		
		E.	

© London Borough of Hillingdon

SITE NAME:	Langley Farm Barn, Breakspear Road North, Harefield
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1080261

C16 barn in private ownership at Langley Farm. The threebay barn is timber-framed and weatherboarded with a tiled roof. It has lost parts of the brick plinth to the north east elevation. Listed Building Consent and Planning Permission have been granted for residential use and work has started

Contact: Mark Butler (LPA) 01895 558196



С
C
C

© Historic England

SITE NAME:	Garden walls to Church Gardens Nursery, Church Hill, Harefield
DESIGNATION:	Listed Building grade II, RPG grade II, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)

C17 red brick garden walls in need of extensive repairs. Some works have already been undertaken to a good standard. Planning Permission and Listed Building Consent applications were approved in 2021 for work which will include repairs to the walls.

OWNER TYPE: Private 1080272 LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Contact: Mark Butler (LPA) 01895 558196



© Historic England

SITE NAME:	Wall in front of numbers 30 to 36 (even), Church Road, Hillingdon
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition. A condition assessment has been prepared, with funding from Historic England, and discussions are underway with the owners of the wall regarding the necessary repairs.

LIST ENTRY NUMBER: 1080277 Contact: Mark Butler (LPA) 01895 558196

Wall in frant of numbers 10 to



© Historic England

SITE INAME:	50 (even), Church Road, Hillingdon
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1358327

C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition. A condition assessment has been prepared, with funding from Historic England, and discussions are underway with the owners of the wall regarding the necessary repairs.

Contact: Mark Butler (LPA) 01895 558196

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

CITE NIAME

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME: Walls in front of numbers 52-58 (even) and along west end of propérty, Church Road, Hillingdon

DESIGNATION: Listed Building grade II, CA

Private

Poor OCCUPANCY: N/A

PRIORITY CATEGORY: C(C)

LIST ENTRY NUMBER: 1286348 C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition. A condition assessment has been prepared, with funding from Historic England, and discussions are underway with the owners of the wall regarding the necessary repairs.

Contact: Mark Butler (LPA) 01895 558196



© Historic England

SITE NAME: Walls to east and south of garden of number 28 (Coombe House), Church Road, Hillingdon

DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor

OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1193014

C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition. A condition assessment has been prepared, with funding from Historic England, and discussions are underway with the owners of the wall regarding the necessary repairs.

Contact: Elizabeth Whitbourn 07889 808145



© London Borough of Hillingdon

Cinema, RAF Uxbridge, Grays SITE NAME: Road, Uxbridge DESIGNATION: Listed Building grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)

OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1392376

Designed in 1918, the building has a large auditorium used historically as a lecture hall, cinema or concert hall. It was converted to a gymnasium in the 1960s. The building is vacant and in poor condition. The slate roof of the main hall was repaired in 2020 and its condition is being monitored. The Local Authority is in discussion with the owner regarding new proposals for its re-use.

Contact: Mark Butler (LPA) 01895 558196



© Historic England


SITE NAME: World War II Bofors gun tower and ancillary building, Kuislip DESIGNATION: Listed Building grade II CONDITION: Very bad OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C(C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1414202

1940s reinforced concrete gun tower platform with red brick infill walls and external access stair. The associated ancillary building is also brick with a flat reinforced concrete roof. It has previously been used as storage for the adjacent football ground. The structure is not weathertight, and the openings and rear roof require securing and repair. There is severe vegetation growth on the ancillary building.





© London Borough of Hillingdon

SITE NAME: The Dower House, 393, High Street, Harlington DESIGNATION: Listed Building grade II CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)OWNER TYPE: Private

1080196

Two-storey house with C18 brick front to an older timberframed structure, with large rebuilt C16 chimney. The house is four bays wide, built of brown brick with red brick quoins and window dressings. The building suffered severe fire damage in May 2011. In May 2018 the Council took enforcement action to ensure that the building was made wind and weathertight, and it has a temporary roof. The house was sold in 2020 and initial pre-application discussions have taken place with the Council regarding its repair and future uses.

Contact: Mark Butler (LPA) 01895 558196

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**



© London Borough of Hillingdon

SITE NAME:	Harefield Park (annexe to Harefield Hospital), Hill End Road, Harefield

DESIGNATION: Listed Building grade II\*, CA

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A (A)

OWNER TYPE: Health authority

LIST ENTRY NUMBER: 1080177

The site comprises the main building and two flanking stable buildings of early C18 date. The house is vacant and in very poor condition, with no use identified. The building is propped and a temporary roof is in place. A condition survey has been prepared to inform repairs.

Contact: Elizabeth Whitbourn 07889 808145



© London Borough of Hillingdon

SITE NAME: The stable block, north east of Harefield Park, (annexe to Harefield Hospital), Hill End

Road, Harefield

DESIGNATION: Listed Building grade II, CA

CONDITION: Fair

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Health authority

LIST ENTRY NUMBER: 1285329

One of two stable buildings of early C18 date. The stable building has had work completed to the roof and interior and is being used for staff offices. Some further repairs to the exterior are required.

Contact: Mark Butler (LPA) 01895 558196



© Historic England

The stable block, south east of Harefield Park, (annexe to Harefield Hospital), Hill End Road, Harefield

DESIGNATION: Listed Building grade II, CA

CONDITION: Poor

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Health authority

LIST ENTRY NUMBER: 1358396

One of two stable buildings of early C18 date. The stable building is currently being used in the short-term for clinical storage and staff accommodation. A long-term use needs to be identified.



© London Borough of Hillingdon

SITE NAME:

Nurses Home in grounds of Hillingdon Hospital, Pield Heath Road, Hillingdon

DESIGNATION:

Listed Building grade II

CONDITION: Poor
OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Health authority

LIST ENTRY NUMBER: 1080 | 53

Early C19 house in the grounds of Hillingdon Hospital, currently used as offices, but generally in poor condition. Applications for Planning Permission and Listed Building Consent have been submitted to repair the building and refurbish the modern extensions so it can continue as part of the hospital complex.

Contact: Mark Butler (LPA) 01895 558196

Contact: Mark Butler (LPA) 01895 558196



© Antonio Cruz, Comer Homes Group

Harefield Grove,
Rickmansworth Road, Harefield

DESIGNATION: Listed Building grade II

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (D)

OWNER TYPE: Private

1181148

Probably early C19 country house of three storeys. Stucco with stone cornice and parapet concealing a fairly low-pitched hipped slate roof. The building has a two-storey modern courtyard wing for office use with an atrium link. It has been vacant for a number of years and is deteriorating. Listed Building Consent and Planning Permission have been granted for residential use but work has not yet started.

Contact: Mark Butler (LPA) 01895 558196

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- O Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

**ABBREVIATIONS** 

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© London Borough of Hillingdon

SITE NAME:	Mount Vernon Hospital, Rickmansworth Road, Northwood
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Health authority

1080083

1902-4 by FL Wheeler in Edwardian Free Style. Built as a hospital for the treatment of tuberculosis patients, and as a branch hospital of the original Mount Vernon hospital in Hampstead (built 1879-80). The building is noted for its advanced plan, including isolation wards and facilities such as an X-ray room and dental unit. It is still in use by the hospital, but in a poor state of repair and under pressure from the redevelopment of the site.

Contact: Mark Butler (LPA) 01895 558196



© Historic England

Cellars of former Cranford House, Roseville Road, Cranford
Listed Building grade II, CA
Poor
Vacant/not in use
F(D)
Local authority

1285115

Brick vaulted cellars to Cranford House circa 1722 (demolished). The cellars are suffering from structural weakening and their condition is deteriorating. The National Lottery Heritage Fund awarded the Local Authority a grant which included funds towards repair of the cellars. Planning Permission and Listed Building Consent applications were approved in 2020. Work is due to start in summer 2022 with an anticipated completion date in spring 2023.

Contact: Mark Butler (LPA) 01895 558196



© Historic England

SITE NAME:	Cranford House Stables, Roseville Road, Cranford
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Local authority

1080157

Stables to Cranford House circa 1720, owned and managed by the London Borough of Hillingdon. The east block is in very  $\underline{p}$ oor condition and the site is in need of a long-term use. The National Lottery Heritage Fund, National Highways and Heritage of London Trust have awarded the Local Authority grants which include funds towards repair of the stables. Planning Permission and Listed Building Consent applications were approved in 2021. Work is due to start in summer 2022 with an anticipated completion date of spring 2023.

Contact: Mark Butler (LPA) 01895 558196



© London Borough of Hillingdon

SITE NAME:	Benlow Works, Silverdale Road, Hayes
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1080121

Orchestrelle Factory of 1909-11. Reinforced concrete frame, with brick exterior. Four storeys with a 19-bay elevation. The entrance bay has a semi-circular stepped brick architrave to the doorway and segmental arched metal casements flanked by rusticated pilasters slightly set forward and breaking the parapet. Temporary repairs have been undertaken so that the building is weathertight. Discussions have been held with the owner, but no solution is agreed for future use as yet.

Contact: Mark Butler (LPA) 01895 558196



© London Borough of Hillingdon

SITE NAME:	Gatehouse at Hillingdon- Uxbridge Cemetery, Uxbridge Road
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1358415

Mid-C19 gatehouse by Benjamin Ferry, with an adjacent stock brick boundary wall. The gatehouse is constructed of rubble with stone dressings, tiled roof and five bays with a wide central entrance under the arch. It is in a deteriorating condition and vacant, and the wall has partially collapsed. A condition survey has been completed and the extent of repairs required agreed, but not yet implemented.

Contact: Mark Butler (LPA) 01895 558196

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. I PA ΝP New Entry is noted).

## **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park

Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© London Borough of Hillingdon

SITE NAME:	Hubbard's Farm Barn and outbuildings, West Drayton Road, Colham Green, Uxbridge
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (F)
OWNER TYPE:	Private

Two barns dating from the C16. Listed Building Consent and Planning Permission were granted for a residential scheme incorporating re-use of the salvaged historic timbers. The barns were re-erected on site in 2021, however the works were not undertaken in accordance with the approved drawings and the Local Authority is currently in discussion with the owner.

Contact: Mark Butler (LPA) 01895 558196



© Historic England

SITE NAME:	Church of St Mary, High Street, Harmondsworth
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Fair
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1080201

1284866

St Mary's has fabric from the C12 to the C16 including a fine C12 stone doorway. It has a tall square tower c1500 on top of which is a cupola and weathervane supported on four cast iron columns. The church is largely constructed in flint with stone dressings; the upper stages of the tower are in brick. The roofs are tiled. Much of the dressed stone, including quoins and the copings to the battlemented parapet, has been refaced in a cementitious render. The refacings are failing in places, exposing the substructure. There is cracking around the western end, particularly severe in the tower.

Contact: Tracey Craig 020 7973 3756



© Alex Veal

SITE NAME:	Church of St John, Royal Lane, Hillingdon
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1080160

C13 chancel arch and C14 nave and aisles. Tower rebuilt 1629. In 1848 Sir G Gilbert Scott refurbished the building and added transepts and chancel. The tower is surmounted by a wooden cupola which is in poor condition with decay, splits and unsympathetic past repairs. Clay tiles are beginning to fail, valley gutters are poor and patched, and rainwater goods are also in need of attention. The flint walling has some loss of pointing. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for a timber survey of the cupola and also some stabilisation works.

Contact: Tracey Craig 020 7973 3756

SITE NAME:	Moated site, west bank of River Pinn, near Ickenha	m (1/2 mile (800m)	north west of church)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002001
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Park Pale, Ruislip		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021402
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Manor Farm moat, Ickenham		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1002006
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Educational (state sector)	CONTACT:	Elizabeth Whitbourn 07889 808145

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

SITE NAME:	Botwell (Nestles), Hayes		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
/ULNERABILITY:	Medium	CONTACT:	Mark Butler (LPA) 01895 558196
ITE NAME:	Bulls Bridge, Hayes		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
/ULNERABILITY:	Medium	CONTACT:	Mark Butler (LPA) 01895 558196
TE NAME:	Cranford Park, Cranford		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
ULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 01895 558196
ITE NAME:	Harlington Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
/ULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 01895 558196
ITE NAME:	Harmondsworth Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
/ULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 01895 558196
ITE NAME:	Longford Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
ULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 01895 558196
ITE NAME:	Northwood Town Centre, Green Lane, No	orthwood	
esignation:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
/ULNERABILITY:	Medium	CONTACT:	Mark Butler (LPA) 01895 558196
ITE NAME:	Old Uxbridge/ Windsor Street, Uxbridge		
DESIGNATION:	Conservation Area, 43 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
/ULNERABILITY:	Medium	CONTACT:	Mark Butler (LPA) 01895 558196
ITE NAME:	The Greenway, Uxbridge		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
CONDITION:	1 001		Deteriorating

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### **HOUNSLOW**



© Historic England

SITE NAME Roman Bridge, Jersey Road, Osterley Park

Listed Building grade II\*, RPG DESIGNATION: grade II\*, part in CA

CONDITION: Very bad OCCUPANCY: N/A

PRIORITY CATEGORY: A(A)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1079401

LIST ENTRY NUMBER:

Rusticated and stone-faced bridge with one segmental arch and flanking pairs of rusticated Doric half columns, dating from 1780, by Robert Adam. The bridge is severed from the historic park by the M4 and straddles the borough boundary between Ealing and Hounslow. It is in need of considerable repair and consolidation, and is subject to heritage crime. Vegetation, potential collapse, and redundancy are key threats to address.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	21, Chiswick High Road W4
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Private

1189230

Stucco-fronted early C19 three-storey house which has been empty for some time. It is in a state of considerable disrepair, including vegetation growth affecting the stonework and balcony. No suitable scheme for repair and re-use of the building has yet been presented. The Local Authority and Historic England are considering appropriate action to secure necessary repairs.

Contact: Sean Doran (LPA) 020 8583 4941



© Historic England

SITE NAME:	Brentford Fountain, Western International Market, Hayes Road
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Local authority

Drinking Fountain of 1877 in grey granite, with railings and lamp standards. Originally located in Brentford and a prominent local landmark, it was moved to its current location on the edge of an industrial estate in 1974. The lamp standards are badly damaged or missing and its setting means that it is subject to anti-social behaviour, fly-tipping, and significant littering. There is interest from a local group, Brentford Voice, in securing its future.

Pair of gate piers with contemporaneous railings designed by Robert Adam. The railings are in need of repair.

LIST ENTRY NUMBER: 1096071 Contact: Sean Doran (LPA) 020 8583 4941



© London Borough of Hounslow

ITE NAME:	Gate piers within Osterley Park, Jersey Road
	Listed Ruilding grade II part in

DESIGNATION: RPG grade II\*, CA

CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY:

OWNER TYPE: Charity (heritage)

C (C)

LIST ENTRY NUMBER: 1391000

Contact: Sean Doran (LPA) 020 8583 4941



Historic England

SITE NAME: Kitchen garden wall, including carved door and wrought iron gate, Gunnersbury Park, Gunnersbury Avenue W3 Listed Building grade II, RPG DESIGNATION: grade II\*, CA CONDITION: Poor OCCUPANCY: N/A

PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority, multiple owners

LIST ENTRY NUMBER: 1080336 C18 brick wall and gateway, with impost bands, iron gate and carved wooden door. Reputedly built by Princess Amelia out of the profits from gambling. A large section of the wall is evidently unstable and requires extensive repair, and other sections also require repair and vegetation removal. Funding is being sought to enable repairs to be undertaken to the western section to allow this area to be used.

Contact: Sean Doran LPA 020 8583 4941

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© Historic England

SITE NAME:	Pair of chapels at Isleworth Cemetery, Park Road
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority

1272433

Contact: Sean Doran (LPA) 020 8583 4941

Pair of cemetery chapels with central porte cochère built in 1879. They were last used for a service in 1970 and subsequently used as a council store and suffered considerable dereliction. Hounslow Men's Shed have secured a lease on the chapels and carried out preliminary works to enable their use for workshops, along with the nearby mortuary buildings. Works have also been carried out to conserve and protect the windows and minor repairs are ongoing, but high-level stonework still requires repair and the group are seeking funding to carry this out.

Modernistic factory building built in 1928 by Wallis, Gilbert and Partners. It is one of a number of factories from this period that line the Great West Road. After being empty for several years, the building is now partially occupied, and all unauthorised works have been addressed by the owners. Discussions are ongoing between the Local Authority and the owners to secure the long-term future of



© Historic England

SITE NAME:	Westlink House, Great West Road
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (C)

1255218

LIST ENTRY NUMBER:

Commercial company

Contact: Sean Doran (LPA) 020 8583 4941

the building.



© Historic England

SITE NAME:	The Keep (Armoury) to Hounslow Cavalry Barracks, Beavers Lane, Hounslow
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1240633

Built in 1875, consisting of three storeys with four-storey staircase towers at each end and in the centre of the southwest front. Many windows retain heavy cast iron shutters with firing loops and massive bolts to the interior. The building has been unused for some years and the top storeys are now inaccessible. This is as a result of rainwater penetration from the rooftop parapet and blockages in the flat roof drainage rainwater pipes. There are currently no specific plans for repairs, but discussions are continuing concerning the future of the wider site.

© Historic England

SITE NAME:	Feltham House, Elmwood Avenue, Feltham
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1189466

Built in the mid-C18 in stock brick and modelled on other Palladian villas, extended in the late C18 with the addition of side wings. The interior has been modernised but retains C18 decorations of interest, which may partly be attributable to James Wyatt who lived at Hanworth. The building has been unused for several years, and there is extensive rot damage in the principal storey and rainwater penetration. Some ceilings have collapsed and extensive repairs are urgently required. Discussions are pending to secure its repair and re-use as part of plans for the wider site.

Contact: Sean Doran (LPA) 020 8583 4941

Contact: Sean Doran (LPA) 020 8583 4941



© Historic England

SITE NAME:	Archway near east entrance lodge, Gunnersbury Park, Gunnersbury Avenue W3
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1080332

Stucco pedimented archway, circa 1837, situated near to the East Lodge, on the eastern edge of Gunnersbury Park. Urgent repairs to secure the structural stability of the arch were undertaken in 2012, grant-aided by Historic England. Vegetation clearance was undertaken by volunteers but repairs are still required. The future of this structure is being considered as part of studies evaluating future uses for the Small Mansion.

Contact: Sean Doran (LPA) 020 8583 4941

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS	
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garde
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

77 Y	
	MATERIAL PARTY IN
(表)	A STATE OF THE STA
100 Sec. 1	CONTRACTOR OF THE STATE OF THE

© Historic England

Boundary wall at Gunnersbury Park, Gunnersbury Avenue W3

DESIGNATION:

Listed Building grade II, RPG grade II\*, CA

CONDITION:

Poor

CONDITION: Poor
OCCUPANCY: N/A
PRIORITY CATEGORY: C (C)

OWNER TYPE: Community interest group

LIST ENTRY NUMBER: | 322060

Part of the boundary wall to the garden of the original Gunnersbury House, built 1658-63 by John Webb for Sir John Maynard. Repairs have been carried out to a large section with funding from the National Lottery Heritage Fund. Further extensive sections require repair.

Contact: Sean Doran (LPA) 020 8583 4941



© Historic England

SITE NAME:	East Lodge to Gunnersbury Park, Gunnersbury Avenue W3
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1080334

Entrance lodge circa 1837. All that remains are small sections of the south and west elevations. Urgent repairs to secure the structural stability of the remaining elements of the lodge have been completed, grant-aided by Historic England. Vegetation clearance was undertaken by volunteers but repairs are still required. The future of this structure is being considered as part of studies evaluating future uses for the Small Mansion.

Contact: Sean Doran (LPA) 020 8583 4941



© Historic England

SITE NAME:	East stables in Gunnersbury Park, Gunnersbury Avenue W3
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority

LIST ENTRY NUMBER: 1358316

OWNER TYPE:

LIST ENTRY NUMBER:

Stable block dating from 1835, on the eastern edge of Gunnersbury Park. The building has suffered considerable dereliction. The Local Authority, Historic England, Gunnersbury 2026 Community Investment Company and other key stakeholders secured significant funding, including from Highways England and Historic England. Following extensive investigative works and urgent repairs, works to replace the roof to make it watertight are at an advanced stage. A feasibility study has tested potential future viable and sustainable uses, with further public consultation planned.

Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Some

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	Gothic Boathouse, Gunnersbury Park, Gunnersbury Avenue
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (C)

1189588

Community interest group

repair and emergency works have been undertaken, partly funded by Historic England. Extensive further repairs are required and a new use needs to be secured. Discussions are continuing between stakeholders in order to set out timescales for a future project, and potential new funding sources are being explored. Works to control the vegetation are planned in the meantime.

Contact: Sean Doran (LPA) 020 8583 4941

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	The Small Mansion - Gunnersbury House, Gunnersbury Park, Gunnersbury Avenue W3
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)

Local authority

1080330

Built circa 1802, the smaller of the two houses on the site of Gunnersbury House which was demolished circa 1801. The house has been deteriorating rapidly. The Local Authority, Historic England, Gunnersbury 2026 Community Investment Company and other key stakeholders secured significant funding, including from Highways England and Historic England. This was used to undertake extensive surveys and investigations and is now being used to repair the roof, balustrades and rainwater goods. A feasibility study has tested potential future viable and sustainable uses, with public consultation planned.

Contact: Sean Doran (LPA) 020 8583 4941



© Historic England

SITE NAME:	West Lodge to Gunnersbury Park, Gunnersbury Avenue
DESIGNATION:	Listed Building grade II, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1389619

Lodge building dating from 1875 in the manner of a gatehouse, located at the south entrance to the park, partly in residential use. Historic England awarded a grant towards urgent repairs to the roofs of the unoccupied part of the lodge and the archway. The Local Authority is considering options for its full repair and re-use.

Contact: Sean Doran (LPA) 020 8583 4941



© Historic England

SITE NAME:	West stable block in Gunnersbury Park, Gunnersbury Avenue W3
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

Local authority

1096950

Early C19 stables situated within Gunnersbury Park. Works to stabilise and repair the shell of the building were completed in 2014. The Local Authority, Historic England, Gunnersbury 2026 Community Investment Company and other key stakeholders secured significant funding, including from Highways England and Historic England, which has been used to undertake extensive surveys and investigative works. A feasibility study has been undertaken to test potential future viable and sustainable uses, with further public consultation planned.

Contact: Sean Doran (LPA) 020 8583 4941



© Historic England

SITE NAME:	St Lawrence's Church (former), High Street, Brentford
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1080302

C15 church tower, with nave dating from 1764 by Thomas Hardwick and later Victorian additions. The building, no longer in use as a church, has been empty since the 1960s and stripped of its fittings. Extensive stonework repairs have been carried out, along with works to the roof and rainwater goods. Listed Building Consent and Planning Permission have been secured for conversion to retail and leisure facilities, and further discussions are taking place.

Contact: Verena McCaig 020 7973 3718



SITE NAME:	The Hermitage, 17, Upper Sutton Lane, Heston
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1260544

Late C15 timber-framed house with later additions. It was badly damaged by fire in 2003 and suffered further deterioration following theft of the temporary protective roof. The Local Authority and developer are in discussion regarding long-term plans.

Contact: Sean Doran (LPA) 020 8583 4941

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**



© Historic England

SITE NAME:	Hanworth Park House, Uxbridge Road, Hanworth
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1240343

Contact: Sean Doran (LPA) 020 8583 4941



SITE NAME:	Church of All Saints, Uxbridge Road, Hanworth
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1241073

Constructed in the 1950s, designed by NF Cachemaille-Day. Built in brick with reinforced concrete dressings and roofs covered in asphalt. It has a tall square nave with lower side aisles and a semi-domical sanctuary. Over the nave is a large circular lantern with twenty-four stained glass panels between slender concrete mullions surmounted by a tall cross finial. Some mullions are suffering from cracking and spalling of the concrete. There is concern over the stability of several of the glass panels, some of the glass is cracked and past repairs have been carried out in non-matching glass.

Country house built after 1828 with an extension circa 1860. The building has suffered significant deterioration. Some urgent works have been undertaken to stabilise the building and a series of condition reports have been produced with recommendations for repair. The owners and the Local Authority are working together to develop a scheme to bring the house back into full repair and re-use for residential and community use under an enabling development scheme. Discussions are at an advanced

Contact: Tracey Craig 020 7973 3756

SITE NAME:	Double ditched enclosure beside A30 road 500yds (460m) west of East Bedfont parish church			
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1002043
CONDITION:	Extensive significa	ant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Commercial com	npany	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Romano-British site 1000yds (910m) west of East Bedfont parish church			
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1002042
CONDITION:	Extensive significant problems		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Commercial com	npany, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
	SITE NAME:	Gunnersbury Park W5		c developed in the C18 by Princess Amelia
			and in the C19 b	y Baron Lionel de Rothschild. It became a



© Historic England

SITE NAME:	Gunnersbury Park W5
DESIGNATION:	Registered Park and Garden grade II*, 22 LBs, part in CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1000808

ia public park in 1925. The Local Authorities have been addressing conservation issues affecting the designed landscape through implementation of a phased masterplan: 'Gunnersbury 2026'. An update to this masterplan, funded by Historic England, is informing priorities for the next phases of works. The majority of the park and buildings are now leased to a Community Interest Company (CIC) to oversee the long-term development and management of the park.

Contact: Christopher Laine 020 7973 3473

SITE NAME:	Grand Union Canal and Boston Manor, Brentford		
DESIGNATION:	Conservation Area, 8 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Sean Doran (LPA) 020 8583 4941

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

SITE NAME:	Gunnersbury Park, Brentford W3		
DESIGNATION:	Conservation Area, 21 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Sean Doran (LPA) 020 8583 4941

### ISLINGTON



© Historic England

SITE NAME: Railings and gates to Islington
Tennis Centre and King
George's Field, Market Road N7

DESIGNATION: Listed Building grade II

CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: | 19568|

Cast iron railings and gates with elaborate piers and finials, probably designed by JB Bunning, 1854. Some cast iron finials have failed, and several have been removed and placed into store for safety reasons. A condition survey has been carried out to inform their future conservation and funding now needs to be identified.

Contact: Claire Sutton (LPA) 020 7527 4936



© Historic England

SITE NAME:

Holy Trinity Church,
Cloudesley Square NI

DESIGNATION:

Listed Building grade II\*, CA

CONDITION:

Very bad

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

A (D)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER: | 195557

Grade II\* church, built 1826-9 to the design of Sir Charles Barry. Repairs to the roof and parapets were funded by the National Lottery Heritage Fund and Historic England in 2006-7. The Diocese of London closed the church and set up the multi-functional Cloudesley Centre to provide for a sustainable future. The aisle roofs were repaired in 2020 and the nave plaster and lath ceiling were renewed in 2021, funded by Historic England and the Diocese. Negotiations are in hand with funders for the completion of external fabric repairs and provision of internal facilities.

Contact: Ian Harper 020 7973 3786



© Historic England

Odeon Cinema, Holloway Road N7

DESIGNATION: Listed Building grade II, CA

CONDITION: Fair

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: F (F)

OWNER TYPE: Commercial company

Cinema, built as the Gaumont 1937-8, architect C Howard Crane of Chicago. The cinema has been in poor general condition, with cracking and damage to faience decoration. Inappropriate modern shop fronts in poor condition have undermined the design aesthetic. However, major upgrading works are at an advanced stage.

LIST ENTRY NUMBER: 1384986 Contact: Rachel Godden (LPA) 020 7527 5967



© Historic England

SITE NAME:

Soley Mews Chapel (former), Lloyd Baker Street WC I

DESIGNATION:

Listed Building grade II, CA

CONDITION:

Fair

OCCUPANCY:

Occupied/in use

PRIORITY CATEGORY:

F (F)

OWNER TYPE:

Private

LIST ENTRY NUMBER:

1195670

Former Chapel of the House of Retreat (Lloyd Baker Street and Lloyd Square), 1891-2 by Ernest Newton. The building is of stock brick with tracery windows in stone, slate roof, late Decorated Gothic style. It now appears to be occupied and in fair condition following its conversion to residential use. However, the Local Authority and Historic England need to reassess the condition of the whole building in order to be assured of its current status.

Contact: Lucy Morrow (LPA) 020 7527 3733

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ry is LB vise, LPA NP

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Islington War Memorial Arch, Manor Gardens N7
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

War memorial designed by Percy Adams, formerly part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs have been carried out, including works to the lettering and stonework, but problems remain with drainage and damp. The Local Authority has been working closely with consultants and stakeholders to better understand the issues with the asset and identify appropriate solutions.

Contact: Rachel Godden (LPA) 020 7527 5967



© Historic England

SITE NAME:	Railings, walls, gate piers and gates to Caledonian Park, Market Road N7
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

LIST ENTRY NUMBER: 1208009

Railings, walls and gates to Caledonian Market built in 1854 (market demolished). There are major failures to the cast iron, with severe cracking in places. As part of the Caledonian Clock Tower Project, funded by the National Lottery Heritage Fund and the Local Authority, general repairs are proposed, with two lamps and eight animal heads to be reinstated. Works on this phase have not yet commenced. Significant further funding is required in order to reinstate all the decorative features and effect suitable repairs.

Contact: Claire Sutton (LPA) 020 7527 4936



SITE NAME:	Street ECI
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Health authority
LIST ENTRY NILIMBER:	1297993

Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. Whilst some urgent works have been carried out, including removal of asbestos, further repairs are still required, particularly to the roof, external walls and windows. Assessment reports and proposals for priority repairs have been prepared and discussions are taking place with the Local Authority and Historic England to secure repair.

Town hall, built in 1895 to the design of C Evans Vaughan in an eclectic 'Free Renaissance' style, with a public hall on the first floor with elaborate plasterwork in Belle Epoque manner. The building is now in use as dance studios with the main halls available for public use. The owners have undertaken some repairs, but further external works are

Contact: Verena McCaig 020 7973 3718



© Historic England

© Historic England

SITE NAME:	Finsbury Town Hall, Rosebery Avenue ECI
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1293112

Contact: Verena McCaig 020 7973 3718

urgently necessary.



© Historic England

SITE NAME:	Cells, former House of Detention, Sans Walk ECI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private multiple owners

LIST ENTRY NUMBER: 1297973

LIST ENTRY NUMBER:

Part of Middlesex House of Detention built 1845-47, previously occupied as a museum. Previous water ingress issues have been addressed but it remains vacant.

Contact: Rachel Godden (LPA) 020 7527 5967

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**



© Historic England

SITE NAME:	St Paul's Church, St Paul's Road NI
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (non-heritage)

1208912

St Paul's Church was built in 1826-28 to the design of Sir Charles Barry in an early Gothic Revival style. It was declared redundant in 1980 when the parish united with St Jude in Mildmay Park. After neglect and vandalism, the building was leased to St Paul's Steiner Project in 1995 for use as a school. Although many repairs have been undertaken, more are required, including the repair of the aisle roofs and internal restoration of the nave and ceilings. An up-dated Conservation Management Plan has been commissioned, and funding options are being explored.

Contact: lan Harper 020 7973 3786



© Historic England

SITE NAME:	Railings, Thornhill Square NI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1297982

Cast iron railings, circa 1852, to the perimeter of the central garden square, with foliated spear-head finials set in a moulded plinth on brickwork. Parts of the railings are misaligned, degraded and cracked, with missing elements. Historic England part-funded pilot repairs in 2010, and a specialist measured survey and costed condition survey in 2017. In 2018 a project to repair the enclosed gardens was not able to proceed after funding was withdrawn Interested parties are in early talks with the Local Authority about another possible initiative to secure the necessary

Contact: Claire Sutton (LPA) 020 7527 4936

Contact: Claire Sutton (LPA) 020 7527 4936



© Historic England

SITE NAME:	Railings, Wilmington Square WC1
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1195789

Cast iron railings of 1819-1841, in very poor condition. Urgent works have previously been carried out, but currently no funding has been identified for a full repair programme.

SITE NAME:

LIST ENTRY NUMBER:

Church of St Andrew, Bridgeman Road, Islington NI

Listed Place of Worship grade II, DESIGNATION:

CONDITION: Very bad PRIORITY CATEGORY: A(A)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1195481 St Andrews was designed by Francis Newman and John Johnson as part of a development laid out by Joseph Kay, surveyor, for the Thornhill family. The church was completed in 1854. It is built of Kentish ragstone with Bath stone used for the architectural dressings and the spire. The church was temporarily closed in July 2019 due to falling stone from the spire. There is serious settlement in the northeast vestry and chancel, In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for the preparation of specifications for a full programme of repairs.

Contact: Ian Harper 020 7973 3786



n	

© Historic England

SITE NAME:	Church of St James and attached railings, Clerkenwell Close, Islington ECI
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1207786

The church was built by architect James Carr between 1788 and 1792 for a Methodist congregation; it was reordered in 1882 by Reginald Blomfield for a Church of England congregation. The steeple was rebuilt in 1849, and in 1900 the vaulted crypt was deepened. The nave parapet gutters and the roofs were repaired in 2018, funded by the Listed Places of Worship Roof Repair Fund. There are cracks on the west front and decayed iron windows. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant towards repairs to the tower and nave roof.

Contact: lan Harper 020 7973 3786

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© Historic England

© Historic England

SITE NAME:	Union Chapel, Compton Terrace NI
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Fair
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1208365

Poor

C (C)

1292870

Essex Road NI

A Congregational chapel, schools and offices by James Cubit, built in 1886-87 with the tower finished in 1889. Three phases of repairs to the tower and high-level roofs were funded by the National Lottery Heritage Fund and Historic England in the 2000s. In 2015 the church carried out repairs to the lower level roofs, funded by the Listed Places of Worship Roof Repair Fund. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for various repairs to address water penetration into the buildings.

Contact: Ian Harper 020 7973 3786



SITE NAME: DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Former Mecca Bingo, 161-169, Listed Place of Worship grade II\* Religious organisation

Built as the Carlton Cinema in 1930 by George Coles, previously a bingo hall and now used as a place of worship by Resurrection Manifestations. The Egyptian-style facade is decorated with multi-coloured faience while the rest is yellow stock brick under a slated roof. The church has temporary consent for use of the building and for division of the main auditorium. A first phase of renovation and repair was completed in 2013, but there is evidence of damage to the faience tiles. Proposals for repair and re-use are being explored in discussion with the Local Authority and Historic England.

Contact: lan Harper 020 7973 3786



© Historic England

SITE NAME:	Church of Our Most Holy Redeemer, clergy house, campanile and parish hall, Exmouth Market, Islington ECI
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Religious organisation

The church was designed by JD Sedding in the Lombard style and completed in 1888. It was extended eastwards by Sedding's pupil H Wilson in 1895, and the campanile, vicarage and parish Institute date from 1905. The interior is modelled on Brunelleschi's Santo Spirito in Florence. In 2020 the congregation commenced external repairs to the Institute, funded by the Cloudesley Trust and Historic England. This work was completed in 2021. Sources of further funding will be sought for internal repair and development to enable the Institute to provide a sustainable income for the church.

Contact: Ian Harper 020 7973 3786



© Jim Linwood

SITE NAME:	Church of St Joseph, Highgate Hill, Islington N19
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1279729

1209007

The Passionists (a Roman Catholic religious order) acquired the site in 1858 and built a monastery and chapel. The chapel was rebuilt in 1887-9 by Albert Vicars in a Neo-Romanesque style. Some localised roof repairs were carried out in 2015 with a grant from the Listed Places of Worship Roof Repair Fund. The interior has been repainted. There are still parts of the external fabric in poor condition and a comprehensive repair programme is needed.

Contact: lan Harper 020 7973 3786



© Historic England

SITE NAME:	Hope Church (former Church of St Mary Magdalene) and attached railings, Holloway Road, Islington N7
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1195637

Closed Church of England church re-opened as Hope Church in 2013; built 1812-14 by William Wickings as the Chapel of Ease to St Mary's Islington. The church is built of London stock bricks with Portland stone dressings. The east end tower has settled structurally, and the north and south porches have settled and pulled away from the aisles. The west end and west porch have also settled. The crypt is at risk of flooding due to high underground water levels, currently controlled by permanent pumping. The Diocese of London is arranging for the north and south porches to be supported.

Contact: Ian Harper 020 7973 3786

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS** I PA ΝP RPG

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Church of St Clement with St Barnabas and St Matthew, King Square, Islington ECI
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1366078

Designed by Thomas Hardwick and built in the 1820s, forming one side of a Georgian square now replaced with 1960s housing blocks. The interior was re-ordered by Norman Haines in 1953. Works to re-slate the nave roof along with repairs to the parapets and coping stones, and the overhauling of rainwater goods were completed in 2019 with funding from the National Lottery Heritage Fund. Further repairs and removal of damaging iron cramps are required to the tower and spire.

Contact: Tracey Craig 020 7973 3756

The second secon	

SITE NAME: Church of St Silas, Penton Street, Islington NI Listed Place of Worship grade II, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: C (F) OWNER TYPE: Religious organisation

1208241

Built in 1860, designed by SS Teulon, completed in 1863 by EP Loftus Brock and chancel added in 1884 by W White. The roofs were re-slated in 2010, the south slope with photovoltaic tiles matching the slates in size and colour. Structural repairs to cracks at the west end were completed in 2016, grant-aided by the National Lottery Heritage Fund. Stone repairs were carried out in 2018 to the north aisle. Repairs were completed to the north clerestory stonework and windows in 2020. The equivalent work is required to the south elevation although one window in urgent need was repaired June 2022.

Contact: Tracey Craig 020 7973 3756

© Historic England	
SITE NAME:	

SITE NAME:	Angel NI		
DESIGNATION:	Conservation Area, 27 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Sutton 02075274636
SITE NAME:	Bunhill Fields, Finsbury Square EC2		
DESIGNATION:	Conservation Area, 95 LBs, RPG grade I	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Sutton 02075274636
SITE NAME:	Chapel Market NI		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Claire Sutton 02075274636
SITE NAME:	Clerkenwell ECI		
DESIGNATION:	Conservation Area, 95 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Sutton 02075274636
SITE NAME:	Hat and Feathers ECI		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Claire Sutton 02075274936
SITE NAME:	Holborn Union Infirmary		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Claire Sutton 02075274636

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### I PA ΝP RPG

SITE NAME:	Moorfields ECI		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Sutton 02075274636
SITE NAME:	St John's Grove N19		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Claire Sutton 02075274636
SITE NAME:	St Lukes EC1		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Sutton 02075274636
SITE NAME:	Tollington Park N4		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Claire Sutton 02075274636

### KENSINGTON AND CHELSEA



© Historic England

SITE NAME: Entrance Arch From Courtfield Gardens, Gaspar Mews SW5 DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: B (B) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1190812

Stucco carriage arch, c1870, with foot arches on either side. The central arch has plain piers, a central channelled arch with vermiculated keystone, and pediment. The stucco has deteriorated, and resultant water penetration is damaging the structure. A sapling has disrupted one side arch, causing loss of stucco and brickwork and extensive cracking. No owner can be traced and the Local Authority has undertaken to fund the works. These have yet to commence.

Contact: Sarah Buckingham (LPA) 07970 944 428



SITE NAME: Mausoleum of Joseph Hudson, Harrow Road, Kensal Green Cemetery W10 Listed Building grade II, RPG DESIGNATION: grade I, CA Very bad N/A

Opulent classical mausoleum of Portland stone dating from circa 1850. Invasive vegetation and saplings are severely damaging the roof, and the joints in the stonework are separating, allowing further water ingress. A condition survey and specification are required.

© Historic England

CONDITION: OCCUPANCY: PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1389190 SITE NAME: Tomb of Mary, Lady

Massive sarcophagus of Carrara marble on a grey granite base with a frieze of paterae and fleurs de lys. It is now completely submerged under ivy. Ash saplings further threaten its structural stability.

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

Montgomerie, Kensal Green Cemetery, Harrow Road W10 Listed Building grade II, RPG DESIGNATION: grade I, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1389241

Contact: Sarah Buckingham (LPA) 07970 944 428

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# I PA ΝP

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Tomb of Robert Coombes, Brompton Cemetery, Old Brompton Road SW10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Unknown

1403329

Elongated Portland stone chest tomb on a York stone slab, with niches at the four corners each containing a statue of an oarsman. An upturned boat surmounts the tomb, draped with a Doggett's coat and badge, the prize awarded in the annual Thames rowing race. The monument commemorates a famous rower. All niche statues have lost their heads and are covered with carbon deposits. The architectural detailing is eroding, and the stone is spalling severely in places leading to a loss of fabric. Listed Building Consent has been granted for cleaning and repair, and further details are being discussed.

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

SITE NAME:	Tomb of Thomas Hardwick and Philip Hardwick, Kensal Green Cemetery, Harrow Road W10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Unknown

Pair of sandstone slab tombs, circa 1870, with marble cross commemorating the architectural dynasty of Thomas, Philip and Philip Charles Hardwick. Philip (1792-1870) was designer of the Euston Arch. The slabs have been subject to considerable subsidence causing the marble cross to lean significantly and progressively.

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

SITE NAME:	31, Brompton Square, South Kensington SW3
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1080723

1246086

House dating from 1824-39, part of Brompton Square. A series of Planning Permissions and Listed Building Consents have been granted for internal alterations and rear extensions. Works on site are ongoing.

CITE NIAME

٨٥ ١١:١١ ١٨/٥

Private house built 1914-15. It represents an Edwardian Arts and Crafts led interpretation of a large C17 country house in an urban setting. The building is in poor condition. Listed Building Consent and Planning Permission have been granted for works in association with repair of the building

Contact: Sarah Buckingham (LPA) 07970 944 428

for use as a family home, and currently awaiting approval of conditions.



© Historic England

SITE NAME:	I, Campden Hill W8
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1391138

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic	England
------------	---------

SITE NAME:	Boundary wall to Kensal Green Cemetery, Harrow Road W10
DESIGNATION:	Listed Building grade II, part in RPG grade I, part in CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1191000

section of which collapsed in 2006. Further bays were subsequently reduced in height due to safety concerns. Historic England awarded a grant towards the first phase of rebuilding the collapsed section which involves piling, casting a ground beam and rebuilding the wall as original. Repair works have been completed to ten bays in total, funded by Historic England and the General Ćemetery Company. However, considerable further funding is required to complete essential works to the entire wall.

High brick boundary wall to Harrow Road, a 100-metre

Contact: Sarah Buckingham (LPA) 07970 944 428

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# I PA ΝP RPG

**ABBREVIATIONS** 



© Historic England

SITE NAME:	Mausoleum of Andrew Ducrow, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade II*, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A

PRIORITY CATEGORY: C(C)

OWNER TYPE: Unknown

LIST ENTRY NUMBER: 1358179

LIST ENTRY NUMBER:

OWNER TYPE:

OWNER TYPE:

LIST ENTRY NUMBER:

Mausoleum erected in 1837 for Andrew Ducrow's wife from a design by George Danson, with later embellishments following Ducrow's own interment. The mausoleum is in poor condition with loss of sculptural elements and ironwork, general erosion and vegetation causing damage at roof level. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has been prioritised for conservation and funding is now being sought to carry this out.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	Mausolea of Isabella Gregory and Hall, Harrow Road, Kensal Green Cemetery NW10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

1227650

condition of much of the Gregory mausoleum but spalled stone due to corroding iron cramps is evident. A comprehensive condition survey of the Gregory tomb was produced in 2013, funded by Historic England. The Hall mausoleum has been cleared of vegetation but now requires a full condition survey. The commissioning of this survey and subsequent works are being considered alongside other priorities in the cemetery.

Two mausolea dating to the early 1830s, amongst the very earliest in the cemetery, one to Isabella Gregory and the other to Hall. Overgrown vegetation obscures the

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

SITE NAME:	The Anglican Chapel, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade I, RPG grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)

1835-36 by John Griffith for the General Cemetery Company. Portland stone and stucco central chapel of a Greek Doric tetra style, with (now roofless) pavilions containing marble memorial sculptures. There are large catacombs below. The building is no longer in use and is suffering from water ingress. An options appraisal and updated condition survey have been carried out. Discussions on the future of the building, in conjunction with key stakeholders, are progressing.

Commercial company 1190995 Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	The North Colonnade, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Commercial company

Built by John Griffith in 1833 to display tablets and monuments, with brick vaulted catacombs underneath. It is currently in poor condition, with damaged stone and plasterwork, encroaching vegetation, and subject to antisocial behaviour. The restoration of a sample bay has been completed, part funded by Historic England, but considerable further funding is required to complete the works.

LIST ENTRY NUMBER: 1080629 Contact: Sarah Buckingham (LPA) 07970 944 428

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Tomb of Admiral Henry Colling Deacon, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade II, RPG

grade I, CA

CONDITION: Poor OCCUPANCY: N/A

PRIORITY CATEGORY: C(C)

OWNER TYPE: Unknown

LIST ENTRY NUMBER: 1389226 Mid-C19 sculptural monument in Portland stone with cannon, flag, rope and cannon balls. Cracks and missing elements on the plinth have caused the shifting of the monument on its base and a significant lean. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.

Contact: Sarah Buckingham (LPA) 07970 944 428

Marble memorial with sculpture of an anchor and cross on

a tall pedestal, commemorating the arctic explorer Sir John

Ross (1777-1856). There is a significant lean to the south and risk from invasive plants. A comprehensive condition

survey was produced in 2013, funded by Historic England.



© Historic England

SITE NAME: Tomb of Admiral Sir John Ross, Harrow Road, Kensal Green Cemetery WI0 Listed Building grade II, RPG DESIGNATION: grade I, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown

LIST ENTRY NUMBER: 1389215

Contact: Sarah Buckingham (LPA) 07970 944 428

Works are being prioritised accordingly.



© Historic England

Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery WÍ0 Listed Building grade II, RPG DESIGNATION: grade I, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown

1389188

Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

Tomb of Alfred Cooke, Harrow SITE NAME: Road, Kensal Green Cemetery Listed Building grade II, RPG DESIGNATION: grade I, CA CONDITION: Poor N/A OCCUPANCY: PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown

1389167

A limestone tomb by Thomas Milnes from the mid C19, with a statue of a horse and infant on a pedestal. The sculpture is very badly damaged. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.

Contact: Sarah Buckingham (LPA) 07970 944 428

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Tomb of Colonel Gideon Gorrequer, Harrow Road, Kensal Green Cemetery NW10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Unknown

1389244

Elaborate military monument dating from 1841 to Colonel Gorrequer, ADC (aide-de-camp) to the Governor of St Helena during Napoleon's banishment. There is evidence of erosion at foundation level and architectural elements are threatened by ivy growth. Fixings have been lost from the stone plaque on the front of the pedestal. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

SITE NAME:	Tomb of Daboda Dewanjee, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

1246079

Indian grave marker of red sandstone from the mid C19. The tomb has a significant lean due to severe erosion of the base and the decorative detail is also eroding. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has been prioritised for conservation and funding is now being sought to carry this out.

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

SITE NAME:	Tomb of Duke of Somerset, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

1389242

Portland stone mausoleum dating from the mid C19. There is erosion at foundation level, and spalling stone due to rusting cramps. The entrance has been secured temporarily to minimise any risk from heritage crime. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.

© Historic England

SITE NAME:	Tomb of Frederick Yates, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C(C)

Portland stone sarcophagus with effigy of a sleeping child in Carrara marble from around 1840. There is a slight lean to the north east, erosion of foundations and invasive vegetation growth. The effigy of the child has been removed for safekeeping. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.

Contact: Sarah Buckingham (LPA) 07970 944 428

OWNER TYPE: Unknown LIST ENTRY NUMBER: 1389182

Contact: Sarah Buckingham (LPA) 07970 944 428

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Tomb of James Poole, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (C)

Unknown

1271534

Slate chest tomb from the mid C18. Structural settlement has led to compression and shearing of some slate elements. This structural movement needs to be arrested. The tomb has also suffered from the loss of decorative features. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has been prioritised for conservation and funding is now being sought to carry this out.

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

SITE NAME:	Tomb of John Gibson, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

1080632

Gothic style tomb of architect John Gibson d. 1859, designed by the architect himself. There is severe erosion of the upper registers and widening of joints. Tree works are also required to minimise the risk of damage from overhanging branches. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has been prioritised for conservation and funding is now being sought to carry this out.

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

SITE NAME:	Tomb of John Lucas, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

Tall grey Cornish granite obelisk with Carrara marble bas-relief dating from the end of the C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.

Unknown LIST ENTRY NUMBER: 1389238

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

SITE NAME:	Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10
DESIGNATION:	Listed Building grade II*, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1293490

Monumental tomb from 1856 comprising a carved coffin under an open aedicule with twelve Corinthian columns which are surmounted by four angels, each with an arm held aloft to support a central wreath, now missing. The monument is in poor condition due to the loss of sculptural elements, sinking on the west side, widespread erosion and dirt accretions. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has been prioritised for conservation and funding is now being sought to carry this out.

Contact: Verena McCaig 020 7973 3718

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

	SITE NAME:	Tomb of Samuel Griffith, Harrow Road, Kensal Green Cemetery W10	Portland stone altar tomb on a stepped granite base, from circa 1830. The tomb is in poor condition due to erosion and loss of detailing, corrosion of ironwork and heavy
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	overgrowth which has exacerbated the disruption of stone Railings are missing and bollards have fallen. A comprehensive condition survey was produced in 2013,
	CONDITION:	Poor	funded by Historic England. Works are being prioritised
	OCCUPANCY:	N/A	accordingly.
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389237	Contact: Sarah Buckingham (LPA) 07970 944 428
	SITE NAME:	Tomb of Sir Charles Newton, Harrow Road, Kensal Green Cemetery W10	Tall Greek grave stele style headstone dating from the end of the C19. Now laid flat and very vulnerable to dirt and organic growth. There is some erosion and cracking. A
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
一人原理院	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389225	Contact: Sarah Buckingham (LPA) 07970 944 428
	SITE NAME:	Tomb of the Earl of Galloway, Harrow Road, Kensal Green Cemetery W10	Large neoclassical chest tomb by JB Papworth dating from 1838. There is damage to the kerb stone, widening of joints, invasive plant growth causing extensive disruption
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	and some collapse on the east face. A comprehensive condition survey was produced in 2013, funded by Historic England. Urgent works are required to this monument to
	CONDITION:	Very bad	halt further extensive damage from plant growth.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389178	Contact: Sarah Buckingham (LPA) 07970 944 428
	SITE NAME:	Tomb of WH Kent, Harrow Road, Kensal Green Cemetery NW10	Carrara marble pedestal surmounted by a draped urn with a relief of a dog at its base, dating from 1874. The tomb is in poor condition due to erosion of its carving,
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	deterioration of the inscription, and heavy lean of the monument towards the west. Arboreal ivy has almost obscured the monument entirely and now presents a high
	CONDITION:	Very bad	risk of wind damage. A comprehensive condition survey
	CONDITION:	very bad	was produced in 2013, funded by Historic England. Works



© Historic England

	Road, Kensal Green Cemetery NW10
DESIGNATION:	Listed Building grade II, RPG grade I, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1389246

ith is Historic England. Works are being prioritised accordingly.

Contact: Sarah Buckingham (LPA) 07970 944 428

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



© Historic England

SITE NAME: Tomb of William Price Lewis, Harrow Road, Kensal Green Cemetery W10

Listed Building grade II, RPG DESIGNATION: grade I, CA

CONDITION: Poor

OCCUPANCY: N/A PRIORITY CATEGORY: C(C)

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE: Unknown

LIST ENTRY NUMBER: 1246083

Portland stone obelisk with armorial and Anthemion reliefs from the mid C19. The corrosion of iron cramps is causing spalling of the stone. The ground is eroded around the tomb resulting in damage to the brickwork below. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.

Contact: Sarah Buckingham (LPA) 07970 944 428

Remains of a large C17 mansion of considerable

architectural and historic importance damaged during

and the courtyard used for summer opera events. The

Further inspection is required to review risk factors, to

World War II. The east wing is occupied as a youth hostel

Local Authority has carried out major works on both wings to repair defective rainwater goods and balustrading.



© Historic England

SITE NAME: Holland House, Kensington High Street W8 Listed Building grade I, RPG DESIGNATION: grade II, CA CONDITION: Fair OCCUPANCY: Occupied/in use PRIORITY CATEGORY: F (F) OWNER TYPE: Local authority

1267135

include the walls to the northern side.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME: Enclosing walls to Moravian Burial Ground, King's Road SW10 Listed Building grade II, part in DESIGNATION: CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (D) OWNER TYPE: Religious organisation

The historic brick walls enclosing the Moravian Burial Ground once enclosed a garden in Sir Thomas More's estate, and are mostly of Tudor origin, with later additions. Historic repairs have used damaging cementitious mortars for pointing. Other problems relate to structural instability and brick decay. A pilot repair project, grant-aided by Historic England, was carried out on three sections of the walls and finished in April 2017. This will be used to inform the strategy for the repair of the remaining walls. The owners are exploring possible sources of funding.

Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

SITE NAME:	All Saints Church, Clydesdale Road, Kensington W I I
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1080701

1224734

Designed by William White and completed in 1861, although the spire was never realised. The sanctuary has paintings by Henry Holiday. The slates are suffering from nail sickness and the gutters have many patch repairs. Rainwater leaks are ongoing. There is cracking through the stonework at the west end of the north aisle and in the south transept. Repairs are necessary to the tower stonework and to the uneven floor internally. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant to undertake a temporary repair to the crack in the south transept.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Church of St John the Baptist, Holland Road, Kensington W14
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Fair
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1080593

Early English style church dating from 1874-1911 by J Brooks and JS Atkins architects. The church has slate pitched roofs, coursed rubble walling with Bath stone dressings and a large rose window at the west end. Extensive repairs to the roofs, high level masonry and rainwater goods were completed in early 2015, grant aided by the National Lottery Heritage Fund and Historic England. Works to repair the west end roofs and masonry, grant aided by the National Lottery Heritage Fund, were completed in 2017. Further roof repairs are required.

Contact: Tracey Craig 020 7973 3756

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

I PA ΝP RPG



© Historic England

SITE NAME:	Church of St Michael and All
	Angels, Ladbroke Grove,
	Kensington W10

Listed Place of Worship grade II, DESIGNATION:

CONDITION: Poor

PRIORITY CATEGORY:

C (C) OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1226579

Designed by J and JS Edmeston, built in 1871. Rhineland Romanesque style in London stock brick with terracotta, red Mansfield and Forest of Dean stone dressings, and clay roof tiles. The roofs and rainwater disposal system are in poor condition with water damage evident internally. Some stone and brickwork is also in need of repair.

Contact: Tracey Craig 020 7973 3756



© Historic England

Church of St Augustine, Queen's Gate, Kensington SW7
Listed Place of Worship grade II*, CA
Poor
C (C)
Religious organisation

1226161

Completed in 1876, designed by William Butterfield in Gothic style. Constructed in Gault brick with stone and red brick banding, areas of patterned diaper work to parapets and gables, and decorative carved stone panels. There is rich polychromatic decoration internally. Re-slating of the north slope of the nave and the north aisle was completed in 2011 with funding from Historic England and the National Lottery Heritage Fund. The south side is in need of similar work, along with brick and stone repairs, particularly to the west elevation where mortar re-facings of brickwork are failing.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Kensal Green (All Souls) Cemetery W10
DESIGNATION:	Registered Park and Garden grade I, 159 LBs, 2 CAs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1000817

London's first metropolitan cemetery, designed by John William Griffith in 1833. The cemetery contains a large number of listed monuments and key buildings also at risk. The Management Plan from 2004 needs revision, but changes to forward planning and operations are beginning to have an impact on tree and vegetation management and other conservation issues. Discussions are taking place between key stakeholders to identify funding opportunities for further investment in key structures and infrastructure.

Contact: Christopher Laine 020 7973 3473

SITE NAME:	Kensal Green Cemetery W10		
DESIGNATION:	Conservation Area, 154 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Sarah Buckingham (LPA) 07970 944 428

### KINGSTON UPON THAMES



© Historic England

SITE NAME:	Garden and boundary walls to Cimero, Thatchers and Wansbeck, Traps Lane
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Mixed, multiple owners

LIST ENTRY NUMBER: 1299858

C17 dark red brick walls about seven feet high with tapered flange and offsets, which run along the frontage of houses along Traps Lane and enclosing the garden of 'Cimero'. The structure of the wall has been compromised by failing pointing and vegetative growth. Part of the wall collapsed in spring 2020 and works are being undertaken on this stretch following the granting of Listed Building Consent. An application for Listed Building Consent to prop a separate section of the wall is being considered.

Contact: Rebecca Eng (LPA) 020 8547 5000

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

LIST ENTRY NUMBER:

CITE NIANAE

OWNER TYPE:



© Historic England

SITE NAME:	Mortuary Chapels, Bonner Hill Road
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1358433

Symmetrical Gothic-style twin chapels either side of a carriageway through the cemetery. The slate roofs are steeply pitched with a central stone spire and open octagonal lantern. The west chapel is still used for memorial purposes. There is general spalling to stonework, and vegetation growing at high level. The east chapel is closed owing to structural movement, and propping is in place. The Local Authority has carried out condition and structural surveys. An application for Listed Building Consent to carry out structural repairs was consented in 2021.

Contact: Rebecca Eng (LPA) 020 8547 5000



© Historic England

SITE NAME:	Kingston Telephone Exchange, Ashdown Road, Kingston upon Thames
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company

1080059

Purpose built telephone exchange, built in 1907 and opened in 1908. Arts and Crafts style with an asymmetrical plan. The building has been vacant for many years. Planning Permission has been granted for a wider redevelopment, including the repair and re-use of this building, and works are at an advanced stage, with shell repairs completed ready for fit out by a new end user.

Contact: Rebecca Eng (LPA) 020 8547 5000



© Historic England

SITE NAME:	Former Head Post Office, 42, Eden Street, Kingston upon Thames
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company

Post office built in 1875. Three storeys in red brick with stone dressings. The building has been vacant for many years. Planning Permission has been granted for a wider redevelopment, including the repair and re-use of this building, and works are progressing well on site. Part of the building is now being used as a marketing suite for the overall development and will later become restaurants and community space.

Contact: Rebecca Eng (LPA) 020 8547 5000



© Historic England

SITE NAME:	including tower and attached tunnels, Portsmouth Road, Surbiton
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (D)

Educational (state sector)

1080100

underground tunnels, built 1851-1852 to the design of James Simpson in a Romanesque style for the Lambeth Waterworks. Sited on what is now a student campus, it has been unused for many years. Works are underway to convert the building for use in relation to the surrounding university.

Uncovered coal store with tower and attached

LIST ENTRY NUMBER: 1031864

Contact: Rebecca Eng (LPA) 020 8547 5000



© Historic England

SITE NAME:	Church of St Matthew, St Matthew's Avenue, Surbiton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1184929

Designed by CL Luck in Gothic style and built in 1875. It has a square tower crowned with a tall octagonal stone spire. The spire and tower suffered from erosion of stone and pointing, and rusting of embedded ironwork had resulted in cracking of stone. The mullions to the belfry openings had to be strapped temporarily due to loss of stone. Repairs to the tower, spire and belfry openings were completed in 2019, grant aided by the National Lottery Heritage Fund. Priority maintenance works to some roofs and stonework was carried out in 2021 but permanent repairs to the roof are still required.

Contact: Tracey Craig 020 7973 3756

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Lindon repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Coombe Wood		
DESIGNATION:	Conservation Area, 8 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rebecca Eng (LPA) 020 8547 5000
SITE NAME:	Fairfield / Knights Park, Kingston Town		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rebecca Eng (LPA) 020 8547 5000
SITE NAME:	Grove Crescent, Kingston Town		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rebecca Eng (LPA) 020 8547 5000

### **LAMBETH**



© London Borough of Lambeth

SITE NAME:	Former Board School, Cormont Road SE5 9RF SE5
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Local authority

1184669

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

A large symmetrical building of 7 sections built in 1912 by TJ Bailey with complex roofs including spirelets, dressings of red brick, stone and terracotta, varied windows and wall enrichment. It became the Kennington Boys' School and later the Charles Edward Brooke Girls' School before becoming vacant following the relocation of the school. The Local Authority commissioned a condition survey in March 2016. Planned works to make the building wind and weathertight have yet to be carried out. No future user has been identified.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Mausoleum of George Dodd, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Unknown

1325944

Mausoleum, circa 1865, by Thomas Allom. Built of white marble in an Italian Gothic style, with a rectangular plan of three bays defined by pinnacle buttresses. The mausoleum is in a poor state of repair and is overgrown with vegetation. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Streatham Hill Theatre, 110, Streatham Hill SW2 SW2
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1244564

Constructed by WGR Spague and WH Barton in 1928. Steel framed construction clad in brick with the frontage clad in Doulton Carrara terracotta. An unusually lavish example, with a significant amount of survival, despite a direct hit during World War II after which the interior was repaired to the original design. It remained in use as a theatre until 1962 and then as a bingo hall until 2017, but now much of the building is no longer in use. There is flooding in the basement subways causing deterioration of the fabric and other areas show signs of water ingress.

Contact: Nicola Xuereb (LPA) 0207 926 1217

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**



© Historic England

SITE NAME:	Tomb of Peter Pandia Rodocanachi and Family, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A

F(D)

1396403

Pink granite table tomb dating from circa 1899 within the Greek Burial Ground. Invasive vegetation is causing damage to the stepped base and the pillars surrounding the central pedestal. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Gates, piers and railings at Western Block of Number 39 (Beaufoy School Technical Block), Black Prince Road, Vauxhall SEII
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor

Local authority

OCCUPANCY: N/A
PRIORITY CATEGORY: C (C)

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

OWNER TYPE: Private

LIST ENTRY NUMBER: | 183436

LIST ENTRY NUMBER:

SITE NAME:

Wrought iron railings in a scalloped pattern on a granite plinth and three pairs of wrought iron gates, circa 1907. Currently in poor condition, suffering from deterioration and pigeon damage. Discussions are underway regarding the necessary repair works and funding sources.



© Historic England

SITE NAME:	Dorchester Court, Herne Hill SE24
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1390780

Eight blocks with 96 flats around a central landscaped courtyard, dating from 1933-4 by Leslie H Kemp and Frederick E Tasker. There are structural problems with the balconies and general external deterioration. A Listed Building Consent application for the extension and refurbishment of the blocks is pending determination.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

	Church of St Mary, Lambeth Road SEI
DESIGNATION:	Listed Building grade II, part in RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1358299

Walls, railings and gates to

Mid-C19 ragstone walls and ironwork in a partial state of collapse. Planning Permission and Listed Building Consent have been granted for their repair and restoration. Work is now complete on the Garden Museum, grant-aided by the National Lottery Heritage Fund, and discussions are ongoing to identify a scheme and funding for the repair of the walls, railings and gates.

Contact: Douglas Black (LPA) 020 7926 4065

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME: Augustus Ralli Mortuary Chapel, Norwood Road, West Norwood Memorial Park SE27 Listed Building grade II\*, RPG DESIGNATION: grade II\*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY:

F (D)

Unknown

1064989

Doric temple mortuary chapel circa 1872, attributed to J Oldrid Scott, within the Greek Burial Ground and known as St Stephen's Chapel. The chapel is in poor condition due to subsidence, collapsed steps and internal water damage. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Catacombs circa 1837; cemetery laid out circa 1837 by Sir

William Tite. A temporary roof has been erected over the

entrance to allow the structure to dry out before agreeing repairs. Moisture surveys are ongoing; levels appear to be

stabilising/reducing. Discussions are ongoing regarding

Contact: Elizabeth Whitbourn 07889 808145

potential funding sources and long-term use.



© Historic England

SITE NAME: Catacombs beneath the Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building grade II, RPG DESIGNATION: grade II\*, CA CONDITION: Very bad OCCUPANCY: N/A

Local authority

C (C)

1263192

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Tomb of Captain John Wimble, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F(D)

Chest tomb dating from 1851 with finely carved reliefs showing ships at sea. The stone ship surmounting the tomb is subject to movement. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

OWNER TYPE: Unknown LIST ENTRY NUMBER: 1065020

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Tomb of Christopher Gabriel, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1064988

Chest tomb in Portland stone dating from 1873 with carvings by Kelsey. There is cracking to the stone panels on the side of the tomb. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Tomb of Elizabeth King, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)

Unknown

1250589

Statue of an angel mounted against a rough headstone over rough base, dating from 1922. In the style of the 1878 Oneto Monument by Giulio Monteverge in Genoa. The statue and headstone are leaning significantly. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Unknown

1250687

Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on a pedestal with grave slab dating from 1904. Tiles are missing and cementitious repairs are causing further damage. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Tomb of James Kershaw, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Unknown

1263197

Chest tomb dating from 1864 in Gothic style with elaborate carving. Designed by Alfred Waterhouse commemorating the MP James Kershaw. The structural ironwork is corroding, causing splitting of the stone. The railings are also being affected by movement to the plinth. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Tomb of Johann and Annie Sparenborg and family, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1250680

Tomb in the style of a small Greek temple, dating from 1904. Movement is evident to the columns and base. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Tomb of John and Virginia Schilizzi, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)

Unknown

1064995

Monument dating from 1908 within the Greek Burial Ground. It comprises a stepped granite base with sarcophagus surmounted by a white marble female figure with flowing robes and veiled head. The figure is subject to movement and is now close to the edge of the sarcophagus. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Tomb of John Stevens, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Unknown

Obelisk monument dating from 1861 by Anderson and McKenzie of Aberdeen with incised fret pattern. The tomb is leaning significantly. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Tomb of Mrs Alice Moffatt, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Unknown

1357922

1064983

An arcaded chest tomb, circa 1847. The columns and top slab have been lost, leaving the structural rods exposed. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Tomb of Thomas De La Garde Grissell, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Unknown

1065021

Chest tomb, circa 1847. Cast iron, stucco and pink granite. The plinth is broken and parts are exposed. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park

RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE:

SITE NAME:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Tomb of William Grane, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (D)

Unknown

1357900

Tomb dating from 1856, noted in the list description as having a pink granite cross with foliated arms and vine trails to stem. This cross is missing and there is clear evidence of movement to the base of the monument. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME:	Tomb of XE Balli Family, Norwood Road, West Norwood Memorial Park SE27
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Unknown

1120820

Ionic temple mausoleum dating from the late C19 within the Greek Burial Ground. There is evidence of movement to the entablature and collapse of the steps. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider project is currently progressing and memorial repair works are now anticipated to take place in 2022.

Contact: Douglas Black (LPA) 020 7926 4065



© London Borough of Lambeth

SITE NAME:	Monument to George Abell, St Leonard's churchyard, Streatham High Road, Streatham SW16
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)

Unknown

1323730

Chest tomb of circa 1826 commemorating George and Elizabeth Abell. The slab of Portland limestone with a curved edged top has broken and the plinth is in a bad condition. A condition survey has been prepared, with support from Historic England, and funding is now being sought to secure the necessary repair works.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

	Leonards churchyard, Streatham High Road, Streatham SW16
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Unknown

1323732

Monument to Joseph Hay, St

Coade stone chest tomb in railed enclosure, dated 1808 by Coade and Sealy. The railings are broken and in a poor state of repair. A condition survey has been prepared, with support from Historic England, and funding is now being sought to secure the necessary repair works.

Contact: Douglas Black (LPA) 020 7926 4065

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**



© Historic England

SITE NAME: Monument to Lt. Col. William Boyce, St Leonards churchyard, Streatham High Road,

Streatham SW16

DESIGNATION: Listed Building grade II, CA

CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A(A)

OWNER TYPE: Private, multiple owners

LIST ENTRY NUMBER: 1323731

Chest tomb in railed enclosure, circa 1808 by Coade and Sealy. The Coade stone is in an advanced state of decay. A condition survey has been prepared, with funding from Historic England, and discussions are now underway to secure the necessary repair works.

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME: Wall on the south side of St John with All Saints' churchyard, . Waterloo Road SEI

DESIGNATION: Listed Building grade II, CA

A(A)

CONDITION: Poor OCCUPANCY: N/A

PRIORITY CATEGORY:

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1068687

Early C19 stock brick walls, spalled with cracked brickwork. Some of the finials are broken or missing. A structural survey has been carried out and the Local Authority is investigating potential funding sources for

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

The Clapham Orangery, SITE NAME: Worsopp Drive SW4 DESIGNATION: Listed Building grade II CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1068843

Orangery built in 1793 to the design of William Burgh, in a Palladian style. It stood in the grounds of Thornton House, demolished in the 1940s. Now standing in the middle of a housing estate. Discussions regarding maintenance of the roof and rainwater goods have commenced.

Designed by J Parkin, built 1841, chancel added 1862 by

from mid C14. The church was burnt out in 1975; repaired and re-ordered by Douglas Feast. The aisle and nave roofs

Benjamin Ferrey. The lower tower and spiral stair date

have been re-slated and the flat roofs either side of the

tower re-covered along with stucco repairs to the north

Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

SITE NAME: Church of St Leonard, Streatham High Road, Streatham SW16 DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: C (C)

1100267

LIST ENTRY NUMBER:

Listed Place of Worship grade II, OWNER TYPE: Religious organisation

side in 2015 and the south side in 2018, both with funding from the National Lottery Heritage Fund. Works to underpin and repair the north porch were completed in 2019. Historic England awarded a Covid-19 response grant to repair the stained-glass windows.

Contact: Tracey Craig 020 7973 3756

SITE NAME:	Leigham Court Estate, Streatham SW2		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Douglas Black (LPA) 020 7926 4065
SITE NAME:	Vassall Road, Brixton SW9		
SITE NAME: DESIGNATION:	Vassall Road, Brixton SW9 Conservation Area, 43 LBs	NEW ENTRY?:	No
	,	NEW ENTRY?: TREND:	No Deteriorating
DESIGNATION:	Conservation Area, 43 LBs		

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	West Norwood SE27		
DESIGNATION:	Conservation Area, 75 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Douglas Black (LPA) 020 7926 4065

### **LEWISHAM**



© London Borough of Lewisham

SITE NAME:	Olympia Convoy's Wharf, Prince Street SE8
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1213012

SITE NAME:

Cast and wrought iron slip covers of 1845-47 by Messrs George Baker and Sons in the former Deptford Royal Dockyard. The arched iron construction of two main spans and perimeter cantilevered aisles is clad in corrugated iron to the roof and sides. The iron frame is heavily corroded in certain areas and previous ad hoc repairs are temporarily providing support. Used previously for storage through to the late C20, it is now empty. Outline planning permission was granted in 2015 for the redevelopment of the wider Convoys Wharf site and a proposal for re-use of this building is expected in 2022.

Contact: Joanna Ecclestone (LPA) 020 8314 9912



© Historic England

SITE NAME:	Holland and Company's Distillery, 14 and 16, Deptford Bridge SE8
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1080000

Former offices of the Holland and Company's Distillery, dating from the late C18. On the ground floor at the east end is a double door and a carriage entrance, framed in late C19 stonework with dentil cornice and an inscription in the small pediment over: "Established 1779. Holland and Co's Distillery and Bonded Store". The building has been empty for a number of years and is deteriorating. The Local Authority has written to the owner to discuss the building's condition.

Contact: Joanna Ecclestone (LPA) 020 8314 9912



© Historic England

SITE TO WIE.	Road, Beckenham Place Park
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1359317

Reckenham Place Foxgrove

Mansion built c1773 and situated within former park land. Historic England grant aided some emergency repairs in 2012. The National Lottery Heritage Fund completed a project in 2019 for the wider park, which restored the setting of the mansion and the listed stableyard. The mansion currently accommodates several meanwhile uses whilst the Local Authority investigates funding options for its full repair, and its long-term use. In 2020 Historic England awarded the Local Authority a Covid-19 Emergency grant for high priority roof repairs, which were completed in March 2021.

Contact: Elizabeth Whitbourn 07889 808145



© Historic England

SITE NAME:	Old Swimming Baths, Ladywell Road SE13
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1391811

Public baths, consisting of first and second class swimming pools, constructed in 1884. Designed in the Gothic style by Wilson and Son and Thomas Aldwinkle. The building is unused and the second class pool hall was badly damaged by fire in 2005. In 2011 urgent works to the roof and to address dry rot stabilised the building although in isolated areas some water ingress persists. The Local Authority successfully secured a restoration partner in 2017 and proposals for the full repair of the building and its long-term use have been prepared.

Contact: Joanna Ecclestone (LPA) 020 8314 9912

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



© Historic England

SITE NAME: Tomb of Captain Limeburner, Lee Terrace, St Margaret's Old Churchyard SE13 DESIGNATION: Listed Building grade II, CA

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY CATEGORY: A(A)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1392002

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER

A stone chest tomb from the middle of the C18 commemorates Captain Limeburner of the Royal Navy and his wife. The south side has lost its central panel and the angle balusters are displaced. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.

Contact: Joanna Ecclestone (LPA) 020 8314 9912

An elaborate Rococo tomb of 1769 in Portland stone and marble. Despite previous repairs, the monument is in very

bad condition with widespread cracking, open joints from vegetation growth, and some collapse. A condition survey

has been prepared, with funding from Historic England, and funding for repair and restoration works has been secured



© Historic England

SITE NAME: Tomb of Fludyer, Lee Terrace, St Margaret's Old Churchyard DESIGNATION: Listed Building grade II\*, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Religious organisation

1391993

Contact: Elizabeth Whitbourn 07889 808145

Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving

of garlanded cherub's head, dating from 1752. The

monument has lost its railings, back plates and inscription

panels, and vegetation growth is causing further damage. condition survey has been prepared, with funding from

Historic England, and funding for repair and restoration

works has been secured through a Section 106 agreement.

through a Section 106 agreement.



© Historic England

SITE NAME: Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Óld Churchyard SE13 DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A (A)

OWNER TYPE: Religious organisation

1391998

Contact: Joanna Ecclestone (LPA) 020 8314 9912



© Historic England

SITE NAME: Tomb of John Crutchley, Lee Terrace, St Margaret's Old Churchyard SEI3 DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

1392012

with funding from Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.

caused some sinking and movement to the ledger, which is

now set at an angle. A condition survey has been prepared,

Raised ledger stone of 1727. Ground subsidence has

Contact: Joanna Ecclestone (LPA) 020 8314 9912



© Historic England

SITE NAME: Tomb of John Hosier, Lee Terrace, St Margaret's Old Churchyard SEI3 DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A(A)

OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1392013

Stone chest tomb erected in 1767. The tomb is badly damaged by vegetation growth through open joints. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.

Contact: Joanna Ecclestone (LPA) 020 8314 9912

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

© Historic England

SITE NAME:	Tomb of Lord Dacre, Lee Terrace, St Margaret's Old Churchyard SE13
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)

1392008

Religious organisation

This composite urn monument to Lord Dacre dates from 1794. All the elements now lie disassembled on the ground. The monument needs urgent attention to avoid further damage or loss of its components. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.

Contact: Joanna Ecclestone (LPA) 020 8314 9912

© Historic England

SITE NAME:	Tomb of Rev. Thomas Negus, Lee Terrace, St Margaret's Old Churchyard SEI3
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1392011

Chest tomb of 1765, badly damaged from vegetation which has infiltrated through open joints and cracked the ledger slab. One angle baluster has been lost and there is a risk of further collapse. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.

Contact: Joanna Ecclestone (LPA) 020 8314 9912



© Historic England

SITE NAME:	Tomb of Thomas Butler, Lee Terrace, St Margaret's Old Churchyard SE13
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1392003

Chest tomb of 1733. The panels on both sides and on one end have collapsed exposing brickwork and making the monument vulnerable to rapid deterioration. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.


© Historic England

SITE NAME:	Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE13
designation:	Listed Building grade II, CA
CONDITION:	Poor

N/A OCCUPANCY: C (C)

A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus. The end panel of the upper part is broken. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.

Contact: Joanna Ecclestone (LPA) 020 8314 9912



Contact: Joanna Ecclestone (LPA) 020 8314 9912



D Historic England	
--------------------	--

SITE NAME:	Tomb of William Chivers, Lee Terrace, St Margaret's Old Churchyard SE13
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1392001

Coade stone chest tomb from the late C18. The loss of the ledger slab has allowed a tree to take root inside the structure and to grow from its top. The tomb is in need of attention to avoid serious structural damage. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.

Contact: Joanna Ecclestone (LPA) 020 8314 9912

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© Historic England

SITE NAME:	Rileys (former Temperance Billiard Hall), 233-241, Lewisham High Street SE13
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation

1392397

A temperance billiard hall built 1909-10, originally incorporating a café, lounge and shops facing Lewisham High Street. Listed as a well-surviving example of an uncommon building type. The building had been empty for a number of years and was showing signs of neglect. Planning Permission and Listed Building Consent were granted in 2017 for conversion to a church, with associated changes to restore and change parts of the building. All structural refurbishment and reconstruction and part of the internal works were completed in 2021, with the final remaining works due to start in 2023.

Public house and stable block designed by Ernest Newton, 1881-1882, with later additions. The pub is a prominent landmark in the centre of Grove Park. It was occupied at ground and basement only and in use as a pub but was closed and broken into during lockdown. The stable block is unoccupied and derelict. The building is now secure but not yet weathertight. Listed Building Consent was granted in 2021 for works to protect and preserve the building and the Council is now (June 2022) looking at enforcement

Contact: Joanna Ecclestone (LPA) 020 8314 9912



© Baring Hall Trust

Baring Hall Hotel and Stable Block, Baring Road, SE12 SE12
Listed Building grade II
Poor
Vacant/not in use
A (A)
Commercial company

1456451

options. The owner is marketing the building. Contact: Joanna Ecclestone (LPA) 020 8314 9912



© Historic England

SITE NAME:	Church of St Swithun, Hither Green Lane, Lewisham SE13
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1192516

This church was completed in 1893 to the designs of Ernest Newton, with an extension in 1905. A small mission church of 1884 survives at the east end. Built of red Wrotham brick, Bath stone is used for windows and dressings, and Portland stone for copings, all under slated roofs. A programme of repairs to windows and masonry at the west end was completed in 2015, grant aided by the National Lottery Heritage Fund and Historic England. Further repairs are required.

Contact: lan Harper 020 7973 3786



0	Historic	England

SITE NAME:	Church of St Mary the Virgin, Lewisham High Street, Lewisham SEI3
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

LIST ENTRY NUMBER: 1193297

This unusual Georgian church, raised over a crypt, was completed in 1774 by George Gibson Jr; it replaced a medieval church and incorporated the original tower. The nave was re-modelled and the chancel added in 1882 by William Blomfield. The chancel was re-ordered in 1995-96. A nave re-roofing and drainage project was completed in 2016 with a grant from the National Lottery Heritage Fund. The congregation is actively exploring options for funding for a second phase of roofing repairs to the tower and chancel.

Contact: Ian Harper 020 7973 3786

SITE NAME:	Deptford High Street SE8		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Joanna Ecclestone (LPA) 020 8314 9912

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# **ABBREVIATIONS**

LIST ENTRY NUMBER:

SITE NAME:

### LONDON LEGACY (MDC)



© Historic England

Abbey Mills Pumping Station (Station C) with associated Valve House, Abbey Lane E15

DESIGNATION: Listed Building grade II, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Utility

1392550

Pumping station 1910-14, white stock brick with terracotta and moulded stone dressings. The internal pumping floor is sunk deep below ground level. Works are planned to ensure that the building remains wind and watertight. There are no long-term proposals for the re-use of the building at this stage, although options are being discussed.

Contact: Planning Officer (LPA) 020 3288 8820



© Historic England

SITE NAME:	Bases of pair of chimneystacks at Abbey Mills Pumping Station, Abbey Lane E15
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Utility

1357995

Elaborate pedimented porches to battered brick plinths crowned by stone bases of octagonal stacks (demolished). The brick and stonework have been severely damaged by invasive plant growth, although this is now being monitored and removed regularly. The stonework porches have suffered partial collapse. A survey has been carried out and Thames Water are considering options for repair.

Two chimney bases built in 1865 by Sir Joseph Bazalgette.

Contact: Planning Officer (LPA) 020 3288 8820



© Historic England

© Historic England

SITE NAME:	Ancillary Pump House at Abbey Mills Pumping Station (Station B), Abbey Road E15
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Utility
LIST ENTRY NUMBER:	1357994

Pump house circa 1868, probably by Bazalgette and Cooper, built in a similar style to the main pumping station. There is some evidence of water ingress and the design of the exterior downpipes makes them vulnerable to plant growth and blockages. The building is vacant and has no identified use.

Contact: Planning Officer (LPA) 020 3288 8820



ı		Mill), Three Mill Lane E3
l	DESIGNATION:	Listed Building grade I, CA
1	CONDITION:	Poor
	OCCUPANCY:	Part occupied/part in use
	PRIORITY CATEGORY:	C (C)
	OWNER TYPE:	Charity (heritage)
	LICT ENITDY NILIMBED.	1000070

Tide Mill dating from 1776 and last used in 1941. Much of the building fabric has been repaired, but work is needed to the undershot water wheels and surviving machinery, and to find a solution to significantly increased flooding at ground floor level. The House Mill Trust continues to work towards a sustainable strategy for repair of machinery, along with improvements to education and community facilities. Consents have been secured to carry out repair and decorative works to external doors and windows, and funding is being sought for implementation.

LIST ENTRY NUMBER: 1080970 Contact: Verena McCaig 020 7973 3718

Tide Mill (known as the House

SITE NAME:	Sugar House Lane, Stratford E15		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Ben Hull (LPA) 020 3373 9574
SITE NAME:	Three Mills, Stratford/Bow E15		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Ben Hull (LPA) 020 3373 9574

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

### **MERTON**



© Historic England

SITE NAME: Electricity Substation at junction with Sunnyside Passage, Sunnyside SW19 DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: F (D) OWNER TYPE: Utility

Late C19 cast iron cylindrical electricity substation with three rows of moulded cast iron patterned panels, projecting cornice, and foliated finial. The structure had an unsuitable paint finish and there was visible rust. The owners have commissioned full conservation and repair works and these are now being carried out.

LIST ENTRY NUMBER: 1358028 Contact: Jill Tyndale (LPA) 020 8545 3041



© Historic England

SITE NAME: Wall to rear of the block of flats west of easternmost block, 9, 11, 15 and 17, Windsor Avenue DESIGNATION: Listed Building grade II, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)

Fragments of medieval and probably later precinct wall of the former Merton Priory, constructed from flint and rubble stone. The walls have been subjected to extensive damage and loss through unauthorised works and the Local Authority are considering appropriate enforcement action.

Private LIST ENTRY NUMBER: 1194014

OWNER TYPE:

SITE NAME:

LIST ENTRY NUMBER:

Contact: Jill Tyndale (LPA) 020 8545 3041



© Historic England

SITE NAME: Garden wall enclosing four sides of playing field, Church Lane, Merton Park SW19 DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

Garden wall dating from the C16 to C17, with later alterations. There are many areas of eroded brick and inappropriate past repair. Damaging vegetation has been removed and a comprehensive survey with specification for repair has been prepared. The Local Authority has previously carried out rebuilding and repairs to a section around the entrance gateway which had been dismantled for safety reasons, but further works are needed, including control of vegetation.

LIST ENTRY NUMBER: 1286387 Contact: Jill Tyndale (LPA) 020 8545 3041



© Historic England

Tomb of Thomas Stanly, St Peter and St Paul's Churchyard, Church Road, Mitcham DESIGNATION: Listed Building grade II, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown

1080949

Table tomb over large podium erected in the early C18. The podium is severely damaged by vegetation. A condition survey has been carried out, funded by Historic England, but no funding has been identified to enable the necessary works to be carried out.

Contact: Jill Tyndale (LPA) 020 8545 3041

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# **ABBREVIATIONS**



© Historic England

SITE NAME: Portion of wall on the west side of River Pickle between Merton High Street and Merantun Way, High Street, Wimbledon Village Listed Building grade II, part in

DESIGNATION:

CONDITION: Very bad

PRIORITY CATEGORY: A(A)

OCCUPANCY:

OWNER TYPE: Charity (heritage)

N/A

LIST ENTRY NUMBER: 1358009 Formerly part of the precinct wall to Merton Priory, consisting of medieval flint and rubblestone. Sections of the wall are in poor condition and have collapsed due to vegetation growth. The National Trust has developed a plan towards its conservation and long-term maintenance, with improved public access. This has been achieved in conjunction with Historic England, the Local Authority, Merton Local History Society and Merton Priory Trust. In 2020 Historic England awarded a Covid-19 Emérgency Heritage at Risk Response Fund grant for emergency stabilisation work pending full repairs.

Contact: Jill Tyndale (LPA) 020 8545 3041



© Historic England

SITE NAME:	Burn Bullock Public House, 315, London Road
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1193391

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Public house, formerly the Kings Head Hotel, with C16 interior and exterior features and C18 front. No longer operating as a public house, it had been illegally occupied as a House in Multiple Occupation and has suffered associated deterioration. Essential repairs have been carried out to make the building weatherproof, and it has been externally decorated. No applications for development and re-use of the building have been submitted by the owner, although early discussions have taken place and a building archaeology study undertaken.

Contact: Jill Tyndale (LPA) 020 8545 3041

Contact: Jill Tyndale (LPA) 020 8545 3041



© Historic England

SITE NAME:	Ravensbury Mill (North Wing), 245, Morden Road, Morden
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1080857

C18 and C19 snuff mill powered by water. The north wing is subject to a Section 106 agreement. There is slow progress towards resolving outstanding planning obligations, enabling a lease for the occupation of the north wing by Wandle Industrial Museum. Discussions are ongoing to resolve these outstanding issues.



© Historic England

SITE NAME:	Mausoleum of Sir Joseph William Bazalgette, St Mary's Churchyard, St Mary's Road, Wimbledon SW19
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Unknown

1080887

Portland stone mausoleum from the end of the C19. Bazalgette was the designer of the main London trunk sewer system and the builder of the Victoria and Albert Embankments in the 1860s. The ironwork requires repair and the gates are missing. Water ingress is causing gradual collapse of the internal brickwork to the roof. Charity Habitats & Heritage and the church have begun to explore possibilities for developing a project and seeking funding to enable the necessary works to be carried out.

Contact: Jill Tyndale (LPA) 020 8545 3041

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Tomb of Gerard De Visme 10 Feet to north of west tower of Chapel in Churchyard of St Mary, St Mary's Road, Wimbledon SW19
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A

C (C)

Unknown

1080883

Stone tomb of Gerard de Visme, who died in 1797, consisting of a square plan, rusticated pyramid with corner acroteria to the base. An acroterion has fallen due to movement in the stone blocks, and another is dislodged. Slow deterioration continues. A condition survey has been carried out, funded by Historic England. Charity Habitats & Heritage and the church have begun to explore possibilities for developing a project and seeking funding to enable the necessary works to be carried out.

Contact: Jill Tyndale (LPA) 020 8545 3041



© Historic England

SITE NAME:	Tomb of Bankes, St Mary's Churchyard, St Mary's Road, Wimbledon SW19
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Unknown

Table tomb from the mid C18 with inset panels and baluster profiled corners. The tomb is suffering from continued waste dumping activity and the stonework is cracking. It has been previously subject to poor quality repairs. A condition survey has been carried out, funded by Historic England, but no funding has been identified to enable the necessary works to be carried out.

1080888 Contact: Jill Tyndale (LPA) 020 8545 3041



© Historic England

SITE NAME:	Tomb of Elizabeth Johnson, St Mary's Churchyard, St Mary's Road, Wimbledon SW19
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1193775

Table tomb, tapered to the base, erected around 1800. The side panels have collapsed and vegetation has rooted in the monument and on its pedestal. A condition survey has been carried out, funded by Historic England, but no funding has been identified to enable the necessary works to be carried out.

© Historic England

SITE NAME:	Tomb of John Lawson, St Mary's Churchyard, St Mary's Road, Wimbledon SW19
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

Table tomb on a stepped podium, dating from circa 1704. There is evidence of joints widening and the plinth collapsing. A condition survey has been carried out, funded by Historic England, but no funding has been identified to enable the necessary works to be carried out.

LIST ENTRY NUMBER: 1080886

Contact: Jill Tyndale (LPA) 020 8545 3041

Contact: Jill Tyndale (LPA) 020 8545 3041



SITE NAME:	Base of windmill at Mill House, Windmill Road
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

Brick with timber framing comprising the base of a hollowpost windmill. It is located within the car park of the Mill House public house with its timber superstructure exposed to the elements. The owners have undertaken works to preserve the timbers which have now been reinstated. The structure remains at risk without a protective cover. Repairs are now required to the supporting walls.

LIST ENTRY NUMBER: 1194005 Contact: Jill Tyndale (LPA) 020 8545 3041 © Historic England

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**



© Historic England

SITE NAME:	Wall to rear of flats, 27-33 (consecutive), Windsor Avenue, Colliers Wood SW19
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1080856

Fragment of medieval, and probably later, precinct wall of the former Merton Priory. Constructed from flint and rubble stone, it is being damaged by vegetation growing out of the wall structure.

Contact: Jill Tyndale (LPA) 020 8545 3041

SITE NAME:	Merton Priory (site of), Merantun Way, Colliers W	ood SW19	
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001976
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145



© Historic England Archive

SITE NAME:	Wimbledon Park SW19
DESIGNATION:	Registered Park and Garden grade II*, 2 CAs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners

A remnant of the C18 landscape by Lancelot Brown for the 1st Earl Spencer's manor house at Wimbledon, itself developed from a C16 estate. The Local Authority manages Brown's lake and land to the east as a public park with an emphasis on sport, with land to the west in private ownership as golf and sports clubs. Divided ownership results in differential landscape management. A masterplan exists for the public park, but a shared vision for the whole historic landscape is needed. Recent works on site have addressed lake safety. Proposals exist for major new development within the golf course.

LIST ENTRY NUMBER: 1000852 Contact: Christopher Laine 020 7973 3473

SITE NAME: Bathgate Road SW19

DESIGNATION: Conservation Area NEW ENTRY: No

SITE NAME:	Bathgate Road SVV19		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	Drax Avenue		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	The Broadway		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
DESIGNATION: CONDITION:	Conservation Area, 2 LBs Poor	NEW ENTRY?: TREND:	No No significant change
	,		
CONDITION:	Poor High	TREND:	No significant change
CONDITION: VULNERABILITY:	Poor	TREND:	No significant change
CONDITION:  VULNERABILITY:  SITE NAME:	Poor High Upper Morden	TREND: CONTACT:	No significant change Jill Tyndale (LPA) 020 8545 3041
CONDITION:  VULNERABILITY:  SITE NAME:  DESIGNATION:	Poor High  Upper Morden  Conservation Area, 9 LBs, SM	TREND: CONTACT:  NEW ENTRY?:	No significant change Jill Tyndale (LPA) 020 8545 3041 No

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair on in fair to good.

  F. Under repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Wimbledon Chase		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	Wimbledon Hill Road		
SITE NAME:  DESIGNATION:	Wimbledon Hill Road Conservation Area, 9 LBs	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No No significant change
DESIGNATION:	Conservation Area, 9 LBs		

### **NEWHAM**



© Historic England

SITE NAME:	Police Station, with walls and gatepiers to side, High Street South, E6
DESIGNATION:	Listed Building grade II CA

isted Building grade II, CONDITION: Poor

OCCUPANCY: Vacant/not in use PRIORITY CATEGORY:

C(C)OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1253087

LIST ENTRY NUMBER

Red brick police station with Portland stone dressings and bands, and a slate roof. 1904, by John Dixon Butler for the Metropolitan Police. The building has been vacant since 2013. Repairs have been carried out to the roof. Applications for Planning Permission and Listed Building Consent were submitted in spring 2021 for works in relation to re-use of the building for educational purposes but have yet to be determined.

Contact: Ben Hull (LPA) 020 3373 9574



© Historic England

SITE NAME:	West Ham Pumping Station Engine House, Abbey Road E15
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Litility

1357997

Engine house, built in 1897, containing original Lilleshall Company beam engines. The building is currently in use as a training facility. Parts of the building are in poor condition, with high level vegetation growth to roofs and rainwater goods and graffiti damaging industrial heritage features. Discussions are ongoing regarding the future of this site but there are no specific plans as yet identified.

Contact: Ben Hull (LPA) 020 3373 9574



© Historic England

SITE NAME:	Dukes Head public house, 593, Barking Road, East Ham E6
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1392558

Impressive corner public house dating from 1900. The ground and first floor function rooms are being used for weddings and parties. The flats on the upper floors are vacant. Restoration works were undertaken following fire damage. There is some unauthorised signage and repairs are needed to the cornice and string courses. Planning consents were secured in spring 2021 for conversion and extension for residential and community uses. Works have not yet started on site.

Contact: Ben Hull (LPA) 020 3373 9574



© Historic England

SITE NAME:	Coach and Horses public house, 100, High Street, Plaistow E13
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Commercial company

1080959

Three-storey C18 public house, yellow brick with red brick arches and reveals. The interior has been extensively damaged. Planning Permission and Listed Building Consent have been granted for conversion of the building into residential units. Works commenced but have now halted on site.

Contact: Ben Hull (LPA) 020 3373 9574

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

LIST ENTRY NUMBER:



© Historic England

© Historic England

SITE NAME:	Chimney to Beckton Sewage Works, Jenkins Lane, Beckton E6
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Utility

Chimney dating from 1887 to 1889, designed by Joseph Bazalgette, as part of the improvements to the northern outfall of the London drainage network. Listed Building Consent has been granted for works to facilitate the Lee Tunnel and Beckton extension works. The chimney has been dismantled and is in storage, pending re-erection following completion of the tunnelling works. Regular surveys are carried out to review its condition and maintenance works are being undertaken based on these findings.

Contact: Ben Hull (LPA) 020 3373 9574

11	D	

SITE NAME:	Silo D, North Woolwich Road, Canning Town E16
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1245030

1393160

Grain silo, 1920, built of reinforced concrete. Vegetation threatening the building has been mostly cleared but pigeon ingress remains an issue. Detailed Planning Permission has been granted for the first phase of development of the Silvertown site. Silo D is envisioned as a landmark building within the new masterplan and discussions are ongoing as to how the building might be brought back into use.

Contact: Ben Hull (LPA) 020 3373 9574



© Historic England

SHE IVALL.	including turntable and platform lamp standards, Pier Road, North Woolwich E16
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

North Woolwich Station

Former railway station, 1847. Extensive works are needed to the roof, and the rear canopy has been dismantled following partial collapse. Essential remedial works were carried out prior to sale of the building. New owners have submitted applications for Planning Permission and Listed Building Consent for repair and conversion of the building into a place of worship. The application has yet to be determined.

Contact: Ben Hull (LPA) 020 3373 9574



© Historic England

SITE NAME:	Earl of Essex public house, 616, Romford Road, Newham E12
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Commercial company

1376229

Commercial company 1357990

Impressive Edwardian public house by Henry Poston and WE Trent, dating from 1902, on a prominent corner site. The ground floor has been empty and boarded up and the upper floors occupied. Repairs are needed, particularly to external architectural details. Planning Permission and Listed Building Consent have been granted for the refurbishment and extension of the building for use as a public house and restaurant, with residential accommodation on upper floors. Works have commenced on site.

Contact: Ben Hull (LPA) 020 3373 9574



© Historic England

SITE NAME:	Central buffet at Custom House, Royal Albert Dock E16
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1380201

Restaurant, built in 1883 to the design of Vigers and Wagstaffe in a free Classical style. Now owned by the London Development Agency and part of Royals Business Park. Security has been improved and some emergency repairs undertaken. Planning Permission and Listed Building Consent have been granted for restoration and use as a restaurant as part of the wider Royals Business Park development of Albert Dock. The implementation phase of these plans has yet to commence.

Contact: Ben Hull (LPA) 020 3373 9574

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# **ABBREVIATIONS**

PRIORITY CATEGORY

SITE NAME:



© Historic England

© Historic England

SITE NAME:	Central offices at Custom House, Royal Albert Dock E16
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Commercial company

Commercial company 1376228

Offices, built in 1883 to the design of Vigers and Wagstaffe in the manner of Norman Shaw. Now owned by the London Development Agency and part of Royals Business Park. Security has been improved and some emergency repairs undertaken. Planning Permission and Listed Building Consent have been granted for restoration and use as a club and art gallery as part of the wider Royals Business Park development of Albert Dock. The implementation phase has yet to commence.

Contact: Ben Hull (LPA) 020 3373 9574



Spotted Dog public house, 212, Upton Lane E7 DESIGNATION: Listed Building grade II CONDITION: Very bad OCCUPANCY: Vacant/not in use

D (D) OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1191297

Weatherboarded C15 timber-framed public house. The property has remained vacant for some years. Urgent repairs have been carried out to stabilise the building. Planning Permission and Listed Building Consent have been secured for the repair and re-use of the building as pub, restaurant and hotel.

Contact: Ben Hull (LPA) 020 3373 9574



© Historic England

SITE NAME:	West Ham Court House, West Ham Lane E15
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1080974

The first Court House of 1884, to the design of Lewis Angell, was extended symmetrically in  $190\overline{5}$  to provide a second courtroom. Having been vacated it suffered from theft, vandalism and decay over many years, as well as from fire damage in 2014, resulting in the loss of much of the historic interior. In 2019 the Local Authority undertook to remove asbestos and decayed fabric, to stabilise the surviving walls and to protect the site. This work was completed in early 2020 with partial grant funding from Historic England. The Local Authority is committed to exploring its long-term future.

Contact: Ben Hull (LPA) 020 3373 9574



© Historic England

	walls of Alice Billings House, Stratford E15
DESIGNATION:	Listed Building grade II, part in CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1443788

Northern block and courtyard

A block of firemen's accommodation built for the West Ham Fire Brigade c 1905-06; a rare example of the incorporation of a practice hose/drying tower separate from the fire station building. It has been vacant and deteriorating since the 1980s. Funding was awarded through Newham Council's Active Spaces programme in 2021 to Creative Land Trust to convert the building into studios to be let at affordable rents to creatives, with teaching areas and a community cafe. Discussions are now taking place to progress this scheme.

Contact: Ben Hull (LPA) 020 3373 9574

### **REDBRIDGE**



© London Borough of Redbridge

SITE NAME:	831, High Road, Ilford
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENITRY NILIMBER:	1271968

Shop with circa 1900 interior, featuring striking glazed decorative wall tiling and Minton floor tiling. The tiles have been severely damaged by nailed studwork and plasterboard to the wall, and cement screeding of the floor. The building requires major tile repairs and replacements to restore the interior, and unauthorised works need to be addressed. Pre-application discussions have taken place with Historic England and the Local Authority with a view to reinstatement of the tiles and refurbishment of the building. A suitable scheme is awaited.

Contact: Suzanne Lansley (LPA) 020 8708 6690

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© Historic England

SITE NAME:	The Grotto, Wanstead Park
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1183624

Ruined grotto boathouse of circa 1762. It consists of a honeycomb rockwork facade of segmental plan with several arches at lake level, and window openings above. The area is fenced off from public access. The grotto has been managed as a ruin but its stability is threatened by mortar failure, loss of rockwork, and self-sown vegetation. The owner, the City of London, has carried out repairs and clearance, and commissioned a Conservation Management Plan to identify the most appropriate approach to securing the structure's long-term future. Further discussions are required to take this forward.

Contact: Suzanne Lansley (LPA) 020 8708 6690



© Historic England

SITE NAME:	Garden Temple in garden of Temple House, 14, The Avenue, Wanstead E11
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1357974

Garden temple, circa 1730-40, with Ionic pedimented portico. The structure once formed part of the Wanstead Grove Estate. Extensive repairs to the roof and one of the columns have been carried out, grant-aided by Historic England. Further repairs are needed to the remaining columns, which are showing signs of significant decay, as well as the decorative finishes. Structural and condition surveys were prepared in 2016 to inform these repairs, with funding from Historic England. The Local Authority and Historic England are jointly considering options to secure full repair of the structure.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	Church of St Mary, Overton Drive, Wanstead EII
DESIGNATION:	Listed Place of Worship grade I, RPG grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081008

This church of 1790 was designed by architect Thomas Hardwick in the neoclassical style. The chancel is designed around the monument to Sir Josiah Child. The west end supports a Doric portico, hipped slate roof and a timber clock tower with open belfry and cupola. The interior has been redecorated and retains all original furnishings. The Portland stone masonry is spalling due to rusting cramps. Two elevations, including the clock turret, were repaired in 2018, funded by the National Lottery Heritage Fund. Funding is being sought for the repair of the two remaining elevations.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Wanstead EII
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081017

Gothic style church built as a chapel of ease to St Mary the Virgin and still sharing the parish. It was built between 1861 between 1867, to the designs of George Gilbert Scott; construction is of ragstone with ashlar dressings under slated roofs. The valley gutters were renewed in 2013. A specialist survey in the same year identified masonry at belfry level in a dangerous condition. Some emergency repairs have been done but the condition is worsening and there is a risk of falls of stone. The tower is in need of a comprehensive repair programme. The parish is investigating sources of funding.

Contact: Ian Harper 020 7973 3786



© Historic England Archive

SITE NAME:	Wanstead Park E12
DESIGNATION:	Registered Park and Garden grade II*, 7 LBs, 2 CAs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1000194

Remains of an important landscape dating from the late C17 to the early C19 and associated with George London and Humphry Repton, further developed in the late C19 by the City of London as a public park. The central area was converted to a private golf course in the early C20. Features of the historic designed landscape survive but are in poor condition. A Parkland Plan has been prepared to inform decision making and forward planning. Possible sources of funding for implementation are being explored.

Contact: Christopher Laine 020 7973 3473

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Mayfield, Ilford		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Suzanne Lansley (LPA) 020 8708 6690
SITE NAME:	Wanstead Park EII		
DESIGNATION:	Conservation Area, 8 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Suzanne Lansley (LPA) 020 8708 6690
SITE NAME:	Woodford Bridge, Bridge		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Suzanne Lansley (LPA) 020 8708 6690

### RICHMOND UPON THAMES



© Historic England

SITE NAME:	Boathouse and deep-water dock, riverside landing stage, steps, balustrade and gates, Thames Eyot, Cross Deep, Twickenham	
DESIGNATION:	Listed Building grade II, CA	
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private, multiple owners	
LIST ENTRY NUMBER:	1400159	

Built in the 1870s as part of Frederick Chancellor's remodelling of the house and grounds of Poulett Lodge for William Punchard. The boathouse and dock are disused and falling into disrepair, with encroaching vegetation threatening the masonry. The balustrade is structurally compromised and shows evidence of cracking and leaning. This also affects the landing stage and gates. Discussions towards a solution are at an early stage with the owners.

Contact: Nicolette Duckham (LPA) 020 8891 7335



© Historic England

SITE NAME:	Building number 14, Platts Eyot, Hampton
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1254430

Late C19 office building in stock brick with an ogee-shaped cupola, formerly with a wooden balcony. It possibly once housed electric works and a boathouse to the ground floor. Long-term solutions for this building are being discussed as part of the expected overall strategy for Platts Eyot island. Some limited damage was caused by fire in 2021. The Local Authority are seeking to secure the reinstatement of the first-floor balcony which was unlawfully removed.

Contact: Lauren Way (LPA) 020 8891 7928



© Historic England

SITE NAME:	Loggia in the grounds of Thames Eyot, Cross Deep, Twickenham
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1401819

Stone loggia of nine Doric columns, probably C18, situated in the grounds of Thames Eyot, a block of 1930s flats on the bank of the Thames. The roof has suffered partial collapse and structural movement has caused distortion to the colonnade. An options appraisal was completed in 2011 but not taken forward. The loggia has now been propped with scaffolding under a time-limited Listed Building Consent and this should prevent major loss of fabric whilst the freeholders develop a permanent scheme. A Listed Building Consent application for further structural investigation is being considered.

Contact: Nicolette Duckham (LPA) 020 8891 7335

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© Historic England

SITE NAME:	Norfolk House, 8, Montpelier Row
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1065390

C18 plain brown brick house with red window arches and many remaining original internal features. Vacant for some years, a major water leak has caused considerable damage to the rear sections of the house, leading to problems with rot and damp. Initial works have been carried out to the rear section of the roof through enforcement action by the Local Authority. The Local Authority are continuing to make efforts to secure the future of the property.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	Grotto or shell house in grounds of Thames Eyot, Cross Deep, Twickenham
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

OWNER TYPE: Private, multiple owners

LIST ENTRY NUMBER: 1080812

Later C18 or early C19 grotto or shell house, altered in the mid C19, now in the grounds of Thames Eyot, a block of 1930s flats on the bank of the Thames. The grotto is decorated in a precise geometric pattern to resemble a coffered vault which is separated by a deep horizontal band from the more randomly decorated vertical walls. Considerable amounts of the shellwork have been lost or damaged and it is in need of conservation to prevent further deterioration. Historic England has provided advice to the owner and Local Authority.

Contact: Verena McCaig 020 7973 3718



© Historic England

SITE NAME:	Pope's Grotto in grounds of Radnor House School, Cross Deep (east side), Twickenham
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F(D)

OWNER TYPE: Educational (independent)

LIST ENTRY NUMBER: 1192178

Grotto with rusticated arched entrance facing the river, with a long passage and two 'chapels'. The grotto is seen as the 'locus classicus' of English C18 garden history. The structural condition is sound, but much of the decorative lining is loose or missing. Conservation of the statuary, grant-aided by Historic England, was carried out in 2016. A pilot project on the South Chamber was completed in 2017. The National Lottery Heritage Fund has awarded a grant to the Pope's Grotto Preservation Trust to complete the conservation project; work has started on site (summer 2022).

Contact: Elizabeth Whitbourn 07889 808145



© Historic England

SITE NAME:	Church of England Cemetery Chapel, Grove Road, Richmond Cemetery
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: | 126|36|

Cemetery chapel built in 1875 by Sir Arthur Blomfield. Formerly leased out by the locally-based charity Habitats and Heritage, it had operated as a nursery until major structural problems meant it had to be vacated. The building is suffering from ground movement and subsidence, causing major cracks above windows and the separation of the gable wall from the roof. It has been propped and is being monitored by structural engineers. Funding is being sought to carry out further propping and investigative reports whilst a long-term solution is sought.

Contact: Nicolette Duckham (LPA) 020 8891 7335



© Historic England

SITE NAME:	lvy Hall Hotel (known as Hobart Hall Hotel), 43-47 (odd), Petersham Road
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1357738

Early C18 three-storey house in L-shaped plan with a river frontage, with mid to late C18 wing of four storeys with bays and C20 link. Whilst last used as a hotel, the building has been largely unoccupied for over ten years and is in very bad condition. The rainwater goods and parts of the roofs have failed, causing damp and rot and some ceilings to collapse. Vegetation is engulfing parts of the building. The Local Authority is in discussion with the owners to secure its repair and re-use, but no suitable scheme has yet been brought forward. Urgent works to stabilise the building are expected.

Contact: Nicolette Duckham (LPA) 020 8891 7335

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise.

New Entry is noted).



© Historic England

SITE NAME:	Boathouse 5 (easternmost 13 bays), Platts Eyot, Hampton
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1254429

Timber-framed boathouse built in 1917 by Augustine Alban Hamilton Scott for the Thorneycroft firm to build torpedo boats for the Admiralty. A full measured survey of the remaining structure has been completed, but it is in very bad condition with a large area of collapse. Solutions for this structure, including the rebuilding of the Belfast trusses, will be discussed as part of the expected overall strategy for Platts Eyot.

Contact: Lauren Way (LPA) 020 8891 7928

	0.000	3	آينها	1
L V		R I	KO QVI	
				1
				4

© Historic England

SITE NAME:	Boathouse 2, Platts Eyot, Hampton
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1254428

Timber-framed boathouse clad in corrugated zinc with a Belfast truss roof. It was constructed in 1916 by Augustine Alban Hamilton Scott for the Thorneycroft firm to build fast launches carrying torpedoes for the Admiralty. In May 2021, a significant fire took place on the island which has destroyed a large extent of Boathouse 2. The cause of the fire has been established as accidental. Prior to the fire, condition surveys were being carried out. Historic England and the Local Authority are discussing the future of the building with the owner.

Contact: Lauren Way (LPA) 020 8891 7928



© Historic England

SITE NAME:	Boathouse 4, Platts Eyot, Hampton
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1261295

Belfast truss roof. It was constructed in 1916 by Augustine Alban Hamilton Scott for the Thorneycroft firm to build fast launches carrying torpedoes for the Admiralty. In May 2021, a significant fire took place on the island which has destroyed a large extent of Boathouse 4. The cause of the fire has been established as accidental. Prior to the fire, condition surveys were being carried out. Historic England and the Local Authority are discussing the future of the building with the owner.

Timber-framed boathouse clad in corrugated zinc with a

Contact: Lauren Way (LPA) 020 8891 7928



© Historic England

SITE NAME:	Wick House, Richmond Hill, Richmond
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1263475

Designed by Sir William Chambers circa 1772 for Sir Joshua Reynolds. Planning Permission has been granted to convert the building from a nurses' home to a single residence. Agreed stabilisation works have taken place to address significant cracks in the later Victorian wing. Further applications for Planning Permission and Listed Building Consent have been approved but no work has taken place on site.

Contact: Nicolette Duckham (LPA) 020 8891 7335



© Historic England

SITE NAME:	Doughty House, 142, Richmond Hill, Richmond
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1249955

C18 house with C19 alterations, including the addition of an art gallery, made by the Cook family. Planning Permission and Listed Building Consent have been granted to retain the main property as a single dwelling and to convert the gallery (listed separately) to ancillary accommodation, along with re-instating Doughty Cottage as the link between the house and gallery. An application for further work has been approved, including an alternative access arrangement, but work has not yet restarted on site.

Contact: Nicolette Duckham (LPA) 020 8891 7335

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	The Gallery at Doughty House, 142, Richmond Hill, Richmond
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

Gallery built c1880 for Sir Francis Cook, extended 1915 by Brewer Smith, comprising eleven bays in giant Ionic order with balustrade, the lower order containing door and window openings between Doric pilasters. Works are needed to the roof, balustrade and rainwater goods. An application for further work has been approved, including an alternative access arrangement, but work has not yet restarted on site.

Contact: Nicolette Duckham (LPA) 020 8891 7335



© Historic England

SITE NAME:	Air Raid Shelter, St Leonard's Court, St Leonard's Road, East Sheen SW14
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

1395422

Private, multiple owners

1387232

Air raid shelter, probably built in 1938 to serve St Leonard's Court which was built in 1934-38 by local builder Mr FG Fox. It was designed to hold 48 people; at the time there were 83 flats. Locally-based charity Habitats and Heritage commissioned a structural survey leading to minor works. The owners are considering the future of the building.

Contact: Nicolette Duckham (LPA) 020 8891 7335

SITE NAME:	Platt's Eyot, Hampton		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Lauren Way (LPA) 020 8891 7928

#### **SOUTHWARK**



© Historic England

SITE NAME:	Office, Licensed Victuallers Almshouses, 12a, Asylum Road SE15
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1376536

Annexe to the offices of the Licensed Victuallers' Almshouses, 1913-14 by FE Harford, in a restrained Baroque style. There are significant structural cracks to the front and side elevations, and failing stonework at upper levels. The Local Authority has carried out remedial works to the pediment and flat roof. They have also commissioned investigatory works, including structural monitoring, and a suitable approach to securing the future of the building is being considered.

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Number 8, Addington Square and attached railings SE5
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1376521

One of a pair of early C19 houses in the Addington Square Conservation Area. The house has suffered from considerable water ingress owing to faulty rainwater goods, and there are signs of some structural movement, particularly to the porch. Some urgent works to the roof have been carried out. Listed Building Consent and Planning Permission have been granted for restoration and extensive repair works to retain the property as a single dwelling. The building has now been sold.

Contact: Catherine Jeater (LPA) 020 7525 5375

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© Historic England

SITE NAME:	Railings and gates to Caroline Gardens, Asylum Road SE15
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1376543

Iron railings to the Licensed Victuallers' Almshouse complex, dating largely to circa 1830-40. Sections of the ironwork are in a poor state of repair with some elements cracked or missing. Some backstays and a pair of gates have been removed to storage. The Local Authority is proactively seeking funding to carry out full conservation.

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Licensed Victuallers Almshouses: Chapel, Asylum Road SEI5
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

building is leased by the Local Authority to a local artists' group. The building needs significant roof repairs and fabric consolidation. The Local Authority is pro-actively seeking funding to carry out full conservation and repair, working with the leaseholders.

Former almshouse chapel, dating from 1827-31. The

LIST ENTRY NUMBER: 1376538 Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Chest tomb, St Mary Magdalene Churchyard, Bermondsey Street SEI
DESIGNATION:	Listed Building grade II, SM, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C(C)

Chest tomb from 1815 with original railings. Overgrowth has caused damage to the stone and ironwork. Historic England has funded a condition survey and specification for works to the tomb but the identified works have not yet been carried out.

OWNER TYPE: Local authority LIST ENTRY NUMBER: 1376573

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Table tomb, St Mary Magdalene Churchyard, Bermondsey Street SEI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

Unusual C18 table tomb under a stone canopy with tapered, fluted columns. There is some deterioration to the stone elements and railings. Historic England has funded a condition survey and specification for works to the tomb but the identified works have not yet been carried out.



© Historic England

SITE NAME:	Tomb of John Sargeant, St Mary Magdalene Churchyard, Bermondsey Street SE1
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair

1376578

OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

1376580

C18 stone chest tomb. The monument has been damaged by erosion and cementitious repairs in the past. Historic England has funded a condition survey and specification for works to the tomb but the identified works have not yet been carried out.


Contact: Catherine Jeater (LPA) 020 7525 5375

Contact: Catherine Jeater (LPA) 020 7525 5375

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME:	Presbyterian Chapel, 109, Borough Road SEI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)

1378375

Educational (state sector)

Former Presbyterian chapel, 1846. Consent was granted in 2006 for facade retention. South Bank University has since secured Planning Permission and Listed Building Consent for a scheme to convert the building for student and community use. Major works are now underway.

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Monument to Charles Waters, Camberwell Old Cemetery, Forest Hill Road, Forest Hill SE23
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Unknown

1385530

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Monument circa 1910 to Charles Waters. Marble group of a seated woman with book/bible in her lap embracing a small child on a battered plinth. The monument, which was leaning, has been returned to an upright position and made structurally stable. However, the figures have been damaged through cleaning processes and have been assessed for further repair. A scheme for stonework stabilisation has been agreed but has yet to be carried out.

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Monument to Rebekah Horniman, Camberwell Old Cemetery, Forest Hill Road, Forest Hill SE23
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

Monument circa 1895 to Rebekah, wife of FS Horniman. Its prominent bronze tablet depicting a figure of an angel is missing, presumed stolen. There are no current plans for its restoration.



© Historic England

SITE NAME:	38, Glengall Road, Peckham SE15
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Private

1385563

1385533

Semi-detached house dating from 1843-1845 by the Brighton architect Amon Henry Wilds. The Ionic entrance porch is in very bad condition, cracking is evident, and the roof is not watertight to the rear. The Local Authority and Historic England are considering approaches to secure stabilisation and repair of the building.

Contact: Catherine Jeater (LPA) 020 7525 5375

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	55, Great Suffolk Street SEI
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1393123

Unaltered mid-C19 warehouse. The building is in a poor condition having been vacant for a number of years. Applications for Listed Building Consent and Planning Permission have been secured for change of use from warehouse use to a mixed-use scheme comprising offices at ground floor level with flats above, and further applications are now being considered for amendments to this scheme.

Contact: Catherine Jeater (LPA) 020 7525 5375

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE:

10年 10年 10年 10日
A STATE OF THE PARTY OF THE PAR
<b>公司</b>
之为是是一个人人的可能的。 第一个人人的可能的是一个人的。
THE RESERVE AND THE PARTY OF TH
<b>一直</b>
Annie de la company de la comp

© Historic England

East Lodge to Nunhead Cemetery, Linden Grove SE15
Listed Building grade II, RPG grade II*, CA
Very bad
Vacant/not in use

Local authority

D (A)

1385647

One of a pair of gate lodges dating from 1840, by James Bunstone Bunning, adjacent to the main entrance gates. The lodge is in a ruinous condition. Condition and structural surveys have been undertaken, along with a feasibility study, both jointly funded by Historic England and the Local Authority to inform options for the building's future. Enabling works have been carried out to stabilise the structure. Listed Building Consent and Planning Permission have been granted for full restoration for café and community facilities and works are expected to commence in 2023.

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Tomb of Maria Proom, Nunhead Cemetery, Linden Grove SE15
DESIGNATION:	Listed Building grade II, RPG grade II*, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

Visually prominent monument of 1872 in pink and grey granite and Carrara marble. Inspired by Catholic monuments from the continent, the structure presents a praying figure carried on a tall column and plinth, and an angel statue at its base which was perhaps originally unrelated to the monument. The railings around it are missing. There is concern over the structural stability of the monument due to ground subsidence nearby. Further investigations are required.

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	St Peter's Church Hall, 522, Lordship Lane, East Dulwich SE22
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1385671

1385651

Situated adjacent to St Peter's Church, the hall was constructed in 1899. Both buildings are believed to be by Charles Barry Junior. The building is currently vacant and is suffering from structural movement and lack of maintenance. Historic England has provided advice on urgent repairs required; however, these have not been carried out. The Local Authority and Historic England are discussing possible action to secure the repair and conservation of the building.

Contact: Catherine Jeater (LPA) 020 7525 5375



© London Borough of Southwark

SITE NAME:	The Kentish Drovers public house, 720, Old Kent Road, Peckham SE15
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	F (F)

Mid-C19 public house, now partly in use as a restaurant. The Local Authority commissioned a specialist survey of the damaged tiled mural and full conservation works commenced in 2020 using Section 106 funding. Works are ongoing.

Commercial company LIST ENTRY NUMBER: 1385740 Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	112, Peckham Park Road, Peckham SE15
designation:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

One of a group of four pairs of early C19 houses. The house is in a poor state of repair, in particular the exterior, and continues to deteriorate.

LIST ENTRY NUMBER: 1385765 Contact: Catherine Jeater (LPA) 020 7525 5375

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	40, Queens Road, Peckham SE15
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Early-C19 terraced building. The building is in poor condition and has suffered from extensive unauthorised works.

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Former Clare College Mission Church, Southwark Park SE16
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1385919

1385796

Former mission church of circa 1900 and 1911-1912, by John W Simpson and Maxwell Ayrton, built for Clare College, Cambridge in Italianate style. The walls are ferroconcrete with shallow pitched tiled roofs. Following refurbishment, the building is used as gallery space by the Bermondsey Artists' Group. There are further repairs required to external walls and tile detail, and investigations necessary into structural movement. The Local Authority and Historic England are helping to advise the Group.

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Number I and attached railings, I, Stamford Street SEI
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Commercial company

1385933

Mid-C19 red brick building that occupies a prominent position looking towards Blackfriars Bridge. Works to convert the building to offices were completed but the building does not appear to have been occupied and is now deteriorating. An application for Listed Building Consent has been secured for extensive repairs and repointing to the flank wall, which is the last phase in the repair of the building. These works have yet to commence.

Contact: Catherine leater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Peckham Rye Station, Station Way, Peckham SE15
DESIGNATION:	Listed Building grade II, 2 CAs
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Utility
LIST ENTRY NUMBER:	1392389

The station is an H-shaped building, built in 1864-65 by Charles Henry Driver for the London, Brighton and South East Coast Railway. The northern wing has been refurbished and brought back into use. The southern wing is largely vacant and in a poor state of repair. Works to restore the staircase are complete, funded by the Railway Heritage Trust, the Local Authority and Network Rail following local campaigns. Further works are planned in relation to eventual community use of the wing.

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Beltwood House, 41, Sydenham Hill, Camberwell SE26
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1385958

Large mid-Victorian villa, possibly by Banks and Barry, Dulwich College architects. The house was remodelled in the neoclassical style circa 1895. The building was suffering from the effects of water ingress and the curtilage buildings were in a very poor state of repair. Consents were granted for conversion to flats, with development in the surrounding gardens, and works are near completion.

Contact: Catherine Jeater (LPA) 020 7525 5375

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

CA ory is LB wise, LPA NP RPG SM



© Historic England

SITE NAME:	Southwark Municipal Offices and attached railings, Walworth Road SE17
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use

PRIORITY CATEGORY: F (C)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1386028

Built as a vestry hall circa 1863-64, then later used as a town hall and more recently as municipal offices for Southwark Council. The building was severely damaged by fire in 2013. It was then stabilised and remedial works undertaken, including construction of a new roof and provision of temporary roofing elsewhere. New leaseholders have now taken possession of the building and have secured Planning Permission and Listed Building Consent for conversion of the building into community centre, start-up office space and café. Works have now commenced on site.

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

SITE NAME:	Kennedy, 305, Walworth Road, Walworth SE17
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1392595

Former Kennedy sausage shop, circa 1923. A wellpreserved example of a 1920s shop. Considerable works have been undertaken to bring the shop back into use. Whilst it is now operating as a restaurant, further repairs are required to historic detailing. Planning Permission and Listed Building Consent have been granted for repair works and these are likely to be carried out under the Walworth Road Heritage Action Zone scheme.

Contact: Catherine Jeater (LPA) 020 7525 5375



SITE NAME:

SITE NAME:

SITE IV VIE.	Station, Windsor Walk SE5
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Utility
	1204053

Former office to Denmark Hill

Church of St Mary Magdalene,

The former office to Denmark Hill Station dates from 1864-66. The building is in a poor condition following a fire. Planning Permission has been granted to convert the building to a café but this has not yet been implemented.

© Historic England

LIST ENTRY NUMBER: 1386053

Contact: Catherine Jeater (LPA) 020 7525 5375



© Historic England

	Bermondsey Street, Bermondsey SEI
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1376567

lower stages of the C15 tower are incorporated. The structure is weak, not helped by remodelling in 1830 and the I 880s. Stucco finished throughout on brick under slate roof with copper gutters within parapets. The roof structures have been heavily repaired historically but are still under stress. This is likely the cause of falls of plaster from ceilings. Leakage through the copper gutters is hard

The church was rebuilt in the late C17 on the site of a

former medieval church developed from the Chapel of the Convent of Bermondsey, first recorded in the late C13. The

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	The Cross and Star Church, Falmouth Road, Bermondsey SEI
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1385523

Built as a Presbyterian chapel in 1888 with Queen Anne and Romanesque influences. It is now the London base for the Church of the Brotherhood of the Cross and Star. It is constructed of red brick and gauged brickwork with stone dressings under a slated roof. The complete gallery survives internally, and the stained glass is good quality. The external fabric is in urgent need of repair, including reroofing, and repairs to brickwork, rainwater goods and the stained-glass windows. The congregation is actively engaged in discussion with potential funders to develop a repair project.

Contact: Ian Harper 020 7973 3786

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise

New Entry is noted).

	ABBR	eviations
	CA	Conservation Area
s	LB	Listed Building
٩,	LPA	Local Planning Authority
	NP	National Park
	RPG	Registered Park and Garde
	SM	Scheduled Monument
	UA	Unitary Authority
	WHS	

LIST ENTRY NUMBER:



© Historic England

© Historic England

Church of St Augustine, Honor Oak Park, Camberwell, Southwark SE23
Listed Place of Worship grade II
Poor
C (C)
Religious organisation

1385617

The church was completed in 1873 by William Oakley, in Kentish ragstone with ashlar details and slated roofs. Underpinning was carried out in two phases in 1993 and 2010. Also in 2010 repairs were carried out to masonry and high-level roofs. The latest phase of stonework repairs and tower re-roofing was completed in 2014, with funding from the National Lottery Heritage Fund and Historic England. Monitoring of the structure continues and funding is being sought for further repairs which will be required in the future.

Contact: lan Harper 020 7973 3786

	1
The a	e 10

Church of St Peter, Lordship Lane, Camberwell SE22

DESIGNATION: Listed Place of Worship grade II, CA

CONDITION: Very bad

PRIORITY CATEGORY: A (A)

OWNER TYPE: Religious organisation

1385670

Work started on this church, by Charles Barry Jnr, in 1873 on land gifted by Dulwich College for a new parish formed from St Giles Camberwell. The tower and spire were completed in 1875 and the vestry enlarged in 1893. The Church of England closed the church in 1984 and sold it to Worth Abbey, who then sold it to the Deeper Life Bible Church. External masonry is in Kentish ragstone with Bath stone dressings; internally the walls are banded in cream London stocks and red brick. Slated roofs of the nave and timber-framed spire are in bad condition. There is settlement on the north side aisle.

Contact: lan Harper 020 7973 3786

SITE NAME:	Roman boat at New Guy's House, Bermondsey SEI		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001979
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Health authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	The Rose Theatre, Rose Court, Southwark SEI		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012707
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
	SITE NAME: Nunhead Cemetery (All Saints)		blic cemetery designed by J Bunstone



© Historic England Archive

SITE IV VIE.	SEI5
DESIGNATION:	Registered Park and Garden grade II*, 13 LBs, part in CA
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Local authority

1000824

An important public cemetery designed by J Bunstone Bunning and consecrated in 1840. The layout of the cemetery skilfully exploits the undulating topography to create picturesque effects and vistas. Vegetation and self-sown saplings are disrupting historic monuments and obscuring the legibility of the landscape. The Local Authority is developing plans to restore the East Lodge, which is a longstanding building at risk, a programme of memorial safety works is underway, and a comprehensive tree survey is informing an updated Conservation Management Plan for the whole of the designed landscape.

Contact: Christopher Laine 020 7973 3473

SITE NAME:	Nunhead Cemetery, Nunhead SE15		
DESIGNATION:	Conservation Area, 13 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Catherine Jeater (LPA) 020 7525 5375

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### CA ory is LB wise, LPA NP RPG

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument

**ABBREVIATIONS** 

Scheduled Monument
 Unitary Authority
 WHS World Heritage Site

SITE NAME:	Walworth Road, Walworth		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Ellie Cook 0205255403

#### SUTTON



© London Borough of Sutton

Boundary walls to Beddington SITE NAME: Place along east side of churchyard and along Church Lane, Church Road DESIGNATION: Listed Building grade II, CA

CONDITION: Good OCCUPANCY: N/A PRIORITY CATEGORY: F (C)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1357592 Substantial length of C16 or C17 wall of red brick with battered coping and roll moulding. Sections have been buttressed. Sections of the wall and buttresses had suffered structural damage from tree growth and also from extensive graffiti. Sections of the wall have now been repaired and rebuilt to secure its long-term structural performance, with works commissioned by the Local Authority.

Contact: Dean James (LPA) 0208 770 5000



© Historic England

SITE NAME:	Churchyard walls, Church Road
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1065671

Circa C19 walls of dressed flint with rounded tops, with pilasters and brick quoins at intervals. Vegetation and mechanical damage caused some sections to collapse, and mortar failure has led to the loss of flints from others. The church has undertaken full repair of extensive sections of the flint wall and these are now in good condition. However, there remain some localised areas where mortar has deteriorated leading to the loss of flints, and brick sections require vegetation clearance, mortar and brickwork repair.

Contact: Dean James (LPA) 0208 770 5000



© Historic England

SITE NAME:	Garden walls at Beddington Place (Carew Manor Special School) to north of Orangery walls, Church Road
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

1200792

C17 to C18 garden walls. The east, south and part of the north walls to the east of Beddington Park Cottages are of brick with battered coping; the west wall is of a later date with plain capping. Damage has been largely caused by vegetation, upper brick courses have been completely dislodged in some sections, and a section of wall has now collapsed. The brickwork is in need of substantial repairs, including extensive repointing and rebuilding.

Contact: Dean James (LPA) 0208 770 5000



© Historic England

SITE NAME:	Orangery wall to Beddington Place, Church Road, Beddington
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1065673

Orangery wall of circa 1720. It has previously been subject to severe vandalism. The soft brickwork is susceptible to erosion and there is invasive plant and shrub growth. There are currently no plans in place to address these issues.

Contact: Dean James (LPA) 0208 770 5000

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Grotto in Carshalton Park, Ruskin Road, Carshalton
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

Early C18 grotto in Carshalton Park. The exterior of the grotto has symmetrical curved walls of brick, ramped up gradually to a central peak. The grotto is vulnerable to vandalism and graffiti and is currently threatened by significant vegetative growth. Survey work has been carried out to assess the extent of repairs needed but no plans have been brought forward.

Contact: Dean James (LPA) 0208 770 5000



© Historic England

SITE NAME:	Parish Church of St Mary the Virgin, Church Road, Beddington
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Religious organisation

1065628

Religious organisation LIST ENTRY NUMBER 1065670

C14 in origin, the church was much rebuilt with additions in C19 by Joseph Clarke. The dormer windows were added in 1914 by HP Burke Downing. The interior has decorative Victorian wall paintings and there is a monument to Richard Carew (d.1520) which is suffering from cracking and friable stone. The congregation received a grant from the National Lottery Heritage Fund for repairing the tower roof, cracks in the tower along with open joints and past cementitious repairs. These are now complete. Work still required to other church roofs and the masonry and monuments to the Carew Chapel.

Contact: Tracey Craig 020 7973 3756

SITE NAME:	Sutton Town Centre High Street Crossroads, Sutton		
DESIGNATION:	Conservation Area, 11 LBs, SM	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Dean James (LPA) 0208 770 5000

#### **TOWER HAMLETS**



© London Borough of Tower Hamlets

SITE NAME:	34, Mount Terrace, Whitechapel EI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Health authority

1065122

Late C18/early C19 stock brick end of terrace house of three storeys with a basement, mansard roof and round headed door with a fanlight. This was originally part of a development of two rows of 17 houses constructed for the City Corporation. The building is empty and is suffering from neglect with some structural cracking on the front elevation. Some emergency repair works have recently been carried out to the flank wall which was found to be unsafe. Planning Permission and Listed Building Consent were granted in 2021 and repair and refurbishment works are expected to start in late 2022.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© London Borough of Tower Hamlets

SITE NAME:	Drinking fountain, Stepney Green El
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1065062

Red and grey granite drinking fountain with a large red bowl, trefoil headed plaques and a small truncated spire. Erected in 1884 at Rutland Street School (now demolished); and moved to its current location in 1939. The fountain is not functioning and has missing architectural details from the top of the spire. Funding has been secured for the repair of the fountain and the reinstatement of its water supply. This is part of a wider project to restore three drinking fountains in Tower Hamlets. An application for Listed Building Consent is anticipated by the end of 2022.

Contact: Andrew Hargreaves (LPA) 020 7364 5576

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© London Borough of Tower Hamlets

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
SITE NAME:	One Lamp Standard in front of the Star of the East Public House, Commercial Road E14	
DESIGNATION:	Listed Building grade II, CA	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	

1065199

One of the three C19 lamp standards on the pavement in front of the Star of the East Public House. A cast iron decorative lantern bearing the inn name with poor and defective paintwork. Two lamp standards were repaired separately in 2019 and their lanterns are now working. The Local Authority is working with the owner to secure funding to repair and reinstate the remaining lantern.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

SITE NAME:	Ragged School Museum, 46 and 48, Copperfield Road E3
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (non-heritage)
LIST ENTRY NUMBER:	1065752

The Ragged School, now museum, was opened as a free school for poor children in the East End in 1877 by Dr Barnardo, in converted warehouses on the Grand Union Canal. The building remains underutilised due to the poor condition of the roof, originally slated but replaced with asbestos-cement sheeting after a fire in the mid C20. There are also structural issues and damp problems. In 2020 the National Lottery Heritage Fund awarded a grant for a repair project. Planning Permission and Listed Building Consent were granted in 2021. Works are on-going and are due to complete in late summer 2022.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

SITE NAME:	Front wall, gate piers and gates at St Clements Hospital, Bow Road, Bow E3
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Government or agency

Decorative gates and railings forming the front boundary to the redundant St Clements Hospital. The freehold has been transferred to the Greater London Authority. Planning Permission and Listed Building Consent were granted for the conversion of the former hospital to housing, and works are now close to completion. The gates have now been repaired and will be reinstated as part of the final stage of works in mid to late 2022.

LIST ENTRY NUMBER: 1065276

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© London Borough of Tower Hamlets

SITE NAME:	St Clements Hospital, Bow Road, Bow E3
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1251493

Redundant hospital, formerly City of London infirmary. Impressive Italianate main block fronting Bow Road. The freehold has been transferred to the Greater London Authority. Planning Permission and Listed Building Consent were granted for the conversion of the former hospital to housing, and works are now close to completion, which is expected in mid to late 2022.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

SITE NAME:	2 bollards (between statue of Gladstone and St Mary's churchyard entrance), Bow Road, Bromley-By-Bow E3
designation:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency

Two C19 bollards which formed a group along with St Mary's Church, its gates and railings and the statue of WE Gladstone. One of the bollards has been removed. The Local Authority is working towards reinstatement of the missing bollard.

LIST ENTRY NUMBER: 1262757

Contact: Andrew Hargreaves (LPA) 020 7364 5576

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Full ladar repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME:	Gentlemen's public convenience, Bow Road, Bromley-By-Bow E3
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A(A)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1392968

Underground gentlemen's public convenience, constructed by the Board of Works and opened in 1899. There are curved entrance steps designed to fit around the statue of WE Gladstone. The decorative interior finish includes russet marble urinals. The public convenience has been disused for many years and the decorative iron gates have been damaged. The interior is also subject to vandalism. The Local Authority is investigating options for the site.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

SITE NAME:	Former Bromley Hall School, Bromley Hall Road, London E14
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

Local authority

LIST ENTRY NUMBER: 1402561

OWNER TYPE:

Former school for physically disabled children, built in 1967-8 by the Greater London Council's Architects' Department and extended in 1978-9. The building has a distinctive architectural form which reflects the local industrial vernacular. It has been vacant for several years following changes in educational requirements. The Local Authority is considering options for the refurbishment and re-use of the building.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

SITE NAME:	How Memorial Gateway, Bromley High Street E3
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

LIST ENTRY NUMBER: 1065281

Gabled Gothic stone arch with double buttresses at each side, circa 1893. Formerly an entrance to St Mary's Churchyard and once the site of St. Leonard's Priory. The gateway is suffering from stonework decay. Volunteers form Bow Church have been working to tidy up the former churchyard open space, having received a Community Gardens Grant. Repair works to the gateway are anticipated to start in late 2022 with the help of external funding.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



SITE NAME:	Limehouse District Library, Commercial Road, Limehouse E14
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1357807

Former Passmore Edwards Library. Built in 1900 by Messrs Clarkson Architects. The library is closed and the building vacant and boarded up. Planning Permission and Listed Building Consent were granted to convert the building to student accommodation with associated educational and ancillary facilities. Works are very close to completion (summer 2022).

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

SITE NAME:	Former Caird & Rayner Ltd Warehouse, 777-783, Commercial Road E14
DESIGNATION:	Listed Building grade II, 2 CAs
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company

1385372

Former sail makers and ship chandler's warehouse, 1869. A rare survival consisting of a brick skin enclosing a timber structure. The building was fire damaged, resulting in the loss of its roof covering. Urgent works were completed in April 2010. The Local Authority has approved Planning Permission and Listed Building Consent for the conversion of the building to office use as part of the wider development of the site. Works have now commenced on site and completion is expected in late 2023.

Contact: Andrew Hargreaves (LPA) 020 7364 5576

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

LIST ENTRY NUMBER:



© Historic England

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
SITE NAME:	Drinking fountain (on pavement outside 31-74 Mile End Road), Mile End Road, Stepney E1
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency

1065113

Late C19 polished granite drinking fountain, with a short column on a plinth. The drinking fountain has an inscription commemorating its erection by the Metropolitan Cattle Trough and Drinking Fountain Association. The bowl has been removed. Funding has been secured for the repair of the fountain and the reinstatement of its water supply. This is part of a wider project to restore three drinking fountains in Tower Hamlets. An application for Listed Building Consent is anticipated by the end of 2022.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© London Borough of Tower Hamlets

SITE NAME:	St Saviours Church, Northumbria Street, Poplar E14
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation

1242275

Former church dating from 1873-4 to the design of Frederick J and Horace Francis. The building was severely damaged by fire in May 2007 and is currently propped by scaffolding. Following detailed negotiations, Planning Permission and Listed Building Consent were granted for residential conversion and all pre-commencement planning conditions have been discharged. Works to repair the damaged stonework and reinstate the roof have been carried out and the overall scheme is due to complete in autumn 2022.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

SITE NAME:	19, Princelet Street, Spitalfields El
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1260421

Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. The building combines a well-preserved Spitalfields Huguenot merchant's house with weaving garrets, and a rare surviving small synagogue. The Local Authority is working with the owner and other local stakeholders to secure the long-term future and the full repair of the building.

Contact: Elizabeth Whitbourn 07889 808145



© Historic England

SITE NAME:	II3, Redchurch Street, Tower Hamlets E2
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company

1393497

A weavers' tenement house built c1735 by William Farmer, a local builder. An early survival of a building type that once dominated Spitalfields. The building is derelict and has structural problems. It was recently braced to prevent further movement and the building is wind and watertight. Further urgent repairs, involving careful dismantling and reerection of fabric to secure the structural stability of the front elevation, are due to be carried out shortly. Planning Permission and Listed Building Consent for retail use have been granted.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

SITE NAME:	Tomb of Joseph Westwood, Southern Grove, Tower Hamlets Cemetery E3
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1378758

A prominent funerary tomb dating from 1883, in the form of a Decorated style wayside cross. It is in poor condition due to the loss of parts of its low railings, tiles, finials and other detailing. The Local Authority commissioned a monument safety survey in 2019. The Friends of Tower Hamlets Cemetery Park, who manage the site for the Local Authority, are working on a Conservation Management Plan, with funding from the National Lottery Heritage Fund. This will identify the conservation requirements for the cemetery park and the monuments, and is due to be completed by summer 2022.

Contact: Andrew Hargreaves (LPA) 020 7364 5576

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

   Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise,

New Entry is noted).



© Historic England

SITE NAME: St Pauls Mission Room and Infant Nursery, Wellclose Square EI
Square E1

DESIGNATION: Listed Building grade II, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1242432

Gothic style structure built in 1874 to designs by Reuben Greatorex. The building is of stock brick with a red brick eaves cornice and red and blue brick bands. It has stone dressings to the doors and windows, a steeply pitched tiled roof with cresting, and a stone banded chimney. The building is empty and boarded up. The owner is considering options for re-use or conversion of the building.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

SITE NAME:	Braithwaite Viaduct, Bishopsgate Goods Yard, Wheler Street / Brick Lane El
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Utility
LIST ENTRY NUMBER:	1063895

Early railway viaduct built in 1840 by John Braithwaite for the Eastern Counties Railway, formerly set within an extensive brick-vaulted goods yard circa 1880, partially demolished in 2003. Planning Permission and Listed Building Consent was granted in 2021 for a mixed-use development which will include repair and reuse of the viaduct and adjacent historic arches.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI
Listed Building grade II, CA
Poor
N/A
C (C)

Local authority

1357512

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Drinking fountain with pink marble basin and plaque set in a Norman style arch. Erected in 1860 but moved to its present position in 1879. Funding has been secured for the repair of the fountain and the reinstatement of its water supply. This is part of a wider project to restore three drinking fountains in Tower Hamlets. An application for Listed Building Consent is anticipated by the end of 2022.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

SITE NAME:	Royal London Hospital - front block, Whitechapel Road, Whitechapel EI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority

1065788

Fine C18 yellow brick hospital building fronting Whitechapel Road. The building, which became redundant following development of new facilities to the rear, has been purchased by Tower Hamlets Council. Plans to convert the building into a Civic Centre are progressing, as part of the new masterplan for Whitechapel. Planning Permission and Listed Building Consent have been granted and works are now nearing completion, which is expected in late 2022.

Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England Archive

SITE NAME:	2, Wilkes Street, EI EI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1242278

Early C18 terraced house. Three storeys, double fronted, with basement and attic in yellow stock brick with red dressings to segmental-arched windows. Wooden doorcase and weavers' windows. Planning Permission and Listed Building Consent were granted in 2021 for repairs to windows, shutters and doors and this work is currently in progress. Further applications are anticipated in 2022 or 2023 for internal repair works.

Contact: Andrew Hargreaves (LPA) 020 7364 5576

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

SI



© Historic England

© Historic England

SITE NAME: Church of St Mary Stratford Bow, Bow Road, Poplar E3	j
DESIGNATION: Listed Place of Worship grad II*, CA	de
CONDITION: Poor	
PRIORITY CATEGORY: D (D)	
OWNER TYPE: Religious organisation	

1065273

St Mary's Bow is shrouded by trees on a traffic island on the All. The tower and chancel were added circa 1490 to an early C14 nave. The south aisle was rebuilt in 1794; the upper tower in 1829 and then restored in the 1950s following war damage. There was a general restoration in C19. Two phases of repairs are now complete to roofs, clock turret, and external masonry, funded by the National Lottery Heritage Fund. The church now urgently needs a drainage system, tree management and suitable access from the highway. Discussions with authorities are ongoing.

Contact: Ian Harper 020 7973 3786



SITE NAME:	St Paul's Church, Burdett Road, Stepney E3
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1241881

Designed by architect Robert Maguire, the church was consecrated on the 30th April 1960. The church is based on a rectangular plan centred on the altar, with projections to the northwest and southeast for the porch and the baptistry, and an adjacent vicarage. Following renewal of the lantern ceiling panels in 2015 and 2016, funded by the National Lottery Heritage Fund, the church was taken off the register. Now the porch roof and the aisle roofs are leaking, and the concrete structures are at risk.

Contact: Ian Harper 020 7973 3786



© Historic England

ITE NAME:	Church of St John on Bethnal Green, Cambridge Heath Road, Bethnal Green E2
designation:	Listed Place of Worship grade I, CA

CONDITION: Poor PRIORITY CATEGORY: C(C)OWNER TYPE:

Religious organisation LIST ENTRY NUMBER: 1065245

The parish church of 1824 was designed by Sir John Soane and heavily restored and extended in the C19 by William Munday and GF Bodley. The church is built of London stock brick with artificial stone dressings and bell tower. Repairs to high-level stonework, complete in 2014, were grant aided by Historic England and the National Lottery Heritage Fund. Funding is being sought for a final phase of repairs to the nave roof, the interior of the narthex and the church steps.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	St Anne's Limehouse Parish Church, Commercial Road, Stepney E14
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

Religious organisation 1357808

St Anne's Church was designed by Nicholas Hawksmoor in the English Baroque style. It was completed in 1730 and consecrated in 1733. The church is faced with Portland stone over brickwork, and the western tower was used as a 'sea-mark' for naval purposes. The interior was restored by Philip Hardwick following a serious fire in 1851. Further work to the roof structure was carried out between 1983 and 1993. The classical interior is much damaged by historic water leakage from parapet gutters. The church has ambitious plans to develop the crypt, provide level access and continue with repairs.

Contact: lan Harper 020 7973 3786



© Historic England

SITE NAME:	Calvary Charismatic Baptist Church (former Trinity Methodist Church), including attached hall and church rooms, East India Dock Road, Poplar E14
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1376625

The church, hall and offices, arranged collegiately, were built in the 1950s as part of the live architectural phase of the 1951 Festival of Britain, which was the first stage of the post-war rebuilding of the heavily damaged Lansbury Estate. The church architects were Cecil Handisyde and D Rogers Stark and the consulting engineer Felix Samuely. Historic significance is being re-assessed. The roof, domed roof lights and exposed concrete frame were repaired in 2017 with a grant from Historic England. CCBC is in discussion about a further phase of repairs to complete the church and the tower.

Contact: Ian Harper 020 7973 3786

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

OWNER TYPE:

LIST ENTRY NUMBER:



0	Historic	England
---	----------	---------

SITE NAME:	New Testament Church of God (former Holy Trinity), Morgan Street, Bethnal Green E3
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	C(C)

Religious organisation

Church constructed of London stock brick with stone dressings, designed by G Austin and built between 1836 and 1839. Repairs to the roofs and stonework were completed in 2007 with a grant from Historic England and the National Lottery Heritage Fund. Internal repairs are needed to the nave ceiling, windows and walls. External stonework repairs are needed to the west end. The congregation worships from a modern adjacent building and is actively exploring options for funding the necessary repairs to the former church to enable its use as a multipurpose community facility.

Contact: lan Harper 020 7973 3786

3		
	1/8	

© Historic England

SITE NAME:	Church of the English Martyrs, Prescott Street, Stepney EI
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1241734

1065118

A town church by EW Pugin with rich internal decoration, completed after his death in 1875 by his brothers. It replaced an earlier mission set up in 1864. The high altar was re-ordered in 1930 as a shrine to the English Martyrs. Bomb damage in 1940 destroyed the pulpit. The nave roof has been re-slated and the dampness problem on the north east side has been resolved, pending monitoring. The remaining issues are stone decay to the belfry and repairs to the rainwater disposal system. The church is investigating sources of funding for repairs.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Sandys Row Synagogue, Sandys Row, Spitalfields EI
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1260323

Former Huguenot chapel which was altered in the mid C19 into a synagogue. Major re-roofing and high-level brick repairs were completed in 2011 with funding from the National Lottery Heritage Fund and Historic England. At the same time emergency works were carried out to temporarily restrain the bowing narrow brick piers to the front elevation windows until funding for permanent repairs can be found. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for the repair of the west end flat roofs.

Contact: Tracey Craig 020 7973 3756

SITE NAME:	Priory and Hospital of St Mary Spital, Steward Street EI		
DESIGNATION:	Scheduled Monument, 11 LBs, part in CA	LIST ENTRY NUMBER:	1001982
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Public utilities	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	London Hospital, Stepney El		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	St Anne's Church E14		
DESIGNATION:	Conservation Area, 31 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS** I PA

SITE NAME:	Tower Hamlets Cemetery, Bow E3		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Wentworth Street, Bethnal Green EI		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Whitechapel High Street, Aldgate EI		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576

#### **WALTHAM FOREST**



© Historic England

SITE NAME:	Chestnuts House, 398, Hoe Street E17
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1191062

LIST ENTRY NUMBER:

Substantial detached house of circa 1745-7 in stock red brick with red dressings. Elaborate stucco interiors survive along with original panelling and cornices. The house fell out of use several years ago and has since been occupied by live-in guardians. Emergency repairs to the roofs and rainwater goods have addressed the worst of deterioration and water ingress, but extensive vegetation to the rear continues to threaten further damage. The Local Authority continues to develop plans for the repair and re-use of the building, and is in discussion with Historic England.

Contact: Verena McCaig 020 7973 3718

© Historic England

SITE NAME:	Essex County Cricket Pavilion, Leyton High Road E10
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

Cricket pavilion, rendered and colour washed timber frame over a brick basement in the Vernacular Revival style, built in 1886 by Richard Creed for the Essex County Cricket Club. Part of the building is occupied by the Local Authority as offices, alongside low-key community use. Urgent works were carried out in 2021 to make the building water-tight and repair damaged elements. The Council is now progressing opportunities to fund full restoration and secure a new long-term occupier.

LIST ENTRY NUMBER: Contact: Mike Fox (LPA) 020 8496 3000 1386803



© London Borough of Waltham Forest

SITE NAME:	Metal Railing to Chingford Mill Pumping Station, Lower Hall Lane E4
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1065575

Metal railing with concrete plinth, 1890-95. Shallow curving plan in twelve sections; alternate uprights supported by curved brackets. The condition of the railings is poor and numerous sections have been removed and replaced with temporary metal fencing. They were repainted in 2015 but require further repair and replacement.

Contact: Mike Fox (LPA) 020 8496 3000

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Wall to south east of St Mary's Churchyard, Church End E17
DESIGNATION:	Listed Building grade II, part in CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

C18 walls, formerly belonging to a house, now demolished, on the adjacent site. A dense covering of ivy is damaging the brickwork, which is in need of repair. A section has collapsed. Efforts are being made to clarify ownership in order that necessary works can be discussed and eventually secured.

Contact: Mike Fox (LPA) 020 8496 3000

Mid-C16 timber-framed property formerly used as a Conservative Club, but now a community centre. Works connected with a previously approved Listed Building Consent have been completed satisfactorily. Following discussions with the Local Authority and Historic England, additional repairs are expected to be carried out, including restoration of the timber porch, for which Planning Permission and Listed Building consent have been granted.

- Lang
111

© Historic England

SITE NAME:	Walnut Tree House, 500, High Road E10
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Other not for profit group

1065586

1357602

Contact: Verena McCaig 020 7973 3718

Contact: Mike Fox (LPA) 020 8496 3000

Works have yet to commence.



© London Borough of Waltham Forest

698a, High Road Leytonstone, Leytonstone E11
Listed Building grade II
Very bad
Part occupied/part in use
D (D)
Private

One of a surviving terrace of three Georgian houses, probably late C18, for many years the home of the local British Legion branch. Planning Permission and Listed Building Consent have been secured for conversion into flats. The Local Authority is in discussion with the owner to ensure that the consented scheme is carried out.

SITE

	SI
	DI
-	C
	0
	PF
4	0

© Historic England

SITE NAME:	Granada Cinema, 186 Hoe Street, Walthamstow E17
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1065590

1357632

The cinema was built 1929-30 as the Granada Cinema to the design of Cecil Masey with fine Art Deco and Moorish style interiors by Theodore Komisarjevsky. The Local Authority has purchased the building and is restoring and redeveloping it as a cultural venue in partnership with Soho Theatre. Major works are underway. Historic England has awarded grants towards repair and restoration of the Hoe Street elevation and towards restoration of internal features, funded by London & SE Region and by the Heritage Stimulus Fund2. The project is due to complete and the venue to open to the public in 2023.

Closed chapel to a hospital (formerly a workhouse), 1840. The building is wind and weathertight but in need of

Contact: Ian Harper 020 7973 3786

moderate repair to bring it back into use.



© Historic England

SITE NAME:	Chapel to south of main hospital block, Langthorne Road Ell
designation:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Health authority

1357634

Contact: Mike Fox (LPA) 020 8496 3000

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Gar

RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Lodge south of main hospital block, Langthorne Road El I
DESIGNATION:	Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Health authority

1293493

1840 lodge to a hospital (formerly a workhouse). Considerable ivy growth that was covering most of the building has largely been removed.

Pumping station built in 1895 for East London Water Works, in a variant of the style popularised by Norman Shaw. The building is in two ownerships. Part of the building is being converted for residential use; part remains for utility use. The roof to the tower section is in very poor condition and rainwater goods require repair. Enforcement action for unauthorised works is ongoing. The Local Authority and Historic England are liaising with the owners

Contact: Mike Fox (LPA) 020 8496 3000



© Historic England

SITE NAME:	Chingford Mill Pumping Station, Lower Hall Lane E4
DESIGNATION:	Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed multiple owners

1250896

to improve the condition and management of the buildings and wider site.

Contact: Mike Fox (LPA) 020 8496 3000



© London Borough of Waltham Forest

SITE NAME:	Water Turbine House, Chingford Mill Pumping Station, Lower Hall Lane E4
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1065574

Water turbine house to pumping station built in 1895 for East London Water Works. Planning Permission and Listed Building Consent for residential use were granted in 2007 and subsequently renewed, subject to a Section 106 agreement. Repairs have been carried out and the building is now occupied. The Local Authority and Historic England are monitoring the building to review the level of current risk and ensure that unauthorised works are remedied or regularised.

Contact: Mike Fox (LPA) 020 8496 3000



© Historic England

SITE NAME:	133, Whipps Cross Road, Leytonstone E11
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1357621

One of six survivors from an original terrace of 12 'middle-class' three-storey houses called Assembly Row, built in 1767. Render and brickwork on the flank wall have suffered from considerable water ingress and are in a parlous condition. Following enforcement action, the roof coverings have been replaced and the front sash windows have been repaired. Historic England and the Local Authority have advised the owner on further necessary repair works, and the Local Authority is taking enforcement action, including for the unauthorised removal of two dormer windows.

Contact: Mike Fox (LPA) 020 8496 3000



© Historic England

SITE NAME:	Church of St Andrew, Colworth Road, Leytonstone El I
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1391544

Sir Arthur Blomfield was commissioned by the Cotton family to build the church in memory of William Cotton of Wallwood House; it was completed by 1893 in Kentish rag with knapped flint walling and freestone dressings. There is an important collection of window glass by Margaret Chilton. The early C20 vestry has a fine timber roof but is poorly founded and its settlement is damaging the church structure. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for repairs to the stained glass and for investigations into the causes of subsidence.

Contact: Ian Harper 020 7973 3786

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	St Michael and All Angels Church, Palmerston Road, Walthamstow E17
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1191154

This church has an imposing interior augmented by stained glass windows by Hardman and the highest nave roof of any church in the Chelmsford Diocese. It was designed in the Gothic style by JM Bignall and opened in 1885. It is constructed of London stock yellow brick with a mixture of red brick and stonework dressings. The original cast iron rainwater goods are in very poor condition and inadequately sized to cope with climate change. The regular wetting of the soft red bricks is causing them to decay internally and externally. In addition, the vestry roof is felted over and needs renewal.

Contact: Ian Harper 020 7973 3786



Historic England

SITE NAME:	Church of St Peter and St Paul, The Green, Chingford E4
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Religious organisation

1065582

The church, with tower and spire of 1844, is by Lewis Vulliamy; the chancel and north and south aisle chapels are by Sir Arthur Blomfield, in 1903. The Lady Chapel was extended and re-ordered in 1936 by NF Cachemaille-Day. Construction is in cream-coloured brick with decorative flint flushwork dressed in Bath stone. The slating is sound but the defective parapet gutters and sumps have caused serious internal leaks. A first phase of repairs was funded by the National Lottery Heritage Fund. Funds are sought for a second phase for the nave parapets, rainwater goods, and reordering access.

Contact: Ian Harper 020 7973 3786



© Historic England

SITE NAME:	Church of St Margaret of Antioch and attached railings, Woodhouse Road, Leyton El I
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1390581

A late C19 basilica style church by architect JT Newman, commenced in 1892, replacing an iron mission church. The Lady Chapel was added in 1910. There are fine decorations and wall paintings internally. Only the north transept and aisle roofs remain to be repaired but this work is urgent as the paintings and parquet floor are being damaged by inadequate rainwater goods and drainage. The contemporary railings and adjacent halls are also in need of repair. The congregation is actively exploring options for funding the repairs.

Contact: Ian Harper 020 7973 3786

#### WANDSWORTH



© London Borough of Wandsworth

SITE NAME:	Battersea Park Station, Battersea Park Road SW8
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Utility
LIST ENTRY NUMBER:	1357652

Italianate style station built circa 1865 for the London, Brighton and South Coast Railway. Alterations to the train service mean that the architecturally significant Platform I is redundant. Repair works are complete, but the building remains underused. A legal agreement with Network Rail for a scheme of works was secured in 2018. In 2019 work was completed on the conversion of the former station master's accommodation into offices. Discussions about the wider station site, including an additional entrance, a new use for Platform I, disability access and improved facilities are underway.

Contact: Barry Sellers (LPA) 020 8871 7564



© Historic England

SITE NAME:	Former St Mark's Infant School, Battersea Rise SWII
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1389136

Church school of 1866-67 designed by Benjamin Ferrey. The building is currently vacant but is wind and weathertight. The owners carried out maintenance and repairs to the roof and rainwater goods and implemented structural support to the north wall early in 2018. Discussions are ongoing between the Local Authority, Historic England and the owners regarding the re-use, extension, and alteration of the building. An outline programme of action is under discussion following further investigative work carried out in 2021. The Local Authority is anticipating application proposals.

Contact: Barry Sellers (LPA) 020 8871 7564

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS	
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garde
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Springfield Hospital (main building), Glenburnie Road SW17
DESIGNATION:	Listed Building grade II, RPG

grade II

CONDITION: Poor

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: F (F)

OWNER TYPE: Health authority

LIST ENTRY NUMBER: 1065553

Former psychiatric hospital built in 1840 in Tudor Gothic style as the Surrey County Asylum. The Hospital Trust appointed a partner in 2018 to progress a programme of works. Planning Permission and Listed Building Consent applications were approved in 2020 for the first phase of re-use, and restoration of the main building and Airing Courts. Further applications were submitted and approved for the second phase in 2021 and works of re-use, restoration and repair are currently (2022) in progress.

Contact: Barry Sellers (LPA) 020 8871 7564



© Historic England

SITE NAME:	Temple in the grounds of Mount Clare, Minstead Gardens SW15
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)

Religious organisation

LIST ENTRY NUMBER: 1065545

OWNER TYPE:

The 'temple' dates from between 1762 and 1769. Some damage was caused as a result of heritage crime in 2017. The site has been re-secured and temporary Planning Permission for perimeter fencing was renewed in 2021. The fence around the building has achieved protection of the building pending repair works, and the site is regularly monitored by Roehampton University. A schedule of proposed conservation repair works is being prepared. Discussions between the Local Authority and the university are still ongoing concerning the future of this building in the wider context of the Mount Clare site.

Contact: Elizabeth Whitbourn 07889 808145



© London Borough of Wandsworth

SITE NAME:	Former White Lion, 14-16, Putney High Street SW15
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1184658

Former White Lion public house, built in 1887. The building is unoccupied following its closure in 2015 and is in poor condition, with access problems. Planning Permission and Listed Building Consent, in line with the permissions granted in 2016, were renewed in April 2019 for extensions and alterations for hotel and public house use but have not yet been implemented. The building is secure and occupied by property guardians. The owners are in discussions with the Local Authority.

Contact: Barry Sellers (LPA) 020 8871 7564



© London Borough of Wandsworth

SITE NAME:	Queenstown Road Station, Queenstown Road SW8
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Utility
LIST ENTRY NUMBER:	1389413

Station built in 1877. Repairs are needed to the doors, windows and floors of the disused areas of this unattended station. The station is routinely inspected, the former station ticket office has been re-used as a café, and redecoration of the lobby area has been carried out. The owners have confirmed that funding is in place for repair works and further discussions are ongoing regarding Network Rail's enhancement proposals for the station. An application for Listed Building Consent for revisions to proposals for a second entrance from Patcham Terrace was submitted in early 2022.

Contact: Barry Sellers (LPA) 020 8871 7564



© London Borough of Wandsworth

SITE NAME:	100, Tooting Bec Road SW17
DESIGNATION:	Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1357661

Early C19 stucco lodge. Planning Permission and Listed Building Consent were granted in 2012 to use the building for retail and ancillary office space, together with a separate new building for use as a café and car sales. A Repairs Notice was served in 2015 and works to comply with the notice were completed in November 2017. An enforcement notice was served in 2018 in respect of hoardings around the site. Applications for Planning Permission and Listed Building Consent for new buildings, and car sales/gym use were refused in 2019. A revised scheme is still awaited.

Contact: Barry Sellers (LPA) 020 8871 7564

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS** Conservation Area Listed Building

Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

#### WESTMINSTER, CITY OF



© Historic England

SITE NAME:	19, Cavendish Avenue NW8
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Private

House dating from the mid C19, with a stuccoed facade and central Tuscan porch with a balcony above. The property is unoccupied and in a poor condition. The stucco is failing in places, plants have taken root at eaves level, and there are signs of water ingress internally. Planning Permission and Listed Building Consent were granted in November 2017 for the full repair of the building and alterations to provide a single family dwelling. Work has now started on site (May 2022).

Contact: John Wilman (LPA) 07866 037008



© Historic England

SITE NAME:	90-93, Piccadilly W I
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1226747

1066300

Corner block of shops and chambers dating from 1883. Red brick with stucco ornament and dressings and slate roofs in an eclectic High Victorian design. Part of the former private club complex with 94 and 95 Piccadilly. Planning Permission and Listed Building Consent were granted in March 2018 for a scheme including the adjacent listed buildings (94 and 95 Piccadilly). Works include the full repair of the buildings for hotel use, with seven residential units, and are currently being implemented.

Contact: Matthew Pendleton (LPA) 07866 039923



© Historic England

SITE NAME:	Former Samaritans Hospital for Women, 161 Marylebone Road NW1 NW1
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Health authority

Hospital building dating from 1889-90 by WC Habershon and F Fawkner. Bold classical style building with a symmetrical front incorporating a giant pilaster order and faced in red brick and terracotta with a slate roof. Vacant and with plant growth externally on the elevations. Discussions are ongoing with regards to its long-term use and repair.

LIST ENTRY NUMBER: | 12398|8

Contact: Alistair Taylor (LPA) 07866037603



© Historic England

SITE NAME:	Snowdon Aviary London Zoo, Regents Park NW I
DESIGNATION:	Listed Building grade II*, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Charity (non-heritage)

1323695

Aviary designed by Lord Snowdon and Cedric Price in 1962-5 as part of an expansion of London Zoo. The Aviary is an aluminium and steel structure on concrete foundations, accessed via a cantilevered concrete bridge. Funding has been secured from the National Lottery Heritage Fund for the full repair of the Aviary, and Planning Permission and Listed Building Consent were granted in September 2017. Works, including the replacement of the aluminium mesh and alterations to the concrete bridge and entrance pods, have now started on site.

Contact: Elizabeth Whitbourn 07889 808145



© Historic England

SITE NAME:	21, Charles Street W1
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Unknown
LIST ENTRY NUMBER:	1357294

Terraced town house circa 1750-53. Some unauthorised works have taken place. Planning Permission and Listed Building Consent were granted in July 2008 for various works including demolition and rebuilding of the mews building to the rear. The street elevation was cleaned and repaired in 2011-12.

Contact: Matthew Pendleton (LPA) 07866 039923

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Westminster City Council

SITE NAME:	112, Eaton Square SW1
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1066851

Grand terraced house, circa 1825. The building is suffering from neglect, water ingress and a serious outbreak of dry rot. Discussions with the owner are ongoing. Planning Permission and Listed Building Consent were granted in August 2017 for the full repair of the building as a single family dwelling, but the works have not yet been implemented.

Contact: Elizabeth Whitbourn 07889 808145



@ Westminster City Council

SITE NAME:	94 and 100, Gloucester Place W1	
DESIGNATION:	Listed Building grade II, CA	
CONDITION:	Poor	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (D)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1066788	(

Terraced houses built circa 1800 for the Portman Estate. Listed Building Consent was granted in July 2009 for the internal refurbishment and alterations to No. 100. Works have yet to be implemented.

Contact: Susanna Miller (LPA) 07866 039239



© Westminster City Council

SITE NAME:	10-11, Lancaster Gate W2
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1221694

Grand terrace of houses dating from 1865, attributed to John Johnson. The building is three bays wide with four storeys plus attic and basement. It has fine classical detailing. The condition of the existing building is very poor, owing to water leakage and a lack of maintenance over many years. The building has, however, been temporarily secured following enforcement action, and discussions are ongoing with regards to its long-term use and repair.

Contact: Alistair Taylor (LPA) 07866037603



© Historic England

SITE NAME:	94, Piccadilly W I
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1226748

Town Mansion of 1756-1760 by Matthew Brettingham for Lord Egremont, with 1822 and later alterations. Naval and Military Club from 1866 until 1999. Planning Permission and Listed Building Consent were granted in March 2018 for a scheme including the adjacent listed buildings (90-93 and 95 Piccadilly). Works include the full repair of the buildings for hotel use, with 7 residential units, and are currently being implemented.

Contact: Elizabeth Whitbourn 07889 808145



© Historic England

SITE NAME:	95, Piccadilly WI
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1265696

Town house dating from 1886, forming part of a larger site with the Former Naval and Military Club. Planning Permission and Listed Building Consent were granted in March 2018 for a scheme including the adjacent listed buildings (90-93 and 94 Piccadilly). Works include the full repair of the buildings for hotel use, with seven residential units, and are currently being implemented.

Contact: Matthew Pendleton (LPA) 07866 039923

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**



© Historic England Archive

SITE NAME:	Wharf side shelter and store to
	rear of builders' merchants, 22,
	Praed Street W2 W2

DESIGNATION: Listed Building grade II

CONDITION:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (D)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1248366

LIST ENTRY NUMBER:

OWNER TYPE:

Wharf side shelter and store circa 1840. Brick ground floor with timber first floor and large slated hipped roof. Part of the redevelopment scheme for Paddington Basin. The shelter is currently being stored off-site and will be reerected as part of the final landscaping proposals.

Contact: Andrew Barber (LPA) 07866 037397



© Historic England

SITE NAME:	140, Westbourne Terrace W2
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Fair
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1267518

Detached villa dating from 1843-8 in an Italianate style. Occupied as a number of bedsits. Planning Permission and Listed Building Consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised works. This is being investigated as an enforcement matter. Some repairs have, however, been carried out.

Contact: John Wilman (LPA) 07866 037008



© Historic England

SITE NAME:	Church of the Annunciation, Bryanston Street, Marble Arch WI
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)

Religious organisation

Designed by Sir Walter Tapper and built 1912-13. Located on a corner site, the church is built up against on two sides which makes access difficult for roof maintenance. The church has a problem with the ingress of rainwater and dampness has resulted in the ongoing detachment and falling of plaster and water staining to the vaulted ceilings. There is also falling masonry externally. The rainwater goods to the north nave were replaced summer 2020.

LIST ENTRY NUMBER: 1066358 Contact: Tracey Craig 020 7973 3756



© Paul Travis

SITE NAME:	Church of St Peter, Eaton Square, Westminster SWI
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER	1356980

A Classical Commissioner's church designed by Henry Hakewill, completed 1827 and enlarged 1875. It has a pedimented west portico, west end narthex carrying the tower and cupola, and rectangular nave with short transepts. The church was partly destroyed by fire in 1987 and the interior reordered, the nave being totally remodelled. The church has had a fall of plaster from the portico ceiling, the buckled copper roofing to the portico needs replacing, and past cementitious repairs to the tower are becoming detached and also falling.

Designed by Ninian Comper and built 1903 in red brick with stone dressings and mainly slated roofs. It has a nave, aisles with large windows, small windows to the clerestory, and a bellcote. The church has a white and gold colour scheme internally with finely detailed furnishings and stained glass also by Comper. The roofs are in need of attention, particularly over the Lady Chapel, which has

Contact: Tracey Craig 020 7973 3756



© Historic England

STE NAME:	Glentworth Street, Marylebone NW1
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

Contact: Tracey Craig 020 7973 3756

	Glentworth Street, Marylebone NWI
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1237476

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).



© Historic England

SITE NAME:	Church of St Mark, Hamilton Terrace, Westminster NW8
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1066681

Gothic church dating from 1846-7 by Thomas Cundy Senior with spire by Thomas Cundy Junior and chancel in 1878 by EB Ferrey. It has slate covered pitched roofs and Kentish ragstone walling with ashlar dressings. The nave roof was re-slated in 2013, with funding from Historic England and the National Lottery Heritage Fund. A further grant was awarded towards masonry repairs to the tower and spire; these works were completed in 2017. The nave parapets, the chancel roof and the baptistry remain in poor condition.

Contact: Tracey Craig 020 7973 3756

1	
	ACCULATION OF THE PARTY OF THE

© Historic England

SITE NAME:	Church of St Augustine, Kilburn Park Road, Kilburn NW6
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1221320

Designed by JL Pearson, built in 1877. The building has slated pitched roofs and red brick walling with Bath stone dressings. Internally the walls are covered in wall paintings by Clayton & Bell. The south aisle roof was re-slated in 2013, with funding from Historic England and the National Lottery Heritage Fund. A new heating system has more recently been installed. The church received funding through the Grants for Programmes of Major Works for the repair of roofs to the nave, chancel, transepts, the lead fleche and some masonry, completed June 2022.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Buddhist Temple, Margaret Street, Westminster WI
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1273611

Former Parish School and Church House to All Saints Margaret Street, dating from 1868-70 by William Butterfield. The building is in full-time occupation and used for worship, library and residential accommodation. The roofs and external elevations are in poor condition. Repairs were carried out in 2018 to the roofs, masonry and rainwater goods of the former Church House, grant aided by the National Lottery Heritage Fund. Similar repairs are required to the former School House.

Contact: Tracey Craig 020 7973 3756



© Historic England

	Marylebone Road, Westminster WI
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Good
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1239817

Church of St Marylebone.

Built c I 818, designed by Thomas Hardwick with chancel remodelled in I 884 by Thomas Harris. Corinthian portico and tower surmounted by a domed cupola supported by golden caryatids. The roof coverings, and the stone in places, were in poor condition. The lath and plaster ceilings and the fibrous plaster ceilings were very fragile. In 2016 the church was awarded a grant from the National Lottery Heritage Fund for their Changing Lives project for the repair of the church fabric. The church also received funding from Grants for Programmes of Major Works for the ceiling works, completing June 2022.

Contact: Tracey Craig 020 7973 3756



© Historic England

SITE NAME:	Church of St Mary Magdalene, Rowington Close, Paddington W2
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Fair
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1235288

Built 1878 by GE Street with crypt chapel of St Sepulchre by Sir Ninian Comper 1895. Roof repairs received funding from the National Lottery Heritage Fund and Historic England in 2008. Further funding saw the replacement of electrics and drainage repairs in 2012. External fabric repairs with cleaning and conservation works to the interior were grant-aided by the National Lottery Heritage Fund, completed in 2018, and a new contemporary extension constructed in 2019. Historic England awarded a Covid-19 emergency response grant to the St Sepulchre Chapel for investigations and project design.

Contact: Tracey Craig 020 7973 3756

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Newbold College (formerly



© Historic England

SITE NAME:	Church of St Gabriel, Warwick Square, Pimlico SWI
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Religious organisation

1357369

LIST ENTRY NUMBER:

Church dating from 1851-3 by the architect Thomas Cundy II with his son Thomas Cundy III. The tower has been repaired, grant aided by the National Lottery Heritage Fund and Historic England. Work was completed in March 2021 to convert an internal courtyard into a WC, provide step free access to the church, carry out improvements to rainwater goods and below ground drainage, and repair the boundary wall. The church has been awarded funds from the Grants for Programmes of Major Works for masonry repairs and internal plaster and decorations, due to complete June 2022.

Contact: Tracey Craig 020 7973 3756

#### **BRACKNELL FOREST (UA)**



© Historic England

	Moor Close), Binfield
DESIGNATION:	Registered Park and Garden grade II*, 7 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Educational (independent)
LIST ENTRY NUMBER:	1000547

Moor Close estate, now the home of Newbold College, was Oliver Hill's first commission in an early C20 Arts and Crafts style. Divided into several sections the garden and its setting will be affected by development and infrastructure proposals within the Local Plan, some of which has now been approved. The garden's built fabric has deteriorated and after a condition survey and some limited site repairs further resources are needed to manage change so that the significance of design, structural fabric and setting may best be considered to restrict further loss of historic design integrity.

Contact: Kay Richardson 0207 973 3647



© Historic England

SITE NAME:	Broadmoor Hospital, Crowthorne
DESIGNATION:	Registered Park and Garden grade II, LB grade II
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Health authority
LIST ENTRY NUMBER:	1001401

A mid-C19 asylum built to designs by Joshua Jebb with rare survival of large kitchen garden as the focus for therapeutic work. Sited on a ridge, formal terraces descend to kitchen gardens and farm estate below. The ornamented farmland has survived with some loss of historic character. Major redevelopment of the hospital completed 2019 with site allocated in the 2013 local plan for comprehensive mixed use/residential development. Any application must be accompanied by a Conservation Management Plan and close liaison is necessary to minimise harm to the historic design integrity.

Contact: Kay Richardson 0207 973 3647

#### BRIGHTON AND HOVE, CITY OF (UA)



© Historic England

Ciri Oi (0/1)	
SITE NAME:	Madeira Terrace and Madeira Walk and Lift Tower and Related Buildings, Madeira Drive, Brighton
DESIGNATION:	Listed Building grade II*, part in RPG grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1381696

The 850 metres of cast iron arches known as Madeira Terrace is an iconic feature of Brighton's eastern seafront. An important example of C 19 engineering, and evocative of the late Victorian heyday of the seaside. The terrace is in a very poor and deteriorating condition. Its structural stability is a serious concern causing the 170 plus bays to be closed off to the public. The restoration of the whole of the terrace will require substantial funding. Brighton and Hove City Council has appointed a design team to develop a scheme for the first phase of the restoration works.

Contact: Alma Howell 0207 9733 627

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

LIST ENTRY NUMBER:



© Historic England

© Historic England

SITE NAME:	53, Brunswick Square, Hove
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1281017

Terraced house by A Wilds and CA Busby, 1825-27. Used for multiple occupancy but largely vacant. The rear elevation and outbuildings are in poor condition and parts of the building are not habitable. Urgent works have been carried to make the building weather and water tight but full repairs are still required and there is no long-term solution in place.

Contact: Alma Howell 0207 9733 627

	pak!"
1000	
1	
	The second second second

SITE NAME:

The West Pier, Kings Road, Brighton

DESIGNATION:

Listed Building grade I, CA

CONDITION:

Very bad

OCCUPANCY:

N/A

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Charity (heritage)

LIST ENTRY NUMBER:

1381655

Pier, 1864-66 by Eugenius Birch. Closed in 1975. Historic England has declared its view that the combination of significant damage and cost of repair make restoration from public funds uneconomic. In early 2013 the eastern side of the structure collapsed following cold weather conditions, and in February 2014, further main supports on the eastern side were washed away, splitting the former pavilion into two sections.

1381655 Contact: Clare Charlesworth 0207 973 3640



© Historic England

SITE NAME:	Saltdean Lido, Marine Drive, Saltdean
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Community interest group

1380905

Lido of 1938, by RWH Jones in Moderne style. The building is currently undergoing an extensive programme of concrete repairs and general upgrading. The Saltdean Community Interest Company is leading the major repair scheme having secured substantial funding from the National Lottery Heritage Fund, Coastal Communities, Social Investment in Business funds, Brighton and Hove City Council, and Historic England.

Contact: Liz Pollard 0207 973 3650



© Historic England

SITE NAME:	Hippodrome, 52-58, Middle Street, Brighton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NILIMBER:	1301703

Originally an ice rink by Kerslake dating from 1896. Converted to Hippodrome in 1901 and again to variety theatre in 1902, both to designs of Frank Matcham. Vacant and in a very bad condition. The ornate plasterwork to the auditorium is particularly at risk. Consent granted in November 2013 for conversion to a multi-screen cinema was not implemented. A new private owner has acquired the building and completed much needed urgent repair works. Historic England and Brighton & Hove City Council are engaged in pre-application discussions about restoration of the building and potential uses.

Contact: Alma Howell 0207 9733 627



© Historic England

SITE NAME:	Marlborough House, 54, Old Steine, Brighton
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1380671

House built in 1765 and remodelled in 1786 by Robert Adam. Converted to an office, the building later became vacant. Consent granted in 2015 for change of use to single family dwelling has not been implemented. Some repair and restoration work has been carried out including to lathe and plaster walls and ceilings. There have been more recent discussions about potential new uses for the building but these have not progressed.

Contact: Alma Howell 0207 9733 627

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

OWNER TYPE

LIST ENTRY NUMBER

LIST ENTRY NUMBER:

CITE NIAME



© Historic England

	SITE NAME:	Church of St Patrick, Cambridge Road, Hove
	DESIGNATION:	Listed Place of Worship grade II, CA
	CONDITION:	Poor
F	PRIORITY CATEGORY:	C (C)

1280980

Religious organisation

Large C19 church constructed of ragstone. Problems with high level roofing and gutters, as well as stonework need addressing. The future use of this church is uncertain and it is now closed. In use by the YMCA as a night shelter for the homeless.

Contact: David John 0207 973 3638



© Historic England

SITE NAME:	Church of All Saints, Eaton Road, Hove
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1187592

Large late Victorian sandstone ashlar church with a rich cathedral like interior in the suburbs of Hove near to the seafront. Five bay nave, north and south aisles, chancel, chapel with apse and incomplete tower. Repairs to leaking roof over north aisle and organ carried out in summer 2013. Recent works (2019-20) include emergency stone repairs to the window mullions and significant repairs to the upper levels of the north-east and south-east towers. More repairs are still needed.

Contact: David John 0207 973 3638



© Historic England

SITE NAME:	Church of St Mary the Virgin, St James's Street, Kemp Town, Brighton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1380884

Late Victorian red brick building by William Emerson. Comprises a chancel with 5-sided apse, two vestries, transepts and four bay nave with north and south aisles and incomplete tower. Following on from major repairs to the North elevation (2016-17) and West front (2018-19) funded by the National Lottery Heritage Fund, recent work (2019-21) includes emergency repair of the south transept, repairs to brickwork, masonry, roofs, rainwater goods to the south aisle funded by Covid-19 Emergency Heritage at Risk Grants. Outstanding repairs remain to be done to the liturgical east end and other areas.

© Historic England

SITE NAME:	Place, Brighton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1380903

Chunch of Ct Doton Ct Doton

Designed by Sir Charles Barry and built between 1824 and 1828. A National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship grant for repairs to the lower tower roof, nave and aisle roofs were completed. Further phases of repair to the tower have also been completed with funding from the National Lottery Heritage Fund Grants for Places of Worship. One of the intermediate pinnacles is in a precarious condition and has been temporarily removed. Further phases of work are planned for the building, including some possible redevelopment work.

Contact: David John 0207 973 3638

Contact: David John 0207 973 3638



© Historic England

SITE NAME:	Church of St Paul, West Street, Brighton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1381098

A church designed by Richard Cromwell Carpenter in 1846-8 and built by George Cheeseman. The tower and spire are by Richard Herbert Carpenter. The narthex, Fishermen's Institute (west end) and covered way are by George Frederick Bodley. Large fragments of stone and flint have fallen from the tower, which is adjacent to a busy shopping street. Temporary protection has been provided. Some other works have been carried out to other parts of the building.

Contact: David John 0207 973 3638

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME:	The Royal Pavilion Gardens, Brighton
DESIGNATION:	Registered Park and Garden grade II, 3 LBs, CA
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners

1000205

John Nash designed picturesque layout of serpentine walks and drives, flowery shrubberies and trees within open lawns of the royal estate. Restored in 1990 high levels of visitor use and recreational pressure affect the garden's condition and distinctiveness. Later insertions and temporary events conceal the estate's overall composition and identity. As highly socially valued urban green space but with little chance to understand the shared sense of place, a 2018 Conservation Management Plan and 2019 National Lottery Heritage Funding are working to conserve the vulnerable Regency landscape.

Contact: Kay Richardson 0207 973 3647

SITE NAME:	Benfield Barn		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	East Cliff		
DESIGNATION:	Conservation Area, 189 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	Old Town		
DESIGNATION:	Conservation Area, 114 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	Sackville Gardens		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	Valley Gardens		
DESIGNATION:	Conservation Area, 139 LBs, RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SOUTH DOWNS (NP)			
SITE NAME:	Earthworks and lynchets near Eastwick Barn, Patch	nam, Brighton and H	Hove, City of (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002303
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Stanmer, Brighton and Hove, City of (UA), Brighto	n and Hove, City o	f (UA)
DESIGNATION:	Conservation Area, 18 LBs, part in RPG grade II, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Michael Scammell (LPA) 01730 814810

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

#### **BUCKINGHAMSHIRE (UA)**



© Historic England

Barn at New Manor Farm, Broughton Lane

DESIGNATION: Listed Building grade II\*

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private, multiple owners

LIST ENTRY NUMBER: 1310584

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Five bay aisled barn, late C12 and later. Roof of early C18 queen posts hipped to the west end and half hipped to east. Barn clad in weatherboarding with a gabled C19 cart entrance to the centre of the north elevation. A historic building analysis has been carried out with Historic England grant aid. Timber structure now supported by full internal birdcage scaffold and robust weatherproof roofing erected early 2019. A longer term conservation plan is required as part of any wider site development.

Remains of probable C15 walls to a strongly defended

for many years but some have been cleared to reveal

moated site. Walls have been overgrown with vegetation

serious structural issues. A grant was offered by Historic England to the owners to understand the extent and cost

of the works needed to conserve the walls. The grant was not accepted. The scheduling description for the site was

updated in 2107. Further proposals are awaited from the

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME: Walls of moated site at Grove Farm, Ashley Green

DESIGNATION: Scheduled Monument, 3 LBs

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY CATEGORY: A (A)

OWNER TYPE: Private

1006946

Contact: David John 0207 973 3638

owner.



© Historic England Archive

SITE NAME:

Barn and fishpond and moated site with dovecote at Church Farm, Edlesborough

DESIGNATION:

Scheduled Monument, 2 LBs

CONDITION:

Poor

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Private

1006955

Church Farm. Dovecote mid-C18, a small rectangular building with each gable with four entrance holes, the east gable also having a door with rectangular barred fanlight. Red and vitreous brick, old tile roof with two queen strut trusses, one altered. Contains about 350 nesting boxes with rectangular openings and continuous brick ledges below. Dovecote at risk due to structural cracking and proximity to the moat. A project needs to be initiated to address these issues.

Barn and fishpond and moated site with dovecote at

Contact: Rachel James 0207 973 3153



© Historic England

Lodging Range/ "courthouse" rear of the George Public House, High Street, Great Missenden

DESIGNATION: Listed Building grade II\*, CA

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

Commercial company

C15 timber framed range, probably built as a court house. Structural problems at one end which is propped with scaffolding to prevent collapse. Although a Community Interest Company has expressed interest in restoring the building, and the pub associated with it, they have not been able to reach agreement with the owner to purchase it. The building and associated pub have been recently acquired.

LIST ENTRY NUMBER: | 124795

OWNER TYPE:

Contact: Rachel Fletcher 0207 973 3846



© Historic England

SITE NAME: Dovecote to north east of Notley Farm, Chearsley Road, Long Crendon DESIGNATION: Listed Building grade I, SM CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)OWNER TYPE: Private LIST ENTRY NUMBER: 1289102

Large rectangular dovecote built from the stone of Notley Abbey. Some moulded stones found in core of wall. High hipped roof of old tiles with dorrmer at eaves on east side and gabled louvres at the ridge on the north and south. Significant historic subsidence, roof tiles and battens failing and admitting rain into the building.

Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Mr George Harper. Image supplied courtesy of Images of England

SITE NAME:	Mentmore Towers, Mentmore
DESIGNATION:	Listed Building grade I, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1117863

Country house built 1852-4 by Sir Joseph Paxton and GH Stokes for Baron Mayer Amschel de Rothschild. An application for Listed Building Consent and Planning Permission for external and internal alterations including repairs was granted in 2014. The programme of repairs identified within the consents has not been undertaken and there is a longstanding lack of regular maintenance. The service wing roof is in very poor condition and the deterioration of the main house is accelerating with areas of water ingress into the main hall and adjacent reception

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME:	The East Boycott Pavilion, Stowe Landscape Garden, Stowe
DESIGNATION:	Listed Building grade I, RPG grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1289656

One of a pair of large stone pavilions, circa 1728, by James Gibbs, altered by Borra in 1754 to change the steep pyramidal roofs to domes with cupolas. It now incorporates domestic accommodation but was previously an open-sided belvedere. With its western twin, these pavilions straddle the Oxford Avenue, at the south west of The Course, which is the main approach to the house. Domed roof replacement needed and cupola reinstatement. The National Trust plan major repairs, removal of 1950s interiors and conservation of original interior space.

Contact: Rachel James 0207 973 3153



© Historic England Archive

SITE NAME:	The Palladian Bridge, Stowe Landscape Garden, Stowe
DESIGNATION:	Listed Building grade I, RPG grade I, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)

1289750

LIST ENTRY NUMBER:

Covered bridge built in 1738; attributed to James Gibbs, situated in the south east corner of the pleasure grounds. The bridge is viewed from the west across the Octagon Lake and from the north west and north across Hawkwell Fields. Steady decay of the roof covering, ceiling plaster and masonry. Holding repairs have been carried out, full conservation and repair is planned.

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME:	Church of St Martin, Dunton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1211972

Church, C12 nave with south wall rebuilt late C18, C13 chancel. CI5 west tower, all much restored late C18. Nave and tower are of large stone blocks, squared and coursed with brick repairs and dressings. Chancel is rendered. Slate roof to nave, tiled roof to chancel. Tower of two stages has clasping buttresses, brick parapet and pointed single openings to bell chamber. Serious cracking to north and south walls of the medieval chancel. Some urgent roof repairs have been completed with the benefit of the Covid-19 Emergency Heritage at Risk Response Scheme, but further repairs are required.

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME:	Church of All Saints, Church End, Hillesden
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1288641

Church with mid-CI5 west tower of rubble stone. Remainder rebuilt after 1493 in ashlar, restored 1874-5 by Sir George Gilbert Scott and again in 1960. The high level stonework was in very bad condition which put the church on the Heritage at Risk Register. Some repairs have been carried out under the National Lottery Heritage Fund Grants for Places of Worship scheme but further repairs to the church are required.

Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



(O)	Historic	Fngland	

SITE NAME:	Church of St Michael and All Angels, Hughenden Park, Hughenden
DESIGNATION:	Listed Place of Worship grade II*, RPG grade II, CA
CONDITION:	Good
PRIORITY CATEGORY:	F (A)

1125743

Religious organisation

Church originally C14, almost totally rebuilt 1875 by Sir A W Blomfield. Knapped flint with stone dressings and tiled roofs. North west tower, nave, south porch, north aisle, north chapel now vestry, and chancel. In Decorated style with arched traceried windows. Tower is of three stages with set back buttresses, battlemented parapet and pyramidal roof. Water ingress in the tower roof caused decay to the timber roof structure. A programme of repairs with funding from the Heritage Stimulus Fund is nearing completion.

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME:	Church of All Saints, The Green, Hulcott
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1281503

Church of C14 and C16, restored. Rubble limestone with tiled roof, C16 wooden bellcote with boarded sides and shingled spire. Serious structural problems in masonry. Church in use for special services. Some roof repairs and survey works have been completed with the benefit of the Covid-19 Emergency Heritage at Risk Response Scheme, but further repairs are required.

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME:	Church of St Mary the Virgin, Church Lane, Ludgershall
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1124276

Largely C14 church with C19 restorations. The nave, porch and north and south aisles were re-roofed, and the decaying roof structure repaired. Repair work to the tower roof, tower stonework, repointing, rainwater goods and drainage also now completed. Both phases were supported by the National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship scheme. The timber belfry structure has been repaired. A National Lottery Heritage Fund Grants for Places of Worship grant application was unsuccessful, but internal repairs to damaged plasterwork need to be addressed.

Contact: Rachel James 0207 973 3153

SITE NAME:	Dam walls; part of Motte and bailey castle, moated s	site and Roman vil	a immediately east of All Saint's Church
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1018007
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Desborough Castle		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020863
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bell barrow 260m WNW of Slough Glebe Farm, pa Saunderton	rt of the Saunderto	on Lee barrow cemetery, Bledlow-cum-
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013953
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

HERITAGE AT RISK 2022 / LOND	on and south eas	T / BUCKINGHAMSHIRE (UA)		
SITE NAME:	Bowl barrow 14 Bledlow-cum-Sa	10m WNW of Slough Glebe Farm, underton	part of the Saunder	rton Lee round barrow cemetery,
DESIGNATION:	Scheduled Monu	ument	LIST ENTRY NUMBER:	1013954
CONDITION:	Extensive signific	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	5	NEW ENTRY?:	No
OWNER TYPE:	Commercial cor	mpany	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow at Saunderton	Molin's Works, part of the Saunde	erton Lee round bar	rrow cemetery, Bledlow-cum-
DESIGNATION:	Scheduled Monu	ument	LIST ENTRY NUMBER:	1013955
CONDITION:	Generally unsati	sfactory with major localised	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Permitted develo	opment	NEW ENTRY?:	No
OWNER TYPE:	Commercial cor	mpany	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Two bowl barrows 450m north west of Slough Glebe Farm, part of the Saunderton Lee barrow cemetery, Bledlow-cum-Saunderton			
DESIGNATION:	Scheduled Monu	ıment	LIST ENTRY NUMBER:	1013952
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Commercial company		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Large multivallat	te hillfort known as Cholesbury Ca	ımp, Cholesbury-cu	m-St. Leonards
DESIGNATION:	Scheduled Monument, part in CA		LIST ENTRY NUMBER:	1015585
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth		NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Roman villa north of Yewden Lodge, Hambleden			
DESIGNATION:	Scheduled Monu	ıment	LIST ENTRY NUMBER:	1014606
CONDITION:	Generally unsati problems	sfactory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646
	SITE NAME:	Halton House, Halton / Aston Clinton	Another of the original seven Rothschild country house the Aylesbury Vale with late C19 formal gardens and provide years in 18	
	DESIGNATION:	Registered Park and Garden grade II, 5 LBs, part in CA	the house is now the Officers' Mess to RAF Halton.  Bisected by a disused arm of the Grand Union Cana	used arm of the Grand Union Canal much
	CONDITION:	Extensive significant problems	of the open park	land has been fragmented and lost to the camp with the historic fabric of the
	VULNERABILITY:	High	ornamental featu	res of the garden in poor condition.The
	TREND:	Stable	overall woodland	d structure survives managed by the ssion. A Conservation Management Plan



© Historic England

SITE NAME:	Halton House, Halton / Aston Clinton
DESIGNATION:	Registered Park and Garden grade II, 5 LBs, part in CA
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000601

Forestry Commission. A Conservation Management Plan has been written to guide future proposals.

Contact: Kay Richardson 0207 973 3647

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



© Historic England

SITE NAME:	Mentmore Towers, Mentmore / Cheddington
DESIGNATION:	Registered Park and Garden grade II*, 10 LBs, 2 CAs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000319

Sir Joseph Paxton designed this largest of the Rothschild family houses in a prominent position in the Vale of Aylesbury, with formal gardens and park to complement it and a contemporary Arts and Crafts estate village. Sold in 2000, permission was sought to convert the house into a hotel and conference centre. With the estate ownership fragmented, much of the park converted to golf, and new development proposals a Landscape & Conservation Area Appraisal funded by Historic England and completed in 2020 assesses the significance, fabric, character and setting of Mentmore to inform decisions.

The oldest portion of this house is the chapel, refectory and dormitory built by the Cluniac's before 1121 as part of the Grange of St Pancras Priory at Lewes. There are later additions of various dates and materials. It is now in use as a house. There is damage to the roof caused by storms and water penetration. There is also structural movement.

Contact: Kay Richardson 0207 973 3647

#### **EAST SUSSEX**

#### **EASTBOURNE**



© Historic England

SITE NAME:	Langney Priory, Langney Rise
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1043639

Contact: David John 0207 973 3638

The Alex	keh 20 mm	
	in City	
K	•	
	-0	

© Historic England Archive

SITE NAME:	Eastbourne Redoubt, Eastbourne
DESIGNATION:	Scheduled Monument and Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

A redoubt built as part of the Martello system, 1806. Main parts are in use as a museum. The aquarium building, which occupies casemates and the mast on the south west side, is in very poor condition. The surviving caponiers suffer from water ingress. Moat walls are decaying. A Conservation Plan has been produced and proposals are being developed.

Local authority LIST ENTRY NUMBER: 1017358 and 1043662 Contact: Rebecca Lambert 0207 973 3630



© Historic England

SITE NAME:	Martello Tower No. 64, Eastbourne
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1017355 and 1043661

Martello tower, 1806. On the beach with a housing development nearby. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use. Historic England is working with owner to find a sustainable conservation solution for the Martello.

Contact: Rebecca Lambert 0207 973 3630

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG

Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Martello Tower No. 66, Langney Point, Eastbourne
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)

Private

1017356 and 1043660

Martello tower, 1806. On the beach near the harbour entrance. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use. Historic England is working with the owner to find a sustainable conservation solution for the Martello.

Contact: Rebecca Lambert 0207 973 3630

	The state of the s	
	P. S.	i i

© Historic England

SITE NAME:	Eastbourne Pier, Grand Parade
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1353116

The pier is 1,000ft long and 52ft wide on a substructure of iron screw piles, designed by Eugenius Birch and completed in 1872. The seaward Pavilion Theatre with 'camera obscura' and two games pavilions were designed and built in 1901 by Noel Ridley. The central windscreens were erected 1902-03 and the music pavilion added in 1925, designed by PD Stoneham. Later additions include the kiosks in 1971 and an entrance building in 1991. In July 2014 the landward arcade building was destroyed by fire. Historic England, the owners and Eastbourne Borough Council have discussed how to reinstate.

Contact: David John 0207 973 3638

SITE NAME:	Shinewater Bronze Age settlement		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1400780
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646

#### **HASTINGS**



© Historic England

SITE NAME:	Chapel to the Former Convent of the Holy Child Jesus,
	Magdalen Road, St Leonards
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1043478

Former convent chapel, partly designed by Augustus Welby Pugin and completed by his son Edward Welby Pugin. The chapel has a good High Victorian Gothic interior and is a rare example of a Roman Catholic Chapel retaining the nuns' choir. The convent complex is used as a language school in the summer. Some of the more urgent repairs to the chapel have started to be addressed, but more work is still required, externally and internally.

Contact: David John 0207 973 3638



© Judith Warren, Hastings Borough Council

SITE NAME:	Church of All Souls, Athelstan Road, Hastings
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1293681

Former church built 1889. Designed by Sir Arthur Blomfield. Vacant since February 2008 and now closed for worship. Its richly decorated interiors mean that it was included on the Victorian Society's top ten list of endangered buildings in 2014. A new owner intends to use the building as a studio and for the display of art works with some change to the interior fittings. Some holding repairs are proposed for the south east chapel roof.

Contact: David John 0207 973 3638

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).



	PRIORITY CATEG
Charles The	OWNER TYPE:
© Historic England	LIST ENTRY NUM

SITE NAME:	Remains of Manor House, Ore Place, Ore
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

Ruins of late medieval manor house surrounded by new housing development, close to Old St Helens Church. The ruins are being damaged by heavy vegetation growth.

Contact: David John 0207 973 3638 LIST ENTRY NUMBER: 1002271



© Historic England

SITE NAME:	Pelham Arcade, I-I2 and I2A, Pelham Place, Hastings
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority, multiple owners

1043389

Semi-subterranean arcade of shops, developed as the first part of the Pelham scheme by Joseph Kay in 1823-5. Poor drainage from the carriage drive above the Arcade and structural failures in its formerly glazed lantern have resulted in problems of damp, particularly to the rear. Investigation work to inform the road repairs, funded jointly by Historic England and Hastings Borough Council, were completed in 2021. Historic England and Hastings Borough Council continue to explore funding opportunities to support the package of repairs to the road and the arcade of shops below.

Contact: Liz Pollard 0207 973 3650



© Historic England

SITE NAME:	Statue of Queen Anne south east of Holmhurst St Mary's School, The Ridge, Baldslow
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (non-heritage)

1192060

Statue, 1711-12 in grounds of former convent (now sold separately). Longstanding lack of regular maintenance meant it was deteriorating rapidly through rainwater from overhanging trees and saline rain from the sea. It has also been recently subject to heritage crime but has now been made secure. An application for residential development which would secure the repair of the statue and improve its setting has now been granted by the Local Planning Authority. The developer has committed to carrying out repairs through a \$106 Agreement.

Contact: Alma Howell 0207 9733 627



1)	[
	(
	F
	(
	L

LIST ENTRY NUMBER:

SITE NAME:	Church of St Leonard, Hastings
DESIGNATION:	Listed Place of Worship grade II, 2 CAs
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1376621

Church built in 1953-61 by Sir Giles and Adrian Gilbert Scott. Buff brick with cream stone dressings. Pantiled low pitched roof to eaves. Rectangular plan with altar against east wall and choir stalls in chancel. Nave with passage aisles. Western tower, with entrance beneath. Simplified modernistic Gothic manner. Exterior dominated by fine blocky Gothic west tower reached by a flight of steps which has parabolic shape with late Gothic mouldings dying into the jambs. Congregation have moved out as there are concerns about the surrounding low cliff that needs stabilising. Church now closed.

Contact: David John 0207 973 3638



© Historic England

© Historic England

SITE NAME:	Former United Reformed Church, Cambridge Road, Hastings
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1393646

Built as a congregational church in 1885. Rainwater system very poor and needs replacing with more outlets, wider rainwater goods, more efficient drops. Movement cracks are allowing rain penetration. Discussions are taking place with the new owners, a new religious group, who are carrying out emergency works and considering funding options for full repairs.

Contact: David John 0207 973 3638

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

ABBREVIATIONS	
CA LB	Conservation Area Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

LIST ENTRY NUMBER



© Thames Valley Drones

SITE NAME:	Christ Church, London Road, St Leonards on Sea, Hastings
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1286965

Late Victorian church designed by Blomfield with later additions in prominent location. Suffering from severe erosion due to vulnerable stonework and proximity to coast. Also rainwater goods in need of overhauling, window ferramenta deteriorating and general deterioration of fabric. Repairs were carried out in 2021 to the tower and spire with funding from the Heritage Stimulus Fund.

Built in 1889 by Charles Alban Buckler with an interior scheme by Nathaniel Westlake, 1908 and 1911 which is deteriorating due to water penetration caused by inappropriate external pointing, poor rainwater disposal

Contact: David John 0207 973 3638

and the roof requiring repairs.

© Historic England

SITE NAME:	Church of St. Thomas of Canterbury and the English Martyrs, Magdalen Road, Hastings
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)

OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1391831

Contact: David John 0207 973 3638



© Historic England

SITE NAME:	Church of the Holy Trinity, Robertson Street, Hastings
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1043423

Victorian church designed by SS Teulon with stained glass windows by Clayton and Bell and Kempe. The stonework is displaying serious effects of erosion, particularly on the south, east and west elevations. The mullions and window tracery are particularly bad, allowing water to penetrate into the building. Awaiting the outcome of project development funding from the National Lottery Heritage Fund.

Contact: David John 0207 973 3638



© Historic England

SITE NAME:	Church of St Mary Magdalen, St Margaret's Road, St Leonards
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1043430

Decorated-style church by Frederick Marrable, 1852, in a prominent position in St Leonards. It has a four-stage south west tower built in 1872. Facing stonework and roofs in a fair condition but the tracery stonework is in a very poor condition. Historic England has given advice on repair and funding options. Repairs to the south aisle roof and drainage have recently been carried out.

Contact: David John 0207 973 3638

SITE NAME:	Hastings Town Centre		
DESIGNATION:	Conservation Area, 24 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Jane Stephen (LPA) 01424 783273

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

#### **LEWES**



© Historic England

SITE NAME: Newhaven Fort; Caponier, Fort Road, Newhaven DESIGNATION: Scheduled Monument CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1002242 Caponier of Newhaven Fort. Victorian caponier is in very poor condition in places. Lunette battery was repaired with a Historic England grant by Lewes District Council in 2009. In 2017 National Lottery Heritage Funding was accepted to develop a project for further repairs and interpretation at the fort. An application for the repairs fund is expected to be made.

Contact: David John 0207 973 3638

#### **ROTHER**



© Historic England

Martello Tower No. 28, Rye SITE NAME: Harbour, Icklesham Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

Private LIST ENTRY NUMBER: 1017353 and 1234372 Martello tower built 1806. Situated on the edge of a caravan park. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use. Historic England is working with the owner of the site to try and achieve a sustainable solution to the long-term conservation of the Martello.

Contact: Rebecca Lambert 0207 973 3630



© Historic England

SITE NAME:	Ruins of the former friary church [Grey Friars (Winchelsea Priory)], Friars Road, Winchelsea, Icklesham
DESIGNATION:	Scheduled Monument and Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1002301 and 1234450

c1310-20, now in the grounds of a C19 mansion. Ruins have significant plant  $\bar{\text{growth}}$  with decay to stonework. In 2016 a quinquennial survey was carried out and recommended various conservation works. At that time discussions took place with the owners regarding a programme of conservation works and maintenance however nothing has progressed. Since, damage from animal burrowing has occured which is causing significant damage to the buried remains, requiring immidate attention to control.

Extensive ruins to full wall height of a monastic church

Contact: Rebecca Lambert 0207 973 3630



© Historic England Archive

SITE NAME:	Austin Friars Chapel, Conduit Hill, Rye
DESIGNATION:	Scheduled Monument and Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1002296 and 1352789

Remains of an Augustinian friary chapel dating from the 1380s. The chapel building underwent alteration in the early C20. The window tracery is suffering from decay and the roof was leaking. Repairs to the roof and damp proofing were completed with funding from Historic England.

Contact: David John 0207 973 3638

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Martello Tower No. 30, Winchelsea Road, Rye
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

Private

1017354 and 1262420

Martello tower built 1806. The moat and glacis on the east side lost. Unconnected with destruction of the moat and glacis, a small housing development was built adjacent to the east. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Church of St Barnabas, Sea Road, Bexhill
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1044250

Late C19 and early C20 church in flint and red brick. Urgent repairs are required to re-cover the south aisle roof and the spire, including renewal of rainwater goods and repairs to stonework and window glass. The congregation was offered grant from the joint Historic England and National Lottery Heritage Fund for Places of Worship scheme in March 2012. However, it was not possible to proceed with the work. Discussions have taken place as to how a repair project might be taken forward.

Contact: David John 0207 973 3638

SITE NAME:	Romano-British iron working site in Beauport Park, Battle		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002250
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### SOUTH DOWNS (NP)



© Historic England

SITE NAME:	Dovecote 160 metres north west of Coombe Place, Offham, Hamsey, Lewes	
DESIGNATION:	Scheduled Monument, LB grade II	
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	

OWNER TYPE: Private

LIST ENTRY NUMBER: 1019248 Contact: David John 0207 973 3638

Early C19 dovecote within the grounds of Coombe Place. Ornate octagonal building of flint with dressings and quoins of red and grey brick. Water ingress and collapse of chalk and brick nesting boxes inside is the cause of risk. Discussions have taken place with the owners as to how a repair project might be completed.



SITE NAME:	Icehouse at Coombe Place, Offham, Hamsey, Lewes
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1019884

Late C18 ice house within the grounds of Coombe Place. The risk arises from heavy vegetation growth on the structure and partial collapse of the entrance tunnel vault. Discussions have taken place with the owners about how a repair project can be completed.

© Historic England LIST ENTRY NUMBER: 1019884 Contact: David John 0207 973 3638

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Anglo-Saxon cemetery 275m north of Comps Farr	n, Beddingham, Lev	ves
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021436
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Round barrow south of Ditchling Beacon, Ditchling	g, Lewes	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002254
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow forming part of a linear round barrow	v cemetery on Roc	okery Hill, Seaford, Lewes
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009953
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Hillfort and a bowl barrow on Seaford Head, Seafo	ord, Lewes	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014523
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Two bowl barrows, the south easternmost pair of a group of six bowl barrows, forming part of a linear round barrow cemetery on Rookery Hill, Seaford, Lewes		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009951
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### SOUTH DOWNS (NP) / BRIGHTON AND HOVE, CITY OF (UA) / LEWES

SITE NAME:



© Historic England Archive

	/ Westmeston, Brighton and Hove, City of (UA), Lewes
DESIGNATION:	Registered Park and Garden grade II, 19 LBs, 4 SMs, part in CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1001447

Stanmer Park, Ditchling / Falmer

Undulating C18 landscape park and downland agricultural estate on city fringe surrounding a country house and incorporating Stanmer village. Bought by the Council (1947) for public amenity, the parkland fabric is highly fragmented by A27 with further housing development being constructed and planned. National Lottery Heritage Fund funded works to improve parking, access and convert the walled garden complete. Collaborative management and visioning of parkland being sought through nested management objectives and Highways England Designated Funds for access improvements.

Contact: Kay Richardson 0207 973 3647

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

#### WEALDEN



© Historic England

SITE NAME:

Cross-In-Hand Windmill, Mill Lane, Heathfield and Waldron

DESIGNATION:

Listed Building grade II\*

CONDITION:

Very bad

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

A (New entry)

Private

1183064

Very bad

Private

Contact: Liz Pollard 0207 973 3650

SITE NAME:	The Mint House, Village Street,, Pevensey
DESIGNATION:	Listed Building grade II*, CA

CONDITION:

OCCUPANCY:

OWNER TYPE:

LIST ENTRY NUMBER:

OCCUPANCY: Vacant/not in use
PRIORITY CATEGORY: A (New entry)

© Historic England LIST ENTRY NUMBER: | 28447 |

OWNER TYPE:

LIST ENTRY NUMBER:

C16 timber framed hall with one of the largest C16 kitchen ranges known to survive in East Sussex. Water penetration is causing wet rot and deterioration of timber frame. Structural movement resulting in failure of first floor wall plate causing slumping of the jetty. Loss of plaster and wall paintings in some areas. Permissions sought for chimney removal and reinstatement due to structural failure. Further investigations and a comprehensive programme of repairs are now urgently necessary. Newly formed charity, Friends of the Mint House, is exploring means to purchase and repair the building.

A remarkably complete post mill dating originally to the

early 19th century. No longer in working order, with the sails and tail removed. At risk due to deteriorating

condition including internal and external timber work, and longstanding lack of regular maintenance. Condition survey

and a comprehensive programme of repairs are needed

Contact: Liz Pollard 0207 973 3650



© Historic England

SITE NAME:	Church of All Saints, Waldron, Heathfield and Waldron
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1284195

Church of C13 built of stone rubble with tiled roof. Consists of chancel, aisled nave, north porch and west tower with higher stairs turret. Tower in the Perpendicular style. South aisle dates from 1859-62. Urgent repairs to the tower have been completed. The Quinquennial Inspection carried out in 2019 identified significant on-going problems with old cement mortar repointing, eroded masonry and roof surfaces. The main issue is the south aisle roof which needs comprehensive repair.

Contact: David John 0207 973 3638



© Historic England

SITE NAME:	Church of St Andrew, The Tye, Alfriston, Wealden
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1043353

spire, known as the Cathedral of the Downs. Knapped flint walls and tiled roof. The spire has recently been repaired. However, the church walls are damp due to hard cementitious mortar trapping moisture. Some of the walls have now been repointed and re-plastered in lime which is helping them to dry out. The south transept requires similar repair work.

C14 church; cruciform in plan with a central tower and

Contact: David John 0207 973 3638



© Historic England

SITE NAME:	Kidbrooke Park, Forest Row
DESIGNATION:	Registered Park and Garden grade II, 2 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000305

C18 park with extensive surviving early C19 features including a designed water system attributed to Repton and later gardens. Sold and broken up after WWII, the house was converted to a school. Development has further reduced the park and with increasing woodland cover fragmented historical design intentions such as designed views. Proposals for using the lower lake as a flood storage facility have also been explored. A 2016 Parkland Plan for the school part-funded by Natural England explored options for restoration works for tree cover management and repair of parkland structures

Contact: Kay Richardson 0207 973 3647

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

#### EAST SUSSEX / KENT

#### WEALDEN / TUNBRIDGE WELLS

SITE NAME:	High Rocks Camp (see also Tunbridge Wells, Kent	), Frant	
DESIGNATION:	Scheduled Monument, SM	LIST ENTRY NUMBER:	1002280
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

#### **HAMPSHIRE**

#### WEST BERKSHIRE (UA) / BASINGSTOKE AND DEANE



© Historic England

SITE NAME:	Sandleford Priory, Greenham / Newtown
DESIGNATION:	Registered Park and Garden grade II, 2 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000333

A mid-late C18 landscape park with waterbodies laid out to designs by Lancelot Brown, surrounding a Gothick house remodelled by James Wyatt. Once straddling the A339 the estate was sold into divided ownership, the house, gardens and core of the park being used as a school. The northern park has been largely developed (housing, waste disposal) leaving the core compromised as a design fragment which in turn is under-resourced in its management. The setting of the house and park and garden is extremely vulnerable to housing and business development potential identified in the Local Plan.

Contact: Kay Richardson 0207 973 3647

#### **BASINGSTOKE AND DEANE**



© Historic England

SITE NAME:	Barn at Manor Farm, Old Burghclere, Burghclere
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1157463

Manorial barn, 1451, built for the Bishop of Winchester. Suffering from water ingress and failure of joints, the building needs comprehensive repair. Emergency repairs have been carried out. Full cost of repairs is very high. The owners have decided to undertake the repairs on a phased basis over 8 years. Works commenced in May 2017 to repair the 3 eastern bays of the barn. These works have been successfully completed. The next phase of repair was scheduled to commence in the summer of 2020 but due to Covid-19 these works have been postponed.

Contact: Marion Brinton 0207 973 3631

SITE NAME:	Roman site north west of Woodgarston Farm		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001857
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### **EAST HAMPSHIRE**

SITE NAME:	Walldown enclosures, Whitehill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017368
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

#### **EASTLEIGH**

SITE NAME:	Promontory defined by an Iron Age linear earthw Common, Hamble-le-Rice	ork, St Andrew's Ca	astle and additional remains on Hamble
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1008695
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alex Bellisario 0207 973 3700

#### **FAREHAM**



© Historic England

SITE NAME:	Brick Kiln, Chimney, Drying Sheds, Boiler and Engine House at Bursledon Brickworks south Section, Coal Park Lane, Swanwick
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

Steam driven brickworks complex in use from C19 until 1970's with what appears to be the earliest surviving Staffordshire type continuous kiln, with ten chambers. Now a museum. At risk due to decay and vulnerability of unsupported walls to roofless drying sheds and leaking roof above the brick kiln. National Lottery Heritage Fund have grant-aided a Development Phase for repairing and converting the drying sheds but funding required to implement the scheme.

Contact: Robert Williams 0207 973 3641



© Historic England

SITE NAME:	Fort Fareham, Newgate Lane, Fareham
DESIGNATION:	Scheduled Monument and Listed Building grade II, LB grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Mixed, multiple owners

1001856 and 1094240

1233725

Royal Commission fort built in 1861. The only one of three proposed 'Gosport Outer Line' forts built due to defence cuts. It was intended to be part of a further line of defence to the already completed 'Gosport Advanced Line' of Forts Elson, Brockhurst, Rowner, Grange and Gomer, built to defend Portsmouth Harbour. Suffering from decay and heritage crime in parts. Interior of Fort functioning as a business and industrial estate.

Contact: Rachel James 0207 973 3153

### **GOSPORT**



© Historic England

SITE NAME:	Gunboat Sheds and Workshops, Haslar Gunboat Yard
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1431190

A row of ten gunboat sheds and three maintenance workshops, designed in 1856 by William Scamp of the Admiralty Works Department as part of the Haslar Gunboat Yard for the housing and repair of British gunboats, and their successor craft, of the Royal Navy. The adjacent traverser system was used for their launch and movement. The site ceased to be used in the mid-1970s but remained in MOD ownership. Once vacant, its condition deteriorated, with only minimum maintenance undertaken. Historic England grant aided a feasibility study in 2019 to help find an appropriate new use for the site.

Contact: Rachel James 0207 973 3153


### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME: Gunboat Yard Boundary Walls, Watchtowers and Gates, Haslar Gunboat Yard, Gosport Listed Building grade II\*, part in

DESIGNATION: CONDITION:

Poor OCCUPANCY: N/A

PRIORITY CATEGORY: C(C)

OWNER TYPE: Mixed, multiple owners

LIST ENTRY NUMBER: 1431191

LIST ENTRY NUMBER:

OWNER TYPE:

OWNER TYPE:

LIST ENTRY NUMBER:

Mid C19 boundary walls incorporating corner watchtowers, walkways and gates. Mainly built of red brick laid in Flemish bond with stone dressings and pyramidal slate roofs to watch towers. At risk due to animal burrowing, defective roofs, eroding brickwork and pointing, missing windows and doors and vegetation growth. Contact with a local construction college has been established who will supervise brickwork repairs at the site to develop heritage skills.

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME: No 2 Battery, Stokes Bay Road, Gosport DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C(C)OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1276305

Batteries No. I and 2 were built in the Stokes Bay area of Gosport, primarily to defend against a sea-borne attack, and are located at the north-west end of the Stokes Bay Lines. They were part of a system of ramparts, moats and batteries built in the 1860s. It has extensive problems of damp penetration and condensation affecting the building fabric. The building is partly in use as a museum. The Trustees have secured funding through the Museum Estate and Development Fund to improve the internal environmental conditions and continue to explore other funding opportunities.

Contact: Rachel James 0207 973 3153

Contact: Rachel James 0207 973 3153

Contact: Iain Bright 0207 9733 739




© Historic England

SITE NAME: Former Guard House, Haslar Gunboat Yard, Haslar DESIGNATION: Listed Building grade II\*, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Charity (non-heritage)

1431192

Former Guard House to Gunboat Yard constructed in mid-19th century. Mainly built of red brick with limestone dressings beneath hipped slate roof. Vacant and at risk due to poor condition of roofs, rainwater disposal, leaning chimney stack, windows, doors, floors and internal finishes. Historic England grant aided a Conservation Management Plan and Feasibility Study. New uses are being explored.



© Historic England Archive

SITE NAME: Gilkicker Fort, Fort Road, Gilkicker Point Scheduled Monument and Listed DESIGNATION: Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D)

1001789 and 1276716

Government or agency

Private

Artillery fort 1865-71 with later additions. Subject to heritage crime in parts, and casemates and magazines are threatened by water penetration. Repair and conversion to residential units approved but scheme has not yet been implemented. Security fencing and monitoring has been erected to try and control levels of heritage crime, and vegetation management is in place for the outer banks.



© Historic England

SITE NAME: Fort Elson, RNAD, Military Road, Gosport DESIGNATION: Scheduled Monument CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)

Polygonal artillery fort of 1853-60. Damaging vegetation has taken hold of the site. Programmes of vegetation removal are intermittent. A management plan has been drafted but not agreed or implemented. The building cannot be occupied because it lies within a munitions storage area.

LIST ENTRY NUMBER: 1001841 Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

TIERT TROUBLE TO TRIBE	ABONT NAB SOOTH BIST / COST CIRT / TIVART		
SITE NAME:	Fortifications S of Trinity Church		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001849
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Motte and bailey castle near Apple Dumpling Bridg	ge, south of Rowner	r
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008694
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Gunboat Traverser System, Haslar Gunboat Yard		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001810
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Louise Forsyth 020 7973 3220
SITE NAME:	High Steet, Gosport		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Rob Harper (LPA) 02392 545456
SITE NAME:	Priddy's Hard		
DESIGNATION:	Conservation Area, 25 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	High	CONTACT:	Rob Harper (LPA) 02392 545456
SITE NAME:	Stoke Road, Gosport		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Rob Harper (LPA) 02392 545456

#### **HART**



SITE NAME:	Garden walls and gateways north of Bramshill House, Bramshill
DESIGNATION:	Listed Building grade I, RPG grade I
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1340026

Walls to early C17 and early C19 formal walled gardens. Some sections of the walls are in a poor condition and in need of repair. Site was sold in 2014 to a development company and proposals for development within the site and the conversion of the mansion were the subject of a public inquiry which finished in February 2018 but the future of the site is still uncertain. The repair of the garden walls will be sought as a positive outcome of the planning process.

Contact: Louise Forsyth 020 7973 3220

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



© Historic England

SITE NAME:	Bramshill Park, Bramshill / Eversley / Mattingley
DESIGNATION:	Registered Park and Garden grade I, 8 LBs, part in SM, part in CA
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000165

Rare early C17 gardens and contemporary house within a park of medieval origin created using the topography and habitat, whose parkland architecture remains intact despite mid-C18 and later extensions, informalisations and some fragmentation of the wider park. Previously in institutional use with numerous college buildings built in the core the estate was sold in 2014 and faces major change through development. With other changes in the wider park the significance, fabric, character, and any collective experience is vulnerable to fragmentation and loss of integrity.

Contact: Kay Richardson 0207 973 3647



© Historic England

SITE NAME:	Warbrook House, Eversley
DESIGNATION:	Registered Park and Garden grade II*, LB grade I
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners

1000249

Seminal in garden history terms, the gardens and house were designed c1724 by the architect John James whose home it was, utilising the formal geometric principles he translated from Dezallier d'Argenville. James' geometrical axes extend beyond the gardens but these, and the wider parkland has fragmented, and conversion to a hotel and conference centre created major local change. Further assessment, visioning, surveys and land management options within Countryside Stewardship are being developed though a Parkland Plan brief in partnership with Natural England.

Contact: Kay Richardson 0207 973 3647

#### HAVANT



1	SI
1	D
	C
	PF
	0

LIST ENTRY NUMBER:

LIST ENTRY NUMBER

SITE NAME:	St Faith's Church, West Street, Havant
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1092120

Cruciform medieval church; flint and stone walls, clay tile roof. Tower with parapet. Following plaster falls an investigation of the roofs recommended a complete overhaul. Temporary repairs were undertaken. Fundraising has led to the congregation being able to undertake internal works but external repairs still required.

Contact: Robert Williams 0207 973 3641

© Historic England

SITE NAME:	Coastguards		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Rachael McMurray (LPA) 02382 446546

#### **NEW FOREST**



© Historic	England

SITE NAME:	Church of St Winfred, Salisbury Road, Totton and Eling
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1094352

Large church completed 1937 and designed by NF Cachemaille-Day. Unusual galleried square nave with monumental concrete font and Father Willis organ. Built of brick with mainly pantiled roofs. At risk due to defects to the brickwork, rainwater disposal system, deteriorating windows and internal plaster. The pantiled roofs were repaired with a grant from the National Lottery Heritage Fund under their Grants for Places of Worship scheme. It is hoped that the remaining repairs will be carried out by a new incoming church plant congregation supported by the Diocese.

Contact: Robert Williams 0207 973 3641

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / LOT	ADDITION AND SOUTH EAST / NEW POREST / NEW POREST (	INF)		
SITE NAME:	Bowl barrow 330m north of Grim's Ditch, r	near Tidpit Common, Mar	tin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011000	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Long Barrow 800m north west of Paradise, Martin			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012512	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Duck's Nest: a long barrow on Rockbourne Down, Rockbourne			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012920	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Long barrow 700m north west of Tenantry	Farm, Rockbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013002	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Rockbourne Down, Spring Pond enclosure,	Rockbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003453	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	

### **NEW FOREST (NP)**



Church of St Katherine, Exbury, SITE NAME: Exbury and Lepe, New Forest Listed Place of Worship grade II, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

Church remodelled in 1907 by JO Scott and Son, with coursed squared Ventnor Greensand facings and tiled roof. The church forms part of a joint benefice and is located in a hamlet constructed to serve the neighbouring Rothschild house and garden. The main problem is the decay and delamination of stonework. The congregation completed some stonework repairs to the tower in 2014. Further funding required to complete the outstanding repairs to the stonework.

LIST ENTRY NUMBER: 1094359 Contact: Robert Williams 0207 973 3641 © Historic England

SITE NAME:	Bell barrow and two bowl barrows 180 metres south west of Stagbury Hill, Furzley Common, Bramshaw, New Forest		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016491
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Rabbit warren and four bowl barrows on Stagbury Hill, Furzley Common, Bramshaw, New Forest		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016490
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow 550m north west of Avon Tyrrell, Rin	ngwood / Sopley, N	lew Forest
SITE NAME: DESIGNATION:	Bowl barrow 550m north west of Avon Tyrrell, Rin	ngwood / Sopley, N	lew Forest 1012637
	<b>,</b> .	1 /-	
DESIGNATION:	Scheduled Monument  Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1012637

#### **RUSHMOOR**



© Historic England

SITE NAME: Building Q121 [24 foot wind tunnel] at former Royal Aircraft Establishment site, Hall Road, Farnborough DESIGNATION: Listed Building grade I CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1259589

Wind tunnel built 1934-35. The external fabric of the building is generally in good condition and actively maintained. Tours are given by arrangement and low-key use for art exhibitions has been permitted (in association with the Farnborough Air Show) However the future use of the building remains uncertain, which is the reason for the at-risk status. Study exploring Farnborough's aviation heritage being commissioned from consultants.

Contact: Robert Williams 0207 973 3641



© Historic England

SITE NAME: Building R133 [Transonic wind tunnel] at former Royal Aircraft Establishment site, O'Gorman Avenue, Farnborough DESIGNATION: Listed Building grade I CONDITION: Fair OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: E (E)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1259586

Wind tunnel built in 1939 and modified in 1956. Externally the building is generally in good condition and actively maintained but some staining of concrete walls due to corroding reinforcement. Tours are given by appointment, but the future use of the building remains uncertain. Study exploring Farnborough's aviation heritage being commissioned from consultants.

The first church to be built in the new town, by Sidney Stapley 1875-78, in the Early English style of Bargate stone with Bath stone dressings and a slate roof. The ashlar stonework is showing signs of decay and repairs required

Contact: Robert Williams 0207 973 3641



© Historic England

SITE NAME:	Church of the Holy Trinity, Albert Road, Aldershot
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1092621

Contact: Robert Williams 0207 973 3641

to the roof and west porch.

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument

#### SOUTH DOWNS (NP)



© Historic England

Ruins of St Nicholas Chapel,
Westbury, East Meon, East
Hampshire

DESIGNATION: Scheduled Monument and Listed Building grade II

CONDITION: Very bad
OCCUPANCY: N/A

PRIORITY CATEGORY: A (A)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1001942 and 1179009

Small ruined medieval church of possibly C13 or later. Designated with associated earthwork remains of contemporary settlement. Standing ruins are suffering from structural cracking and deferred maintenance. A project to see the ruins conserved, explained and maintained needs to be agreed and put into action.

Contact: Robert Williams 0207 973 3641

Brambridge House, Kiln Lane, Colden Common, Winchester

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private, multiple owners

Country house, 1762 and 1872, converted to flats in the 1950s. Suffering from deferred maintenance due to uncertainty about areas of responsibility amongst leaseholders. Some repairs have been carried out, but more are needed.

© Historic England

LIST ENTRY NUMBER: 1350494

Contact: Robert Williams 0207 973 3641

SITE NAME:	Bowl barrow 60m south east of the junction of the cemetery, East Hampshire	A32 and Fawley La	ane, part of The Jumps round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019120
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow on Chalton Down, 350m south east of	of Manor Farm, Cla	ınfield, East Hampshire
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020511
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow 620m north east of Warhill Cottage, East Meon, East Hampshire		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019116
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Group of four bowl barrows 660m north of Warhi	II Cottage, East Me	on, East Hampshire
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019115
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Lindon repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Bowl barrow 100m south east of Lower Bordean	Farm, Langrish, East	: Hampshire
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017051
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Three disc barrows on Longmoor Common, 250m	n north west of the	church, Whitehill, East Hampshire
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016843
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Round barrow cemetery, Roman road and hollow East Hampshire	ways 200m south v	vest of Woolmer Cottages, Whitehil
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020502
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	St Catherine's Hill hillfort, Winchester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016489
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Educational (independent)	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Roman villa in Bottom Copse, Soberton, Winchest	ter	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1001848
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	David Wilkinson 0207 973 3644
SITE NAME:	Boundary earthwork and barrow at Sheepbridge, \	Warnford / West M	leon, Winchester
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1003562
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alex Bellisario 0207 973 3700
SITE NAME:	Easton, Winchester (District), Winchester		
DESIGNATION:	Conservation Area, 31 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Michael Scammell (LPA) 01730 814810
SITE NAME:	Hambledon, Winchester (District), Winchester		
	Conservation Area, 82 LBs	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 62 Lbs		
designation: condition:	At risk	TREND:	No significant change

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Itchen Stoke, Winchester (District), Winchester		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Michael Scammell (LPA) 01730 814810
SITE NAME:	Martyr Worthy, Winchester (District), Wincheste	r	
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Michael Scammell (LPA) 01730 814810
SITE NAME:	Twyford, Winchester (District), Winchester		
DESIGNATION:	Conservation Area, 50 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
vulnerability:	Unknown	CONTACT:	Michael Scammell (LPA) 01730 814810
TEST VALLEY			
SITE NAME:	Long barrow 400m south east of Moody's Down F	arm, Barton Stacey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012515
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	The Andyke, Bransbury, Barton Stacey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015678
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Long barrow and two bowl barrows, 400m north	of Chattis Hill Hou	se, Broughton
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1012998
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Long barrow 300m south east of Middlebarn Farm	, Chilbolton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012517
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Castle Hill, Chilworth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001885
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Alison McQuaid 0207 973 3646

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

ITE NAME:	Bowl barrow 780m NNE of Hampshire Gap, Grate	ley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014816
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
ITE NAME:	Barrow cemetery 730m north of Hampshire Gap, 0	Grateley / Quarley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014817
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
ITE NAME:	Andover-Redbridge canal, Chalk Hill Lock, Horsebridge, Kings Somborne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001794
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
ITE NAME:	The Moat, Longstock		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1001940
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No



© Historic England

SITE NAME:	Embley Park, Wellow
DESIGNATION:	Registered Park and Garden grade II, 8 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners

1000215

Hursley

Poor

Ruins of Merdon Castle,

Scheduled Monument

C19 and early C20 woodland and shrub garden of late C18 origin, once the home of Florence Nightingale. After WWII the estate was divided, the house and historic core becoming a school. A Conservation Management Plan covers the school although the historic character is vulnerable to additional developement. The wider open and wooded park has multiple owners and accumulative development pressures. A Heritage Impact Assessment was commissioned by Test Valley in 2016 in response to local plan proposals. The need to widen understanding of significance and conservation to sustain value remains.

Contact: Kay Richardson 0207 973 3647

#### WINCHESTER



(A)	1

© Historic England

CONDITION.	1 001
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1019123

LIST ENTRY NUMBER:

SITE NAME:

DESIGNATION:

CONDITION:

Circular Late Bronze Age or Early Iron Age earthwork with remains of Norman tower structure and length of curtain surviving as flint core work, all in need of structural repair and consolidation. A development phase, including vegetation clearance and investigations works has been undertaken with the benefit of a Countryside Stewardship grant and assistance from Historic England. More recently a repair grant has been offered by Historic England and works are due to commence in the summer of 2022.

Contact: Robert Williams 0207 973 3641

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of the Holy Trinity, North Walls, Winchester

CONDITION: Poor PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | 1350718

Designed by Henry Woodyer and built 1853-1855. It has a continuous seven-bay clerestoried nave with north and south aisles and chancel and fleche with spire and lunettes. The walls are of flint with limestone blocks and limestone dressings. Vestry on south east and enclosed porch on the west door dating from 1894. There are slipped and missing slates, the roof leaks and the rainwater goods do not function effectively, putting the church at risk.

Contact: Robert Williams 0207 973 3641

SITE NAME:	'Banjo type' native settlement, Itchen Valley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001814
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Roman villa and earlier prehistoric settlement 400	m west of Lone Far	m, Itchen, Itchen Valley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012693
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Norsebury Ring hillfort, Micheldever		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020317
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Long barrow and bowl barrow 440m north west o	of Sanctuary Farm, V	Vonston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021109
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Compton Street		
DESIGNATION:	Conservation Area, 14 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Hursley		
DESIGNATION:	Conservation Area, 33 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	New Alresford		
DESIGNATION:	Conservation Area, 125 LBs, SM	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Improving
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

TIERT / GE / TI MOR 2022 /	ESTABLISHED SOUTH ENDING THE CONTROLLED FERT TO REST TO SET IT.	0. (0.1)	
SITE NAME:	Southwick		
DESIGNATION:	Conservation Area, 48 LBs, SM	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Sparsholt		
DESIGNATION:	Conservation Area, 13 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	No significant change
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Sutton Scotney		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Wickham		
DESIGNATION:	Conservation Area, 50 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Improving
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Wonston		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	No significant change
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222

#### PORTSMOUTH, CITY OF (UA) / WINCHESTER



© Historic England

SITE NAME:	Portsmouth, Southwick and Widley
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade I, SM
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

Fort Couthwick Portedown Hill

1860s fort, part of the Palmerston Portsmouth defences. Parts of the monument are in poor condition. Following disposal by Defence Estates, the site is now operated by an estate management company as a business park with a number of different companies operating from the site. The new owners have carried out some repairs but more are needed, together with a carefully planned maintenance regime.

1001808 and 1104368; 1167213 Contact: Rachel James 0207 973 3153

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

#### ISLE OF WIGHT (UA)



© Historic England

SITE NAME:	The Guildhall, High Street
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1278563

Former Guildhall, now museum, in the centre of Newport. Designed by John Nash and constructed 1814-6, with clock tower added in 1887 for Queen Victoria's Golden Jubilee. Slate roofs, rendered walls and stone columns and dressings to tower. At risk due to deferred maintenance and defects to roofs, render, stonework and rainwater disposal.

Contact: Robert Williams 0207 973 3641

	*
-	
	MXIN .

© Historic England

SITE NAME:	Hammerhead Crane, Thetis Road, West Cowes, Cowes
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1390949

Giant cantilever crane, also called 'hammerhead' crane, built 1911. One of a handful of this type of crane now surviving in the world, and witness to a major local industry. Disused and surrounded by a potential development site. Historic England has been assisting the Local Authority with grant aid and technical advice. Essential holding repairs to the legs and upper structure have been undertaken under the auspices of an Urgent Works Notice. Historic England has grant-aided a feasibility study and will be working with all stakeholders on the site to secure the full repair of the crane.

Contact: Robert Williams 0207 973 3641



© Historic England Archive

SITE NAME:	Northwood House, Ward Avenue, Cowes
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1223779

Large house, 1837, with spectacular interiors. The long-term future of this partly used building is unresolved and maintenance needs to be addressed in the short term. Some progress has been made and areas of the building have been brought back into use, but the comprehensive repair of the external envelope is still required. The Trustees of Northwood House have been urged to appoint a conservation architect, compile a full package of repairs and improvements and to engage with the National Lottery Heritage Fund. The cost of full repair is very high.

Contact: Robert Williams 0207 973 3641



© Historic England

	House, Two Cottages and Kitchen Garden Wall, Newbarn Road, East Cowes
DESIGNATION:	Listed Building grade I, RPG grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

Norris Castle Farm, the Bailiff's

Model Farm designed by James Wyatt around 1800. It includes farm buildings, Bailiff's house, cottages, walled garden and glass houses all contained within a rectangular plan surrounded by high castellated walls with corner towers. The walls are mainly built of rubble stonework with Welsh slate roofs to the buildings. At risk due to lack of long-term maintenance, leaking roofs and defective rainwater disposal. Proposals for repair and sustainable reuse are awaited from the owner. Some emergency repairs carried out.

Contact: Robert Williams 0207 973 3641



© Isle of Wight Council

SITE NAME:	Norris Castle, Newbarn Road, East Cowes
DESIGNATION:	Listed Building grade I, RPG grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1267468

1223182

overlooking the Solent. Constructed with galletted stone facings to the walls and slate roofs behind parapets. At risk due to backlog of maintenance, heritage crime and deterioration of significant historic fabric including to roofs, walls, windows and interiors. Historic England is working with representatives of the owners to address repairs in both the short and long term.

Mock castle of 1799 by James Wyatt on a spectacular site

Contact: Robert Williams 0207 973 3641

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

		**	
		99	1
18.			

© Historic England

SITE NAME:	Remains of Old Quarr Abbey, Fishbourne Park Road, Binstead Fishbourne / Ryde
DESIGNATION:	Scheduled Monument and Listed Building grade II*, LB grade II
CONDITION	D

CONDITION: Poor

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY:

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1012714 and 1234997

Cistercian foundation of 1131. The upstanding remains are in an advanced state of decline due to longstanding lack of regular maintenance and vegetation growth. The National Lottery Heritage Fund grant aided repairs to the barn, some structures and walling as part of a wider project. Further repairs are necessary to remove the remains from the Heritage at Risk Register. Historic England grant-aided an update of the condition survey, hydrological survey and temporary propping of the leaning east precinct wall which was in danger of collapse.

Contact: Robert Williams 0207 973 3641



SITE NAME: Yaverland Battery, Sandown, Sandown DESIGNATION: Scheduled Monument CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company

Royal Commission coastal battery completed in 1864 with later alterations. Mainly built of red brick with stone dressings. At risk due to vegetation growth and partial collapse of carnot wall. A plan for the long-term conservation of the monument needs to be developed with the owner.

© Historic England

LIST ENTRY NUMBER: 1021443

SITE NAME:

Contact: Robert Williams 0207 973 3641



© Forestry Commission

SITE NAME:	Bouldnor Battery, Shalfleet
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1010011

Battery built in 1938 situated on the west coast of the Isle of Wight to help protect the Solent. Buried components no longer accessible but survive. Mainly constructed from reinforced concrete which is now spalling and decaying due to corrosion of the internal reinforcement. Historic England has grant-aided temporary propping and waterproofing of the roofs. An Options Appraisal, also grant-aided by Historic England, was completed in early 2020 and options for the repair and possible re-use of the monument are being explored.

Contact: Robert Williams 0207 973 3641

Contact: Robert Williams 0207 973 3641



	Drake Road
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1278820

Church of St John the Bantist

Spacious Gothic style church to the south of Newport town centre. It was designed by R G Wetten and mainly constructed 1835-7 of rubblestone with ashlar buttresses and turrets and Roman cement window surrounds, mouldings and corbels. Slate roof behind tall parapets. At risk due to deterioration of the historic fabric including the stonework and window surrounds.

© Historic England	

	AND DESCRIPTION OF THE PERSON NAMED IN
ACCUSE OF THE PARTY OF THE PART	

© Historic England

SITE NAME:	Church of St Thomas, St Thomas's Square	
DESIGNATION:	Listed Place of Worship grade I, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1034494	

Large church standing in central square. It was rebuilt on the site of an earlier church in 1854-6 by the architect SW Dawkes. Previous Historic England/National Lottery Heritage Fund grant-aided repairs to the stonework, windows and roofs to the lady chapel, north aisle, upper tower stonework, chancel, vestry and south chapel. Further repairs to south aisle including re-pointing and works to the roof and windows carried out in 2022 but stonework repairs to tower required.

Contact: Robert Williams 0207 973 3641

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

**ABBREVIATIONS** 

LIST ENTRY NUMBER:



© Historic England

© Historic England

SITE NAME:	Church of St Mary, Church Road, Cowes
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1222748

Large church adjacent to Northwood Park. The west tower was designed by John Nash in 1816 and the rest of the church was rebuilt in 1867. Built of stone with colour banded slate roof. Historic England/National Lottery Heritage Fund grant-aided repairs to tower and north roof slopes but further repairs needed including to the south nave and aisle roofs, rainwater disposal, and addressing structural movement to south west corner, which is currently being monitored.

Contact: Robert Williams 0207 973 3641



SITE NAME: Church of St James, East Cowes DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1222746

A C19 church by local Isle of Wight architect T Hellyer. Constructed in Romanesque style of stone rubble with slated roof. Incorporates tower of earlier 1830s church by John Nash. Nash is buried in the church yard. Repairs, including to the rainwater goods and south transept rose window, have been completed but further works are required to address the structural problems to the north vestry.

Contact: Robert Williams 0207 973 3641



Church of All Saints, Church SITE NAME: Hill, Godshill Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1209229

Mainly dating from the C14 with an unusual plan of double nave and arcade continuous to chancel. Early C16 south transept with crucifixion wall painting of similar date. Historic England/National Lottery Heritage Fund grantaided repairs to rainwater goods, drainage and south west corner, including west window to south nave, have been successfully completed. Further repairs required to the stonework.

Contact: Robert Williams 0207 973 3641

© Historic England

© Historic England

SITE NAME:	St Mary's Roman Catholic Church, High Street, Ryde
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1216915

Town centre church on compact site designed by Joseph Hansom in the Gothic style. It was mainly built 1846-8 of rubble limestone with unusual angular pantile roofs. Listed Places of Worship Roof Repair Fund grant aided repairs to the roofs and Covid 19 Emergency Grant funded report on internal decorative scheme, but conservation work to this is reauired.

Contact: Robert Williams 0207 973 3641



The same of		
0.11	oric Englan	

SITE NAME:	Church of St John, Carter Street, Sandown
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1034282

A Victorian church in the Early English style; by the architect CL Luck. Walls of soft local stone, roof has concrete tiles. Nave and chancel, south aisle with south porch. Shingled spirelet. The main problem is the eroding stonework but also the roof over the clergy vestry leaks and there has been a partial collapse of the ceiling. A programme of repairs is required to address these issues.

Contact: Robert Williams 0207 973 3641

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Saviour's on the Cliff, Queen's Road, Shanklin
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1212831

Victorian church by Thomas Hellyer in the Early English style. Built of soft local limestone with tiled roof. The principal problem is the condition of the stonework which is badly spalled all over. The church is in a coastal location. The windows at the west end are very fragile and are protected with Perspex to prevent them from being blown out. Some repairs have been carried out, but more are required. In February 2021 the hall roof suffered storm damage.

Contact: Robert Williams 0207 973 3641

© Historic England

© Historic England



SITE NAME:	Church of St Paul's, Regent Street, Shanklin
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1212881

Town centre church designed by CL Luck 1875-90, with west porch added 1911. Built of local Greensand stone with tiled roofs and slender tower with timber framed top storey and shingled roof. At risk due to timber decay to top of tower, decaying stonework, bulging window glazing, and slipped and missing shingles. Phase One repairs to the main roofs, rainwater goods and high level stonework were successfully completed in 2016 with the help of a grant from Historic England/National Lottery Heritage Fund. Further phases of repair are now required.

Contact: Robert Williams 0207 973 3641



SITE NAME:

Holy Trinity Church, Trinity Road, Ventnor

DESIGNATION:

Listed Place of Worship grade II\*, CA

CONDITION:

Poor

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER:

1343326

Victorian church in the Early English style by the architect CE Giles. Nave, aisles and chancel with slender tower and spire at the south east corner. Built of soft local stone with concrete tiles on the roof. The main problem is the soft stone work which continues to decay. Some repairs have been carried out to the tower.

© Historic England

Contact: Robert Williams 0207 973 3641

SITE NAME:	Medieval settlement 100m south east and 350m north east of East Ashey Manor Farm, Brading / Havenstreet and Ashey			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015622	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Two bowl barrows 110m north-east of Heatherdov	wn, Totland		
SITE NAME: DESIGNATION:	Two bowl barrows 110m north-east of Heatherdox Scheduled Monument	wn, Totland	1010619	
		•	1010619 Declining	
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:		

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Swainston
DESIGNATION:	Registered Park and Garden grade II, 3 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000930

Mid-late C18 woodland garden, set in parkland, with intersecting avenues and water features incorporating earlier fishponds from a Bishopric manor, now a hotel, Remnant garden features lie in several ownerships and woodland compartments. Where parkland has been converted to arable land or and light industrial use loss of historic character and designed landscape intentions has occured. The southern portion of the estate, including a temple, is separated from the core by a road. A joint approach to further action research has been recommended as part of a parkland plan process in 2020.

Contact: Kay Richardson 0207 973 3647



© Historic England

SITE NAME:	Norris Castle, East Cowes			
DESIGNATION:	Registered Park and Garden grade I, 12 LBs, part in RPG grade II*, part in CA			
CONDITION:	Generally unsatisfactory with major localised problems			
VULNERABILITY:	High			
TREND:	Declining			
NEW ENTRY?:	No			
OWNER TYPE:	Commercial company			
LIST ENTRY NUMBER:	1000927			

Norris is an exemplar marine villa with castellated model farm/walled garden from 1799 by James Wyatt for Lord Seymour as part of the early villa development on this coast. A single phase, intimate designed landscape that appropriates the topography and commanding views, the historical completeness of its parkland architecture survives mostly intact. Benign decay allowed the parkland features to survive relative to historic structure and design intent whilst their condition slowly declined due to lack of management. Sold in 2015 and with major development proposals its future is uncertain.

Contact: Kay Richardson 0207 973 3647

SITE NAME:	Brading		
DESIGNATION:	Conservation Area, 52 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (LPA) 01983 823552
SITE NAME:	Carisbrooke, Newport		
DESIGNATION:	Conservation Area, 37 LBs, 3 SMs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (LPA) 01983 823552
SITE NAME:	Cowes		
DESIGNATION:	Conservation Area, 73 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (LPA) 01983 823552
SITE NAME:	Godshill		
DESIGNATION:	Conservation Area, 37 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (LPA) 01983 823552
SITE NAME:	Newport		
DESIGNATION:	Conservation Area, 194 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (01983) 823552

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Ryde		
DESIGNATION:	Conservation Area, 310 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (01983) 823552
SITE NAME:	Sandown		
SITE NAME:  DESIGNATION:	Sandown Conservation Area	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No Deteriorating
DESIGNATION:	Conservation Area		

#### KENT

#### **ASHFORD**



SITE NAME: Palace Farmhouse, Market Place, Charing DESIGNATION: Listed Building grade I, SM, CA CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1070756

The present farmhouse forms part of the north range of the former manor house of the Archbishops of Canterbury and includes part of the former chapel. The top floor is inaccessible and unoccupied. An options appraisal for the whole site has been carried out by Ashford Borough Council with funding from Historic England.

LIST ENTRY NUMBER: © Historic England

Contact: David John 0207 973 3638



© Historic England

SITE NAME: Remains of Archbishops Palace, Market Place, Charing Scheduled Monument and Listed DESIGNATION: Buildings - 2 grade I; I grade II, 2 LBs, CĂ CONDITION: Very bad OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: A(A)

OWNER TYPE: Private 1011028 and 1185861; LIST ENTRY NUMBER: 1186008; 1362627

Remains of palace built in C13 and C14. Farm complex converted from remains includes barn (east range of palace courtyard) and outhouse (west range). The outhouse requires substantial maintenance repairs. Grant aided emergency works to north end of the barn have been carried out. An options appraisal for the whole site has been carried out by Ashford Borough Council with funding from Historic England. A further stage of repairs is being considered.

Contact: David John 0207 973 3638



© Historic England

SITE NAME: Ruins of Church of St Mary, Pluckley Road, Little Chart Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C(C)OWNER TYPE: Local authority

1004208 and 1329709

Possibly C13 church with tower built around 1500. Damaged during WWII by a VI flying bomb. Now ruinous but with tower still standing to c. I5m. High level stonework requires inspection, and the considerable growth of ivy and other vegetation needs controlling. The grounds are well maintained and the site is open to the public. Vegetation clearance has been discussed with the owners.

Contact: David John 0207 973 3638

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME: Late medieval threshing barn, Mersham Manor, Church Road, Mersham

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A (C)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1233497

A late medieval barn that has for some time been suffering from water ingress and structural movement. Its roof tiles were removed without Listed Building Consent and replaced with protective sheeting which is now failing. Historic England is working with the Local Planning Authority and owners to secure the barn's long-term future.

Contact: Alice Brockway 0207 973 3655

SITE NAME:	Castle Toll Saxon burgh and medieval fort, Newenden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013041
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### **CANTERBURY**



© Historic England

TE NAME:	Monuments in the precinct of Canterbury Cathedral, The Precinct, Canterbury

Scheduled Monument and Listed DESIGNATION: Buildings - 2 grade I; I grade II\*, 22 LBs, CA, WHS

CONDITION: Very bad

N/A OCCUPANCY: PRIORITY CATEGORY:

B (B) OWNER TYPE: Religious organisation

1004195 and 1253715; LIST ENTRY NUMBER 1085082; 1085079

Medieval ruinous structures of Christchurch Priory, which have suffered from years of decline. Major backlog of repairs; work has started with Historic England grant to Llanfrancs dormitory and the city wall. Slow progress is being made. Detailed evaluation of the various assets is being carried out in order to decide priorities.

Contact: David John 0207 973 3638



© Historic England

SITE NAME: Greyfriars Monastery, Stour Street, Canterbury

Scheduled Monument and Listed DESIGNATION: Building grade I, 2 LBs, CA

CONDITION: Very bad

OCCUPANCY: N/A PRIORITY CATEGORY: A(A)

OWNER TYPE: Other not for profit group

LIST ENTRY NUMBER: 1005195 and 1242684

Boundary walls from Tudor house built on site of the friary and one part of the friary church. Friary built in 1267. At risk from deterioration and development pressures.



© Historic England

SITE NAME: Dovecote at Burnt House Farm, Chartham Scheduled Monument, LB grade DESIGNATION: II, CA CONDITION: Poor OCCUPANCY: Vacant/not in use

1018874

PRIORITY CATEGORY: B (B) OWNER TYPE: Private

Cleverly designed dovecote of three storeys built into a slope and dated to C18. Original design saw pigs kept on ground floor providing heating for poultry on middle floor and doves on third floor. In need of repair. New owner plans to undertake repairs as part of proposals for future low key use. Repairs carried out to the roof and doors. Further repairs required to the flooring and other features.

Contact: David John 0207 973 3638

Contact: David John 0207 973 3638

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument

Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Horton Manor Cha Chartham	apel, Horton
	6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

Scheduled Monument and Listed Building grade II

CONDITION: Poor

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: F (F)

OWNER TYPE:

Private LIST ENTRY NUMBER: 1005150 and 1085714 Two cell C14 chapel, now roofless. Planning Permission and Scheduled Monument Consent for the conversion of the oast houses to residential use have been granted and the works completed.

Contact: Paul Roberts 0207 973 3636



© Historic England Archive

SITE NAME:	Barn at Hardres Court, Upper Hardres
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Private

LIST ENTRY NUMBER: 1085505

Late CI5 to early CI6 aisled timber barn. Damaged by fire in 1993. It would suit a variety of different forms of re-use which retain its characteristic open volume and leave exposed its impressive structural timbers.

Contact: Alice Brockway 0207 973 3655



© Historic England

SITE NAME:	Church of St Bartholomew, King Edward Avenue, Herne Bay
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1084977

Early C20 church in Gothic style built to serve expanding population. Substantial church with yellow brick and terracotta detailing. Has some defective tiling especially to the south aisle roof and generally poor condition of guttering and downpipes around the building. There is evidence of water ingress with blown plaster to south aisle at high level and within the chancel at the north east corner. Deterioration of external brick work particularly on north side. South porch showing further signs of water

Contact: David John 0207 973 3638




© Historic England

SITE NAME:	Church of St Mary the Virgin, Church Lane, Chislet
DESIGNATION:	Listed Place of Worship grade I, $CA$
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1085653

Church with Norman nave and tower and later C13 chancel and aisles. Cement render on both north and south sides is defective and coming away. Coursed rubble walls contain loose material particularly on south side and deterioration of quoins to south side of tower. Substantial ivy coverage to east end. Hoppers need unblocking and some guttering on north side is failing. The building has been the victim of heritage crime.





© Historic England

SITE NAME:	Church of St Martin, Herne Street, Herne, Herne and Broomfield
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1084972

A large church, predominantly of the C14, but with substantial C19 restoration. Roof tiles have slipped and there are other roof defects and rainwater goods are blocked and leaking. Also, there are issues with internal plasterwork. The building has been the victim of heritage crime. Several phases of repairs to the tower, chancel roof and west front, funded by the National Lottery Heritage Fund Grants for Places of Worship and others have now been completed.

Contact: David John 0207 973 3638

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Enclosures wes	t of Woodlands, Adisham		
DESIGNATION:	Scheduled Mon	ument, part in CA	LIST ENTRY NUMBER:	1004191
CONDITION:	Extensive signifi	cant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughin	g	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Rubury Butts b	owl barrows, Womenswold / Nonin	gton	
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1427315
CONDITION:	Extensive signifi	cant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grov	wth	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Maria Buczak 0207 973 3642
DARTFORD				
SITE NAME:	Palaeolithic site	s near Baker's Hole		
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1003557
CONDITION:	Generally unsat problems	Generally unsatisfactory with major localised problems		Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth		NEW ENTRY?:	No
OWNER TYPE:	Commercial co	Commercial company		Alison McQuaid 0207 973 3646
SITE NAME:	Roman enclosu	re south east of Vagniacae, Southflee	et	
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1004226
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughin	Arable ploughing		No
OWNER TYPE:	Private			Alison McQuaid 0207 973 3646
SITE NAME:	Springhead Ror	nan site, Southfleet		
DESIGNATION:	Scheduled Mon	ument	LIST ENTRY NUMBER:	1005140
CONDITION:	Extensive signifi	cant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughin	Arable ploughing		No
OWNER TYPE:	Private, multiple owners		CONTACT:	Alison McQuaid 0207 973 3646
DOVER				
	SITE NAME:	Ruins of St James' Church, Dover	building but resto	church in public park, originally a Norma ored in the C19. The church was virtuall
	DESIGNATION:	Scheduled Monument, LB grade II, part in CA	kept as a comme Dover. Emergen	Second World War. The ruins have be emorative monument to the people of cy propping of some elements have bee
CO TO THE PARTY OF	CONDITION:	Poor	carried out by D	over District Council. A condition repo



@ Historic	Fnσ	land

SITE NAME:	Dover
DESIGNATION:	Scheduled Monument, LB grade II, part in CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1005151

has been published. Repairs are underway to the stonework.

Contact: David John 0207 973 3638

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



© Historic England

SITE NAME:	The Western Heights fortifications, Dover
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, part in CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)

OWNER TYPE Mixed, multiple owners

LIST ENTRY NUMBER: 1020298 and 1375598: 1375599

The fortifications of the Western Heights are a spectacular complex of earthworks and structures that are the largest and most elaborate example of 19th century fortification in England. Various issues contribute to risk, including fragmented ownership and lack of co-ordinated management; poor condition leading to a huge conservation deficit; lack of sustainable uses; poor connectivity to town centre; poor visitor infrastructure; poor permeability and way finding; unmanaged vegetation that obscures historic form and views; and heritage crime.

1860s polygonal-plan fort now part of a later barracks. The earth-covered terraced casemates are vacant and the structures on the ramparts (the brick-built Haxo

casemates) have been at risk from lack of maintenance and invasive ivy growth. The site is owned by The Land Trust which is working on plans for its sustainable future. Substantial progress for brick work repair and vegetation control was made using Homes and Community Agency funds. Further vegetation works and conversion of the

Contact: Paul Roberts 0207 973 3636



© Historic England Archive

SITE NAME:	Fort Burgoyne, Connaught Barracks, Guston / Dover
DESIGNATION:	Scheduled Monument
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Charity (non-heritage)
LIST ENTRY NUMBER:	1004224

former Officers Stables has also been undertaken. Contact: Liam Delaney



© Historic England Archive

SITE NAME:	St Radegunds Abbey, Abbey Road, Hougham Without
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II*; I grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

C13 monastic site with standing remains of the church and claustral buildings. Heavily overgrown and fabric in a ruinous state. The site is now a farm with roofed buildings used as barns and a farmhouse. These are in fair condition. Recent negotiations have looked at consolidation of the ruins and explore funding streams and options.

1005196 and 1070023; LIST ENTRY NUMBER: 1068889; 1356562; 1363382 Contact: David John 0207 973 3638



© Historic England Archive

SITE NAME:	The Belvedere, Waldershare Park, Shepherdswell with Coldred
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1051607

Belvedere, 1725 to 1770, probably by Colen Campbell for Sir Henry Furnese. Located at the southern end of the western side of an early C18 Wilderness and overlooking the park to the north and south. Derelict for many years and now in a ruinous state. Temporary scaffolding and a protective canopy have been completed with grant aid from Historic England.

Contact: Alice Brockway 0207 973 3655



© Historic England

SITE NAME:	Church of St Martin, Church Hill, Great Mongeham
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1069782

Church built of flint dating from C12 and later restored by Butterfield in C19. Kentish ragstone window tracery and surrounds and quoins are deteriorating throughout the building. Investigation work looking at guttering and hoppers has been completed. Ground level water disposal is poor and is encouraging plant growth. Possible structural movement at north east corner of north aisle. Slipped tower louvres and vegetative growth on tower and north aisle roof.

Contact: David John 0207 973 3638

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© Diocese of Canterbury

SITE NAME:	Church of St Margaret, High Street, St. Margaret's At Cliffe
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

Church of c I I 50 rebuilding of earlier building with late C I 2 tower. Restored in the C I 8 and I 864 by Ewan Christian. Flint and rubble with red brick dressings and slate roof, with plain tiled roof to south side. Two stage west tower largely rebuilt; chancel, nave and aisles and north porch. Some water ingress, stone repairs and repointing required. Also, some repairs to the west door roof and other areas requiring attention.

Contact: David John 0207 973 3638

	SITE NAME:	Church of St Mary, Canterbury Road, Wingham
	DESIGNATION:	Listed Place of Worship grade I, CA
	CONDITION:	Poor
	PRIORITY CATEGORY:	C (C)
	OWNER TYPE:	Religious organisation

1101743

Church dating to c1200 with C13 chancel, C14 tower and C16 nave and aisle. Restored 1874-5 by Benjamin Ferrey, particularly the chancel. Some repairs have been carried out to the tower gutter and stair turret. Further repairs are needed including stone work around the church, gutters and soakaways, and the bases of the timber arcade columns are rotting.

LIST ENTRY NUMBER: | 107009 | Contact: David John 0207 973 3638

SITE NAME:	Great Mongeham Anglo-Saxon cemetery, G	Great Mongeham / Sutton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003124
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Ring ditch and enclosure 200yds (180m) east of Parsonage Farm, Preston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003121
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	London Road, Dover, Dover		
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	G Simone Senior Heritage Officer (LPA) 01304 872480
SITE NAME:	Mongeham Road, Great Mongeham, Great	Mongeham	
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	G Simone Senior Heritage Officer (LPA) 01304 872480
SITE NAME:	Western Heights, Dover, Dover		
DESIGNATION:	Conservation Area, 2 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	G Simone Senior Heritage Officer
			(LPA) 01304 872480

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park

NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

#### FOLKESTONE AND HYTHE



© Historic England

The Leas Lift, including Waiting Rooms, Brake Houses and Railings, the Leas, Folkestone

DESIGNATION: Listed Building grade II\*, CA

condition: Poor

OCCUPANCY: Part occupied/part in use
PRIORITY CATEGORY: C (C)

PRIORITY CATEGORY: C (C)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1061185

The Listed grade II\* Leas Lift, a cliff funicular railway built in 1885 to transport people between The Leas, the beach and promenade. It is not operational and a trust has been formed to carry out repairs to bring it back into use. Historic England is working closely with the trust as they develop their proposal and seek funding to carry out the

Contact: Alice Brockway 0207 973 3655



© Historic England

SITE NAME: Martello Tower No. 4, The Leas, Folkestone

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

Private

1019148

not agreed and repair of fabric and removal of obscuring vegetation is necessary.

A good example of a Martello tower but now derelict and

situated in the grounds of a private house. Tower is used in

part for an art installation but a long term sustainable use is

Contact: Rebecca Lambert 0207 973 3630



© Historic England

SITE NAME:

Dymchurch Redoubt, Hythe Ranges, Hythe

DESIGNATION:

Scheduled Monument

CONDITION:

Poor

OCCUPANCY:

Part occupied/part in use

PRIORITY CATEGORY:

E (E)

OWNER TYPE:

Government or agency

The original fort of 1806 is a massive brick circular structure within a dry moat, and has C20 additions. Located on Ministry of Defence ranges, some parts have been brought back into use as a military training facility. There is brickwork deterioration to both the original fort and later additions. A Conservation Management Plan was prepared in 2005. Phased repairs are in progress. There is continuing erosion from the seaward side of the fort.

LIST ENTRY NUMBER: 1017352 Contact: David John 0207 973 3638



© Historic England

SITE NAME: Martello Tower No. 5, Sandgate

DESIGNATION: Scheduled Monument, part in
CA

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: E (E)

PRIORITY CATEGORY: E (E)

OWNER TYPE: Educational (state sector)

LIST ENTRY NUMBER: 1017172

Martello tower situated in the grounds of a school and vacant but with potential for re-use by the school. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.



© Historic England

Martello Tower no 6,
Shorncliffe Camp, Sandgate

DESIGNATION: Scheduled Monument and Listed Building grade II, part in CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (D)

OWNER TYPE: Private

1017173 and 1068919

A Martello tower sold by the Ministry of Defence to a private owner who proposed a repair and conversion scheme, including residential use. Permissions now lapsed with no works having started, including for agreed enabling development. Alternative solution under a different owner now under discussion.

Contact: Rebecca Lambert 0207 973 3630

Contact: David John 0207 973 3638

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

Marian Marian	
Salley Salley	o-
	05
	ME.
See	Si mile
	1
<b>一种</b>	1
	35
<b>被国际</b> 国际中心。 网络拉尔巴克	
<b>《中国》</b>	
<b>建设工程</b>	100
	NE .
	8

© Historic England Archive

SITE NAME:	Martello Tower no 7, Shorncliffe Camp, Sandgate
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)

Private

A Martello tower sold by the Ministry of Defence to a private owner who proposed a repair and conversion scheme, including residential use. Permissions now lapsed with no works having started, including for agreed enabling development. Alternative solution under a different owner now under discussion.

Contact: Rebecca Lambert 0207 973 3630



© Historic England

SITE NAME:	Martello Tower No. 9, Shorncliffe Camp, Sandgate / Hythe
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

1017174 and 1068920

OWNER TYPE: Private

LIST ENTRY NUMBER: 1017226 and 1061167

archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.

Martello tower, 1806. Derelict, disposed by Ministry of Defence to private owner. The preservation of

Contact: Rebecca Lambert 0207 973 3630



SITE NAME:	Church of St James, Elmsted
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1241752

Church with origins in the CII, but of multiple subsequent phases. Although some repairs have been undertaken recently, including an overhaul of the roofs and internal redecoration, there are corroding rainwater goods, blocked hoppers and gullies, and vegetation growth. The building has been the victim of heritage crime.

Contact: David John 0207 973 3638



SITE NAME:	Church of St Mary, Stowting
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1061070

Church of C13. Chancel restored 1843-4 by Carpenter, rest 1876 and 1890. North aisle and tower added 1857-68 by Slater. Flint with stone dressings. Plain tile roof. Nave, south porch, chancel with north lean-to, north aisle with west tower. The roof is in poor condition and reason for inclusion in the Register.

Contact: David John 0207 973 3638

SITE NAME:	Roman villa, Folkestone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005158
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area s LB Listed Building c, LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME: Motte and Bailey Castle 200m north west of Stowting Church, Stowting  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  OWNER TYPE: Private  Motte and Bailey Castle 200m north west of Stowting Church, Stowting  LIST ENTRY NUMBER: 1012099  Declining  NEW ENTRY?: No  Alison McOuaid			
CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  New Entry:  No			
PRINCIPAL VULNERABILITY: Animal burrowing - extensive New entry?: No			
OWNER TYPE: Private CONTACT: Alison McQuaid			
7 Misori requald	0207 973 3646		
Bowl barrow 150m north east of Red House Farm, Swingfield	Bowl barrow 150m north east of Red House Farm, Swingfield		
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011765			
CONDITION: Extensive significant problems TREND: Declining			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No			
OWNER TYPE: Mixed, multiple owners CONTACT: Alison McQuaid	0207 973 3646		
Bowl barrow at Minnis Beeches, Swingfield			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER:  0  766			
CONDITION: Extensive significant problems TREND: Declining			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No			
OWNER TYPE: Mixed, multiple owners CONTACT: Alison McQuaid	0207 973 3646		

#### **MAIDSTONE**



II, Lower Stone Street, SITE NAME: Maidstone DESIGNATION: Listed Building grade II\* CONDITION: Fair OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company

A large early C18 house of three storeys. Some repairs and redecoration have been carried out in recent years and it is now partly occupied, but it continues to suffer from a lack of appropriate regular maintenance.

LIST ENTRY NUMBER: 1086332 Contact: Alice Brockway 0207 973 3655 © Historic England



© Historic England

SITE NAME: The Dungeons at the Archbishop's Palace, Mill Street, Maidstone DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

Partially ruined stone building of medieval date. Previous alterations and lack of repair are contributing to structural problems. Early discussions with the owners about repairs have taken place.

LIST ENTRY NUMBER: 1086309 Contact: David John 0207 973 3638



© Historic England

SITE NAME: Boxley Abbey: Barn and Precinct Walls, including Gatehouse, Boxley, Boxley Scheduled Monument and Listed DESIGNATION: Building grade I, 2 LBs CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C(C)

Private, multiple owners

Parts of a Cistercian abbey founded in 1143. Main threat is to a medieval roofed range converted to a barn, but which now has other uses. Eastern end of barn repaired; western end requires repairs but now has a temporary roof of profiled steel sheeting. The extensive precinct walls are also in need of repair and maintenance with collapsed sections and heavy plant growth. Discussions are ongoing with the owner and a scheme to address the walls is in preparation.

LIST ENTRY NUMBER: Contact: Liz Pollard 0207 973 3650 1012264 and 1086229

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

OWNER TYPE:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Former St Andrews Chapel, Boarley Lane, Boxley Abbey, Boxley
DESIGNATION:	Listed Building grade II*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (C)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1185580

Former late C15 chapel, no longer used for worship, but converted to a house early on in its history. Unoccupied and in need of repair. Location affected by proximity of motorway. Purchased by the Society for the Protection of Ancient Buildings as an exemplar in sensitive conservative repair and craft skills training. Improved security, temporary propping, structural monitoring, ground clearance and survey work carried out. A scheme for the repair of the building is underway with financial support from the Architectural Heritage Fund, The Pilgrim Trust and Historic England.

Contact: Liz Pollard 0207 973 3650



© Historic England Archive

SITE NAME:	Dovecotes at Leeds Priory, Lower Street, Leeds
DESIGNATION:	Scheduled Monument and Listed Buildings - 4 grade II, 4 LBs
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1011027 and 1185691; LIST ENTRY NUMBER: 1336305; 1086132; 1344275

Mid C16, overgrown and roofless dovecotes from a post-Dissolution mansion. The building is at risk from serious structural decay and extensive damaging vegetation growth. Possible proposal for enabling development.

Contact: Rebecca Lambert 0207 973 3630

Contact: Rebecca Lambert 0207 973 3630



© Historic England Archive

SITE NAME:	Slype and associated remains at Leeds Priory, Lower Street, Leeds
DESIGNATION:	Scheduled Monument and Listed Buildings - 4 grade II, 4 LBs
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1011027 and 1185691;

1336305; 1086132; 1344275

LIST ENTRY NUMBER:

brickwork additions and attached walls. It was potentially related to monastic water management. Formerly known as "The Abbey" and more recently as "The Slype". The buildings are at risk of serious structural decay and extensive damaging vegetation growth.

The remains of a medieval building with post-medieval



© Historic England

SITE NAME:	Church of All Saints, Mill Street, Maidstone
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1225056

Large Perpendicular church of the late C14. Extensive highlevel vegetation and erosion of stonework. Blocked and damaged rainwater goods and drains have resulted in water ingress and internal dampness. Wall paintings in chancel are also suffering damage. Extensive roof repairs are necessary.

Contact: David John 0207 973 3638



© Historic England

SITE NAME:	Church of St Nicholas, Lower Street, Leeds
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1086125

Medieval church built of ragstone and tufa with a broad Romanesque tower. Roofing and stonework are in poor condition. An application to the National Lottery Heritage Fund Grants for Places of Worship scheme was unsuccessful. However, some roof repairs have taken place but more repairs, particularly to the stonework are needed.

Contact: David John 0207 973 3638

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Mary the Virgin, Thurnham Lane, Thurnham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1086165

Church of C12 to early C17. North chapel of galleted stone, porches of small uneven blocks of stone, rest random flint and stone. Plain tile roofs. West tower, continuous nave and chancel with opposed north and south porches at the west end. Rectangular north chapel towards east end of nave. Roofs over nave, chancel and chapel require replacement and east wall of the chancel is in a poor state; all contributing factors to the building's risk.

Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Leeds Priory: Augustinian Priory of St Mary and St N of the C18 Meredith Mansion, Leeds	Nicholas with asso	ciated dovecotes and slype, and the site
DESIGNATION:	Scheduled Monument and Listed Buildings - 4 grade II, 4 LBs	LIST ENTRY NUMBER:	1011027 and 1185691; 1336305; 1086132; 1344275
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Rebecca Lambert 0207 973 3630
SITE NAME:	Binbury motte and bailey castle, Thurnham		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1010713
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Elmstone Hole, Grafty Green, Boughton Malherbe		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Mike Parkinson (LPA) 01622 602335
SITE NAME:	Maidstone Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Paul Robertshaw 01622 602723

#### **SEVENOAKS**



© Historic England Archive

	Otford
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

1005197

Remains of corner tower to

Remains of gatehouse range to early C16 Archbishops Palace. Ruinous parts are in need of consolidation work.
Following Urgent Repair Works in 2017, a local community group has leased the building and is looking at options for its repair and re-use. A report and scheme have been commissioned and an initial phase of repairs have been carried out with funding from various sources.

Contact: David John 0207 973 3638

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

SITE NAME:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

## **ABBREVIATIONS** LPA

Conservation Area Listed Building Local Planning Authority National Park ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

SITE NAME:	Chapel, Maplescombe, West Kingsdown		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1005134
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646



© Historic England

SITE NAME: Combe Bank, Sundridge with Ide Hill / Brasted Registered Park and Garden DESIGNATION: grade II\*, 17 LBs CONDITION: Extensive significant problems VUI NERABILITY: High TREND: Declining NEW ENTRY?: Nο OWNER TYPE: Mixed, multiple owners

1000365

A classical landscape garden and small park surrounding a palladian villa associated with some of the greatest artistic exponents of the early pictureque movement. Sold and divided up the house and gardens becaming a school in 1924. Numerous remant built features survive in varying condition in the gardens which suffered considerable storm damage in 1987. Bissected by the M25, development proposals and fragmentation of ownership and management is a threat. A partnership project to deliver a Conservation Management Plan is required.

Contact: Kay Richardson 0207 973 3647

#### SEVENOAKS / TUNBRIDGE WELLS



© Historic England

SITE NAME:	Swaylands, Penshurst / Bidborough
DESIGNATION:	Registered Park and Garden grade II, 4 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1001280

Small landscape park with terraced gardens and pleasure grounds, including extensive rockwork developed in the late C19. Now split into several ownerships with the house converted into apartments development of residential facilities is fragmenting the park and inappropriate forms of management may precipitate loss of historic design integrity. Understanding the presentation of the lower lake and kitchen garden as part of the parkland landscape, which are in separate ownership, much neglected and subject to change through development is also imperitive to ensure appropriate stewardship.

Contact: Kay Richardson 0207 973 3647

#### **SWALE**



© Historic England

SITE NAME:	Murston Old Church, Murston, Sittingbourne
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

LIST ENTRY NUMBER: 1011768

Originally a large church with three aisles and three chancels with a square tower and wooden turret, built between 1375 and 1550; only the southern chapel remains. The rest of the church survives as buried archaeological remains. Building has been the victim to heritage crime. The owners are also looking at possible future uses for the site, including the provision of studios and a cafe in a new, separate building at the edge of the site. A grant from Historic England to carry out repairs are now nearing completion.

Contact: David John 0207 973 3638



© Historic England

SITE NAME: Former Royal Dockyard Church and attached wall and railings, Sheerness Dockyard DESIGNATION: Listed Building grade II\*, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C(C)OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1273239

Former St Paul's Parish Dockyard Church. Built in 1828, by architect George Taylor, but partially rebuilt after a fire in 1884. Empty since 1970 and severely damaged by fire in 2001. The Sheerness Dockyard Preservation Trust has planning consent to repair and convert it to a community facility and National Lottery Heritage Fund grant for this has now been secured. Work on site is progressing well, which has been partly funded by the Heritage Stimulus Fund. Repairs to the upper part of the tower have recently been completed.

Contact: David John 0207 973 3638

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### A DDDE\/IATIONIC

ARREAIN LION2		
CA	Conservation Area	
LB	Listed Building	
LPA	Local Planning Authority	
NP	National Park	
RPG	Registered Park and Garde	
SM	Scheduled Monument	
UA	Unitary Authority	
WHS	World Heritage Site	

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	The Boat Store, Sheerness Dockyard
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1273160

Boat store, built in 1859. Since the destruction of the Crystal Palace and the first South Kensington Museum, this is the earliest surviving example of a multi-storey ironframe and panel structure. Its condition is rapidly deteriorating. Discussions with the Local Planning Authority and Port Company about its repair and reuse are on-going.

Moated artillery fortifications from C17-C20. A major complex defending the dockyard. A repair programme

Contact: David John 0207 973 3638

needs to be agreed and implemented.



© Historic England Archive

SITE NAME:	Sheerness Defences, Swale
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1005145 and 1259029

Contact: David John 0207 973 3638

Contact: David John 0207 973 3638

Contact: David John 0207 973 3638



© Historic England Archive

SITE NAME:	Former Working Mast House, 26, Jetty Road, Sheerness Dockyard
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1244509

Large C19 industrial building used as part of a complex for constructing and storing masts and small boats. Used in the past for storage within the commercial port, it is now vacant.



© Historic England

SITE NAME:	Parish Church of the Holy Trinity, North Street, Milton Regis, Sittingbourne.
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1061036

HolyTrinity is a large medieval church with Saxon herringbone masonry. There are issues with damp walls and staining of plasterwork as well as slipped tiles and stonework. Some repairs have been carried out to the tower and north windows of the nave.

© Historic England

SITE NAME:	Church of St Peter, Church Road, Oare
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1069126

A predominantly Perpendicular church, much restored by Joseph Clarke in 1868. The church has had serious structural movement at its east end with disturbance to the flooring and serious cracking to the walls at the east end. This appears to have been partly resolved, but there is still evidence of movement that requires monitoring. Repairs are also required to the spire shingles.

Contact: David John 0207 973 3638

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Church of St Peter and St Paul, Water Lane, Ospringe
DESIGNATION:	Listed Place of Worship grade

 $_{\rm ON:}$  Listed Place of VVorsnip grade II\*, CA

CONDITION: Poor PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1343988

A C13 church, with later accretions, all substantially restored in 1858-70 by EL Blackburne. Despite its apparent fair condition, the north and the south side of the church is suffering from serious internal damp as a result of multiple slipped tiles, blocked rainwater goods and extensive ivy growth. There is probable structural movement in the chancel.

Contact: David John 0207 973 3638

Section 1	
The state of the s	- The State of the
THOUSE STATE	A STATE OF THE PARTY OF THE PAR
	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW
Page	S10-14-100-00-00-00-00-00-00-00-00-00-00-00-00
No. of the last of	HALL BOOK THE STATE OF
A STATE OF THE PARTY OF THE PAR	ERITE AND LOSSES
	THE REAL PROPERTY.
	E DESKONES ES DESHITO
	TO SHEET SHEET TO
	THE RESERVE OF THE PARTY OF THE
A SECTION AND SECTION	SERVICE OF MALE IN
N CONTRACTOR OF THE PARTY OF TH	MARKET WATER
	M NEWSCHOOL STATE
the superior of the same of the same	WHEN WENT PROPERTY AND PROPERTY.

SITE NAME:	Church of St Giles, Church Road, Tonge
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1322821

Originally C12 flint church with unconventional valley gutter arrangement. Structural monitoring has established that movement is generally stable. The state of the fabric has been improved. The congregation is applying for a grant to conserve the medieval wall paintings and is about to have the building re-wired.

Contact: David John 0207 973 3638

©	Н	list	or	ic	۲ı	ng	ar	nd
---	---	------	----	----	----	----	----	----

SITE NAME: Cel	llar Hill and Greenstreet, Lynsted with Kingsdown	ı / Teynham	
DESIGNATION: Col	nservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION: Poo	or	TREND:	Deteriorating
VULNERABILITY: Lov	N	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME: Mile	ton Regis High Street		
DESIGNATION: Col	nservation Area, 37 LBs	NEW ENTRY?:	No
CONDITION: Poo	or	TREND:	Deteriorating
VULNERABILITY: Me	dium	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME: Ne	wington High Street, Newington		
DESIGNATION: Col	nservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION: Poc	or	TREND:	No significant change
VULNERABILITY: Hig	rh	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME: She	eerness: Marine Town		
DESIGNATION: Col	nservation Area	NEW ENTRY?:	No
CONDITION: Fair	r	TREND:	Deteriorating
VULNERABILITY: Me	dium	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME: She	eerness: Mile Town		
DESIGNATION: Col			
	nservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION: Poo	·	NEW ENTRY?: TREND:	No Deteriorating
VULNERABILITY: Low	pr		
vulnerability: Lov	pr	TREND:	Deteriorating
VULNERABILITY: Low SITE NAME: She	or W	TREND:	Deteriorating
VULNERABILITY: Lov  SITE NAME: She  DESIGNATION: Coi	or w eerness: Royal Naval Dockyard & Bluetown	TREND: CONTACT:	Deteriorating Simon Algar (LPA) 01795 417375

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Sittingbourne High Street		
DESIGNATION:	Conservation Area, 26 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Upchurch		
SITE NAME:  DESIGNATION:	Upchurch Conservation Area, LB grade I	NEW ENTRY?:	No
	,	NEW ENTRY?: TREND:	No Deteriorating
DESIGNATION:	Conservation Area, LB grade I		

#### **THANET**



SITE NAME: Dreamland Cinema, Marine Terrace, Margate DESIGNATION: Listed Building grade II\* CONDITION: Fair OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: E (E) OWNER TYPE: Private

Cinema, 1935. The first English cinema in the style based on the Titania Palast of Berlin, a style subsequently used extensively by Odeon. The first major phases of a programme of repairs and reinstatement of architectural features are now complete. Parts are now in use for the Dreamland Park and the remainder is proposed for a variety of entertainment uses.

© Historic England



© Historic England	

SITE NAME:	The Clock House, Royal Harbour, Ramsgate
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1336325

1260315

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

The harbour clock house of 1817 designed by Benjamin Wyatt and George Louch. Altered by John Rennie. Located on the Ramsgate Meridian Line and originally designed to tell "Ramsgate time" being 5 minutes, 41 seconds ahead of Greenwich Mean Time. Partly in museum use. Covid-19 Emergency Heritage At Risk Response funding saw repairs to the roof and high level masonry (2021), although a full scheme of repairs is still required. Plans need to be developed to see the building fully repaired and brought back into a sustainable use.

Contact: Liz Pollard 0207 973 3650

Contact: Alice Brockway 0207 973 3655



© Thanet District Council

SITE NAME:	Barn about 50 metres east of Ozengell Grange, Haine Road, Ramsgate
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Late medieval grain barn on land formerly owned by St Augustine's Abbey, Canterbury. In a very bad condition with missing roof tiles and structural issues. Discussions are on-going about how repairs may be organised.

1336669

Prominent church with octagonal top to tower. Although some repairs to the upper tower and roofs, the building is at risk due to continuing problems from heritage crime, as well as external stone erosion and damage to internal plaster from water ingress.

© Historic England

SITE NAME:	Church of St George, Broad Street, Ramsgate
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1085430

Contact: David John 0207 973 3638

Contact: Alice Brockway 0207 973 3655

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise.

I PA ΝP New Entry is noted). RPG

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of St Augustine of England, St Augustine's Road, Ramsgate
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1281779

Constructed by AWN Pugin and containing his tomb. The site consists of a churchyard to the south and a cloister to the north with chapels, sacristy and ancillary accommodation. The church comprises a nave, crossing with tower and confessional, chancel, south aisle and chapel. A National Lottery Heritage Fund grant for Places of Worship addressed urgent repairs to roofs, gutters and high level masonry in 2010 with further phases in 2011, 2012 and 2013. The first phases are now complete with further repairs still required to the north range which are due to be carried out in 2022.

Contact: David John 0207 973 3638

SITE NAME:	Quex Park settlements, Birchington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005137
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Anglo-Saxon cemetery, Dane Valley Road,	Broadstairs and St. Peters	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003601
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Settlement one mile (1610m) east of village, Manston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005135
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Anglo-Saxon cemetery south of Ozengell (	Grange, Ramsgate / Manstor	n
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004228
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Ramsgate		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Josie Sinden 01843 577126

#### TONBRIDGE AND MALLING



© Historic England

SITE NAME:	Church of All Saints, Snodland
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1347897

Church with C12 origins restored and extended by Blomfield in C19. Poor stonework repairs have been carried out in the past including rendering walling stones and dressings with a cement based mortar which is failing. Areas of deeply eroded stonework and defective rainwater drainage system. High level stonework and plaster repairs have been successfully completed using funds from the National Lottery Heritage Fund Grants for Places of Worship scheme, but further phase of repairs required for the lower level stonework and drainage.

Contact: David John 0207 973 3638

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Town Banks, Tonbridge		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1003599
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Romano-British villa, Anglo-Saxon cemetery and as	ssociated remains a	t Eccles, Aylesford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011770
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Chapel of St Blaise, Offham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005488
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### **TUNBRIDGE WELLS**



SITE NAME:

Providence Chapel, Stone Street

DESIGNATION:

Listed Building grade II\*, CA

CONDITION:

Very bad

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Private

Baptist chapel, no longer used for worship. 1795 with early to mid C19 alterations. A temporary scaffold roof has been erected to limit water ingress. A feasibility study has been completed recommending its use by the community and restoration led by a potential preservation trust. The current owner is considering this option but the building's condition is rapidly worsening. Some urgent works have recently been carried out by the owner.

© Historic England Archive LIST ENTRY NUMBER: 1084808 Contact: David John 0207 973 3638

SITE NAME: Royal Tunbridge Wells

DESIGNATION: Conservation Area, 266 LBs, 2 RPGs NEW ENTRY?: No

CONDITION: At risk TREND: Improving

VULNERABILITY: Unknown CONTACT: Mark Stephenson (LPA) 01892 526121

#### KENT / EAST SUSSEX

#### **TUNBRIDGE WELLS / WEALDEN**

SITE NAME:	High Rocks Camp (see also Wealden, East Sussex), Frant		
DESIGNATION:	Scheduled Monument, SM	LIST ENTRY NUMBER:	1003816
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site




© Historic England

SITE NAME:	Bayham Abbey, Lamberhurst / Frant
DESIGNATION:	Registered Park and Garden grade II, 8 LBs, SM
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000257

Late C19 mansion gardens with formal terraces and informal pleasure grounds set within a Humphry Repton Red Book park focused on the abbey ruins, Now managed by English Heritage. Partly in East Sussex and Kent. The estate was divided in the 1970s with further fragmentation of the site since. Mixed arable conversion has impacted the landscape fabric integrity supporting the composition of the parkland. A parkland plan exists in part around Bayham Old Abbey (2012) and recommendation of a joint approach to a parkland plan process have been made through Countryside Stewardship advice.

Contact: Kay Richardson 0207 973 3647

#### KENT (OFF)



© Pascoe Archaeology Services and MSDS Marine

SITE NAME:	Northumberland, Goodwin Sands
DESIGNATION:	Protected Wreck Site, part in PWS
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1000058

Third Rate 70-gun warship built 1678 as part of Samuel Pepys' regeneration of the English navy. The first third rate ship to be built under contract, after it was realised that the naval dockyards could not cope with the construction of the number of ships requested. The warship foundered on Goodwin Sands during the 'Great Storm' of 1703. The site has experienced significant exposure due to sediment migration and associated threats. The licensee and Historic England are in the process of formulating a plan to mitigate these risks.

Contact: Hefin Meara 07879 113318



© University of St Andrews and Wessex Archaeology

SITE NAME:	Restoration, Goodwin Sands
DESIGNATION:	Protected Wreck Site, part in PWS
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1000057

Although there is no definite evidence, this wreck of a wooden warship is thought to be the remains of the Restoration, a Third Rate 70-gun warship built 1678 as part of Samuel Pepys' regeneration of the English navy. Along with the Northumberland and Stirling Castle, she foundered on Goodwin Sands during the 'Great Storm' of 1703. Site currently at its most exposed. Historic England funded project undertaken 2021 to record site and work continues.

Contact: Hefin Meara 07879 113318



© RCE

SITE NAME:	Rooswijk, towards the north eastern end of the Kellett Gut
DESIGNATION:	Protected Wreck Site
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1000085

The VOC (Dutch East Company) ship Rooswijk was built in Amsterdam in 1737 but stranded on the Goodwin Sands in 1739 while en route from the Texel to the East Indies. The site represents archaeological evidence for the practice of large-scale overseas commerce between the Netherlands and Asia during the C18. As with other sites in the Goodwins, archaeological material is at risk owing to mobile sediments causing periodic exposure. The site was not visited in 2021 and therefore the risk to the site remains 'High'

Contact: Hefin Meara 07879 113318

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument

OWNER TYPE:

LIST ENTRY NUMBER:

#### MEDWAY (UA)



© Historic England

SITE NAME: Brompton Lines, Chatham	
DESIGNATION: Scheduled Monument, part in CA	
condition: Poor	
OCCUPANCY: N/A	
PRIORITY CATEGORY: C (C)	

1003364

Charity (heritage)

Landward defences to dockyard at Chatham, subsequently used in part as a pleasure ground for officers. Defences cross Ministry of Defence owned land, housing and Brompton Barracks. Section between Sallyport and Prince of Wales bastion (including the Couvre Porte) are most in need of conservation.

Contact: Rebecca Lambert 0207 973 3630



© Historic England Archive

SITE NAME:	Fort Darnet
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1019642

A Royal Commission fort circa 1860, in the Medway Estuary. Constructed as part of the 1859 Royal Commission inspired refortification programme of the 1860s and 70s to protect Chatham dockyard. Partially flooded.

Contact: Rebecca Lambert 0207 973 3630



SITE NAME:

No. 8 machine shop, Dock Head Road, Chatham Dockyard

DESIGNATION:

Listed Building grade II\*

CONDITION:

Poor

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

C (C)

1840 former dry dock cover which was later used as a Machine Shop but is now disused. Cladding removed so the cast iron members and joints are now corroding. Applications to repair and convert it for leisure uses were approved by the Local Authority but not fully implemented. An updated application for its conversion to a retail use has not yet been determined.

© Historic England

PRIORITY CATEGORY: C (C)

OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1267822

Contact: Alice Brockway 0207 973 3655



© Historic England

SITE NAME:	351, High Street, Rochester
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company

1320136

Brewery mansion. Early C18, refronted early C19 and with C20 alterations and additions as a shop to front. Painted brick, slate roofs. Last used as a shop in 1980s the fittings for which have been removed. Later industrial buildings to the rear. Empty since closed as a shop; however a programme of repairs is underway.

Contact: Alice Brockway 0207 973 3655



© Historic England

SITE NAME:	Former Church of St John the Divine, Railway Street, Chathan
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1268218

Closed Italianate style church of 1820-21 by Sir Robert Smirke, 1863 apse by GM Hills. Plans are being developed by the Diocese of Rochester to bring this disused church back into use as a place of worship and for community use. Grant to carry out emergency works to the roof and interior rotting timber has now been completed, part funded by Historic England and the Church Commissioners. Further funding will be required to complete the works to allow the building to be brought back into use. Works are proceeding in some areas of the building.

Contact: David John 0207 973 3638

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England Archive

SITE NAME:	Cliffe Fort, Cliffe and Cliffe Woods
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

1003403

Commercial company

Fort c1860. Fort is now flooded. Much of it is stable due to massive construction, but significant detail is vulnerable to decay. The building has been the victim of heritage crime. Remains of Brennan Torpedo Rail are also vulnerable to erosion. Historic England has carried out a detailed survey. Investigation is to be carried out as to the source of the flood water.

Contact: David John 0207 973 3638

1	

© Historic England Archive

SITE NAME:	Cooling Castle, Cooling
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade I, LB grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1009018 and 1085771; 1085770

A quadrangular castle with ruined fabric, some of which is in need of major repair.

Contact: Rebecca Lambert 0207 973 3630



© Historic England

SITE NAME:	Barn 30 yards south east of the manor, Upnor Road (south side), Frindsbury Extra
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company

Medieval barn, redundant for agricultural use and subject to major fire damage. The reconstruction of fire damaged bays and a programme of repair was completed in 2019. A planning application for the partial conversion of the barn to a wedding venue was approved in 2021.

© Historic England Archive

SITE NAME:	Cockham Wood Fort, Hoo St. Werburgh
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1204320

A rare C17 artillery fort. The brick lower battery is very decayed as it is washed by the tidal Medway. The higher earthwork batteries survive but in woodland, with the remains of a redoubt and commander's house.

Sister fort to Fort Darnet circa 1860. Fort lies abandoned

DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1003362

Contact: Rebecca Lambert 0207 973 3630

on an island in the Medway.

Contact: Alice Brockway 0207 973 3655



© Historic England Archive

SITE NAME:	Fort Hoo, Hoo St. Werburgh
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1019643

Contact: Rebecca Lambert 0207 973 3630

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

Artillery Tower (Grain Tower), SITE NAME: Isle of Grain

Scheduled Monument and Listed DESIGNATION: Building grade II

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE:

LIST ENTRY NUMBER: 1019955 and 1204520

Private

Artillery tower of 1855 with C20 additions. Forms part of the defences to Sheerness dockyard. Abandoned and surrounded by the sea at high tide.

Contact: Rebecca Lambert 0207 973 3630

SITE NAME:	Gillingham Green		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Martin McKay (LPA) 01634 331721
SITE NAME:	Halling		
DESIGNATION:	Conservation Area, 4 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Martin McKay (LPA) 01634 331721
SITE NAME:	Railway Street		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Martin McKay (LPA) 01634 331721
SITE NAME:	Rainham		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Martin McKay (LPA) 01634 331721

#### MILTON KEYNES (UA)



© Bryan Martin

SITE NAME:	Church of St Peter, Gayhurst Court, Gayhurst	
DESIGNATION:	Listed Place of Worship grade I, RPG grade II	
CONDITION:	Very bad	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1211931	

Renaissance design, built in 1728 for the Wrighte family. Only the crypt remains from the previous medieval church. Limestone with grey rusticated plinth with yellow ashlar above. Interior: ashlar stone above panelled dado, plaster ceilings. Nave walls of 5 bays with Corinthian pilasters. Two-stage west tower, arcaded cupola and ogee domed roof. Water penetrating cupola and tower resulting in timber decay of the structure. An application for a National Lottery Heritage Fund Grants for Places of Worship in 2017 was unsuccessful but these structural repair works remain urgent.

Contact: Rachel James 0207 973 3153

SITE NAME:	Roman town of Magiovinium and Roman fort, Bletchley and Fenny Stratford		
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1006943		
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	, ,		
SITE NAME:	St Martin's Chapel (site of), Emberton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021373
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Moated site 70m south of Long Plantation, Hanslope Park, Hanslope		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011303
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Moated site 410m south east of Maukins, Hardmead		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018726
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Wolverton, Wolverton and Greenleys / Stantonbury		
DESIGNATION:	Conservation Area, 17 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Simon Peart (LPA) 01908 252613

#### **OXFORDSHIRE**

#### **CHERWELL**



SITE NAME: Ruins of Hampton Gay Manor House, Hampton Gay and Poyle Scheduled Monument and Listed DESIGNATION: Building grade II, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Private

Ruins of late C16 manor house which burnt down in 1887. The ruin is in very poor condition, suffering from structural problems and with substantial vegetation growth. A programme of consolidation works is being developed. Implementation and management as a ruin is required.

© Historic England

LIST ENTRY NUMBER: 1006334 and 1220230

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME:	Defence and ancillary structures at RAF Bicester, Bicester, Launton
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1021455

The most complete and strongly representative example of an RAF airbase from the interwar expansion, built as a bomber station as part of the 1920s Home Defence Expansion Scheme. In 2016 and 2018 grant aided repairs to scheduled airfield structures were completed and further repairs to the Watch Office have been completed with the benefit of the Covid-19 Emergency Heritage at Risk Response Scheme. Repairs are required to the Southern bomb stores and use for it identified.

Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

© Historic England

SITE NAME:	Church of St Mary, Horse Fair, Banbury
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation

1369519

St Mary's Church Banbury is a late C18 classical church with a distinctive tower by S P Cockerell with additions by C R Cockerell 1818-22. Listed Places of Worship Roof Repairs Grant in 2015 implemented in early 2016. Urgent repairs to the east end funded by the National Lottery Heritage Fund Grant for Places of Worship have been completed. 2021 Covid 19 Recovery Fund Grant has been used to address problems with the rainwater goods. Further funding for high level stone repairs is still required.

Contact: Rachel James 0207 973 3153

Annual Control of the last of
EAST-ROSSER
A STATE OF THE PARTY OF THE PAR
CHARLES AND ADDRESS OF THE PARTY OF THE PART

SITE NAME:	Church of St Lawrence, Caversfield
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1046533

Saxon, possibly C10, base to the west tower and bell stage rebuilt in the C13 with a saddleback roof covered in plain clay tiles. Late C12 rebuilding of the chancel and nave; the chancel being remodelled in the C13. Henry Woodyer, in 1874, rebuilt the aisles, restored the chancel and added the north vestry. The nave and aisle roofs are very steep; covered in thin, stone slates. Water ingress occurring and repairs are needed. An application to the National Lottery Heritage Fund Grants for Places of Worship scheme in 2017 was unsuccessful.

Contact: Rachel James 0207 973 3153

Ilbury Camp hillfort, Deddington		
Scheduled Monument	LIST ENTRY NUMBER:	1015167
Generally satisfactory but with significant localised problems	TREND:	Declining
Animal burrowing - Badger - localised/limited	NEW ENTRY?:	No
Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
Islip Roman villa, 300m east of Hillside Farm, Islip		
Scheduled Monument	LIST ENTRY NUMBER:	1015161
Extensive significant problems	TREND:	Declining
Arable ploughing	NEW ENTRY?:	No
Private	CONTACT:	Alison McQuaid 0207 973 3646
Banbury Grimsbury, North Oxfordshire, Banbury		
Conservation Area, 2 LBs	NEW ENTRY?:	No
Very bad	TREND:	Deteriorating significantly
Low	CONTACT:	Emma Harrison 01295 221846
RAF Upper Heyford, Upper Heyford, Ardley, Upper Heyford / Ardley / Somerton		
Conservation Area, 5 LBs, part in SM	NEW ENTRY?:	No
Very bad	TREND:	Deteriorating
Medium	CONTACT:	Emma Harrison 01295 221846
	Scheduled Monument  Generally satisfactory but with significant localised problems  Animal burrowing - Badger - localised/limited  Private, multiple owners  Islip Roman villa, 300m east of Hillside Farm, Islip Scheduled Monument  Extensive significant problems  Arable ploughing  Private  Banbury Grimsbury, North Oxfordshire, Banbury  Conservation Area, 2 LBs  Very bad  Low  RAF Upper Heyford, Upper Heyford, Ardley, Upper  Conservation Area, 5 LBs, part in SM  Very bad	Scheduled Monument  Generally satisfactory but with significant localised problems  Animal burrowing - Badger - localised/limited Private, multiple owners  CONTACT:  Islip Roman villa, 300m east of Hillside Farm, Islip Scheduled Monument  Extensive significant problems  Arable ploughing Private  CONTACT:  Banbury Grimsbury, North Oxfordshire, Banbury  Conservation Area, 2 LBs  Very bad  Low  CONTACT:  RAF Upper Heyford, Upper Heyford, Ardley, Upper Heyford / Ardley Conservation Area, 5 LBs, part in SM  NEW ENTRY?:  TREND:  TREND:

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

#### **OXFORD**



© Historic England

Church Of The Holy Family,
Blackbird Leys

DESIGNATION: Listed Place of Worship grade II

CONDITION: Very bad PRIORITY CATEGORY: A (A)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | 14645|3

Innovative church designed by Colin Shewring 1964-5, with a timber hyperbolic paraboloid roof designed by the engineer Hugh Tottenham. It comprises a spacious heart-shaped worship space with sacristy, small square campanile, narthex and toilets. The timber boarded roof was originally covered in aluminium sheet which was later replaced with a membrane: this now leaks leading to localised failure of the main roof structure. There are proposals to demolish the church and re-develop the site.

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME:

Church of St Thomas the Martyr, St Thomas Street, Oxford

DESIGNATION:

Listed Place of Worship grade II

CONDITION:

Poor

PRIORITY CATEGORY: A (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1047122

Church with chancel dating to late C12 and C15-16 nave, west tower and north chapel. Roof covering is in poor condition though structurally sound overall. The rainwater goods are generally adequate apart from one gutter, and the stonework is fair to poor. The church applied for a Listed Places of Worship Roof Repair Fund grant but was not successful. The repair of the roof coverings is still required.

Contact: Rachel James 0207 973 3153

#### SOUTH OXFORDSHIRE



SITE NAME:	Well house, Wick Farmhouse, Barton, Beckley and Stowood
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1047637

Well house associated with Wick Farmhouse, late C17, in poor condition and not in use. Square plan ashlar structure in Baroque style with stone benches lining walls. Well now filled in. Historic England has been in discussion with the owner regarding maintenance and conservation repairs. We understand that quotations for the work were obtained. The structure sits within a larger unused farmyard which forms part of larger planning discussions.

Contact: Rachel James 0207 973 3153

© Historic England

© Historic England

SITE NAME:	Walled garden approximately 30 metres west of Manor Farmhouse, North Weston, Great Haseley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)

Private

1369269

Walled garden with loggia, dating from early C18. Built of brick with limestone ashlar details and a plain tile roof to the loggia. The wall has a moulded brick coping. It was formerly part of the North Weston Manor which was largely demolished in the early C19. The wall tops are disintegrating; there are structural cracks and the loggia is propped to prevent collapse. A project to address the issues needs to be agreed.

Contact: Rachel James 0207 973 3153



© Historic	England
------------	---------

SITE NAME:

Fernhouse, archway, gateway and walls, Mapledurham

DESIGNATION:

Listed Building grade II\*, CA

CONDITION:

Poor

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Private

LIST ENTRY NUMBER:

1059520

Fern house, archway, gateway and walls of the walled garden to Mapledurham House. C17 and C18. The Fern house is roofless and in need of repair. The condition of the walls and gateway varies. There have been discussions regarding possible appropriate use and repair, including a proposal for reuse with heat provided by bio-mass heating. No works have physically been undertaken.

Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

OWNER TYPE:

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



© Historic England

Remains of St Nicholas's College, Wallingford Castle, Wallingford

Scheduled Monument, 3 LBs,

CA CONDITION: Poor

OCCUPANCY: N/A

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE: Local authority

D (A)

LIST ENTRY NUMBER: 1006324

Remains of C13 St Nicholas's College, the King's Chapel built within the Castle, with C15 and C16 additions. The site has suffered from heritage crime and part is fenced off. Structures also in need of consolidation and a sustainable management plan. Historic England is working with the owners to see the site conserved, explained and maintained. Major programme of conservation is now under way with substantial funding from Historic England. The Project Development Stage is now almost complete with the repair stage due to be carried out during 2022.

Contact: David Wilkinson 0207 973 3644



© Historic England

Church of All Saints, Church Street, North Moreton

DESIGNATION: Listed Place of Worship grade I, CA

CONDITION: Poor

PRIORITY CATEGORY: D (D)

OWNER TYPE: Religious organisation

1181258

Church, mainly flint and sandstone, with tiled roofs to nave and chancel, and sheet roof to south aisle. Mostly mid C13/C14 but altered in C15 and restored in C19. The tower and chantry chapel have had works carried out to them. Two National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship projects have been completed. Works are still needed to the South Aisle roof. The outstanding important early C14 St Nicholas stained glass window within the chantry chapel remains in urgent need of repair to the glazing and stonework and funds need to be raised for this work.

Contact: Rachel James 0207 973 3153

SITE NAME:	North Stoke henge and ring ditch site, Crown	marsh / South Stoke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006335
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Dike Hills, Dorchester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006364
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Rabbit - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Settlement site at Northfield Farm, Long Witt	tenham / Little Wittenha	m
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002925
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Grim's Ditch; portion from Mongewell Park Lodge to S of Nuffield church, Nuffield / Crowmarsh / Ipsden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006368
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

HERITAGE AT RISK 2022 / LOI	NDON AND SOUTH EAST / SOUTH OXFORDSHIRE		
SITE NAME:	Defences to the Saxon town [within Bull and Ki	ne Croft], Wallingford	i
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1006329
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	David Wilkinson 0207 973 3644
SITE NAME:	Motte of Wallingford Castle, Wallingford		
DESIGNATION:	Scheduled Monument, 3 LBs, CA	LIST ENTRY NUMBER:	1006324
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	David Wilkinson 0207 973 3644
SITE NAME:	Long barrow 340m north west of Cooks Cottages, Warborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016632
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Romano-British settlement 520m north west of Cooks Cottages, Warborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016630
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Camp on Bozedown, Whitchurch-on-Thames /	Camp on Bozedown, Whitchurch-on-Thames / Goring Heath	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003704
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

#### SOUTH OXFORDSHIRE / WOKINGHAM (UA)



© Historic England

SITE NAME:	Fawley Court and Temple Island, Fawley / Henley-on- Thames / Remenham / Bix and Assendon
DESIGNATION:	Registered Park and Garden grade II*, 18 LBs, 2 CAs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1000390

Early C18 garden and pleasure grounds surrounding a 1680s house set within a park landscaped by Lancelot Brown. Interacting with the adjacent River Thames, an eyecatcher stands on Temple Island downstream in Brown's principal vista. The gardens and wooded pleasure grounds have a number of parkland architectural elements linked by paths. Most of the estate and park are in separate ownership with previous development and planting impacting on the parkland structure and designed views There is a need to identify a partnership approach to deliver conservation management.

Contact: Kay Richardson 0207 973 3647

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

#### VALE OF WHITE HORSE




© Historic England

SITE NAME:	Milton Manor House, High Street, Milton
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

Manor house built circa 1670 in classical style with later attached flanking wings, (one of which includes a chapel), kitchen and brewhouse range added circa 1776. North and south wings, and stable and carriage house roofs in poor condition and cornice to main block in very poor condition. The condition of the timberwork to the windows is also cause for great concern. Discussions between Historic England and the owners led to a grant being offered to prioritise and cost the repairs need but this was not enacted.

Contact: Rachel James 0207 973 3153



SITE NAME:	Church of St Mary, Buckland
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1181905

1048220

Cruciform plan with west tower. Early C12 nave, Early English (c1240) transepts, tower and chancel; church rebuilt with late C18 windows. Coursed limestone rubble, limestone ashlar walling; stone slate roofs, except to nave and chancel; limestone ashlar flue. The limestone stone slate roofs to the north and south transept have been repaired. Stonework repairs are required at high level on the tower.

Contact: Rachel James 0207 973 3153

© Historic I	Eng	and
--------------	-----	-----

SITE NAME:	Castle mound at Fitzharris		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006311
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Settlement site south east of church, Appleford-	on-Thames / Long W	ittenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004849
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Two round barrows 520m and 550m north of Lower Chance Farm, Blewbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018716
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Yew Down round barrow 950m south west of Butterbush Reservoir, Lockinge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018719
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise,

New Entry is noted).


#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

#### WEST BERKSHIRE (UA) / VALE OF WHITE HORSE

•	<i>'</i>		
SITE NAME:	Two bowl barrows 500m north east of Stancombe Farm, Lambourn / Letcombe Bassett		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012349
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

#### WEST OXFORDSHIRE



SITE NAME: Church of St Nicholas, Kiddington Park, Kiddington with Asterleigh

Listed Place of Worship grade II\*, RPG grade II

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

© Historic England LIST ENTRY NUMBER: | 198490

A mostly C14 church with a C12 core, restored 1879 with addition of a vestry. Constructed of coursed limestone rubble with stone slates to chancel. The floors are in poor condition and there are problems with damp. A drainage survey is proposed to identify the possible sources of the problems.

Contact: Rachel James 0207 973 3153

Waterman's Lodge bowl barrow, one of a pair of Forest, Cornbury and Wychwood Scheduled Monument	of Bronze Age barrow	s on the western edge of Wychwood
Scheduled Monument		
	LIST ENTRY NUMBER:	1011221
Extensive significant problems	TREND:	Declining
Animal burrowing - Badger - extensive	NEW ENTRY?:	No
Private	CONTACT:	Alison McQuaid 0207 973 3646
Pair of bowl barrows immediately south of Blindwell Wood, Crawley		
Scheduled Monument	LIST ENTRY NUMBER:	1015212
Extensive significant problems	TREND:	Declining
Animal burrowing - Badger - extensive	NEW ENTRY?:	No
Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
I45m section of the north Oxfordshire Grim's Ditch situated 200m west of Grimsdyke Farm, Kiddington with Asterleigh		
Scheduled Monument	LIST ENTRY NUMBER:	1012905
Extensive significant problems	TREND:	Declining
Arable ploughing	NEW ENTRY?:	No
Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
Medieval settlement and church of Asterleigh, Kiddington with Asterleigh		
Scheduled Monument	LIST ENTRY NUMBER:	1020966
Generally unsatisfactory with major localised problems	TREND:	Declining
Scrub/tree growth	NEW ENTRY?:	No
Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
	Animal burrowing - Badger - extensive Private  Pair of bowl barrows immediately south of Blind Scheduled Monument Extensive significant problems Animal burrowing - Badger - extensive Private, multiple owners  I 45m section of the north Oxfordshire Grim's Ewith Asterleigh Scheduled Monument Extensive significant problems Arable ploughing Commercial company  Medieval settlement and church of Asterleigh, K Scheduled Monument Generally unsatisfactory with major localised problems Scrub/tree growth	Animal burrowing - Badger - extensive Private  CONTACT:  Pair of bowl barrows immediately south of Blindwell Wood, Crawley Scheduled Monument  Extensive significant problems  Animal burrowing - Badger - extensive Private, multiple owners  CONTACT:  145m section of the north Oxfordshire Grim's Ditch situated 200m with Asterleigh Scheduled Monument  Extensive significant problems  TREND: Arable ploughing  Commercial company  Medieval settlement and church of Asterleigh, Kiddington with Asterleigh Scheduled Monument  LIST ENTRY NUMBER: CONTACT:  Medieval settlement and church of Asterleigh, Kiddington with Asterleigh Scheduled Monument  Generally unsatisfactory with major localised problems  Scrub/tree growth  NEW ENTRY?:

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area
Listed Building
LPA
Local Planning Authority
NP
National Park
RPG
Registered Park and Garden
SM
Scheduled Monument
UA
Unitary Authority
WHS
World Heritage Site

SITE NAME:	Pump Copse earthwork, Kiddington with Asterlei	igh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003242
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Rectangular enclosures 1100yds (1010m) north w	est of Mount Owen	Farm, Lew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006348
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Linear earthworks east of Callow Hill Roman villa Wootton / Glympton / Stonesfield	forming part of the	north Oxfordshire Grim's Ditch,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014751
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

#### PORTSMOUTH, CITY OF (UA)



© Historic England

Fort Purbrook, Portsdown Hill SITE NAME: Road, Portsmouth DESIGNATION: Listed Building grade II\*, SM CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

1387127

Fort c1860 by Captain William Crossman of the Royal Engineers. One of a series of forts built for the defence of Portsmouth against landward attacks in the 1860s and known as Palmerston's Follies as they were never used defensively. Used by a charitable trust as an outdoor activities centre. The wrought iron bridges have been repaired with funding from the Heritage Stimulus Fund and a structural survey and vegetation management plan through the Countryside Stewardship Scheme. Problems related to the drainage of the ramparts and maintenance of the moat's retaining walls put it at risk.

Contact: Rachel James 0207 973 3153



© Historic England

Hilsea Lines - Centre Bastion SITE NAME: (excluding casemates referred to as Bastion 4), East Centre Curtain (Railway) west side (formerly known as Bastion no. Hilsea Scheduled Monument, part in DESIGNATION: CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B) OWNER TYPE: Local authority, multiple owners LIST ENTRY NUMBER: 1001861

Earthwork defence dating from 1858-1869, with batteries, magazines and barracks. The central section of the site, comprising three quarters of the Centre Bastion, and the west side of East Centre Curtain, where the railway enters Portsea Island (all formerly referred to broadly as Bastion no. 5) are continuing to suffer from heritage crime, a lack of regular maintenance and very limited access to the site. Opportunities to manage the monument, improve access and interpretation, and reduce anti-social behaviour through the creation of a linear park are being explored by Portsmouth City Council.

Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:



© Historic England Archive

	` ,
SITE NAME:	Former Royal Naval Academy (Buildings 1/14 and 1/116-9), HM Naval Base, Portsmouth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

1244573

Government or agency

found in the roof and must be removed before full surveys can be undertaken.

Contact: Louise Forsyth 020 7973 3220



© Historic England

SITE NAME:	Fort Widley, Portsmouth
DESIGNATION:	Scheduled Monument, 2 LBs
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1001862

Fort c1860 by Captain William Crossman of the Royal Engineers. It is one of a series of forts built for the defence of Portsmouth against landward attacks in the 1860s and known as Palmerston's Follies as they were never used defensively. It is laid out in a massive polygonal trace plan and surrounded on three sides by a dry moat. The fort is run by a charitable trust as an outdoor activities centre. Maintenance issues are now becoming repair problems. A structural survey of the counterscarp wall and a vegetation management plan has been funded through Countryside Stewardship.

One of the oldest structures in the Dockyard, this building is a Georgian forerunner of the Britannia Royal Naval College at Dartmouth. This building has long been vacant. Natural ventilation and background heating has been introduced and furnishings removed, reducing damp levels. Remedial works to roof coverings and parapet gutters have reduced water ingress and the dry rot appears to be dying back. The cupola has been repainted. Asbestos has been

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME:	Horse Sand Fort, Solent
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1018588

Horse Sand Fort is a circular 19th century Royal Commission sea fort lying in the Solent 3.6km south east of Southsea Castle. Horse Sand Fort was one of a chain of four sea forts in the Solent recommended by the Royal Commission on the Defence of the United Kingdom in 1860 and designed to protect Portsmouth dockyard from seaborne attack. The Fort also was armed during both World Wars. The Fort provides a visual reminder of the strategic importance of the Solent in the late 19th to earlier 20th century. The Fort currently has no sustainable use aside from occasional visitor tours.

Contact: Rebecca Lambert 0207 973 3630



© Defence Estates

SITE NAME:	No.5 and No.6 Dock, Basin No.1, Portsmouth Dockyard
DESIGNATION:	Scheduled Monument and Listed Building grade I, part in CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1001852 and 1272267

Docks 5 and 6 are part of a complex of late C18 and early C19 ship building and repairing docks with associated quay walls and mooring fixtures. The docks have stepped sides with flights of steps and haulage slides; some retain later gates. Dock 6 is suffering from rotation, and mortar joints on the stonework treads on the north side have opened up; it is also vulnerable to water penetration action and the stonework is spalling. Dock 5 has recently been flooded due to failure of the gates and is vulnerable to algal growth and saturation of stonework with risk of accelerated decay.

Contact: Iain Bright 0207 9733 739



© Historic England

SITE NAME:	Fort Cumberland, Fort Cumberland Road, Eastney
DESIGNATION:	Scheduled Monument and Listed Building grade II*, 3 LBs
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1015700 and 1104273

Coastal fort of 1746-1812 with later buildings and features. The casemates are suffering from water ingress and associated decay. In addition, there is localised deterioration of the Fort's defences, particularly the curtain and counterscarp. A programme of works to address some of the most urgent issues has been completed and the causes of water ingress into the casemates are being investigated. With local partners, Historic England is considering options for the sustainable re-use of the vacant parts of the site, both in the long and short-term.

Contact: Clare Charlesworth 0207 973 3640

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME: No. 25 Store, Yard Services Manager's Office, I/II8, Jago Road, HM Naval Base, Portsmouth

DESIGNATION: Listed Building grade II\*, CA

CONDITION:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: F (F)

OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1244578

Two storey storehouse of 1782, with internal courtyard. In poor condition and vacant. Some evidence of water ingress and pigeon infestation. Some remedial works have been completed and further roof works are planned. The Ministry of Defence is in discussion with a potential user of the building, to take occupation once repairs are complete.

Contact: Louise Forsyth 020 7973 3220



© Historic England

SITE NAME: The Beneficial School, Kent Street, Portsea DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1271859

Charity school of 1784 and 1836, now in use as a dancedrama school/theatre by the Groundlings Theatre Trust. An updated condition survey has been completed which has identified problems including with the roof structure and windows. The governance of the building needs to be rationalised, so that a comprehensive funding package for the necessary repairs can be sought. Historic England, the Theatres Trust and Groundlings have had positive meetings about the way forward. Some repairs to the front elevation have been successfully completed with the aid of a Covid 19 Emergency grant.

Contact: Robert Williams 0207 973 3641

Contact: Liz Pollard 0207 973 3650



© Historic England

SITE NAME: Wymering Manor, Old Wymering Lane, Cosham DESIGNATION: Listed Building grade II\*, CA CONDITION: Fair OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Charity (heritage)

1245180

LIST ENTRY NUMBER:

Manor house with medieval fabric and later work. Acquired by a Trust in 2013. A condition survey and an investigation into options for future sustainable uses have been completed with grant aid from Historic England and the Architectural Heritage Fund. The house is in need of some structural repair, general renovation and a new use.



© Historic England

2-8, The Parade, HM Naval SITE NAME: Base, Portsmouth DESIGNATION: Listed Building grade II\*, CA CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Government or agency LIST ENTRY NUMBER: 1272307

Terrace of dockyard officers' lodgings, 1715-19. Partially converted to office use c1995, but now empty. Prone to wet rot and some structural movement. Structural and drainage problems persist between the main building and the rear extensions. There is extensive decay in panelling and some plaster ceilings have collapsed. An extensive programme of repair is underway and the roof has been reslated and the gutters repaired. Render and window joinery repairs are also underway as well as the repair of the timber porches. Further works to the rear extensions are planned.

Contact: Louise Forsyth 020 7973 3220



© Historic England

SITE NAME: Iron and Brass Foundry, 1/140, Victoria Road, HM Naval Base, Portsmouth DESIGNATION: Listed Building grade II\*, CA CONDITION: Fair OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C(C)OWNER TYPE: Government or agency

1272310

Iron foundry and smithery built 1857-1861, by Col GT Greene RE and Andrew Murray, Chief Engineer; extended 1878, with later alterations. The main part of the building was converted to office use in 2003. The east wing (Building 1/136) remains unused and at risk. There were concerns over drainage and regular flooding of the building but this has been resolved. Roof repairs are due to be undertaken in 2021/22.

Contact: Louise Forsyth 020 7973 3220

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is

shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

© Historic England

SITE NAME:	Church of St Mary, Fratton Road, Kingston
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1104279

Church designed by Sir Arthur Blomfield and built of flint and Bath stone with plain tile roofs between 1887-9. The church has received significant grant aid from Historic England and the National Lottery Heritage Fund in three phases and this has dealt with some of the roofs and tower. Recent repairs to the building fabric have been carried out in connection with the Organ Project but further repairs are required including to the roofs, south clerestory and chancel windows.

Contact: Robert Williams 0207 973 3641

3	1	
		200
1	min	1000
	HOUSE	

SITE NAME: Church of St Luke, Greetham Street, Portsmouth DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1104307

Neo-Norman church by Thomas Hellyer of Ryde. Dated 1858-61. Built of flint and stone with a Welsh slate roof. At risk due to extensive damp problems caused by water ingress resulting mainly from faulty and undersized rainwater goods. Cementitious repointing worsens the damp problems. Ambitious plans for redevelopment which will hopefully also address the outstanding repair issues.

Contact: Robert Williams 0207 973 3641



© Historic England


SITE NAME:	Church of St Cuthbert, Hayling Avenue, Portsmouth
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1333225

1914-15. By E Stanley Hall. The original east end apse was destroyed by bombing, and the present east end wall is a post-war reconstruction. This has been remodelled in the last 10 years to provide community facilities and the present church sits in the western two bays of the former nave of the church only. The roofs over the worship space and the bell tower are in poor condition. A National Lottery Heritage Fund Grants for Places of Worship scheme grant was used to develop the project, but funding for repairs has yet to be found.

Substantial standing remains of abbey established by Henry I in 1121. The majority of the ruins including the gatehouse, refectory wall and elements within the ownership of St James's church have been repaired. The mill arch, C12 to C13, is the surviving western wall of the Abbey Mill. The original flint rubble wall faces have been much repaired with inset areas of chalk ashlar and brickwork. There are areas of re-pointing in hard cement mortar and open joints. Implementation of repairs and long-term management is

Contact: Robert Williams 0207 973 3641

#### **READING (UA)**



© Historic England

SITE NAME:	Remains of Reading Abbey: a Cluniac and Benedictine monastery
DESIGNATION:	Scheduled Monument, 14 LBs, part in RPG grade II, part in CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

OWNER TYPE: Local authority, multiple owners LIST ENTRY NUMBER: 1007932

Contact: Rachel James 0207 973 3153

required.



© Historic England

SITE NAME:	Chazey Farm barn, The Warren, Reading
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1113603

for a healthcare development. Ground works for the new development commenced in spring 2010. Following close working between the leaseholder, Local Planning Authority and Historic England urgent work to prevent any further decay of the building commenced in 2020. Work will then be required to restore the barn and find a viable use for it.

A very large seven bay red brick barn C17 or earlier. There is structural cracking and the gable currently has temporary shoring. The building forms part of a larger site proposal

Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Russell Street / Castle Hill		
DESIGNATION:	Conservation Area, 52 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Mark Worringham 07855 126084

#### SOUTHAMPTON, CITY OF (UA)



© Historic England

SITE NAME:

Former Chapel Mills, American Wharf, Elm Street, Southampton

DESIGNATION:

Listed Building grade II\*

CONDITION:

Poor

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

D (D)

OWNER TYPE: Commercial company, multiple owners

LIST ENTRY NUMBER: 1091968

Rare survival of former steam mill, 1781 and 1800, built to produce ship's biscuits for the Navy. Built of brick with mainly concrete tiled roofs. Now partly used as a sail loft [East] and part vacant [West], suffering from longstanding lack of regular maintenance. Eastern part re-roofed in 2022 including gutter repairs, and internal structural repairs to timber posts and beams. Planning Permission granted for repair and residential conversion of Western part, but permanent repairs not yet implemented.

C15 hall house now commercial premises, suffering from water ingress and deferred maintenance and therefore considered to be at risk. Condition survey undertaken and programme of repairs identified. Repairs need to take place



© Historic England

SITE NAME:

Red Lion Public House, 55, High Street, Southampton

DESIGNATION:

Listed Building grade II\*

CONDITION:

Poor

OCCUPANCY:

Part occupied/part in use

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Private

LIST ENTRY NUMBER:

1092055

Contact: Robert Williams 0207 973 3641

to prevent deterioration.

Contact: Robert Williams 0207 973 3641



SITE NAME:

St Denys Church, St Denys Road, St Denys Road, St Denys

DESIGNATION:

Listed Place of Worship grade II

CONDITION:

POOR

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER:

1179 | 20

Church designed by Sir George Gilbert Scott in 1868 and built of brick. At risk due to falls of ceiling plaster internally. Historic England/National Lottery Heritage Fund grantaided repairs to rainwater goods, east and west windows, bell turret stonework and some areas of ceilings completed. A further phase of repairs is required.

1179120 Contact: Robert Williams 0207 973 3641

© Historic England

SITE NAME:	Old Town North		
DESIGNATION:	Conservation Area, 15 LBs, 4 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jon Willetts 023 8083 2479

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

#### **SURREY**

#### **ELMBRIDGE**



© Historic England Archive

SITE NAME:

Brooklands Motor Racing Circuit

DESIGNATION:

Scheduled Monument and Listed Building grade II, part in CA

CONDITION:

Poor

OCCUPANCY:

N/A

PRIORITY CATEGORY:

F (F)

OWNER TYPE:

Mixed, multiple owners

The world's first purpose-built motor racing circuit, constructed in concrete in 1907. It was in use until 1939 when aircraft production buildings took over part of the circuit. Historic England funded a Conservation Management Plan for the entire site which identified various parts of the track to be at risk. Historic England is now working with owners and interested parties to ensure the necessary works take place and significant progress is being made in reducing the risks to the track. However, further action is required.

Contact: Iain Bright 0207 9733 739



© Historic England

SITE NAME:	The Belvedere, Claremont Park, Esher
DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade I
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Educational (independent)

1020137 and 1272444

LIST ENTRY NUMBER: 1005931 and 1030204 Contact

Eye-catcher and viewpoint in the form of a mock castle, 1717 by Sir John Vanbrugh. In need of repair to bring it back into use as a focal point of the Grade I Registered landscape of Claremont Park. A commitment to improving the immediate landscape surrounding the Belvedere was sought as part of a planning application made by Claremont Fan Court School for long term development. Some of the improvements have been implemented.

Contact: Alma Howell 0207 9733 627



© Historic England

SITE NAME:	Former kitchen garden walls to Claremont House, Claremont Park Road, Esher
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners

Nationally significant garden walls of 1717 by Vanbrugh. Suffering from vegetation growth in wall tops, mortar loss and in need of general repair. Investigations for possible repair techniques and materials completed with one of the owners. Some repairs have taken place as an exemplar but more are needed. A full survey of the walls is being undertaken to understand the overall condition and the extent and cost of repairs needed.

LIST ENTRY NUMBER: 1377465 Contact: David John 0207 973 3638

SITE NAME:	Brooklands, Byfleet		
DESIGNATION:	Conservation Area, 5 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Jon Kilner 01372 474824

#### **EPSOM AND EWELL** SITE NAME: Epsom Town Centre, Epsom NEW ENTRY?: DESIGNATION Conservation Area, 39 LBs No CONDITION: TREND: Poor Deteriorating Epsom & Ewell Borough Council VULNERABILITY: CONTACT: low 01372 732394 Horton, Epsom SITE NAME

5112110112	riorton, Epsoni		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Lance Penman 01372732000

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Full ladar repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### egory is LI erwise, LI N R

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park

RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site OWNER TYPE:

LIST ENTRY NUMBER:

#### **GUILDFORD**



© Historic England

SITE NAME:	West Horsley Place, Epsom Road, West Horsley
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)

1188949

Charity (heritage)

Country house, C15 timber-framed hall and domestic wing, refronted in brick in the C17 with C18 alterations and internal features. The house has suffered from deferral of maintenance under private ownership and now stands in need of a major renovation of the frame, brickwork and roof as well as all decorative finishes. A recently created Trust has taken on the building which is now being used in conjunction with Grange Park Opera, operating from the grounds. Further uses being explored. Immediate structural remediations have been addressed and a phased programme of repairs is in progress.

Contact: Alma Howell 0207 9733 627

Contact: David John 0207 973 3638

	1	
		A
	The state of the s	
	14	

Church of St Luke, Burpham Lane, Burpham Lane, Burpham

DESIGNATION: Listed Place of Worship grade II

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1029301

Church designed by Henry Woodyer in 1859. Built of Bargate stone with tiled roofs. At risk due to defective roof tiling and rainwater disposal goods.

© Historic England



© Historic England

SITE NAME:	Clandon Park, West Clandon
DESIGNATION:	Registered Park and Garden grade II, 8 LBs, part in CA
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001171

Gardens and pleasure grounds within a landscaped park by Lancelot Brown. Gutted by fire in 2015 the house and garden are owned by the National Trust while the park is privately owned. Management without a plan for guidance has lead to lack of suitable conservation priorities around the park, damaging its overall integrity and its character further vulnerable to development proposals. With separate plans drawn up for restoration in the house and garden and management of the park, a coordinated approach to park use and appropriate management is needed to secure this landscape's future.

An important group of C19 and C20 brick built lime kilns. Three of the structures (the Dietsch, remains of the six Flare kilns and remaining Hoffman kiln) are at risk due to a longstanding lack of regular maintenance. A condition survey of the structures has been completed and estimated

cost of the repairs produced. Sources of funds to implement the repairs now need to be identified.

Contact: Kay Richardson 0207 973 3647

#### **MOLE VALLEY**



© Historic England

SITE NAME:	Lime kilns at Betchworth Quarry, Betchworth
DESIGNATION:	Scheduled Monument, 3 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Commercial company, multiple

owners

LIST ENTRY NUMBER: 1021346

46 Contact: Iain Bright 0207 9733 739



© Historic England

SITE NAME:	Brockham Lime Kilns, Brockham
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (non-heritage)

The site includes a disused eastern battery of eight kilns and a western battery of two. The eastern battery, originally built in 1870, comprises four pairs of linked flare kilns. The northern two pairs were modified to the Brockham patent, as was the western battery. Now also an important bat habitat. Parts of the kilns remain in a very bad condition and supported by scaffold. Funds need to be raised which will allow the identified repairs to take place and improve interpretation for visitors.

1021322 and 1230730 Contact: David John 0207 973 3638

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

ABBR	EVIATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garde
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Ruins of Betchworth Castle, Reigate Road, Brockham
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1017996 and 1378073

Late C17 ruined house built on site of medieval castle. Consolidation works to ruins completed 2013. A section of the terrace retaining wall was rebuilt in 2014, but a long section of the terrace is still held up only by tree roots and temporary geotextile fabric shoring. This will fail once the tree roots rot or if strong winds blow over any of the trees on the terrace edge. This and on-going management/ maintenance needs to be addressed before the monument can be removed from the Register. The owner is trying to secure funding to assure the long term future of the ruins.

Contact: David John 0207 973 3638

A

SITE NAME: Church of St John the Baptist, Church Lane, Okewood Hill, Abinger DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1028844

Church dating from C13, virtually doubled in size in 1879 by the architect Basil Champneys. Rendered rubble stone walls with slab roofs and shingled spire to low timber tower. At risk due to defective rainwater goods and roofs. A phase of repairs has been completed under the National Lottery Heritage Fund Grants for Places of Worship scheme, however further repairs are required and funds are needed for these.

Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Anstiebury Camp: a large multivallate hillfort south east of Crockers Farm, Capel		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1007891
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bell barrow in Deerleap Wood, Wotton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007878
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No



© Historic England

SITE NAME:	Ashtead Park, Ashtead
DESIGNATION:	Registered Park and Garden grade II, 20 LBs, part in SM, part in CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001490

A C17 park, developed with successive owners throughout the C18 and C19 the well wooded open parkland estate was broken up and sold in the 1920s with the historic landscape split into two principle ownerships, the house, gardens and southern park a school, and the northern park with ponds managed as open access land now a nature reserve. The school has improved its management of the landscape amongst proposals for further facilities following a Conservation Management Plan since 2010. A joint heritage-led approach should support the park's historic character and balance its cultural services.

Contact: Kay Richardson 0207 973 3647

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

#### **REIGATE AND BANSTEAD**



© Historic England

SITE NAME:	Alderstead (Merstham) Fort, Shepherd's Hill, Reigate
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1018073

LIST ENTRY NUMBER:

C19 mobilisation centre, one of 13 constructed on the North Downs for the defence of London. The scheduling comprises the infantry fort and detached tool store. Tree growth and poor drainage are causing problems and the fort has no current use or management. Discussions need to take place with the owners to agree a project to enable the site to be conserved and maintained.

An Arcadian 'ferme ornée' designed by Philip Southcote from 1734-5, highly influential in the history of garden design but rather ephemeral in nature. Now in divided ownership and varying uses very little of the landscape laid out by Southcote remains today apart from the wooded banks of the Bourne stream that was part of Southcote's circuit around the farm. Isolated parkland architecture features sit within highly frangmented settings. With such high levels of loss of historic design intention and character the overall integrity of the registered area need reassessing.

Contact: lain Bright 0207 9733 739

#### **RUNNYMEDE**



© Historic England

SITE NAME:	Woburn Farm, Addlestone
DESIGNATION:	Registered Park and Garden grade II, 5 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000342

Contact: Kay Richardson 0207 973 3647

#### **SPELTHORNE**



SITE NAME:	Church of St Mary Magdalene, Squires Bridge Road, Littleton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1377699

A medieval church with an C18 tower. Constructed of ragstone, chalk, conglomerate and brown brick with a clay tiled roof. The tiled roofs are in a poor condition, especially on the north slopes although there is no evidence of water penetration at the moment. The interior walls have been painted with a non-micro porous paint which is causing decay of the carved stone details.

Contact: David John 0207 973 3638

#### **TANDRIDGE**

© Historic England



© Historic England

SITE NAME:	Ruins at Bletchingley Castle, Bletchingley
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1013374

Norman ringwork and bailey, with the remains of a rare stone built Norman house. The ruins were previously excavated. Some trees are growing close to the fragile masonry of the house, which is overgrown with vegetation and in need of consolidation. The condition of the ruins of the house put the site at risk. It is hoped that a project can be developed to conserve the ruins.

Contact: David John 0207 973 3638

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP

Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Mary the Virgin, Church Lane, Oxted	
DESIGNATION:	Listed Place of Worship grade I	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1189608	

Large church of medieval origins constructed from a mixture of sandstone, Reigate, Kentish rag and ironstone. At risk due to deterioration of the stonework and render. The National Lottery Heritage Fund's Grants for Places of Worship grant-aided repairs to the chancel and aisles completed in 2018 but further repairs, including to the tower, are required.

Contact: David John 0207 973 3638

© Historic England

#### WAVERLEY



SITE NAME: Church of St Peter and St Paul, The Street, Ewhurst Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor B (B) PRIORITY CATEGORY: OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1190455

C12 church with nave, C13 transepts, C15 porch. Chancel largely rebuilt 1838 after the central tower collapse. Wealden sandstone rubble and dressed sandstone blocks on buttresses. Stone slab roofs with short, wood-shingled broach spire to tower. Cruciform plan. Water ingress through the roof of the chancel has led to the ceiling plaster falling. National Lottery Heritage Fund Grants for Places of Worship scheme repairs to the chancel, south transept and south nave slopes were completed in 2019, but the remaining roofs are in urgent need of repair.

Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Four bowl barrows 30m south east of Tilford Barrows: part of The Barrows round barrow cemetery, Tilford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007883
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### WOKING



©	Historic	England

SITE NAME:	Brookwood Cemetery, Brookwood
DESIGNATION:	Registered Park and Garden grade I, 18 LBs, part in CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1001265

A commercial garden cemetery of immense scale founded in 1852 for London's dead with its own railway. Still active with tombs and monuments for many denominations, faiths, nationalities and groups, C20 military and woodland sections heighten the site's significance. Acquired by the Local Authority after longstanding lack of overall management, restoration of signficant structures is being undertaken. Historic England funded a Conservation Framework in 2014 to scope the visioning and management task with Master plan, experience and business plans completed in 2020.

Contact: Kay Richardson 0207 973 3647

SITE NAME:	Brookwood Cemetery		
DESIGNATION:	Conservation Area, 18 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Tom Simpson 01483 743871

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### I PA ΝP

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

#### WEST BERKSHIRE (UA)



© Historic England

SITE NAME: Former Chapel of St Leonard, east of Manor Farmhouse, Brimpton Road, Brimpton

Scheduled Monument and Listed DESIGNATION: Building grade II\*

CONDITION:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: E (E)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1005378 and 1303413

Former chapel. C12 and later. Structure is generally sound, with main repair programme completed. Planning Permission and Scheduled Monument Consent granted for sympathetic conversion to office use not implemented. The vegetation is being managed. The chapel is part of the adjacent Manor Farmhouse leasehold demise.

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME: Pair of gate piers and approximately 2 metres of wall to east and west of piers on edge of Park Lane 162 metres west of entrance to church yard, Park Lane, Hampstead

Listed Building grade II\*, RPG DESIGNATION:

grade II

Private

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY CATEGORY: C(C)OWNER TYPE:

LIST ENTRY NUMBER: 1117222

LIST ENTRY NUMBER:

Early C18 brick gate piers and attached walling. Formerly in the gardens of a C17 house which burnt down in 1718. The piers suffer from open joints to the brickwork and capitals and a corroding pintle which has caused the brickwork to bulge. A programme of repairs needs to be agreed with the owners and the works undertaken.

Gate piers to house which burnt down in 1718. The piers

remain in the north west corner of the park. Some of the

and a shell niche. A programme of repairs needs to be

bricks have eroded; there is vegetation growth to the tops; severely cracked stone and fractures through brickwork

Contact: Rachel James 0207 973 3153



© Historic England

SITE NAME: Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshall Listed Building grade I, RPG DESIGNATION: grade II CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1136042

Contact: Rachel James 0207 973 3153

agreed and taken forward by the owners.



© Historic England

Three pairs of gate piers and SITE NAME: walls around gardens and terrace at Home Farm, Park Lane, Hampstead Marshall Listed Building grade I, RPG DESIGNATION: grade II CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

OWNER TYPE: Private, multiple owners LIST ENTRY NUMBER: 1136034

Two late C17 walled gardens (one with raised terrace) and three pairs of gate piers located in the north west corner of the park. Formerly the gardens to the C17 house which burnt down in 1718. Now forming the boundary walls to various private properties. Some sections have open joints. One of the gate piers has vegetation growth to the cornice and there is a large crack in one of the decorative urns, which puts the significance of the structure at risk. Repairs to this section need to take place.

Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



@ Historic	Fng	land

© Historic England

SITE NAME:	Church of All Saints, Station Road, East Garston
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1321874

SITE NAME: Church of St Gregory, Welford DESIGNATION: Listed Place of Worship grade II\* CONDITION: PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

1117225

Church, C12 with C13/C14 work. Central tower, nave, chancel, transepts, south aisle, south porch and a Lady Chapel. Walls are of flint with brick banding and limestone dressings. Roofs with Welsh slate coverings except the porch. C19 works to the nave roof, and a west window installed, also work to the Lady Chapel, chancel, the south arcade and windows. Following porch repairs in 2019/20, repairs to the tower are planned comprising masonry repair, re-pointing, repairs to upper windows and louvres. The pyramidal Welsh slate roof and parapet gutters to the tower roof also require repair.

Contact: Rachel James 0207 973 3153

Church 1852-5 by T Talbot Bury, the Norman tower taken down and re-built late C19. Flint, with stone dressings and clay plain tiled roofs. Tower, nave, aisles, chancel and south porch. Four bay nave and aisles, arcade of two centred arches. Three bay chancel with stone vaulted roof, Slipped and deteriorated roof tiles to the nave, aisles and porch in need of repair to avoid water ingress. Rainwater goods in poor condition. An application made to the National Lottery Heritage Fund Grants for Places of Worship scheme in 2017 was unsuccessful and the works continue to be necessary.

Contact: Rachel lames 0207 973 3153

⊚ Firstoric England		Contact: Rachel	Contact: Rachel James 0207 973 3153	
SITE NAME:	Long barrow on Sheep Down, 1km north of East	llsley, East Ilsley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013056	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Membury Camp (see also Wiltshire Unitary Auth	ority), Ramsbury / L	ambourn	
DESIGNATION:	Scheduled Monument, SM	LIST ENTRY NUMBER:	1003818	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Woodland management	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Moated site and three fishponds at Ufton Nervet,	Ufton Nervet		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013176	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103 102	
SITE NAME:	Remains of St John the Baptist church at Ufton Green Farm, Ufton Nervet			
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006967	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME-

SITE NIAME

LIST ENTRY NUMBER:



© Historic England

	(- ).
SITE NAME:	Aldermaston Court, Aldermaston
DESIGNATION:	Registered Park and Garden grade II, 12 LBs, part in CA
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000530

The remaining portion of Aldermaston Park, a mid-late C19 landscape with remains of C17/C18 pleasure grounds, wooded deer park including wood pasture with many veteran or ancient trees of evidential value. Sold into commercial use with an office complex juxtaposed between the house and lake, planning permission remains for more offices. Sold in 2014 discussions for a sustainable long term future for the buildings, avoiding further loss of historic design integrity and establishing a conservation management approach to the designed landscape and enhancing the veteran tree interest is required.

Contact: Kay Richardson 0207 973 3647



© Historic England

SITE INALIE.	Donnington / Newbury
DESIGNATION:	Registered Park and Garden grade II, 6 LBs, 2 CAs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Low
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1001446

Shaw House Shaw cum

C16 or early C17 garden laid out by the Dolman family and a complex of early C18 water gardens by the Duke of Chandos. Bought by Berkshire County Council in 1946, National Lottery Heritage Fund and Historic England grants in 2005 restored the house as a conference centre and heritage attraction which opened to the public in 2008. The development of an academy school, fragmented land management and poor public realm affects views and landscape components. A Conservation Area Management Plan funded by Historic England to understand and sustain significance and manage change is now complete.

Contact: Kay Richardson 0207 973 3647

#### **WEST SUSSEX**

#### **ADUR**



© Historic England

SITE INAITE:	Church Lane, Shoreham by Sea
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1192780

Church of St Mary Do Haura

Norman church built of Caen stone, containing a tall crossing tower with transepts to north and south, and a large aisled chancel to the east. It is a mixture of Romanesque and Transitional architecture. At risk due to the need for stone, roof and gutter repairs. Some urgent works have been completed, including stone and mortar repairs to the lower stages of the tower with the benefit of a grant from the Covid-19 Emergency Heritage at Risk Response Scheme. Most recently (2021) there have been roof repairs to the south transept and stone repairs, but further repairs are required.

Contact: Robert Williams 0207 973 3641

SITE NAME:	Southlands		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Medium	CONTACT:	Colette Blackett (LPA) 01273 263242

Dialiala Cassana Dialiala Dand

#### ARUN



© 2021 Google

SITE NAME:	Felpham
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1353792

Thatched brick and flint cottage dating from C17 with later alterations and extensions. It was the home of the poet, artist and visionary William Blake and his wife Catherine from 1800-1803, and where he wrote the words to the hymn 'Jerusalem'. Purchased by a trust in 2015 since when the building has remained vacant. At risk due to decay and failure of part of the roof structure and thatch, and structural problems to the masonry. Now in need of sympathetic repair and maintenance.

Contact: Robert Williams 0207 973 3641

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

ABBR	EVIATIONS
CA LB	Conservation Area Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garde
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England Archive

SITE NAME:	Littlehampton Fort, Littlehampton
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1005809

C19 fort. The fort is partly covered in ivy which poses the main threat to the structure. Other parts of the fort are engulfed by sand dunes which have Site of Special Scientific Interest status. A project to remove the ivy from the fort walls and ditches is in progress. This work is being undertaken by a local interest group in partnership with the owner and will help to inform understanding of the risks to the monument and guide a long-term strategy for its management.

Contact: Rebecca Lambert 0207 973 3630



© Historic England

SITE NAME:	Church of St Mary the Virgin, Church Street, Littlehampton
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1353769

A large imposing geometric red brick church located in the town centre of Littlehampton. Originally constructed in 1826 by George Draper on the site of a medieval church and then transformed in 1935 by WH Randoll Blacking. It has an impressive galleried interior. The interior of the tower, aisles and galleries above are in poor condition with water damage, structural problems in the tower, erosion of stone around the windows and loss of plaster on walls of the gallery. Further investigations and a comprehensive programme of repairs are now urgently necessary.

Contact: Robert Williams 0207 973 3641

#### **CHICHESTER**



© Historic England

SITE NAME:	Bell Tower of the Cathedral, Chichester
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1026825

Grade I listed freestanding bell tower, adjacent to Chichester Cathedral. Circa early C15, probably the work of William Wynford who also designed the cloisters, with Perpendicular style openings. The external surfaces of the stonework are degrading, and structural movement is evidenced by cracks in the buttresses. The Cathedral Restoration and Development Trust aspire to see the fabric repaired and new, sustainable uses found for some of the under-utilised internal spaces.

Contact: Robert Williams 0207 973 3641

Contact: Alma Howell 0207 9733 627



© Historic England

SITE NAME:	Former Church of the Assumption, Church Farm Lane, East Wittering
designation:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)

OWNER TYPE: Private LIST ENTRY NUMBER: 1354484 Medieval church, restored 1875-6. Not used for worship for some years. Some repairs have been made but future new uses have not been agreed.

A Romano-Celtic temple, Iron Age shrine and associated remains 250m north west of Ratham Mill,

SITE NAME:	Funtington		,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018354
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Devil's Ditch, sec	Devil's Ditch, section extending 200yds (180m) east from Chapel Lane, Funtington			
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1005880	
CONDITION:	Generally unsatis	factory with major localised	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Devil's Ditch, sec	ction extending 400yds (370m) wes	t from Chapel Lan	e, Funtington	
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1005881	
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping		NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646	
	SITE NAME:	Lavington Park, East Lavington / Duncton, Chichester	Late C18 and C19 garden at the foot of the South Dow on the site of a late C16 house and garden set within a pof C18 origin largely planted in the C19 further altered the C20. The house with extensive panoramic views no is now a school. School and enabling development with the park has led loss of historic character and designed landscape intentions. A heritage led estate plan by the school was discussed with The South Downs NPA in 20 to improve conservation management as the historic and		
	DESIGNATION:	Registered Park and Garden grade II, 7 LBs			
	CONDITION:	Generally satisfactory but with significant localised problems			
	VULNERABILITY:	Medium			
	TREND:	Stable	aesthetic value of development.	f the site is vulnerable to futher change ar	
Historic England	NEW ENTRY?:	No			
	OWNER TYPE:	Educational (independent)			
	LIST ENTRY NUMBER:	1001213	Contact: Kay Ric	hardson 0207 973 3647	

SITE NAME:	Graylingwell, Chichester, Chichester		
DESIGNATION:	Conservation Area, 2 LBs, part in RPG grade II, 2 SMs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Improving significantly
VULNERABILITY:	High	CONTACT:	Lone Le Vay (LPA) 01243 534688

#### **HORSHAM**



@ Historic	Fngland	4

SITE NAME:	Ruins of Sedgwick Castle, Moated site, Nuthurst	5
DESIGNATION:	Scheduled Monument, RPG grade II	r
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private, multiple owners	

1009579

Ruinous moated medieval castle. The exposed parts of this structure are in a very poor state of repair and continue to deteriorate. A conservation strategy has been agreed but needs to be implemented to enable the monument to be conserved and maintained.

Contact: Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument LPA NP RPG SM UA Unitary Authority
WHS World Heritage Site



© Historic England

© Historic England

SITE NAME:	Church of St Peter, Station Road, Cowfold
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1354161

Large medieval village church built of Wealden sandstone with stone roofs. At risk due to defective roofing to the chancel and internal plaster ceilings. Previous Historic England/National Lottery Heritage Fund grant-funded repairs successfully completed but a final phase now required in order to remove the church from the Heritage at Register. The weathervane was repaired in 2021.

Contact: Robert Williams 0207 973 3641

SITE NAME:	Church of St Peter, Upper Beeding
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NILIMBER	1027214

Medieval church built of a mixture of ashlar and rubble stone with areas of flint. The roofs have stone slab on the outer slopes and tiled inner slopes. The church is at risk due to defects to the roofs, rainwater disposal and stonework. Historic England/National Lottery Heritage Fund grant-aided repairs to the tower and valley gutter, and repairs have been carried out to the chancel roof and gable walls. However further repairs are required to the rainwater drainage and the window behind the organ. There has been some work to the dangerous church walls recently (2021).

Contact: Robert Williams 0207 973 3641

SITE NAME:	Bowl barrow on Black Hill, Colgate		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011596
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Alfoldean Roman site, Slinfold		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005838
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Billingshurst		
DESIGNATION:	Conservation Area, 34 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Horsham District Council (LPA)

#### MID SUSSEX



© Historic England

SITE NAME:	Church of Holy Trinity, Church Street, Cuckfield
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1191625

Church mainly constructed in the C13 and C14, comprising nave, chancel, aisles, chapels, vestry, north and south porches, and W tower with shingled broach spire. Walls of sandstone rubble with some areas of rough squared ashlar and render. Significant C19 painted decorative scheme to nave and chancel ceilings by Kempe. At risk due to falls of high level cementicious pointing and decaying stonework to tower; leaking, corroded and blocked rainwater goods and slipping roof slabs,

Contact: Robert Williams 0207 973 3641

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Motte and bailey castle 240m east of Dean's Mill, Lindfield Rural		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011776
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Fairfields, Burgess Hill, Burgess Hill		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Angela Heyward (LPA) 01444 477385

#### SOUTH DOWNS (NP)



SITE NAME: The chapel at the former King Edward VII Hospital, Easebourne, Chichester Listed Building grade II\*, RPG DESIGNATION: grade II CONDITION: Poor

Vacant/not in use

L-shaped former chapel for tuberculosis patients by Charles Holden, 1903-6. Later mortuary wing has been demolished and replaced with a new swimming pool which is in use, but the chapel remains vacant. Most of the repairs have been completed but lack of maintenance is leading to water penetration and damage of original building fabric. Historic England has provided advice to the owner on addressing these issues.

© Historic England

OWNER TYPE: Commercial company

C (C)

LIST ENTRY NUMBER: 1232485

OCCUPANCY:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Contact: Alma Howell 0207 9733 627



© Historic England Archive

SITE NAME: Amberley Limeworks; entrance buildings, Kiln 2 and Office. Houghton Bridge, Amberley / Houghton, Horsham DESIGNATION: Scheduled Monument CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C(C)OWNER TYPE: Charity (heritage)

1005810

C19 lime works including kilns and associated buildings. Historic England grant aided repairs to the Locomotive Shed, Blacksmith's Shop and part of the Loading Shed are now complete. However, the ingress of rainwater, vegetation growth and decay have led to structural weaknesses to the rest of the Loading Shed, the Southern Lime Kilns and Kiln No. 2. The De Witt Kilns were added to the Register following the collapse of part of the parapet wall in 2021. Secured Covid-19 Emergency Heritage at Risk Response funding in 2021.

Contact: Robert Williams 0207 973 3641



© Historic England

SITE NAME:	Castle Goring, Arundel Road , Worthing
DESIGNATION:	Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1025839

Large house. Built by the poet Shelley's grandfather, Sir Bysshe Shelley, about 1797-8. The house was in very poor condition for many years. In 2013 the house was sold to a private individual who is now using it as a private residence and wedding/conference venue. Consent for change of use was granted and repairs to the roof, stairs and structural timbers were carried out but further repairs remain necessary, including to the glass dome.

Contact: Robert Williams 0207 973 3641

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of St Nicholas, London Road, Arundel, Arun
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1027914

Church of England town church, re-built in I 380. The adjacent Fitzalan Chapel and Lady Chapel to the east are in Roman Catholic use. The church is at risk due to spalling stonework, decay to the west window, defective roofs and drainage. In 2020 emergency holding repairs were carried out to the west window, with further discussions to consider its full repair. There were also emergency repairs to the north aisle. However further permanent repairs are required, including to the south aisle.

Contact: Robert Williams 0207 973 3641

SITE NAME:	Flint mine and a bowl barrow on Church Hill, 400r	n south west of Fin	don Place, Findon, Arun
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015238
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Duncton Common round barrow cemetery, Dunc	ton / Petworth, Ch	ichester
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009329
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Devil's Ditch, section extending 900yds (820m), Lye Wood, West Stoke, Funtington, Chichester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005882
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Linear boundary on Stoke Down, 800m north of West Stoke House, Funtington, Chichester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018564
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Flint mine on Stoke Down, immediately north of St	toke Clump, Funtin	gton / Lavant, Chichester
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1018563
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow 500m WNW of Barnett's Bridge, Gr	affham, Chichester	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009910
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Bowl barrow on Gallows Hill, 150m east of Millbor	ough House, Graff	ham, Chichester
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009905
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Two bowl barrows on Gallows Hill, 200m east of I	Millborough House,	Graffham, Chichester
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009906
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow 350m WNW of Barnett's Bridge, Gra	affham / Lodsworth	, Chichester
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009916
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bexley Bushes earthworks, Lavant, Chichester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005892
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Devil's Ditch, section 230yds (210m) long from Ch	ichester main road	to Pook Lane, Lavant, Chichester
designation:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1005877
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Devil's Ditch, section extending 530yds (480m) we	st from Lavant Lod	ge, Lavant, Chichester
DESIGNATION:	Scheduled Monument, part in RPG grade I	LIST ENTRY NUMBER:	1005878
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Remains of iron works and gun foundry at North P	ark Furnace, Linchi	mere / Fernhurst, Chichester
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021403
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Flooding - Local	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Robert Williams 0207 973 3641

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

**ABBREVIATIONS** CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow on Gallows Hill, 300m east of Millborough House, Lodsworth, Chichester			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009908	
CONDITION:	Generally unsatisfactory with major localised TREND: Unknown problems		Unknown	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	Scrub/tree growth NEW ENTRY?:		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Bowl barrow on Fitzhall Rough, 330m ENE of Fit Stedham with Iping, Chichester	zhall: part of Fitzhall	Rough round barrow cemetery,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008503	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth NEW ENTRY?: No		No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Motte and bailey castle in Pulborough Park, Pulborough, Horsham			
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBE		1017547	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Bowl barrow 950m south west of Grey Friars Fa Hill, Storrington and Sullington, Horsham	rm: part of a disperse	ed round barrow cemetery on Kithur	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015711	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Greatham, Horsham (District), Parham, Horshar	n		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	Deteriorating	
vulnerability:	Medium	CONTACT:	Michael Scammell (LPA) 01730 814810	

#### WORTHING



SITE NAME:	Holy Trinity Church, Shelley Road, Worthing		
DESIGNATION:	Listed Place of Worship grade II		
CONDITION:	Poor		
PRIORITY CATEGORY:	C (C)		
OWNER TYPE:	Religious organisation		
LIST ENTRY NILIMBER:	1393419		

Large church, brick with stone dressings. Designed by Henry Coe and Stephen Robinson and built 1882-88. At risk due to eroding high level brick and stonework to the tower and decaying timber shingling to spire. Included in current discussions as part of a wider review of churches in Worthing.

Contact: Robert Williams 0207 973 3641

© Historic England

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

#### WINDSOR AND MAIDENHEAD (UA)



© Historic England

SITE NAME:	Royal Mausoleum, The Home Park, Windsor		
DESIGNATION:	Listed Building grade I, 2 RPGs		
CONDITION:	Fair		
OCCUPANCY:	N/A		
PRIORITY CATEGORY:	F (F)		
OWNER TYPE:	Crown		

1117781

Mausoleum of Queen Victoria and Prince Albert, 1862-71. Damp problems put external and internal historic fabric at risk, including internal paintings. Original rainwater drainage was inadequate and poorly designed. Consented programme of repairs was completed in 2019 to make the exterior weather-tight and prevent moisture from entering the building via the raised perimeter paving. Since 2009 an environmental monitoring regime confirms high level drying out. Regular monitoring continues. It will be some years before the building is dry enough to accommodate interior conservation work.

Contact: Jane Sidell 020 7973 3738



© Historic England

SITE NAME:	Noah's Boathouse, Stonehouse Lane (Off), Cookham
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1323741

LIST ENTRY NUMBER:

1930 by Colin Lucas for his father. Constructed of monolithic reinforced concrete with a flat roof. An early and pioneering example of Modern Movement architecture by one of the major figures in the movement. The building floods regularly and is derelict. The roof is leaking and the concrete is spalling. A project to address the issues needs to be agreed.

Contact: Rachel Fletcher 0207 973 3846



© Historic England

SITE NAME:	The Cock Pitt, 47-49, High Street, Eton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1290036

C15 timber framed building, with approvals for conversion to residential use retaining commercial units at ground floor, works commenced on site, but the developer suffered financial difficulties and as a result work stopped leaving the building partially stripped and in deteriorating condition. An Urgent Works Notice to secure the building was served in 2020, which was complied with by the owner. The property has changed hands and a schedule of repairs is being developed.

Contact: Rachel James 0207 973 3153

SITE NAME:	Beenham's Heath, Waltham St. Lawrence	ham's Heath, Waltham St. Lawrence		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	No significant change	
VULNERABILITY:	Medium	CONTACT:	Roderick McDonald 07969 504 872	

#### **WOKINGHAM (UA)**



© Historic England

SITE NAME:	Ruins of St Bartholomews Church (Arborfield), Arborfield and Newland
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)

OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1006975

Previously the parish church, now a roofless ruin. Originally C13 and built in flint and stone, with substantial probable C18 brick rebuilding. One wall partially standing, with other fragments of later brick segments. Very overgrown and there is a risk of further collapse. A project to see the ruins conserved, explained and maintained still needs to be agreed and implemented.

Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME: Former Infirmary Stables, Arborfield Garrison, Barkham DESIGNATION: Scheduled Monument CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Commercial company

A specialised 'horse hospital' built 1911-12. The building became redundant by virtue of changes in army practices (reduced cavalry activity). Planning Permission for the development of Arborfield Garrison included a requirement to repair the stables. Works to clear asbestos from the site and repair the external envelope have been completed. An end use for the building is being considered and long-term management/maintenance plan agreed.

LIST ENTRY NUMBER: 1006949 Contact: Rachel James 0207 973 3153 © Historic England

SITE NAME:	Ring ditch cropn	Ring ditch cropmark east of St Patrick's Avenue, Charvil			
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1006965	
CONDITION:	Extensive significant problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Educational (state sector)		CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Cropmark complex south west of St Patrick's Avenue, Sonning				
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1006964	
CONDITION:	Extensive significant problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Educational (state sector)		CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Cropmark site east of Broadmoor Lane, Sonning				
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1006963	
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Educational (state sector)		CONTACT:	Alison McQuaid 0207 973 3646	
	SITE NAME:	Bearwood College, Arborfield and Newland / Barkham / Winnersh	This C19 landscape park and woodland surrounds a Victorian country house on formal terraces overlooking picturesque lake with early designs by Gilpin and a		
	DESIGNATION:	Registered Park and Garden grade II*, 5 LBs	gardens and plea charitable trust, 1	n. Subject to resent alterations with the sure grounds a private school and the wider park a golf course and Reading	
	CONDITION:	Extensive significant problems	FC's training site	, the parkland features are varying in nservation Management Plan and liaison	
	VULNERABILITY:	Medium	group agreed fur	nded proposals for the limit and maison	

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

TREND:

**NEW ENTRY?:** 

OWNER TYPE:

LIST ENTRY NUMBER:

Stable

1000414

Mixed, multiple owners

Nο

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

Pulhamite garden works in 2018 with Historic England

advising on how proposals can be progressed.

Contact: Kay Richardson 0207 973 3647

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

This document is one in a series of regional registers produced as part of Historic England's national Heritage at Risk programme.

The registers for other regions and previous Heritage at Risk publications can be found at historicengland.org.uk/advice/heritage-at-risk/registers-and-publications/

More information about Historic England's Heritage at Risk programme can be found at historicengland.org.uk/advice/heritage-at-risk/

Heritage at Risk
Published November 2022
4th Floor, Cannon Bridge House
25 Dowgate Hill
London EC4R 2YA
© Copyright Historic England 2022
Product code: HE0072

